

Programming Guide 11/2002 Edition

sinumerik

Cycles  
SINUMERIK 840D/840Di/810D

**SIEMENS**



# SIEMENS

## SINUMERIK 840D/840Di/810D

### Cycles

#### Programming Guide

General	1
Drilling Cycles and Drilling Patterns	2
Milling Cycles	3
Turning Cycles	4
Error Messages and Error Handling	5
Appendix	A

#### Valid for

<i>Control</i>	<i>Software Version</i>
SINUMERIK 840D	6
SINUMERIK 840DE (export version)	6
SINUMERIK 840D powerline	6
SINUMERIK 840DE powerline	6
SINUMERIK 840Di	2
SINUMERIK 840DiE (export version)	2
SINUMERIK 810D	3
SINUMERIK 810DE (export version)	3
SINUMERIK 810D powerline	6
SINUMERIK 810DE powerline	6

## SINUMERIK® Documentation

### Printing history

Brief details of this edition and previous editions are listed below.

The status of each edition is shown by the code in the "Remarks" column.

*Status code in the "Remarks" column:*

**A ....** New documentation.

**B ....** Unrevised edition with new order no.

**C ....** Revised edition with new status.

If factual changes have been made on the page since the last edition, this is indicated by a new edition coding in the header on that page.

	Order No.	Remarks
02.95	6FC5298-2AB40-0BP0	A
04.95	6FC5298-2AB40-0BP1	C
03.96	6FC5298-3AB40-0BP0	C
08.97	6FC5298-4AB40-0BP0	C
12.97	6FC5298-4AB40-0BP1	C
12.98	6FC5298-5AB40-0BP0	C
08.99	6FC5298-5AB40-0BP1	C
04.00	6FC5298-5AB40-0BP2	C
10.00	6FC5298-6AB40-0BP0	C
09.01	6FC5298-6AB40-0BP1	C
11.02	6FC5298-6AB40-0BP2	C

This manual is included in the documentation available on CD ROM (**DOCONCD**)

Edition	Order No.	Remarks
11.02	6FC5298-6CA00-0BG3	C

### Trademarks

SIMATIC®, SIMATIC HMI®, SIMATIC NET®, SIROTEC®, SINUMERIK®, SIMODRIVE® and SIMODRIVE POSMO® are registered trademarks of Siemens AG. Other names in this publication might be trademarks whose use by a third party for his own purposes may violate the rights of the registered holder.

Further information is available on the Internet under:  
<http://www.ad.siemens.de/sinumerik>

This document was produced with WinWord V8.0 and Designer V7.0.  
The reproduction, transmission or use of this document or its contents is not permitted without express written authority. Offenders will be liable for damages. All rights, including rights created by patent grant or registration of a utility model or design, are reserved.

© Siemens AG, 1995–2002. All rights reserved

Other functions not described in this documentation might be executable in the control. This does not, however, represent an obligation to supply such functions with a new control or when servicing.

We have checked that the contents of this document correspond to the hardware and software described. Nonetheless, differences might exist and we, therefore, cannot guarantee that they are completely identical. The information contained in this document is, however, reviewed regularly and any necessary changes will be included in the next edition. We welcome suggestions for improvement.

Subject to change without prior notice

## Contents

<b>General .....</b>	<b>1-17</b>
1.1 General information.....	1-18
1.2 Overview of cycles .....	1-18
1.2.1 Drilling cycles, drill pattern cycles, milling cycles and turning cycles.....	1-19
1.2.2 Cycle auxiliary subroutines.....	1-20
1.3 Programming cycles.....	1-21
1.3.1 Call and return conditions .....	1-21
1.3.2 Messages during execution of a cycle .....	1-22
1.3.3 Cycle call and parameter list.....	1-23
1.3.4 Simulation of cycles .....	1-26
1.4 Cycle support in program editor (SW 4.3 and higher).....	1-27
1.4.1 Overview of important files.....	1-28
1.4.2 Configuring cycle selection.....	1-29
1.4.3 Configuring input screen forms for parameter assignment.....	1-31
1.4.4 Configuring help displays .....	1-34
1.4.5 Configuring tools (MMC 100 / MMC 100.2 only) .....	1-35
1.4.6 Loading to the control.....	1-36
1.4.7 Independence of language.....	1-37
1.4.8 Operating the cycles support function.....	1-38
1.4.9 Integrating user cycles into the MMC 103 simulation function .....	1-38
1.4.10 Typical user cycle configuration .....	1-39
1.5 Cycle support in program editor (SW 5.1 and higher).....	1-40
1.5.1 Menus, cycle selection .....	1-40
1.5.2 New functions in input screen forms .....	1-41
1.6 Cycle support for user cycles (SW 6.2 and higher).....	1-48
1.6.1 Overview of important files.....	1-48
1.6.2 Entry to cycle support.....	1-48
1.6.3 Cycle support configuration.....	1-49
1.6.4 Bitmap size and screen resolution .....	1-50
1.6.5 Storing bitmaps in data management for HMI Advanced .....	1-51
1.6.6 Handling bitmaps for HMI Embedded .....	1-51
1.7 Cycle startup (SW 6.2 and higher) .....	1-53
1.7.1 Machine data.....	1-53
1.7.2 Definition files for the cycles GUD7.DEF and SMAC.DEF.....	1-54
1.7.3 New form of delivery for cycles in HMI Advanced.....	1-55
1.8 Special functions for cycles.....	1-56

<b>Drilling Cycles and Drilling Patterns .....</b>	<b>2-59</b>
2.1 Drilling cycles.....	2-60
2.1.1 Preconditions.....	2-62
2.1.2 Drilling, centering – CYCLE81.....	2-64
2.1.3 Drilling, counterboring – CYCLE82.....	2-67
2.1.4 Deep-hole drilling – CYCLE83.....	2-69
2.1.5 Rigid tapping – CYCLE84.....	2-77
2.1.6 Tapping with compensating chuck – CYCLE840 .....	2-83
2.1.7 Boring 1 – CYCLE85 .....	2-91
2.1.8 Boring 2 – CYCLE86 .....	2-94
2.1.9 Boring 3 – CYCLE87 .....	2-98
2.1.10 Boring 4 – CYCLE88 .....	2-101
2.1.11 Boring 5 – CYCLE89 .....	2-103
2.2 Modal call of drilling cycles .....	2-105
2.3 Drill pattern cycles .....	2-108
2.3.1 Preconditions.....	2-108
2.3.2 Row of holes – HOLES1.....	2-109
2.3.3 Hole circle – HOLES2.....	2-113
2.3.4 Dot matrix – CYCLE801 (SW 5.3 and higher).....	2-116
<b>Milling Cycles .....</b>	<b>3-119</b>
3.1 General information.....	3-120
3.2 Preconditions.....	3-121
3.3 Thread cutting – CYCLE90.....	3-123
3.4 Elongated holes on a circle – LONGHOLE .....	3-129
3.5 Slots on a circle – SLOT1.....	3-135
3.6 Circumferential slot – SLOT2 .....	3-143
3.7 Milling rectangular pockets – POCKET1 .....	3-149
3.8 Milling circular pockets – POCKET2.....	3-153
3.9 Milling rectangular pockets – POCKET3 .....	3-157
3.10 Milling circular pockets – POCKET4.....	3-167
3.11 Face milling – CYCLE71 .....	3-173
3.12 Path milling – CYCLE72 .....	3-179
3.13 Milling rectangular spigots – CYCLE76 (SW 5.3 and higher).....	3-189
3.14 Milling circular spigots – CYCLE77 (SW 5.3 and higher).....	3-194
3.15 Pocket milling with islands – CYCLE73, CYCLE74, CYCLE75 (SW 5.2 and higher)...	3-198

3.15.1	Transfer pocket edge contour – CYCLE74 .....	3-199
3.15.2	Transfer island contour – CYCLE75 .....	3-201
3.15.3	Contour programming .....	3-202
3.15.4	Pocket milling with islands – CYCLE73 .....	3-204
3.16	Swiveling – CYCLE800 (SW 6.2 and higher) .....	3-227
3.16.1	Operation, parameter assignment, input screen form .....	3-229
3.16.2	Operating instructions .....	3-233
3.16.3	Parameters.....	3-234
3.16.4	Starting up CYCLE800 .....	3-238
3.16.5	User cycle TOOLCARR.spf.....	3-253
3.16.6	Error messages.....	3-258
3.17	High Speed Settings – CYCLE832 (SW 6.3 and higher) .....	3-259
3.17.1	Calling CYCLE832 in the HMI menu tree.....	3-262
3.17.2	Parameters.....	3-265
3.17.3	Customizing technology .....	3-266
3.17.4	Interfaces .....	3-268
3.17.5	Error messages.....	3-270
<b>Turning Cycles .....</b>		<b>4-271</b>
4.1	General information.....	4-272
4.2	Preconditions.....	4-273
4.3	Grooving cycle – CYCLE93.....	4-277
4.4	Undercut cycle – CYCLE94.....	4-287
4.5	Stock removal cycle – CYCLE95 .....	4-291
4.6	Thread undercut – CYCLE96 .....	4-304
4.7	Thread cutting – CYCLE97 .....	4-308
4.8	Thread chaining – CYCLE98.....	4-316
4.9	Thread recutting (SW 5.3 and higher).....	4-323
4.10	Extended stock removal cycle – CYCLE950 (SW 5.3 and higher) .....	4-325
<b>Error Messages and Error Handling .....</b>		<b>5-347</b>
5.1	General information.....	5-348
5.2	Troubleshooting in the cycles.....	5-348
5.3	Overview of cycle alarms .....	5-349
5.4	Messages in the cycles .....	5-355

<b>Appendix .....</b>	<b>A-357</b>
A Abbreviations .....	A-358
B Terms .....	A-367
C References .....	A-375
D Index .....	A-389
E Identifiers .....	A-393



## Structure of the manual

The SINUMERIK documentation is organized in three parts:

- General Documentation
- User Documentation
- Manufacturer/Service Documentation.

## Target group

This documentation is intended for users of machine tools. This publication provides detailed information that the user requires for operating the SINUMERIK 810D and 840D controls.

## Standard scope

This programming guide describes the standard functions. Differences and additions implemented by the machine-tool manufacturer are documented by the machine manufacturer.

More detailed information about other publications concerning SINUMERIK 810D and 840D and publications that apply to all SINUMERIK controls (e.g. Universal Interface, Measuring Cycles...) can be obtained from your local Siemens branch office.

Other functions not described in this documentation might be executable in the control. This does not, however, represent an obligation to supply such functions with a new control or when servicing.

## Applicability

This Programming Guide is valid for the following controls:

SINUMERIK 840D	SW 6
SINUMERIK 840DE (export version)	SW 6
SINUMERIK 840Di	SW 2
SINUMERIK 840DiE (export version)	SW 2
SINUMERIK 810D	SW 6
SINUMERIK 810DE (export version)	SW 6
with operator panels OP 010, OP 010C, OP 010S, OP 12 or OP 15 (PCU 20 or PCU 50)	

## SINUMERIK 840D powerline

From 09.2001 onwards, higher-performance versions of

- SINUMERIK 840D powerline and
- SINUMERIK 840DE powerline

will be available. For a list of the available powerline modules, please refer to Section 1.1 of the Hardware Description /PHD/.

## SINUMERIK 810D powerline

From 12.2001 onwards, higher-performance versions of

- SINUMERIK 810D powerline and
- SINUMERIK 810DE powerline

will be available. For a list of the available **powerline** modules, please refer to Section 1.1 of the Hardware Description /PHC/.

## Structure of descriptions

All cycles and program functions were laid out according to the same structure, as far as possible and practicable. The various levels of information have been structured so that you can find the information you are looking for quickly.

### 1. The function at a glance

If you need to look up a cycle that is rarely used or the meaning of a parameter, you will see at a glance how the function is programmed together with an explanation of the cycles and parameters.

This information always appears at the beginning of the page.

#### Note:

In order to keep the documentation succinct we have not provided all the methods or representation of the individual cycles and parameters that are possible in the programming language. Cycles have been programmed in the form in which they most frequently arise on the shop floor.

2 Drilling cycles and drilling patterns 03.96
2

### 2.1 Drilling cycles

#### 2.1.2 Drilling, centering – CYCLE81


##### Programming

CYCLE81 (RTP, RFP, SDS, DP)

RTP	real	Retraction plane (absolute)
RFP	real	Reference plane (absolute)
SDS	real	Safety clearance (enter without sign)
DP	real	Final drilling depth (absolute)
DPR	real	Final drilling depth relative to reference plane (enter without sign)

##### Function

The tool drills at the programmed spindle speed and feedrate to the programmed final drilling depth.



##### Operating sequence

Position reached before the beginning of the cycle:  
The drilling position is the position in the two axes of the selected plane.

The cycle implements the following motion sequence:

- Approach of the reference plane brought forward by the safety clearance with G0
- Travel to the final drilling depth at the feedrate programmed in the calling program (G1)
- Retraction to retraction plane with G0

2-36 © Siemens AG 1997 All rights reserved. SINUMERIK 840D/810D/810DE Programming Guide, Cycles (PGZ) – 11.02 Edition.



## 2. Detailed explanations

In the theoretical sections, you are provided with a detailed description of the following:



What is the cycle used for?



What does the cycle do?



What is the sequence of operations?



What do the parameters do?

What else do you have to look out for?

The theoretical sections provide learning material for the NC beginner. You should work through the manual at least once to get an idea of the scope of the functions and capability of your SINUMERIK control.



## 3. From theory to practice

The programming example shows you how to include the cycles in an operating sequence.

An application example of almost all the cycles is provided after the theoretical section.

2 Drilling cycles and drilling patterns 2.1 Drilling cycles 2

**Explanation of parameters**

**RFP and RTP**  
Generally, the reference plane (RFP) and the retraction plane (RTP) have different values. In the cycle it is assumed that the retraction plane lies in front of the reference plane. The distance between the retraction plane and the final drilling depth is therefore greater than the distance between the reference plane and the final drilling depth.

**SDIS**  
The safety clearance (SDIS) refers to the reference plane, which is brought forward by the safety clearance. The direction in which the safety clearance is active is automatically determined by the cycle.

**DP and DPR**  
The drilling depth can be defined either absolute (DP) or relative (DPR) to the reference plane. If it is entered as an absolute value, the value is traversed directly in the cycle.

**Additional notes**

If a value is entered both for the DP and the DPR, the final drilling depth is derived from the DPR. If the DPR deviates from the absolute depth programmed via the DP, the message "Depth: Corresponds to value for relative depth" is output in the dialog line.

© Siemens AG 1987. All rights reserved. SINUMERIK 840D/840Di/810D Programming Guide, Cycles (PGZ) – 08.07 Edition. 2-37

2 Drilling cycles and drilling patterns 2.1 Drilling cycles 2





If the values for the reference plane and the retraction plane are identical, a relative depth must not be programmed. The error message 01101 "Reference plane incorrectly defined" is output and the cycle is not executed. This error message is also output if the retraction plane lies behind the reference plane, i.e. the distance to the final drilling depth is smaller.

**Programming example**

**Drilling centering**  
You can use this program to make 3 holes using the drilling cycle CYCLE81, whereby this cycle is called with different parameter settings. The drilling axis is always the Z axis.

N10 G0 G90 F200 S300 M3	Specification of the technology values
N20 S3 T1 Z10	Traverse to retraction plane
N30 X40 Y120	Traverse to first drilling position
N40 CYCLE81 (110, 100, 2, . 35)	Cycle call with absolute final drilling depth, safety clearance and incomplete parameter list
REF F30	Traverse to next drilling position
N60 CYCLE81 (110, 102, . 35)	Cycle call without safety clearance
N70 G0 G90 F180 S300 M03	Specification of the technology values
N80 X90	Traverse to next position
N90 CYCLE81 (110, 100, 2, . 65)	Cycle call with relative final drilling depth and safety clearance
N100 M30	End of program

© Siemens AG 1987. All rights reserved. SINUMERIK 840D/840Di/810D Programming Guide, Cycles (PGZ) – 08.07 Edition. 2-38

 Explanation of symbols Sequence of operations Explanation Function Parameters Sample program Programming Additional notes Cross-reference to other documentation or sections Danger notes and sources of error Additional notes or background information

### Warning notes

The following warning notes with graded degrees of importance are used in this documentation.



### Danger

Indicates an imminently hazardous situation which, if not avoided, **will** result in death or serious injury or in substantial property damage.



### Warning

Indicates a potentially hazardous situation which, if not avoided, **could** result in death or serious injury or in substantial property damage.



### Caution

Used with the safety alert symbol indicates a potentially hazardous situation which, if not avoided, **may** result in minor or moderate injury or in property damage.

### Caution

Used without safety alert symbol indicates a potentially hazardous situation which, if not avoided, **may** result in property damage.

### Notice

Used without the safety alert symbol indicates a potential situation which, if not avoided, **may** result in an undesirable result or state.

**Principle**

Your SIEMENS 810D and 840D have been designed and constructed to the latest standards of technology and recognized safety rules, standards and regulations.

**Additional equipment**

The applications of SIEMENS controls can be expanded by adding special additional devices, equipment and expansion units supplied by SIEMENS.

**Personnel**

Only **authorized and reliable personnel who have been trained in the use of the equipment** may be allowed to handle the control. Nobody without the necessary training must be allowed to operate the control, even temporarily.

The corresponding **responsibilities** of personnel who set up, operate and maintain the equipment must be clearly **defined** and adherence to these responsibilities **monitored**.

**Behavior**

**Before** the control is started up, the personnel who are to work on the control must be thoroughly acquainted with the Operator's Guides. The operating company is also responsible for **constantly monitoring** the overall technical state of the control (noticeable faults and damage, altered service performance).

**Servicing**

Repairs must be carried out by personnel who are **specialty trained and qualified** in the relevant technical subject according to the information supplied in the service and maintenance guide. All relevant safety regulations must be followed.

**Note**

The following is deemed to be **improper usage** and **exempts the manufacturer from any liability**:

**Any** application which does not comply with the rules for proper usage described above.

If the control is **not in technically perfect condition** or is operated without due regard for safety regulations and accident prevention instructions given in the Instruction Manual.

If faults that might affect the safety of the equipment are not rectified **before** the control is started up.

Any **modification, bypassing** or **disabling** of items of equipment on the control that are required to ensure fault-free operation, unlimited use and active and passive safety.



Improper usage may result in **unforeseen dangers** to:

- life and limb of personnel
- the control, machine and other assets of the owner and the user.

## Notes



## General

1.1	General information.....	1-18
1.2	Overview of cycles .....	1-18
1.2.1	Drilling cycles, drill pattern cycles, milling cycles and turning cycles .....	1-19
1.2.2	Cycle auxiliary subroutines .....	1-20
1.3	Programming cycles.....	1-21
1.3.1	Call and return conditions .....	1-21
1.3.2	Messages during execution of a cycle .....	1-22
1.3.3	Cycle call and parameter list.....	1-23
1.3.4	Simulation of cycles .....	1-26
1.4	Cycle support in program editor (SW 4.3 and higher).....	1-27
1.4.1	Overview of important files.....	1-28
1.4.2	Configuring cycle selection .....	1-29
1.4.3	Configuring input screen forms for parameter assignment.....	1-31
1.4.4	Configuring help displays .....	1-34
1.4.5	Configuring tools (MMC 100 / MMC 100.2 only).....	1-35
1.4.6	Loading to the control.....	1-36
1.4.7	Independence of language .....	1-37
1.4.8	Operating the cycles support function.....	1-38
1.4.9	Integrating user cycles into the MMC 103 simulation function.....	1-38
1.4.10	Typical user cycle configuration .....	1-39
1.5	Cycle support in program editor (SW 5.1 and higher).....	1-40
1.5.1	Menus, cycle selection .....	1-40
1.5.2	New functions in input screen forms .....	1-41
1.6	Cycle support for user cycles (SW 6.2 and higher).....	1-48
1.6.1	Overview of important files.....	1-48
1.6.2	Entry to cycle support.....	1-48
1.6.3	Cycle support configuration.....	1-49
1.6.4	Bitmap size and screen resolution .....	1-50
1.6.5	Storing bitmaps in data management for HMI Advanced .....	1-51
1.6.6	Handling bitmaps for HMI Embedded.....	1-51
1.7	Cycle startup (SW 6.2 and higher) .....	1-53
1.7.1	Machine data.....	1-53
1.7.2	Definition files for the cycles GUD7.DEF and SMAC.DEF.....	1-54
1.7.3	New form of delivery for cycles in HMI Advanced.....	1-55
1.8	Special functions for cycles .....	1-56

## 1.1 General information

The first section provides you with an overview of the available cycles. The following sections describe the general conditions that apply to all cycles regarding

- Programming the cycles and
- Operator guidance for calling the cycles.

## 1.2 Overview of cycles

Cycles are generally applicable technology subroutines with which you can implement specific machining processes such as tapping a thread or milling a pocket. These cycles are adapted to individual tasks by defining parameters.

The system provides you with various standard cycles for the technologies

- Drilling
- Milling
- Turning.

### 1.2.1 Drilling cycles, drill pattern cycles, milling cycles and turning cycles

You can perform the following cycles with the SINUMERIK 810D and 840D controls:

#### Drilling cycles

CYCLE81	Drilling, centering
CYCLE82	Drilling, counterboring
CYCLE83	Deep hole drilling
CYCLE84	Rigid tapping
CYCLE840	Tapping with compensating chuck
CYCLE85	Boring 1
CYCLE86	Boring 2
CYCLE87	Boring 3
CYCLE88	Boring 4
CYCLE89	Boring 5

#### Drill pattern cycles

HOLES1	Machining a row of holes
HOLES2	Machining a circle of holes

New in SW 5.3 and higher:

CYCLE801	Grid of holes
----------	---------------

#### Milling cycles

LONGHOLE	Milling pattern of elongated holes on a circle
SLOT1	Groove milling pattern arranged on a circle
SLOT2	Circumferential groove milling pattern
POCKET1	Rectangular pocket milling (with face cutter)
POCKET2	Circular pocket milling (with face cutter)
CYCLE90	Thread milling

New in SW 4 and higher:

POCKET3	Rectangular pocket milling (with any milling tool)
POCKET4	Circular pocket milling (with any milling tool)
CYCLE71	Face milling
CYCLE72	Contour milling

## 1.2 Overview of cycles

New in SW 5.2 and higher:

CYCLE73 Pocket milling with islands

CYCLE74 Transfer of pocket edge contour

CYCLE75 Transfer of isolated contour

New in SW 5.3 and higher:

CYCLE76 Mill a rectangular spigot

CYCLE77 Mill a circular spigot

### Turning cycles

CYCLE93 Groove

CYCLE94 Undercut (shape E and F according to DIN)

CYCLE95 Stock removal with relief cut

CYCLE96 Thread undercut (shapes A, B, C and D according to DIN)

CYCLE97 Thread cutting

CYCLE98 Chaining of threads

New in SW 5.1 and higher:

CYCLE950 Extended stock removal

### 1.2.2 Cycle auxiliary subroutines

The following auxiliary routines are part of the cycles package

- PITCH and
- MESSAGE.

These must always be loaded in the control.

### 1.3 Programming cycles

A standard cycle is defined as a subroutine with a name and a parameter list. The conditions described in "SINUMERIK Programming Guide Part 1: Fundamentals" apply when calling a cycle.



The cycles are supplied on diskette or, for the MMC 102, with the corresponding software release. They are loaded into the parts program memory of the control via the RS-232 interface (see Operator's Guide).


#### 1.3.1 Call and return conditions

The G functions active before the cycle is called and the programmable frame remain active beyond the cycle.

Define the machining plane (G17, G18, G19) before calling the cycle. A cycle operates in the current plane with

- Abscissa (1st geometry axis)
- Ordinate (2nd geometry axis)
- Applicate (3rd geometry axis of the plane in space).

In drilling cycles, the hole is machined in the axis that corresponds to the applicate of the current plane. The depth infeed is performed in this axis with milling applications.



#### Plane and axis assignments

Command	Plane	Perpendicular infeed axis
G17	X/Y	Z
G18	Z/X	Y
G19	Y/Z	X

### 1.3.2 Messages during execution of a cycle

For some cycles, messages that refer to the state of machining are displayed on the control screen during execution.

These messages do not interrupt program processing and continue to be displayed on the screen until the next message appears.

The message texts and their meanings are listed together with the cycle to which they refer.



You will find a summary of all the relevant messages in Appendix A of this Programming Guide.

#### **Block display during execution of a cycle**

The cycle call is displayed in the current block display for the duration of the cycle.

### 1.3.3 Cycle call and parameter list

The standard cycles use user-defined variables. You can transfer the defining parameters for the cycles via the parameter list when the cycle is called.



*Cycle calls must always be programmed in a separate block.*

#### **Basic instructions regarding assignment of standard cycle parameters**

The Programming Guide describes the parameter list of every cycle together with the

- sequence and
- type.

The sequence of the defining parameters must be observed.

Each defining parameter of a cycle is of a specific data type. The parameter type in use must be specified when the cycle is called. In the parameter list, you can transfer

- variables or
- constants.

If variables are transferred to the parameter list, they must first be defined as such and assigned values in the calling program. Cycles can be called

- with an incomplete parameter list or
- by leaving out parameters.

If you want to exclude the last transfer parameters that have to be written in a call, you can prematurely terminate the parameter list with ")". If you wish to leave out parameters in between, a comma, "...", "... " is used as placeholder.



No plausibility checks are made of parameter values with a discrete or limited value range unless an error response has been specifically described for a cycle.

If the parameter list contains more entries than defined as parameters in the cycle when the cycle is called, the general NC alarm 12340 "Too many parameters" is generated. The cycle is not executed in this case.

### Cycle call

The various methods for writing a cycle call are shown in the following example, CYCLE100, which requires the following input parameters.

#### Example

FORM	Definition of the machined shape Values: E and F
MID	Infeed depth (to be entered without a sign)
FFR	Feedrate
VARI	Machining type Values: 0, 1 or 2
FAL	Final machining allowance

The cycle is called with command  
CYCLE100 (FORM, MID, FFR, VARI, FAL).

#### 1. Parameter list with constant values

Rather than input individual parameters, you can directly enter the concrete values to be used in the cycle.

#### Example

CYCLE100 ("E", 5, 0.1, 1, 0)	Cycle call
------------------------------	------------

#### 2. Parameter list with variables as transfer parameters

You can transfer the parameters as arithmetic variables that you define and assign values before you call the cycle.



**Example**

DEF CHAR FORM="E"	Definition of a parameter, value assignment
DEF REAL MID=5, FFR, FAL	Definition of parameters with or without value assignments
DEF INT VARI=1	
N10 FFR=0.1 FAL=0	Value assignments
N20 CYCLE100 (FORM, MID, FFR, -> -> VARI, FAL)	Cycle call

**3. Use of predefined variables as transfer parameters**

For defining cycles with parameters you may use variables such as R parameters (R variables).

**Example**

DEF CHAR FORM="E"	Definition of a parameter, value assignment
N10 R1=5 R2=0.1 R3=1 R4=0	Value assignments
N20 CYCLE100 (FORM, R1, -> -> R2, R3, R4)	Cycle call

As R parameters are predefined as real, it is important to ensure that the type of the target parameter in the cycle is compatible with the type real.



More detailed information about data types and type conversion and compatibility is given in the Programming Guide. If the types are incompatible, alarm 12330 "Parameter type ... incorrect" is issued.

**4. Incomplete parameter list and omission of parameters**

If a defining parameter is not required for a cycle call or it is to be assigned the value zero, it can be omitted from the parameter list. A comma, "... , ..." must be written in its place to ensure the correct assignment of the following parameters or the parameter list must be concluded prematurely with ")".

## 1.3 Programming cycles

### Example

```
CYCLE100 ("F", 3, 0.3, , 1)
```

Cycle call,  
omit 4th parameter (i.e. zero setting)

```
CYCLE100 ("F", 3, 0.3)
```

Cycle call  
the value zero is assigned to the last two  
parameters (i.e. they have been left out)

### 5. Expressions in the parameter list

Expressions, the result of which is assigned to the corresponding parameter in the cycle are also permitted in the parameter list.

### Example

```
DEF REAL MID=7, FFR=200
```

Definition of the parameters, value  
assignments

```
CYCLE100 ("E", MID*0.5, FFR+100,1)
```

Cycle call  
Infeed depth 3.5, feedrate 300

### 1.3.4 Simulation of cycles

Programs with cycle calls can be tested initially by the simulation function.



#### Function

In configurations with an MMC 100.2, the program is executed normally in the NC and the traversing motion is recorded on the screen during the simulation run.

In configurations with an MMC 103, the program is simulated solely in the MMC. For this reason, it is possible to execute cycles without tool data or without prior selection of a tool offset in the MMC with SW 4.4 and higher.

The finished contour is then traversed in the case of cycles which have to include tool offset data in the calculation of their traversing motion (e.g. milling pockets and grooves, turning with recess) and a message is output that simulation without tool is active.

This function can be used, for example, to check the position of the pocket.

## 1.4 Cycle support in program editor (SW 4.3 and higher)

The program editor in the control provides you with programming support to add cycle calls to the program and enter parameters.

In this way, support is provided both for Siemens cycles and user cycles.



### Function

The cycle support consists of the three components:

1. Cycle selection
2. Input screen forms for parameter setting
3. Help display per cycle.

It is not absolutely necessary to create help displays when incorporating separate cycles; then, only the input screen forms are displayed for the cycles.

It is also possible to configure the text files of the cycle support as language-independent. In this case, the corresponding text files, located in the MMC, are also required.



A detailed description of the program editor is given in

**References:** /BA/, "Operator's Guide"

### 1.4.1 Overview of important files

The following files form the basis for cycle support:

<b>Assignment</b>	<b>File</b>	<b>Application</b>	<b>File type</b>
Cycle selection	cov.com	Standard and user cycles	Text file
Input screen form for parameter setting	sc.com	Standard cycles	Text file
Input screen form for parameter setting	uc.com	User cycles	Text file
Help displays	*.bmp	Standard or user cycles	Bitmap



For MMC 100/MMC 100.2 the help displays must be converted into another format (\*.pcx) and linked to produce a loadable file (cst.arj).

## 1.4.2 Configuring cycle selection



### Function


The cycle selection is configured in the cov.com file:

- The cycle selection is assigned directly to soft keys that are configured in the cov.com file.
- Up to three soft key levels with up to 18 soft keys are supported; this enables the cycles to be classified in subsets, e.g. of one technology.
- If a maximum of six cycles are configured on one of the soft key levels, they all lie on a vertical soft key tree. The 7th and 8th soft keys are reserved for operator functions such as **"Back"** or **"Abort"** or **"OK"**.

If the corresponding level contains more than six cycles, then the program labels the 7th soft key with ">>" and switches the vertical soft key over to the 2nd level.

- Only five soft keys are available on the first level, the first soft key is reserved.

Example for cycle selection





## Programming

### Syntax of the cov.com file (example)

```

%_N_COV_COM
; $PATH=/_N_CUS_DIR
; V04.03.01/10.09.97
S2.0.0\Turning\
S3.0.0\Drilling\
S4.0.0\Milling\
S5.0.0\Threads\
S6.0.0\Users\
S3.1.0\Deep hole %ndrilling\C3(CYCLE83)           Deep hole drilling
S3.2.0\Boring\
S3.2.1\Boring%n1\C6(CYCLE85)                       Boring 1
...
M17

```

### Explanation of syntax

$Sx.y.z$	Soft key number and level, the decimal point is used to separate the three numbers x denotes the soft key of the 1st level (2 to 18 are possible) y denotes the soft key of the 2nd level (1 to 18 are possible). z denotes the soft key of the 3rd level (1 to 18)
$\backslash\text{text}\backslash$	Soft key text, maximum of 2 · 9 characters The separator character is "%n"
$Cxx$	Help display name, a "p" is added to the name of the help display file for cycle support, e.g. Cxpx.bmp
(Name)	Cycle name that is written to the program and is present in the input screen form for parameter setting.

After the cycle name, you can write a comment separated from the name by at least one blank.



### Special points relating to MMC 102/103

If this file is language-independent, i.e. configured in plain text, the file name must include a language code, e.g.:

- COV\_GR.COM for German,
  - COV\_UK.COM for English,
  - COV\_ES.COM for Spanish,
  - COV\_FR.COM for French,
  - COV\_IT.COM for Italian,
- or other codes for different languages.

### 1.4.3 Configuring input screen forms for parameter assignment

The SC.COM (Siemens cycles) and UC.COM (user cycles) files provide the basis for configuring the input screen form for parameter setting. The syntax is identical for both files.



#### Explanation

The following is an example of the cycle header:

```

Name of help display
|
|   Cycle name
|   |
|   |   Comments
|   |   |
//C6 (CYCLE85) Boring 1
  
```

//	Header detection for a cycle description
C6	Name of the help display with a p added (C1 – C28 Siemens Cycles)
(CYCLE85)	Name of the cycle. This name is also written to the NC program.
Boring 1	Comments (is not evaluated)

#### Cycle parameterization

```
(R/0 2/1/Return plane, absolute)[return plane/RTP]
```

Start	(
Variable type	R     REAL I     INTEGER C     CHARACTER S     STRING
Separator	/
Value range	Lower limit, blank, upper limit (e.g. 0 2)
Separator	/
Default value	one value (e. g. 1)
Separator	/
Long text	is output in the dialog line
End	)
Start option	[
Short text	appears in the parameterization screen form
Separator	/
Text in bitmap	Parameter name
End option	]

Instead of limiting a value range, it is possible to define individual values by enumeration. These are then selected for input using the toggle button.

## 1.4 Cycle support in program editor (SW 4.3 and higher)

```
(I/* 1 2 3 4 11 12 13 14/11/Selecting the
operating mode)[Operating mode / VARI]
```



In order to achieve compatibility with the states of the cycle support for interactive programming of the MMC 102/103, only the section in round brackets is mandatory. The section in square brackets is optional. Values do not have to be provided for lower/upper limit and default, see programming example.



### Explanation

If the section in square brackets is missing, proceed as follows:

Short text=	the first 19 characters of the long text but only up to the first blank from the right or up to the first comma from the left. Shortened texts are marked with an asterisk " * "
Text in bitmap=	is read from the Cxx.awb file





### Programming example

Cycle support for the cycle:  
 corresponds to the COM files SW4  
 MMC 100/MMC 100.2 and cycle support ASCII  
 Editor MMC 102/103

```
//C6(CYCLE85)                                     Boring 1
(R///Retraction plane, absolute)[Retraction plane/RTP]
(R///Reference plane, absolute)[Reference plane/RFP]
(R/0 99999//Safety distance, without sign)
[safety distance/SDIS]
(R///Final drilling depth, absolute)[Final drilling depth/DP]
(R/0 99999/0/Final drilling depth relative to reference plane)[Final
drilling depth rel./,DPR]
(R/0 99999//Dwell at drilling depth)[Dwell BT/DTB]
(R/0.001 999999//Feedrate)[Feedrate/FFR]
(R/0.001 999999//Return feedrate)[Return feedrate/RFF]
```

CYCLE85

→ G0   → G1   ⚙ G4

Retraction plane	RTP	<input type="text" value=""/>
Reference plane	RFP	<input type="text" value=""/>
Safety clearance	SDIS	<input type="text" value=""/>
Final drilling depth	DP	<input type="text" value=""/>
Final drilling depth, rel. DPR		<input type="text" value="0"/>
Dwell BT	DTB	<input type="text" value=""/>
Feedrate	FFR	<input type="text" value=""/>
Return feedrate	RFF	<input type="text" value=""/>

Retraction plane, absolute

EXIT

Abort

OK

### 1.4.4 Configuring help displays



#### Explanation

##### Help displays for MMC 100/MMC 100.2

If you wish to modify the standard graphics or create additional graphics, you will need to have a graphic program on your PC. The size of the graphic is limited to max. 272 · 280 pixels. It is recommended that you make all graphics the same size.

The MMC uses the PCX format of Zsoft Paintbrush as graphic format. If you do not have a graphic program that can create this format, you can use the Paint Shop Pro program to convert your graphics.


The names of the bitmaps are directly related to file uc.com. If a file is configured there, for example with //C60 (POSITION1), the bitmap must be called C60.bmp for MMC 100.2 or C60p.bmp for MMC 103.



**The Paint Shop Pro application is not included on the diskette supplied by Siemens.**

##### Help displays for MMC 102/103

The help displays of the MMC 102/103 are located in the file system under the directory H\DP.DIR\HLP.DIR. You can use the "Copy" function in the Services menu to read data from a floppy disk. To do this, select the destination directory via "Interactive programming" and "DP Help".



### 1.4.5 Configuring tools (MMC 100 / MMC 100.2 only)



#### Explanation

For MMC 100 / MMC 100.2, you also require a conversion tool to convert the file format from \*.bmp to \*.pcx.

This tool is located on the delivery diskette under the path MMC100/MMC100.2\TOOLS.

This enables you to carry out conversion and compression to produce a loadable file for MMC 100 / MMC 100.2.



The PCX files are converted and subsequently compressed into an archive file by means of the tools **PCX\_CON.EXE** and **ARJ.EXE**. These tools are contained on the diskette.

The files to be converted must all reside on one path, multiple paths are not supported.

Conversion routine call:

```
makepcx.bat
```

All parameters required have already been stored in this file.

The conversion produces the files \*.b00 \*.b01 and \*.b02. Prior to compression, copy all these files (\*.b0\*) as well as the arj.exe tool into a path and start the following call:

```
arj a cst.arj *.*
```

### 1.4.6 Loading to the control

#### Loading with MMC 100 / MMC 100.2

##### Precondition

The application diskette has already been installed on your PC.



##### Sequence of operations

- Change to directory "**INSTUTIL**" in your application path and start "**APP\_INST.EXE**". The selection menu for software installation is displayed.
- Select menu option "**Modify configuration**". A further selection menu appears. In this menu select the option "**Add \*.\* Files ...**". As the file name enter your graphics file path and file name "**CST.ARJ**" in the input screen form.
- Press the Return key to confirm your input.
- Press **Esc** to return to the main menu where you can transfer your software to the hardware.

#### Loading to MMC 102/103



##### Sequence of operations

The help displays for cycle support are located in the directory

Interactive programming\DP help.

They are entered from the diskette in long format using the operations

- "Data Management" and
- "Copy".

### 1.4.7 Independence of language



#### Explanation

Cycle support files can also be configured as language-independent.

This is done by replacing all the texts in the cov.com and sc.com files by text numbers. In addition, a text file is also required in the control.

The aluc.txt file with text number range 85000...89899 is reserved for user cycles.

This file is named aluc\_(language).com in the MMC 103 and stored in directory DHMB.DIR (MBDDE alarm texts) in the file system.

#### Example:

```
//C60 (POSITION1)
(R///$85000) [$85001/XWERT]
(R///$85002) [$85003/YWERT]
(R///$85004) [$85005/ZWERT]
```

#### Relevant text file:

85000	0	0	Position for the 1st axis of the plane
85001	0	0	Position X
85002	0	0	Position for the 2nd axis of the plane
85003	0	0	Position Y
85004	0	0	Position for the 3rd axis of the plane
85005	0	0	Position Z

#### Explanation of the syntax:

\$	Identifier for text numbers
85000...89899	Text number for user cycles
\$85000... \$...	Several texts are concatenated

**1.4.8 Operating the cycles support function****Explanation**

Carry out the steps below to add a cycle call to a program:

- Soft key "Support" in the horizontal soft key bar.
- Soft key "new cycle" (MMC 102/103 only).
- Select the cycle via the vertical soft key bar until the corresponding input screen form appears (the help display appears on the MMC 100 / MMC 100.2 when you press the Info key).
- Enter the parameter value.
- With the MMC 103, it is also possible to input the name of a variable instead of a value in the screen form; the variable name always starts with a letter or an underscore.
- Hit "OK" to confirm (or "Abort" if the input is incorrect).

**1.4.9 Integrating user cycles into the MMC 103 simulation function****Explanation**

If you wish to simulate user cycles in the MMC 103, the call line for each cycle must be entered in file dpcuscyc.com in directory DH\DP.DIR\SIM.DIR. The call line must be entered there for each cycle.

**Programming example**

A user cycle named POSITION1 with 3 transfer parameters is loaded to the control for simulation.

```

%_N_POSITION1_SPF
; $PATH=/_N_CUS_DIR
PROC POSITION1 (REAL XWERT, REAL YWERT, REAL ZWERT)
...
M17

```

The following line

```
PROC POSITION1 (REAL XWERT, REAL YWERT, REAL ZWERT)
```

must then be entered in file dpcuscyc.com.

### 1.4.10 Typical user cycle configuration



#### Programming example

1. Change cov.com (menu configuration)

S6.0.0\User\  
S6.1.0\Position1\

2. Configuring in uc.com (master configuration)

```
//C60 (POSITION1)
(R///$85000) [$85001/XWERT]
(R///$85002) [$85003/YWERT]
(R///$85004) [$85005/ZWERT]
```

3. Configuring in aluc.txt (text file)

85000	0	0	Position for the 1st axis of the plane
85001	0	0	Position X
85002	0	0	Position for the 2nd axis of the plane
85003	0	0	Position Y
85004	0	0	Position for the 3rd axis of the plane
85005	0	0	Position Z

4. Bitmap

C60.bmp for MMC 100.2

C60p.bmp in path DH\DP.DIR\HLP.DIR for MMC 103

5. Integrate in simulation MMC 103

see Subsection 1.4.9

## 1.5 Cycle support in program editor (SW 5.1 and higher)

As from SW 5.1, the program editor offers an extended cycle support for Siemens and user cycles.



### Function

The cycle support offers the following functions:

- Cycle selection via soft keys
- Input screen forms for parameter assignment with help displays
- Online help for each parameter (with MMC 103 only)
- Support of contour input.

Retranslatable code is generated from the individual screen forms.

### 1.5.1 Menus, cycle selection




#### Explanation

The cycle selection is carried out technology-oriented via soft keys:

Contour	Geometry input via the geometry processor or contour definition screen forms.
Drill	Input screen forms for drilling cycles and drilling patterns.
Milling	Input screen form for milling cycles.
Turning	Input screen forms for turning cycles.

After confirming the screen form input by clicking OK, the technology selection bar is still visible.





Similar cycles are supplied from shared screen forms. Within one screen form, the user may switch between cycles via soft key, e.g. with tapping or undercut.

The editor cycle support also contains screen forms that insert a multi-line DIN code in the program instead of a cycle call, e.g. contour definition screen forms and the input of any drilling position.

### 1.5.2 New functions in input screen forms




#### Function

- In many cycles, the processing type may be influenced by means of the VARI parameter. It contains several settings composing one code. These individual settings are divided up into several input fields in the screen forms of the new cycle support. You can switch between the input field with the toggle key.
- The input screen forms are changed dynamically. Only those input fields are displayed that are required for the selected processing type. Unrequired input fields are not displayed. In the example, this is the case with the parameter for the dressing feedrate.
- One input may therefore automatically assign several depending parameters. This is the case with threading which presently supports metric thread tables. With the threading cycle CYCLE97, for example, entering 12 in the thread size input field (MPIT parameter) automatically assigns 1.75 to the thread pitch input field and 1.137 to the thread depth input field (TDEP parameter). This function is not active if the metric thread table has not been selected.
- If a screen form is displayed a second time, the last entered values are assigned to all fields. When cycles are called up several times in a row in the same program (e.g. pocket milling when roughing and dressing), only few parameters then have to be changed.


Machining: Complete/roughing/finishing	
NPP	Welle1
Working	Complete
Select	Longitudinal
Select	Outside
Infeed depth	MID 2.0000


## 1.5 Cycle support in program editor (SW 5.1 and higher)

- In screen forms of drilling and milling cycles, certain parameters may be input as absolute or incremental values. The abbreviation ABS for absolute and INC for incremental values is displayed behind the input field. You may switch between them with the "Alternative" soft key. This setting will remain with the next call of these screen forms.




- With the MMC 103 you may display additional information on the individual cycle parameters by means of the online help. If the cursor is placed

on a parameter and the help icon  is displayed on the bottom right-hand side of the screen, the help function can be activated.



By pressing the info key the parameter explanation is displayed from the Cycle Programming Guide.





## Operator commands in the help display

Page up	Paging backward in the documentation.
Page down	Paging forward in the documentation.
next entry	Enables the jump to another piece of text included in the help display.
Go to	Enables the jump to a selected piece of text.
Zoom +	Zoom the text in the help window.
Zoom -	Reduce the text in help window.
Exit help	Return to the cycle screen form.



## Contour input support


### Free contour programming

Generate contour	Starts free contour programming for entering assembled contour sections (refer to References: /OG/, Chapter 6).
------------------	---

### Blueprint programming

Contour 1 line	These soft keys support blueprints that are possible with SW 5 or higher.
Contour 2 lines	
Contour 3 lines	

It consists of one or several straight lines with contour transition elements in-between (radii, chamfers). Each contour element may be preassigned by means of end points or point and angle and supplemented by a free DIN code.



## 1.5 Cycle support in program editor (SW 5.1 and higher)

### Example

The following DIN code is created from the following input screen form for a 2-straight-line contour definition creates the following DIN code:

X=AC(20) ANG=87.3 RND=2.5 F2000 S500 M3  
X=IC(10) Y=IC(-20); end point incremental



### Drilling support

The drilling support includes a selection of drilling cycles and drilling patterns.

Drilling centering

Deep hole drilling

Bore

Tapping

Selection of drilling patterns

Hole pattern pos.

Deselect modal



Cycles CYCLE81, CYCLE87 and CYCLE89 cannot be parameterized with this support.

The function of CYCLE81 is covered by CYCLE82 (soft key "Drilling center."), as is the function of CYCLE89.

The function of CYCLE87 is covered by the function of CYCLE88 (soft keys "Drilling center." → "Drilling with stop").

Drilling patterns may be repeated if, for example, drilling and tapping are to be executed in succession. Thus, a name is assigned to the drilling pattern which will later be entered in the screen form "Repeat position".



### Programming example generated by cycle support

N100 G17 G0 G90 Z20 F2000 S500 M3	Main block
N110 T7 M6	Change drilling machine
N120 G0 G90 X50 Y50	Initial drilling position
N130 MCALL CYCLE82(10,0,2,0,30,5)	Modal drilling cycle call
N140 Circle of holes 1:	Marker – Name of drilling pattern
N150 HOLES2(50,50,37,20,20,9)	Call drilling pattern cycle
N160 ENDLABEL:	
N170 MCALL	Deselect modal call
N180 T8 M6	Change tap
N190 S400 M3	
N200 MCALL CYCLE84(10,0,2,0,30,,3,5,0.8,180,300,500)	Modal call of tapping cycle
N210 REPEAT Circle of holes 1	Repeat drilling pattern
N220 MCALL	Deselect modal call

Moreover, any drilling position may be entered as repeatable drilling pattern by means of screen forms.

Parameter	Value	Mode
Select plane	G17	
Name of label	PATTERN_1	
X0	40.0000	abs
Y0	40.0000	abs
X1	15.0000	inc
Y1	80.0000	abs
X2	154.0000	inc
Y2	60.0000	abs
X3		abs
Y3		abs
X4		abs
Y4		abs

Thus, up to five positions may be programmed in the plane, all values either absolute or incremental (alternate with "Alternat." soft key). The "Delete all" soft key creates an empty screen form.




## Milling support

The milling support includes the following selection possibilities:

Face milling	Thread milling
Path milling	Swiveling cycles
Standard pockets	
Grooves	
Spigot	
>>	<<

The "Standard pockets", "Grooves" and "Spigots" soft keys each branch into submenus offering a selection of pocket, groove and spigot milling cycles.



Pocket milling cycles POCKET1 and POCKET2 cannot be parameterized with this support.




## Turning support

The turning support includes the following selection possibilities:

Cut
Thread
Groove
Undercut

The undercut cycles for the E and F forms (CYCLE94) as well as for the thread undercuts of the A to D forms (CYCLE96) are all stored under the "Undercut" soft key.



The "Thread" soft key contains a submenu for selecting between single thread cutting or thread chaining.



### **Retranslation**

The retranslation of program codes serves to change an existing program with the help of the cycle support. The cursor is set to the line to be changed and the "Retranslation" soft key is pressed.

Thus, the corresponding input screen form which created the program piece is reopened and values may be modified.

Directly entering modifications in the created DIN code may result in the fact that retranslation is no longer possible. Therefore, consistent use of the cycle support is required and modifications are to be carried out with the help of retranslation.



### **Configuring support for user cycles**



#### **References: /IAM/, MMC Installation Instructions**

BE1 "Expand the Operator Interface"

## 1.6 Cycle support for user cycles (SW 6.2 and higher)

### 1.6.1 Overview of important files

The following files form the basis for cycle support:

Assignment	File	Application	File type
Cycle selection	aeditor.com	Standard and user cycles	Text file
	common.com (HMI Embedded only)	Standard and user cycles	Text file
Input screen form for parameter setting	*.com	Standard or user cycles	Text file
Help displays	*.bmp	Standard or user cycles	Bitmap
Online Help (HMI Advanced only)	pgz_<language>.pdf and pgz_<language>.txt	standard cycles only	pdf-file



Any names can be chosen for the cycle support configuration files (\*.com ).

### 1.6.2 Entry to cycle support



#### Function

The horizontal soft key HS6 in program editor is designated the Entry soft key for user cycles. Its function must be configured in file aeditor.com.

Assign a text to the soft key and configure a function in the press block for soft key operation.

#### Example:

```
//S(Start)
...
HS5=($80270,,se1)
PRESS(HS5)
LS("Turning",,1)
END_PRESS
HS6=("Usercycle",,se1) ; HS6 is configured with the "Usercycle" text
```



## 1.6 Cycle support for user cycles (SW 6.2 and higher)

### PRESS(HS6)

```
LS("SK_Cycles1","cycproj1")          ; operating a soft key loads the soft key bar from ;
                                       ; file cycproj1.com
```

### END\_PRESS

A detailed description of the configuration is given in:

**References:** /IAM/ HMI/MMC Installation and  
Start-Up Guide

BE1 "Expand the Operator Interface"

With HMI Embedded, make the entry in file  
common.com to activate this soft key as follows:

```
%_N_COMMON_COM
```

```
;$PATH=/_N_CUS_DIR
```

```
...
```

```
[MMC_DOS]
```

```
...
```

```
SC315=AEDITOR.COM
```

```
SC316=AEDITOR.COM
```

### 1.6.3 Cycle support configuration



#### Function

The soft key bars and input screen forms of cycle support can be configured in any files and stored as type \*.com in the HMI of the control.

A detailed description of the configuration is given in:

**References:** /IAM/ HMI/MMC Installation and  
Start-Up Guide

BE1 "Expand the Operator Interface"

In HMI Advanced, the \*.com files are stored in data management in the directories:

- dh\cst.dir
- dh\cma.dir or
- dh\cus.dir

and the usual search sequence is followed:

cus.dir, cma.dir, cst.dir. The files are not loaded into the NCU.

For HMI Embedded, the \*.com files can be loaded into the NCU (read in via "Services" by means of RS-232-C). But as they occupy NC memory there, it is better to integrate them in the HMI. They must be packed and incorporated into the application software of the HMI version. The tool to pack the files is included with the standard cycle software under \hmi\_emb\tools.



### Step sequence for creation

- Copy file arj.exe from directory \hmi\_emb\tools into an empty directory on a PC.
- Copy the separate configuration files \*.com to this directory.
- Pack each individual com file with the command  
arj a <name target file> <name source file>.  
The target files must have the extension **co\_**.  
Example: pack configured file cycproj1.com to:  
arj a cycproj1.co\_ cycproj1.com.
- Copy the \*.co\_ files to the relevant directory of the HMI application software and create a version.



**References:** /BEM/, Operator's Guide HMI Embedded  
/IAM/, HMI/MMC Installation &  
Start-Up Guide

IM2 "Installation and Start-Up Guide  
HMI Embedded"

#### 1.6.4 Bitmap size and screen resolution

With SW 6.2, there are three different screen resolutions in the HMI. For each of the resolutions, there is a maximum bitmap size for the cycle screen forms (see the following table), to be observed when creating your own bitmaps.

Screen resolution	Bitmap size
640 * 480	224 * 224 pixels
800 * 600	280 * 280 pixels
1024 * 768	352 * 352 pixels

Bitmaps are created and stored as 16-color bitmaps.

### 1.6.5 Storing bitmaps in data management for HMI Advanced

New paths have been set up in data management (as from HMI 6.2) for the different screen resolutions, so that the bitmaps can be stored in parallel in various sizes.

Standard cycles:

- dh\cst.dir\hlp.dir\640.dir
- dh\cst.dir\hlp.dir\800.dir
- dh\cst.dir\hlp.dir\1024.dir

Manufacturer cycles:

- dh\cma.dir\hlp.dir\640.dir
- dh\cma.dir\hlp.dir\800.dir
- dh\cma.dir\hlp.dir\1024.dir

User cycles:

- dh\cus.dir\hlp.dir\640.dir
- dh\cus.dir\hlp.dir\800.dir
- dh\cus.dir\hlp.dir\1024.dir

In accordance with the current resolution, the search begins in the appropriate directory (for example in dh\...\hlp.dir\640.dir for 640 \* 480) and then moves to dh\...\hlp.dir. Otherwise the search sequence cus.dir, cma.dir, cst.dir applies.

### 1.6.6 Handling bitmaps for HMI Embedded



#### Function

With HMI Embedded, the bitmaps are incorporated in the HMI software. So far they are grouped together in a package, **cst.arj**, as with MMC100.2. Bitmaps can always be integrated in \*.bmp format. However, to save more space and display faster, use a \*.bin binary format. To do this, you need the tools supplied with the standard cycle software in the \hmi\_emb\tools directory:

- arj.exe, bmp2bin.exe, and
- sys\_conv.col

and the script files:

- mcst\_640.bat,
- mcst\_800.bat or
- mcst1024.bat.

File cst.arj contains all the standard and user cycle bitmaps. So you will have to link together the standard cycle bitmaps and your own bitmaps.



### Step sequence for creation

- Copy all the files from directory \hmi\_emb\tools into an empty directory on a PC.
- Create a subdirectory \bmp\_file there.
- Copy your own bitmaps \*.bmp to this subdirectory \bmp\_file.
- Depending on the resolution for which a cst.arj is being created, start mcst\_640.bat / mcst\_800.bat or mcst1024.bat.
- The cst.arj that you create will then be in the same directory as the generation tools.



cst.arj is then integrated in the HMI software as described in Subsection 1.4.6.



**References:** /BEM/, Operator's Guide HMI Embedded  
/IAM/, HMI/MMC Installation & Start-Up  
Guide

IM2 "Installation and Start-Up Guide HMI  
Embedded"

## 1.7 Cycle startup (SW 6.2 and higher)

### 1.7.1 Machine data

The following machine data are used for the cycles.  
The minimum values for these machine data are given in the table below.

#### Relevant machine data

MD No.	MD name	Minimum value
18118	MM_NUM_GUD_MODULES	7
18130	MM_NUM_GUD_NAMES_CHAN	20
18150	MM_GUD_VALUES_MEM	2 * Number of channels
18170	MM_NUM_MAX_FUNC_NAMES	40
18180	MM_NUM_MAX_FUNC_PARAM	500
28020	MM_NUM_LUD_NAMES_TOTAL	200
28040	MM_NUM_LUD_VALUES_MEM	25



*This information applies to Siemens standard cycles only. The relevant values have to be added for user cycles. When using ShopMill or ShopTurn, comply with the information relevant to these products.*

The following machine data settings are also required:

MD No.	MD name	Value
20240	CUTCOM_MAXNUM_CHECK_BLOCK	4

The machine data files are delivered with these defaults by the machine manufacturer.

It is important to remember that a power ON must be performed if these machine data are changed.



*Axis-specific machine data MD 30200: NUM\_ENCS must also be noted with respect to cycle CYCLE840 (tapping with compensating chuck).*

### 1.7.2 Definition files for the cycles GUD7.DEF and SMAC.DEF

Standard cycles need Global User Data definitions (GUDs) and macro definitions. These are stored in definition files GUD7.DEF and SMAC.DEF, supplied with the standard cycles.

In SW 6.3 and higher, these definition files GUD7.DEF and SMAC.DEF that are used jointly by a number of cycle packages, will be split. Each package will only have its own definitions. New cycle files GUD7\_xxx.DEF and SMAC\_xxx.DEF will be introduced, that will be in data management in the definition directory DEF.DIR.

The new files for the standard cycles are:

- GUD7\_SC.DEF and
- SMAC\_SC.DEF.



#### Startup, upgrades for standard cycles:

- if a GUD7.DEF is already active in the control, use "Services", "Data out", "NC active data" to select the user data of GUD7 and back up the current values in an archive or onto a diskette;
- read in files GUD7\_SC.DEF and SMAC\_SC.DEF from the diskette and load them to the NCU;
- read in and activate GUD7.DEF and SMAC.DEF;
- turn on the NCU;
- read the archive of saved values back in;



#### Loading an additional cycle package:

- unload GUD7.DEF and SMAC.DEF (having backed up the values if necessary),
- read in cycles GUD7\_xxx.DEF and SMAC\_xxx.DEF of the package and load them to the NCU;
- reactivate GUD7.DEF and SMAC.DEF.



#### Handling in the HMI Advanced simulation:

After upgrading the cycle version in the NCU, machine data adjustment followed by an NC reset of the simulation is necessary as soon as you start the simulation, in order to activate the modified definition files.

### 1.7.3 New form of delivery for cycles in HMI Advanced



As from HMI Advanced 6.3, the delivery form of standard cycles in the HMI will change. The cycle files will no longer be stored directly in the relevant data management directories, but will be available as archive files under:

→ Archives/Cycle archives.

This will enable the previously existing cycle version in data management to be retained unchanged when the HMI is upgraded.

To upgrade, these archive files must be read in via "Data in". If these archive files are read in, after the upgrade there are no longer different versions of the cycles in the NCU and on the hard disk. The loaded cycles are overwritten in the NCU, not loaded on the hard drive. The new cycle files are always stored on the hard disk.



**References:** for current infos see:

- the file "siemensd.txt" from the delivery software (standard cycles) or
- for HMI Advanced, F:\dh\cst.dir\HLP.dir\siemensd.txt.

## 1.8 Special functions for cycles



### Function

To provide an overview and for diagnosis of the cycle versions, it will be possible as from SW 6.3 to display and use version screens.

**This function can also only be run with HMI software versions SW 6.3 and higher.**

Different overviews are possible with cycle version display:

- An overview of all available cycles
- An overview of the individual directories of data management for user cycles (CUS.DIR), manufacturer cycles (CMA.DIR) and Siemens cycles (CST.DIR)
- A package overview of all the cycle packages available in the control
- Details of the individual packages and cycle files



**References:** /BAD/, **Operator's Guide HMI Advanced**  
/BEM/, **Operator's Guide HMI Embedded**  
Service display chapter

The version display includes all the \*.SPF cycle files and all the \*.COM files of cycle support.

No additional files are required for version display via directories or of all cycles.

In order to display overviews of individual cycle packages, each cycle package must hold a package list of all the associated files.



### Package lists

A new file type is introduced for package lists  
\*.cyp (for cycle package),  
in plain text, cycle package list.

The user can create package lists for his own cycle packages. They must look like this:



Structure of a package list:

- First line: version entry (after the vocabulary word ;**VERSION:** ) and package name (after the vocabulary word ;**PACKAGE:** )
- from second line: list of the files associated with the cycle package with name and type
- last line: M30

**Example:**

```

%_N_CYC_USER1_CYP
; $PATH=/_N_CUS_DIR
;VERSION: 01.02.03 31.10.2002 ;PACKAGE: $85200
ZYKL1.SPF
ZYKL2.SPF
ZYKL3.COM
M30

```

Input in the text file uc.com:

85200 0 0 "cycle package 1"

The following is displayed in the package overview:

Name	Version
Measuring cycles	06.02.08 Mar 21, 2002
Cycle package	01.02.03 31.10.2002

The following is displayed in the file overview:

Diagnosis	CHAN1	AUTO	MPF0		
Channel RESET		Program aborted			
		ROV	SBL1		
Version data ShopMill cycles					
Name	Type	Load	Length	Directory	Version
ZYKL1	SPF	1234	CUS.DIR	01.02.03	31.10.2002
ZYKL2	SPF	778	CUS.DIR	01.02.03	31.10.2002
ZYKL3	COM	521	CUS.DIR	01.02.03	31.10.2002

### Further notes

The cycle package name after the vocabulary word PACKAGE can also be written as a string in " ", but then it is language-specific.

### Version entries in cycles

Just as with package lists, the entry after the vocabulary word ";VERSION:" is classed as the version ID. The version entry has to be in the first ten lines of the cycle, the search does not go any further.

#### Example:

```

%_N_ZYKL1_SPF
; $PATH=/_N_CUS_DIR
;VERSION: 01.02.03 31.10.2002
;Comments
PROC ZYKL1 (REAL PAR1)
...

```

■

## Drilling Cycles and Drilling Patterns

2.1	Drilling cycles .....	2-60
2.1.1	Preconditions .....	2-62
2.1.2	Drilling, centering – CYCLE81.....	2-64
2.1.3	Drilling, counterboring – CYCLE82 .....	2-67
2.1.4	Deep-hole drilling – CYCLE83 .....	2-69
2.1.5	Rigid tapping – CYCLE84 .....	2-77
2.1.6	Tapping with compensating chuck – CYCLE840.....	2-83
2.1.7	Boring 1 – CYCLE85.....	2-91
2.1.8	Boring 2 – CYCLE86.....	2-94
2.1.9	Boring 3 – CYCLE87.....	2-98
2.1.10	Boring 4 – CYCLE88.....	2-101
2.1.11	Boring 5 – CYCLE89.....	2-103
2.2	Modal call of drilling cycles.....	2-105
2.3	Drill pattern cycles.....	2-108
2.3.1	Preconditions .....	2-108
2.3.2	Row of holes – HOLES1 .....	2-109
2.3.3	Hole circle – HOLES2 .....	2-113
2.3.4	Dot matrix – CYCLE801 (SW 5.3 and higher) .....	2-116

## 2.1 Drilling cycles

The following sections describe how

- drilling cycles and
- drilling pattern cycles

are programmed.

These Sections are intended to guide you in selecting cycles and assigning them with parameters. In addition to a detailed description of the function of the individual cycles and the corresponding parameters, you will also find a programming example at the end of each section to familiarize you with the use of cycles.

The sections are structured as follows:

- Programming
- Parameters
- Function
- Sequence of operations
- Explanation of parameters
- Additional notes
- Sample program.

"Programming" and "Parameters" explain the use of cycles sufficiently for the experienced user, whereas beginners can find all the information they need for programming cycles under "Function", "Sequence of operations", "Explanation of parameters", "Additional notes" and the "Programming example".



Drilling cycles are motion sequences defined according to DIN 66025 for drilling, boring, tapping, etc.

They are called in the form of a subroutine with a defined name and a parameter list.

Five cycles are available for boring. They all follow a different technological procedure and are therefore parameterized differently:

Boring cycle		Special parameterization features
Boring 1 -	CYCLE85	Different feedrates for boring and retraction
Boring 2 -	CYCLE86	Oriented spindle stop, definition of retraction path, retraction in rapid traverse, definition of spindle direction of rotation
Boring 3 -	CYCLE87	Spindle stop M5 and program stop M0 at drilling depth, continued machining after NC Start, retraction in rapid traverse, definition of spindle direction of rotation
Boring 4 -	CYCLE88	As for CYCLE87 plus dwell time at drilling depth
Boring 5 -	CYCLE89	Boring and retraction at the same feedrate



Drilling cycles can be modal, i.e. they are executed at the end of each block that contains motion commands. Other cycles written by the user can also be called modally (see Section 2.2).

## 2.1 Drilling cycles


There are two types of parameter:

- Geometrical parameters and
- Machining parameters.

Geometrical parameters are identical for all drilling cycles, drilling pattern cycles and milling cycles.

They define the reference and retraction planes, the safety distance and the absolute and relative final drilling depths. Geometrical parameters are written once in the first drilling cycle CYCLE81.

The machining parameters have a different meaning and effect in each cycle. They are therefore written in each cycle.



### 2.1.1 Preconditions

#### Call and return conditions

Drilling cycles are programmed independently of the actual axis names. The drilling position must be approached in the higher-level program before the cycle is called.

The required values for the feedrate, spindle speed and spindle direction of rotation must be programmed in the parts program if there are no assignment parameters for these values in the drilling cycle.

The G function and current frame active before the cycle was called remain active beyond the cycle.

### Plane definition

In the case of drilling cycles, it is generally assumed that the current workpiece coordinate system in which the machining operation is to be performed is defined by selecting plane G17, G18 or G19 and activating a programmable frame. The drilling axis is always the applicator of this coordinate system. A tool length compensation must be selected before the cycle is called. Its effect is always perpendicular to the selected plane and remains active even after the end of the cycle (see also Programming Guide).




### Spindle programming

The drilling cycles are written in such a way that the spindle commands always refer to the master spindle control. If you want to use a drilling cycle on a machine with several spindles, you must first define the spindle that is to be used for the operation as the master spindle (see also Programming Guide).



### Dwell time programming

The parameters for the dwell times in the drilling cycles are always assigned to the F word and must therefore be assigned with values in seconds. Any deviations from this procedure must be expressly stated.



## 2.1.2 Drilling, centering – CYCLE81


**Programming**

CYCLE81 (RTP, RFP, SDIS, DP, DPR)

RTP	real	Retraction plane (absolute)
RFP	real	Reference plane (absolute)
SDIS	real	Safety distance (enter without sign)
DP	real	Final drilling depth (absolute)
DPR	real	Final drilling depth relative to reference plane (enter without sign)

**Function**

The tool drills at the programmed spindle speed and feedrate to the programmed final drilling depth.

**Sequence of operations****Position reached prior to cycle start:**

The drilling position is the position in the two axes of the selected plane.

**The cycle implements the following motion sequence:**

Approach of the reference plane brought forward by the safety distance with G0

- Traverse to final drilling depth with the feedrate (G1) programmed in the calling program
- Retraction to retraction plane with G0.





## Description of parameters

### RFP and RTP (reference plane and retraction plane)

Generally, the reference plane (RFP) and the retraction plane (RTP) have different values. In the cycle it is assumed that the retraction plane lies in front of the reference plane. The distance between the retraction plane and the final drilling depth is therefore greater than the distance between the reference plane and the final drilling depth.

### SDIS (Safety distance)


The safety distance (SDIS) is effective with regard to the reference plane which is brought forward by the safety distance.

The direction in which the safety distance is active is automatically determined by the cycle.

### DP and DPR (final drilling depth)

The final drilling depth can be defined as either absolute (DP) or relative (DPR) to the reference plane.

If it is entered as a relative value, the cycle automatically calculates the correct depth on the basis of the positions of the reference and retraction planes.



## Further notes

If a value is entered both for the DP and the DPR, the final drilling depth is derived from the DPR. If the DPR deviates from the absolute depth programmed via the DP, the message "Depth: Corresponds to value for relative depth" is output in the dialog line.


If the values for the reference plane and the retraction plane are identical, a relative depth must not be programmed. The error message 61101 "Reference plane incorrectly defined" is output and the cycle is not executed. This error message is also output if the retraction plane lies behind the reference plane, i.e. the distance to the final drilling depth is smaller.



### Programming example

#### Drilling\_centering

You can use this program to make three holes using the drilling cycle CYCLE81, whereby this cycle is called with different parameter settings. The drilling axis is always the Z axis.



N10 G0 G90 F200 S300 M3	Specification of technology values
N20 D1 T3 Z110	Traverse to retraction plane
N21 M6	
N30 X40 Y120	Traverse to first drilling position
N40 CYCLE81 (110, 100, 2, 35)	Cycle call with absolute final drilling depth, safety distance and incomplete parameter list
N50 Y30	Traverse to next drilling position
N60 CYCLE81 (110, 102, , 35)	Cycle call without safety distance
N70 G0 G90 F180 S300 M03	Specification of technology values
N80 X90	Approach next position
N90 CYCLE81 (110, 100, 2, , 65)	Cycle call with relative final drilling depth and safety distance
N100 M30	End of program

### 2.1.3 Drilling, counterboring – CYCLE82



#### Programming

CYCLE82 (RTP, RFP, SDIS, DP, DPR, DTB)



#### Parameters

RTP	real	Retraction plane (absolute)
RFP	real	Reference plane (absolute)
SDIS	real	Safety distance (enter without sign)
DP	real	Final drilling depth (absolute)
DPR	real	Final drilling depth relative to reference plane (enter without sign)
DTB	real	Dwell time at final drilling depth (chip breaking)



#### Function

The tool drills at the programmed spindle speed and feedrate to the programmed final drilling depth. A dwell time can be allowed to elapse when the final drilling depth has been reached.




#### Sequence of operations

##### Position reached prior to cycle start:

The drilling position is the position in the two axes of the selected plane.

##### The cycle implements the following motion sequence:

- Approach of the reference plane brought forward by the safety distance with G0
- Traverse to final drilling depth with the feedrate (G1) programmed in the calling program
- Dwell time at final drilling depth
- Retraction to retraction plane with G0.






### Description of parameters



See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters RTP, RFP, SDIS, DP, DPR

#### DTB (dwell time)

Parameter DTB is the dwell time at the final drilling depth (chip breaking) in seconds.




### Programming example

#### Boring\_counterboring

This program machines a single hole to a depth of 27mm at position X24, Y15 in the XY plane with cycle CYCLE82.

The dwell time programmed is 2 sec, the safety distance in the drilling axis Z is 4mm.



```
N10 G0 G90 F200 S300 M3
```

Specification of technology values

```
N20 D1 T3 Z110
```

Traverse to retraction plane

```
N21 M6
```

```
N30 X24 Y15
```

Traverse to drilling position

```
N40 CYCLE82 (110, 102, 4, 75, , 2)
```

Cycle call with absolute final drilling depth and safety distance

```
N50 M30
```

End of program

## 2.1.4 Deep-hole drilling – CYCLE83



### Programming

CYCLE83 (RTP, RFP, SDIS, DP, DPR, FDEP, FDPR, DAM, DTB, DTS, FRF, VARI, \_AXN, \_MDEP, \_VRT, \_DTD, \_DIS1)



### Parameters

RTP	real	Retraction plane (absolute)
RFP	real	Reference plane (absolute)
SDIS	real	Safety distance (enter without sign)
DP	real	Final drilling depth (absolute)
DPR	real	Final drilling depth relative to reference plane (enter without sign)
FDEP	real	First drilling depth (absolute)
FDPR	real	First drilling depth relative to reference plane (enter without sign)
DAM	real	Degression: (enter without sign) Values: > 0 degression as value < 0 degression factor = 0 no degression
DTB	real	Dwell time at drilling depth (chip breaking) Values: > 0 in seconds < 0 in revolutions
DTS	real	Dwell time at starting point and for swarf removal Values: > 0 in seconds < 0 in revolutions
FRF	real	Feedrate factor for first drilling depth (enter without sign) Value range: 0.001 ... 1
VARI	int	Type of machining Values: 0 chip breaking 1 swarf removal
_AXN	int	Tool axis: Values: 1 = 1st geometry axis 2 = 2nd geometry axis or else 3rd geometry axis
_MDEP	real	Minimum drilling depth
_VRT	real	Variable retraction distance for chip breaking (VARI=0): Values: > 0 is retraction distance 0 = setting is 1mm

**2.1 Drilling cycles**

<code>_DTD</code>	real	Dwell time at final drilling depth Values: > 0 in seconds < 0 in revolutions = 0 value as for DTB
<code>_DIS1</code>	real	Programmable limit distance on re-insertion in hole (VARI=1 for swarf removal) Values: > 0 programmable value applies = 0 automatic calculation

**Function**

The tool drills at the programmed spindle speed and feedrate to the programmed final drilling depth. Deep hole drilling is performed with a depth infeed of a maximum definable depth executed several times, increasing gradually until the final drilling depth is reached.

The drill can either be retracted to the reference plane + safety distance after every infeed depth for swarf removal or retracted in each case by 1mm for chip breaking.



## Sequence of operations



### Position reached prior to cycle start:

The drilling position is the position in the two axes of the selected plane.

### The cycle implements the following motion sequence:


#### Deep hole drilling with swarf removal (VARI=1):

- Approach of the reference plane brought forward by the safety distance with G0
- Traverse to the first drilling depth with G1, the feedrate for which is derived from the feedrate defined with the program call which is subject to parameter FRF (feedrate factor)
- Dwell time at final drilling depth (parameter DTB)
- Retraction to the reference plane brought forward by the safety distance with G0 for swarf removal
- Dwell time at starting point (parameter DTS)
- Approach last drilling depth reached, reduced by the calculated (by cycle) or programmable limit distance with G0
- Traverse to next drilling depth with G1 (sequence of motions is continued until the final drilling depth is reached)
- Retraction to retraction plane with G0



**Deep hole drilling with chip breaking (VARI=0):**

- Approach of the reference plane brought forward by the safety distance with G0
- Traverse to the first drilling depth with G1, the feedrate for which is derived from the feedrate defined with the program call which is subject to parameter FRF (feedrate factor)
- Dwell time at final drilling depth (parameter DTB)
- Retraction by 1 mm from the current drilling depth with G1 and the feedrate programmed in the calling program (for chip breaking)
- Traverse to next drilling depth with G1 and the programmed feedrate (sequence of motions is continued until the final drilling depth is reached)
- Retraction to retraction plane with G0

**Description of parameters**

See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters RTP, RFP, SDIS, DP, DPR

**FDEP and FDPR (first drilling depth absolute or relative)**

The first drilling depth is programmed by either one of these two parameters. The parameter FDPR has the same effect in the cycle as parameter DPR. If the values for the reference and retraction plane are identical, the first drilling depth can be defined as a relative value.

**DAM (degression)**

With deep holes, drilled in several steps, it is useful to work with degressive values for the individual drilling strokes (degression). This allows the swarf to get away and there is no tool breakage.

In the parameter, either program an incremental degression value in order to reduce the first drilling depth step by step or a % value to act as a degression factor.

**DAM=0 no degression**

**DAM>0 degression as value**

The current depth is derived in the cycle as follows:



- In the first step, the depth parameterized with the first drilling depth FDEP or FDPR is traversed as long as it does not exceed the total drilling depth.
- From the second drilling depth on, the drilling stroke is obtained by subtracting the amount of degression from the stroke of the last drilling depth, provided that the latter is greater than the programmed amount of degression.
- The next drilling strokes correspond to the amount of degression, as long as the remaining depth is greater than twice the amount of degression.
- The last two drilling strokes are divided equally and traversed and are therefore always greater than half of the amount of degression.
- If the value for the first drilling depth is opposed to the total depth, error message 61107 "First drilling depth incorrectly defined" is generated and the cycle not executed.

Example:

Programming the values REP=0, SDIS=0, DP=-40, FDEP=-12 and DAM=3 results in the following drilling strokes:

-12	corresponds to the first drilling depth
-21	the incremental difference 9 comes from the first drilling depth 12 reduced by the amount of degression 3
-27	previous drilling depth reduced and amount of degression 3
-30, -35, -36	amount of degression
-38, -40	remaining depth divided into two cuts.

#### **DAM<0 (-0.001 to -1) degression factor**

The current depth is derived in the cycle as follows:

- In the first step, the depth parameterized with the first drilling depth FDED or FDPR is traversed as long as it does not exceed the total drilling depth.
- The next drilling strokes are calculated from the last drilling stroke multiplied by the degression factor for as long as the stroke remains larger or equal to the minimum drilling depth.
- The last two drilling strokes are divided equally and traversed and are therefore always greater than half of the minimum drilling depth.
- If the value for the first drilling depth is opposed to the total depth, error message 61107 "First drilling depth incorrectly defined" is generated and the cycle not executed.

## 2.1 Drilling cycles

Example:

Programming the values REP=0, SDIS=0, DP=-40, FDEP=-10, DAM=-0.8 and MDEP=5 results in the following drilling strokes:

- 10 corresponds to the first drilling depth
- 18 the incremental difference 8 corresponds to 0.8 \*of the first drilling depth
- 29.4, -29.52 in each case the previous drilling depth \* degression factor
- 39.52 minimum drilling depth MDEP takes effect
- 37.26, -40 remaining depth divided into two cuts.

### DTB (dwell time)

The dwell time at final drilling depth (chip breaking) is programmed in DTB in seconds or revolutions of the main spindle.

- 0 in seconds
- < 0 in revolutions

### DTS (dwell time)

The dwell time at the starting point is only performed if VARI=1 (swarf removal).

- Value > 0 in seconds
- Value < 0 in revolutions

### FRF (feedrate factor)

With this parameter you can enter a reduction factor for the active feedrate which only applies to the approach to the first drilling depth in the cycle.

### VARI (machining mode)

If parameter VARI=0 is set, the drill retracts 1mm after reaching each drilling depth for chip breaking. When VARI=1 (for swarf removal), the drill traverses in each case to the reference plane moved forward by the safety distance.

**\_AXN (tool axis)**

By programming the drilling axis via `_AXN`, it is possible to omit the switchover from plane G18 to G17 when the deep hole drilling cycle is used on turning machines.

Meaning:

`_AXN=1` 1st axis of the current plane


`_AXN=2` 2nd axis of the current plane

`_AXN=3` 3rd axis of the current plane

For example, to machine a center drilling (in Z) in plane G18, you program:

```
G18
```

```
_AXN=1
```

**\_MDEP (minimum drilling depth)**

You can define a minimum drilling depth for drill stroke calculations based on degression factor. If the calculated drilling stroke becomes shorter than the minimum drilling depth, the remaining depth is machined in strokes equaling the length of the minimum drilling depth.

**\_VRT (variable retraction value for chip breaking with VARI=0)**

You can program the retraction path for chip breaking in seconds or revolutions.

Value > 0 retraction value

Value = 0 retraction value 1mm

**\_DTD (dwell time at final drilling depth)**

The dwell time at final drilling depth can be entered in seconds or revolutions.

Value > 0 in seconds

Value < 0 in revolutions

Value = 0 dwell time as programmed in DTB

**\_DIS1 (programmable limit distance when VARI=1)**

The limit distance after re-insertion in the hole can be programmed.

Value > 0 position at programmed value

Value = 0 automatic calculation




## Programming example

### Deep hole drilling

This program executes the cycle CYCLE83 at positions X80 Y120 and X80 Y60 in the XY plane. The first hole is drilled with a dwell time zero and machining type chip breaking.

The final drilling depth and the first drilling depth are entered as absolute values. In the second cycle call, a dwell time of 1 sec is programmed. Machining type swarf removal is selected, the final drilling depth is relative to the reference plane. The drilling axis in both cases is the Z axis.

The drilling stroke is calculated on the basis of a degression factor and must not become shorter than the minimum drilling depth of 8mm.



```
DEF REAL RTP=155, RFP=150, SDIS=1,
DP=5, DPR=145, FDEP=100, FDPR=50,
DAM=20, DTB=1, FRF=1, VARI=0,
_VRT=0.8, _MDEP=10, _DIS1=0.4
```

Definition of parameters

```
N10 G0 G17 G90 F50 S500 M4
```

Specification of technology values

```
N20 D1 T42 Z155
```

Traverse to retraction plane

```
N30 X80 Y120
```

Traverse to first drilling position

```
N40 CYCLE83 (RTP, RFP, SDIS, DP, , ->
-> FDEP, , DAM, , , FRF, VARI, , , _VRT)
```

Cycle call, depth parameter with absolute values

```
N50 X80 Y60
```

Traverse to next drilling position

```
N55 DAM=-0.6 FRF=0.5 VARI=1
```

Assignment of value

```
N60 CYCLE83 (RTP, RFP, SDIS, , DPR, , ->
-> FDPR, DAM, DTB, , FRF, VARI, , _MDEP,
-> , , _DIS1)
```

Cycle call with relative data for final drilling depth and 1st final drilling depth; the safety distance is 1mm; the feedrate is 0.5

```
N70 M30
```

End of program

-> Must be programmed in a single block

### 2.1.5 Rigid tapping – CYCLE84



#### Programming

CYCLE84 (RTP, RFP, SDIS, DP, DPR, DTB, SDAC, MPIT, PIT, POSS, SST, SST1, \_AXN, \_PTAB, \_TECHNO, \_VARI, \_DAM, \_VRT)



#### Parameters

RTP	real	Retraction plane (absolute)
RFP	real	Reference plane (absolute)
SDIS	real	Safety distance (enter without sign)
DP	real	Final drilling depth (absolute)
DPR	real	Final drilling depth relative to reference plane (enter without sign)
DTB	real	Dwell time at thread depth (chip breaking)
SDAC	int	Direction of rotation after end of cycle Values: 3, 4 or 5
MPIT	real	Pitch as thread size (with sign) Value range: 3 (for M3) ... 48 (for M48), the sign determines the direction of rotation in the thread
PIT	real	Pitch as value (with sign) Value range: 0.001 ... 2000.000mm), the sign determines the direction of rotation in the thread SW 6.2 or higher: If _PTAB=0 or 1: in mm (as earlier SW versions) If _PTAB=2 in thread starts per inch
POSS	real	Spindle position for oriented spindle stop in the cycle (in degrees)
SST	real	Speed for tapping
SST1	real	Speed for retraction
_AXN (SW 6.2 or higher)	int	Tool axis Values: 1 = 1st geometry axis 2 = 2nd geometry axis or else 3rd geometry axis
_PTAB (SW 6.2 or higher)	int	Evaluation of thread pitch PIT Values: 0...according to programmed system of units inch/metric 1...pitch in mm 2...pitch in thread starts per inch 3...pitch in inches/revolution

_TECHNO (SW 6.2 or higher)	int	Technological settings UNITS DIGIT: Exact stop behavior Values: 0...and as programmed before cycle call 1...(G601) 2...(G602) 3...(G603) TENS DIGIT: Feedforward control Values: 0...and as programmed before cycle call 1...with feedforward control (FFWON) 2...without feedforward control (FFWOF) HUNDREDS DIGIT: Acceleration Values: 0...and as programmed before cycle call 1...soft acceleration of axes (SOFT) 2...brisk acceleration of axes (BRISK) 3...reduced acceleration of axes (DRIVE) THOUSANDS DIGIT: Values: 0...activate spindle mode again (with MCALL) 1...stay in position-control mode (with MCALL)
_VARI (SW 6.2 or higher)	int	Type of machining Values: 0...tapping in one pass 1...deep hole tapping with chip breakage 2...deep hole tapping with stock removal
_DAM (SW 6.2 or higher)	real	Incremental drilling depth Value range: 0 <= max. value
_VRT (SW 6.2 or higher)	real	Variable retraction distance for chip breakage Value range: 0 <= max. value



## Function

The tool drills at the programmed spindle speed and feedrate to the programmed thread depth.

With cycle CYCLE84 you can perform rigid tapping operations.

In SW 6.2 or higher, the cycle is also capable of performing tapping operations in several stages (deep hole drilling).



*Cycle CYCLE84 can be used if the spindle to be used for the boring operation is technically able to go into position-controlled spindle operation.*



A separate cycle CYCLE840 exists for tapping with compensating chuck (see Subsection 2.1.6).




### Sequence of operations

#### Position reached prior to cycle start:

The drilling position is the position in the two axes of the selected plane.

#### The cycle implements the following motion sequence:

- Approach of the reference plane brought forward by the safety distance with G0
- Oriented spindle stop with SPOS (value in parameter POSS) and conversion of spindle to axis mode
- Tapping to final drilling depth with G331 and speed SST
- Dwell time at thread depth (parameter DTB)
- Retraction to the reference plane brought forward by the safety distance with G332, spindle speed SST1 and reversal of direction of rotation
- Retraction to the retraction plane with G0, spindle mode is reintroduced by reprogramming the spindle speed active before the cycle was called and the direction of rotation programmed under SDAC.



### Description of parameters



See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters RTP, RFP, SDIS, DP, DPR


#### DTB (dwell time)

You program the dwell time in seconds. It is recommended that the dwell time is omitted for the tapping of blind holes.

#### SDAC (direction of rotation after end of cycle)

Under SDAC you program the direction of rotation after completion of the cycle.

For tapping, the direction is changed automatically by the cycle.



## 2.1 Drilling cycles

### MPIT and PIT (as thread size and as value)

The value for the thread pitch can either be defined as the thread size (for metric threads between M3 and M48 only) or as a value (distance from one thread turn to the next as a numerical value). The parameter not required in each case is omitted from the call or assigned the value zero.

Right or left threads are specified by the sign of the pitch parameter:

- Positive value → right (like M3)
- Negative value → left (like M4).

If the two pitch parameters have contradictory values, the cycle generates alarm 61001 "Incorrect pitch" and cycle machining is aborted.

### POSS (spindle position)

Before tapping starts in the cycle, oriented spindle stop is performed with command SPOS and the spindle is brought into position control.

You program the spindle position for this spindle stop under POSS.

### SST (speed)

Parameter SST contains the spindle speed for the tapping block with G331.

### SST1 (retraction speed)

Under SST1 you program the speed for the retraction out of the thread hole in the hole with G332.

If this parameter is assigned the value zero, the retraction movement is performed with the speed programmed under SST.

### \_AXN (tool axis)


By programming the drilling axis via \_AXN, it is possible to omit the switchover from plane G18 to G17 when the deep hole tapping cycle is used on turning machines.

Meaning:

- \_AXN=1 1st axis of the current plane
- \_AXN=2 2nd axis of the current plane
- \_AXN=3 3rd axis of the current plane.

For example, to machine a center drilling (in Z) in plane G18, you program:

```
G18
_AXN=1
```





**\_PTAB (evaluation of thread pitch PIT)**

Parameter `_PTAB` determines the unit of measurement of the thread pitch.

- 0=according to programmed system of units inch/metric
- 1=pitch in mm
- 2=pitch in thread starts per inch
- 3=pitch in inches/revolution

This parameter is needed in connection with the option for selecting different thread tables in the cycles support.

**\_TECHNO (technological settings)**

Parameter `_TECHNO` can be set to select technological characteristics for tapping operations.

Possible values are:

**Ones digit (exact stop behavior):**

- 0=as programmed before cycle call
- 1=(G601)
- 2=(G602)
- 3=(G603)

**Tens digit (feedforward control):**

- 0=as programmed before cycle call
- 1=with feedforward control (FFWON)
- 2=without feedforward control (FFWOF)

**Hundreds digit (acceleration):**

- 0=as programmed before cycle call
- 1=soft acceleration of axes (SOFT)
- 2=brisk acceleration of axes (BRISK)
- 3=reduced acceleration of axes (DRIVE)

**Thousands digit:**

- 0=activate spindle mode again (with MCALL)
- 1=stay in position-control mode (with MCALL)

**Deep hole tapping `_VARI`, `_DAM`, `_VRT`**

Parameter `_VARI` can be set to select between simple tapping (`_VARI = 0`) and deep hole tapping (`_VARI ≠ 0`).

In conjunction with deep hole tapping, it is possible to choose between chip breakage (retraction by variable distance from current drilling depth, parameter `_VRT`, `_VARI = 1`) and stock removal (withdrawal from reference plane `_VARI = 2`). These functions work analogously to the normal deep hole drilling cycle `CYCLE83`.

The incremental drilling depth for one pass is specified via parameter `_DAM`. The cycle internally calculates the intermediate depth as follows:

- The programmed incremental depth is drilled in each pass until the remaining distance to the final drilling depth is  $<$  than  $2 * \_DAM$
- The remaining depth is halved and drilled in 2 passes, thereby ensuring that the minimum drilling depth is not less than  $\_DAM/2$ .


### Further notes

The direction of rotation is always reversed automatically for tapping in cycle.

### Programming example

#### Rigid tapping

A thread is tapped without a compensating chuck at position X30 and Y35 in the XY plane, the tapping axis is the Z axis. No dwell time is programmed. The depth is programmed as a relative value. The parameters for the direction of rotation and the pitch must be assigned values. A metric thread M5 is tapped.



N10 G0 G90 T4 D1	Specification of technology values
N20 G17 X30 Y35 Z40	Traverse to drilling position
N30 CYCLE84 (40, 36, 2, , 30, , 3, 5, -> ->, 90, 200, 500)	Cycle call, parameter PIT has been omitted, no value is entered for the absolute depth or the dwell time. Spindle stop at 90 degrees, speed for tapping is 200, speed for retraction is 500
N40 M30	End of program
-> Must be programmed in a single block	

## 2.1.6 Tapping with compensating chuck – CYCLE840



### Programming

CYCLE840 (RTP, RFP, SDIS, DP, DPR, DTB, SDR, SDAC, ENC, MPIT, PIT- AXN, \_PTAB, \_TECHNO)



### Parameters

RTP	real	Retraction plane (absolute)
RFP	real	Reference plane (absolute)
SDIS	real	Safety distance (enter without sign)
DP	real	Final drilling depth (absolute)
DPR	real	Final drilling depth relative to reference plane (enter without sign)
DTB	real	Dwell time at thread depth SW 6.2 or higher: Always operative now if >0 is programmed Value range: 0<=DTB
SDR	int	Direction of rotation for retraction Values: 0 (automatic reversal of direction of rotation) 3 or 4 (for M3 or M4)
SDAC	int	Direction of rotation after end of cycle Values: 3, 4 or 5 (for M3, M4 or M5)
ENC	int	Tapping with/without encoder Values: 0 = with encoder, without dwell time (SW 6.2 or higher) 1 = without encoder, first programs the cycle, then the feed (SW 6.2 or higher) 11 = without encoder, calculates the feed in the cycle (SW 6.2 or higher) 20 = with encoder, with dwell time (SW 6.2 or higher)
MPIT	real	Thread pitch as thread size Value range: 3 (for M3) ... 48 (for M48)
PIT	real	Thread pitch as value Value range: 0.001 ... 2000.000mm SW 6.2 or higher: If _PTAB=0 or 1: in mm (as earlier SW versions) If _PTAB=2 in thread starts per inch
_AXN (SW 6.2 or higher)	int	Tool axis: Values: 1 = 1st geometry axis 2 = 2nd geometry axis or else 3rd geometry axis
_PTAB (SW 6.2 or higher)	int	Evaluation of thread pitch PIT Values: 0...according to programmed system of units inch/metric 1...pitch in mm 2...pitch in thread starts per inch 3...pitch in inches/revolution

---

_TECHNO (SW 6.2 or higher)	int	Technological settings UNITS DIGIT: Exact stop behavior Values: 0...and as programmed before cycle call 1...(G601) 2...(G602) 3...(G603) TENS DIGIT: Feedforward control Values: 0...and as programmed before cycle call 1...with feedforward control (FFWON) 2...without feedforward control (FFWOF) HUNDREDS DIGIT: Brake application point Values: 0...without calculation 1...with calculation
----------------------------------	-----	--

---



### Function

The tool drills at the programmed spindle speed and feedrate to the programmed thread depth.

With this cycle, tapping with compensating chuck can be performed

- without encoder and
- with encoder.



### Sequence of operations


#### Tapping with compensating chuck without encoder (ENC=1)

##### Position reached prior to cycle start:

The drilling position is the position in the two axes of the selected plane.

##### The cycle implements the following motion sequence:

- Approach of the reference plane brought forward by the safety distance with G0
- Tapping to the final drilling depth with G63
- Retraction to the reference plane brought forward by the safety distance with G63
- Retraction to retraction plane with G0



The spindle override must be set to 100%.


#### Tapping with compensating chuck without encoder with encoder (ENC=0)

##### Position reached prior to cycle start:

The drilling position is the position in the two axes of the selected plane.

##### The cycle implements the following motion sequence:

- Approach of the reference plane brought forward by the safety distance with G0
- Tapping to the final drilling depth with G33
- Dwell time at thread depth (parameter DTB)
- Retraction to the reference plane brought forward by the safety distance with G33
- Retraction to retraction plane with G0





### Description of parameters



See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters RTP, RFP, SDIS, DP, DPR

#### **DTB (dwell time)**

You program the dwell time in seconds. It works in parameter ENC depending on which technological variant you selected.

#### **SDR (direction of rotation for retraction)**

The direction of rotation for retraction when tapping is programmed in parameter SDR. For tapping with an encoder, the direction of spindle travel can be reversed automatically, for which SDR=0 is set.

#### **SDAC (direction of rotation)**

As the cycle can also be called modally (see Section 2.2), it requires a direction of rotation for tapping further threads. This is programmed in parameter SDAC and corresponds to the direction of rotation programmed before the first call in the higher-level program. If SDR=0, the value assigned to SDAC is of no significance in the cycle and can be omitted from the parameterization.

#### **ENC (tapping)**

If tapping is to be performed without encoder although an encoder exists, parameter ENC must be assigned the value 1.

However, if no encoder exists and the parameter is assigned the value 0, it is ignored in the cycle.

- **Tapping without encoder with input of the lead (SW 6.2 or higher):**

From **SW 6.2** you can calculate the correlation between feed and speed via the programmed lead within the cycle for tapping without encoder (G63 thread). The speed must be programmed before the cycle is called.

You can specify the lead either via MPIT (metric thread unit) or via PIT (thread lead as value) just as for tapping without encoder.

The feed is then calculated in the cycle from the lead and the speed. After the cycle has ended, the last programmed feed applies again.

Programming:

ENC=11, programming the lead in MPIT or PIT

- **Tapping with encoder with dwell time (SW 6.2 or higher):**

As an alternative, you can program a dwell time in the parameter DTB for tapping with encoder (G33 thread) from **SW 6.2**. It applies after tapping and before retraction to the retraction plane RTP, and is required for machines with unfavorable spindle dynamics.

Programming:

ENC=20, entering the dwell time in parameter DTB

#### MPIT and PIT (as thread size and as value)

The parameter for the spindle pitch only has a meaning if tapping is performed with encoder. The cycle calculates the feedrate from the spindle speed and the pitch.

The value for the thread pitch can either be defined as the thread size (for metric threads between M3 and M48 only) or as a value (distance from one thread turn to the next as a numerical value). The parameter not required in each case is omitted from the call or assigned the value zero.

If the two thread pitch parameters have conflicting values, alarm 61001 "Thread pitch wrong" is generated by the cycle and cycle execution is aborted.

#### \_AXN (tool axis)

By programming the drilling axis via \_AXN, it is possible to omit the switchover from plane G18 to G17 when the deep hole tapping cycle is used on turning machines. Meaning:

\_AXN=1 1st axis of the current plane


\_AXN=2 2nd axis of the current plane

\_AXN=3 3rd axis of the current plane.

For example, to machine a center drilling (in Z) in plane G18, you program:

G18

\_AXN=1



## 2.1 Drilling cycles

### **\_PTAB (evaluation of pitch PIT)**

Parameter `_PTAB` determines the unit of measurement of the pitch.

- 0=according to programmed system of units inch/metric
- 1=pitch in mm
- 2=pitch in thread starts per inch
- 3=pitch in inches/revolution.

This parameter is needed in connection with the option for selecting different thread tables in the cycles support.

### **\_TECHNO (technological settings)**

Parameter `_TECHNO` can be set to select technological characteristics for tapping operations.

Possible values are:

#### **Ones digit (exact stop behavior):**

- 0=as programmed before cycle call
- 1=(G601)
- 2=(G602)
- 3=(G603)

#### **Tens digit (feedforward control):**

- 0=as programmed before cycle call
- 1=with feedforward control (FFWON)
- 2=without feedforward control (FFWOF)

#### **Hundreds digit (brake application point):**

- 0=without calculation
- 1=with calculation.





### Further notes

Depending on the setting in machine data NUM\_ENC\_S, the cycle selects whether tapping is to be performed with or without encoder.

The direction of rotation for the spindle must be programmed with M3 or M4 before the cycle is called.

In thread blocks with G63, the values of the feedrate override switch and spindle speed override switch are frozen at 100 percent.


A longer compensating chuck is usually required for tapping without encoder.



### Programming example

#### Thread without encoder

In this program a thread is tapped without encoder at position X35 Y35 in the XY plane, the drilling axis is the Z axis. Parameters SDR and SDAC for the direction of rotation must be assigned, parameter ENC is assigned the value 1, the value for the depth is absolute. Pitch parameter PIT can be omitted. A compensating chuck is used in machining.




N10 G90 G0 D2 T2 S500 M3	Specification of technology values
N20 G17 X35 Y35 Z60	Traverse to drilling position
N30 G1 F200	Specification of path feedrate
N40 CYCLE840 (59, 56, , 15, , 1, 4, 3, 1)	Cycle call, dwell time 1 sec, SDR=4, SDAC=3, no safety clearance, parameters MPIT, PIT are not programmed, i.e. the lead results from the correlation between the freely programmable values F and S.
N50 M30	End of program



### Thread with encoder

In this program a thread is tapped with encoder at position X35 Y35 in the XY plane; the boring axis is the Z axis. The pitch parameter must be defined, automatic reversal of the direction of rotation is programmed. A compensating chuck is used in machining.



DEF INT SDR=0	Definition of parameters with value assignments
DEF REAL PIT=3.5	
N10 G90 G0 D2 T2 S500 M4	Specification of technology values
N20 G17 X35 Y35 Z60	Traverse to drilling position
N30 CYCLE840 (59, 56, , 15, , , , , -> ->, PIT)	Cycle call, without safety distance, value for depth programmed as an absolute value, SDAC, ENC, MPIT are omitted (i.e., are assigned the value zero)
N40 M30	End of program

-> Must be programmed in a single block

### 2.1.7 Boring 1 – CYCLE85



#### Programming

CYCLE85 (RTP, RFP, SDIS, DP, DPR, DTB, FFR, RFF)



#### Parameters

RTP	real	Retraction plane (absolute)
RFP	real	Reference plane (absolute)
SDIS	real	Safety distance (enter without sign)
DP	real	Final drilling depth (absolute)
DPR	real	Final drilling depth relative to reference plane (enter without sign)
DTB	real	Dwell time at final drilling depth (chip breaking)
FFR	real	Feedrate
RFF	real	Retraction feedrate



#### Function


The tool drills at the programmed spindle speed and feedrate to the programmed final drilling depth. The inward and outward movement is performed at the feedrate that is assigned to FFR and RFF respectively. This cycle can be used to ream drill holes.



#### Sequence of operations

##### Position reached prior to cycle start:

The drilling position is the position in the two axes of the selected plane.



### The cycle implements the following motion sequence:

- Approach of the reference plane brought forward by the safety distance with G0
- Traverse to final drilling depth with G1 and at the feedrate programmed under parameter FFR
- Dwell time at final drilling depth
- Retraction to the reference plane brought forward by the safety distance with G1 and the retraction feedrate defined under parameter RFF
- Retraction to retraction plane with G0.



### Description of parameters



See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters RTP, RFP, SDIS, DP, DPR

#### DTB (dwell time)


Parameter DTB is the dwell time at the final drilling depth (chip breaking) in seconds.

#### FFR (feedrate)

The feedrate value assigned to FFR is active for boring.

#### RFF (retraction feedrate)

The feedrate value assigned to RFF is active for retraction from the plane.






### Programming example

#### First boring pass

Cycle CYCLE85 is called at position Z70 X50 in the ZX plane. The boring axis is the Y axis. The value for the final drilling depth in the cycle call is programmed as a relative value, no dwell time is programmed. The top edge of the workpiece is positioned at Y102.



```
DEF REAL FFR, RFF, RFP=102, DPR=25,
SDIS=2
```

Definition of parameters with value assignments

```
N10 G0 FFR=300 RFF=1.5*FFR S500 M4
```

Specification of technology values

```
N20 G18 T1 D1 Z70 X50 Y105
```

Traversal to drilling position

```
N21 M6
```

```
N30 CYCLE85 (RFP+3, RFP, SDIS, , DPR, , -> Cycle call, no dwell time programmed
-> FFR, RFF)
```

```
N40 M30
```

End of program

-> Must be programmed in a single block

## 2.1 Drilling cycles

### 2.1.8 Boring 2 – CYCLE86



#### Programming

CYCLE86 (RTP, RFP, SDIS, DP, DPR, DTB, SDIR, RPA, RPO, RPAP, POSS)



#### Parameters

RTP	real	Retraction plane (absolute)
RFP	real	Reference plane (absolute)
SDIS	real	Safety distance (enter without sign)
DP	real	Final drilling depth (absolute)
DPR	real	Final drilling depth relative to reference plane (enter without sign)
DTB	real	Dwell time at final drilling depth (chip breaking)
SDIR	int	Direction of rotation Value: 3 (for M3) 4 (for M4)
RPA	real	Retraction path in abscissa of the active plane (incremental, enter with sign)
RPO	real	Retraction path in ordinate of the active plane (incremental, enter with sign)
RPAP	real	Retraction path in applicate of the active plane (incremental, enter with sign)
POSS	real	Spindle position for oriented spindle stop in the cycle (in degrees)



#### Function

The tool drills at the programmed spindle speed and feedrate to the programmed final drilling depth. With Boring 2, oriented spindle stop is activated with the SPOS command once the drilling depth has been reached. Then, the programmed retraction positions are approached in rapid traverse and, from there, the retraction plane.




### Sequence of operations

#### Position reached prior to cycle start:

The drilling position is the position in the two axes of the selected plane.

#### The cycle implements the following motion sequence:

- Approach of the reference plane brought forward by the safety distance with G0
- Traverse to final drilling depth with G1 and the feedrate programmed before the program call
- Dwell time at final drilling depth
- Oriented spindle stop at the spindle position programmed under POSS
- Traverse retraction path in up to three axes with G0
- Retraction to the reference plane brought forward by the safety distance with G0
- Retraction to the retraction plane with G0 (initial drilling position in both axes on the plane).



### Description of parameters


See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters RTP, RFP, SDIS, DP, DPR

#### DTB (dwell time)

Parameter DTB is the dwell time at the final drilling depth (chip breaking) in seconds.

#### SDIR (direction of rotation)

With this parameter you determine the direction of rotation with which boring is performed in the cycle. If values other than 3 or 4 (M3/M4) are generated, alarm 61102 "No spindle direction programmed" is output and the cycle is not executed.



## 2.1 Drilling cycles

### RPA (retraction path, in abscissa)

Under this parameter you define a retraction movement in the abscissa, which is executed after the final drilling depth has been reached and oriented spindle stop has been performed.

### RPO (retraction path, in ordinate)

Under this parameter you define a retraction movement in the ordinate which is executed after the final drilling has been reached and oriented spindle stop has been performed.

### RPAP (retraction path, in applicate)

Under this parameter you define a retraction movement in the boring axis which is executed after the final drilling has been reached and oriented spindle stop has been performed.

### POSS (spindle position)

Under POSS the spindle position for the oriented spindle stop which is performed after the final drilling depth has been reached is programmed in degrees.



### Further notes

With the SPOS command you can perform an oriented spindle stop of the active master spindle. The angular value is programmed with a transfer parameter.



*Cycle CYCLE86 can be used if the spindle to be used for the boring operation is technically able to go into position-controlled spindle operation.*

### Turning machine without Y axis (SW 6.2 or higher)

You can now use the cycle CYCLE86 for turning machines without Y axis. Retraction to drilling depth is then traversed in two axes only. If a retraction path was programmed for the 3rd axis, it would be ignored.

If you call the cycle without Y axis in the G18 plane, the following alarm appears: 61005 "3rd geometry axis not available", as the Y axis would then be the boring axis.






### Programming example

#### Second boring pass

Cycle CYCLE86 is called at position X70 Y50 in the ZX plane. the boring axis is the Z axis. The final drilling depth is programmed as an absolute value, a safety distance is not defined. The dwell time at the final drilling depth is 2 secs. The top edge of the workpiece is positioned at Z110. In the cycle, the spindle is turned with M3 and stops at 45 degrees.



DEF REAL DP, DTB, POSS	Definition of parameters
N10 DP=77 DTB=2 POSS=45	Value assignments
N20 G0 G17 G90 F200 S300	Specification of technology values
N30 D1 T3 Z112	Traverse to retraction plane
N40 X70 Y50	Traverse to drilling position
N50 CYCLE86 (112, 110, , DP, , DTB, 3, -> -> -1, -1, +1, POSS)	Cycle call with absolute drilling depth
N60 M30	End of program

-> Must be programmed in a single block

## 2.1 Drilling cycles

### 2.1.9 Boring 3 – CYCLE87



#### Programming

CYCLE87 (RTP, RFP, SDIS, DP, DPR, SDIR)



#### Parameters

RTP	real	Retraction plane (absolute)
RFP	real	Reference plane (absolute)
SDIS	real	Safety distance (enter without sign)
DP	real	Final drilling depth (absolute)
DPR	real	Final drilling depth relative to reference plane (enter without sign)
SDIR	int	Direction of rotation Value: 3 (for M3) 4 (for M4)



#### Function

The tool drills at the programmed spindle speed and feedrate to the programmed final drilling depth. With Boring 3, a spindle stop without orientation M5 and then a programmed stop M0 are generated when the final drilling depth is reached. The NC START key is pressed to continue the retraction movement in rapid traverse mode until the retraction plane is reached.




### Sequence of operations

#### Position reached prior to cycle start:

The drilling position is the position in the two axes of the selected plane.

#### The cycle implements the following motion sequence:

- Approach of the reference plane brought forward by the safety distance with G0
- Traverse to final drilling depth with G1 and the feedrate programmed before the program call
- Spindle stop with M5
- Press NC START key
- Retraction to retraction plane with G0.




### Description of parameters

See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters RTP, RFP, SDIS, DP, DPR

#### SDIR (direction of rotation)

With this parameter you determine the direction of rotation with which boring is performed in the cycle. If values other than 3 or 4 (M3/M4) are generated, alarm 61102 "No spindle direction programmed" is output and the cycle is aborted.






### Programming example

#### Third boring pass

Cycle CYCLE87 is called at position X70 Y50 in the ZX plane. the boring axis is the Z axis. The final drilling depth is programmed as an absolute value. The safety distance is 2mm.



DEF REAL DP, SDIS	Definition of parameters
N10 DP=77 SDIS=2	Value assignments
N20 G0 G17 G90 F200 S300	Specification of technology values
N30 D1 T3 Z113	Traverse to retraction plane
N40 X70 Y50	Traverse to drilling position
N50 CYCLE87 (113, 110, SDIS, DP, , 3)	Cycle call with programmed spindle direction M3
N60 M30	End of program

### 2.1.10 Boring 4 – CYCLE88



#### Programming

CYCLE88 (RTP, RFP, SDIS, DP, DPR, DTB, SDIR)



#### Parameters

RTP	real	Retraction plane (absolute)		
RFP	real	Reference plane (absolute)		
SDIS	real	Safety distance (enter without sign)		
DP	real	Final drilling depth (absolute)		
DPR	real	Final drilling depth relative to reference plane (enter without sign)		
DTB	real	Dwell time at final drilling depth		
SDIR	int	Direction of rotation	Value: 3 (for M3)	4 (for M4)



#### Function

The tool drills at the programmed spindle speed and feedrate to the programmed final drilling depth. With Boring 4, a dwell time, a spindle stop without orientation M5 and a programmed stop M0 are generated when the final drilling depth is reached. Pressing the NC START key continues the retraction movement in rapid traverse mode until the retraction plane is reached.




#### Sequence of operations

##### Position reached prior to cycle start:

The drilling position is the position in the two axes of the selected plane.

##### The cycle implements the following motion sequence:

- Approach of the reference plane brought forward by the safety distance with G0
- Traverse to final drilling depth with G1 and the feedrate programmed before the program call
- Dwell time at final drilling depth
- Spindle stop with M5 ( $\_ZSD[5]=1$ ) or
- spindle and program stop with M5 M0 ( $\_ZSD[5]=0$ ). Press the NC START key after program stop.
- Retraction to retraction plane with G0.





### Description of parameters




See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters RTP, RFP, SDIS, DP, DPR Cycle setting data \_ZSD[5] see Section 3.2.

#### DTB (dwell time)

Parameter DTB is the dwell time at the final drilling depth (chip breaking) in seconds.

#### SDIR (direction of rotation)

The programmed direction of rotation is active for the movement to the final drilling depth.  
If values other than 3 or 4 (M3/M4) are programmed, alarm 61102 "No spindle direction programmed" is output and the cycle is aborted.




### Programming example

#### Fourth boring pass

Cycle CYCLE88 is called at position X80 Y90 in the ZX plane. The boring axis is the Z axis. The safety distance is programmed as 3mm. The final drilling depth is defined as a value relative to the reference plane.

M4 is active in the cycle.



DEF REAL RFP, RTP, DPR, DTB, SDIS	Definition of parameters
N10 RFP=102 RTP=105 DPR=72 DTB=3 SDIS=3	Value assignments
N20 G17 G90 T1 D1 F100 S450	Specification of technology values
N21 M6	
N30 G0 X80 Y90 Z105	Traverse to drilling position
N40 CYCLE88 (RTP, RFP, SDIS, , DPR, -> -> DTB, 4)	Cycle call with programmed spindle direction M4
N50 M30	End of program

-> Must be programmed in a single block

### 2.1.11 Boring 5 – CYCLE89



#### Programming

CYCLE89 (RTP, RFP, SDIS, DP, DPR, DTB)



#### Parameters

RTP	real	Retraction plane (absolute)
RFP	real	Reference plane (absolute)
SDIS	real	Safety distance (enter without sign)
DP	real	Final drilling depth (absolute)
DPR	real	Final drilling depth relative to reference plane (enter without sign)
DTB	real	Dwell time at final drilling depth (chip breaking)



#### Function

The tool drills at the programmed spindle speed and feedrate to the programmed final drilling depth. Once the final drilling depth has been reached a dwell time can be programmed.




#### Sequence of operations

##### Position reached prior to cycle start:

The drilling position is the position in the two axes of the selected plane.

##### The cycle implements the following motion sequence:

- Approach of the reference plane brought forward by the safety distance with G0
- Traverse to final drilling depth with G1 and the feedrate programmed before the program call
- Dwell time at final drilling depth
- Retraction to the reference plane brought forward by the safety distance with G1 and the same feedrate value
- Retraction to retraction plane with G0.






### Description of parameters

See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters RTP, RFP, SDIS, DP, DPR

#### DTB (dwell time)


Parameter DTB is the dwell time at the final drilling depth (chip breaking) in seconds.



### Programming example

#### Fifth boring pass

Boring cycle CYCLE89 is called at position X80 Y90 in the XY plane with a safety distance of 5mm and the final drilling depth specified as an absolute value. the boring axis is the Z axis.



```
DEF REAL RFP, RTP, DP, DTB
```

Definition of parameters

```
RFP=102 RTP=107 DP=72 DTB=3
```

Value assignments

```
N10 G90 G17 F100 S450 M4
```

Specification of technology values

```
N20 G0 T1 D1 X80 Y90 Z107
```

Traverse to drilling position

```
N21 M6
```

```
N30 CYCLE89 (RTP, RFP, 5, DP, , DTB)
```

Cycle call

```
N40 M30
```

End of program



## 2.2 Modal call of drilling cycles

With NC programming it is possible to call any subroutine modally.

This feature is of special importance for drilling cycles.



### Programming

Modal call of a subroutine

MCALL

with drilling cycle (for example)

```
MCALL CYCLE81 (RTP, RFP, SDIS, DP, DPR)
```



### Function


In NC programming, subroutines and cycles can be called modally, also i.e. maintaining the parameters previous values.

You generate a modal subroutine call by programming the keyword **MCALL** (modal subroutine call) in front of the subroutine name. This function causes the subroutine to be called and executed automatically after each block that contains traversing movement.

The function is deactivated by programming **MCALL** without a subroutine name or by a new modal call of another subroutine.

Nesting of modal calls is not permissible, i.e., subroutines that are called modally cannot contain any further modal subroutine calls.

Any number of modal drilling cycles can be programmed, the number is not limited to a certain number of G functions reserved for this purpose.




## 2.2 Modal call of drilling cycles



### Programming example

#### Row of holes\_5

With this program you can machine a row of 5 thread holes positioned parallel to the Z axis in the ZX plane. The distance between each of the holes is 20mm. The row of holes starts at Z20 and X30, the first hole in the row being 20mm from this point. In this example, the geometry of the row of holes has been programmed without using a cycle. First of all, drilling is performed with cycle CYCLE81 and then with CYCLE84 tapping (rigid). The holes are 80mm deep. This is the difference between the reference plane and the final drilling depth.



DEF REAL RFP=102, DP=22, RTP=105, -> -> PIT=4.2, SDIS	Definition of parameters with value assignments
DEF INT COUNT=1	
N10 SDIS=3	Value for safety distance
N20 G90 F300 S500 M3 D1 T1	Specification of technology values
N30 G18 G0 Y105 Z20 X30	Approach starting position
N40 MCALL CYCLE81 (RTP, RFP, SDIS, DP)	Modal call of the drilling cycle
N50 MA1: G91 Z20	Traverse to next position (ZX plane) Cycle is executed
N60 COUNT=COUNT+1	Loop for drilling positions along the row of holes
N70 IF COUNT<6 GOTOB MA1	
N80 MCALL	Deselect modal call
N90 G90 Y105 Z20	Approach starting position again
N100 COUNT=1	Set counter to zero
N110 ...	Tool change
N120 MCALL CYCLE84 (RTP, RFP, SDIS, -> -> DP, , , 3, , PIT, , 400)	Modal call of tapping cycle
N130 MA2: G91 Z20	Next drilling position
N140 COUNT=COUNT+1	Loop for drilling position of the row of holes
N150 IF COUNT<6 GOTOB MA2	
N160 MCALL	Deselect modal call
N170 G90 X30 Y105 Z20	Approach starting position again
N180 M30	End of program

-> Must be programmed in a single block



### Further notes

#### Explanation of this example

The modal call must be deselected in block N80 because in the next block the tool is traversed to a position where no drilling is to be performed.

It is advisable to store the drilling positions for a machining task of this type in a subroutine which is then called at MA1 or MA2.



In the description of the drilling pattern cycles on the following pages in Section 2.3, the program using these cycles has been adapted and thus simplified.

The drilling pattern cycles are based on the call principle.

MCALL DRILLING CYCLE (...)

DRILLING PATTERN (...).

## 2.3 Drill pattern cycles

The drilling pattern cycles only describe the geometry of an arrangement of holes on a plane. The link to a drilling cycle is established via the modal call (see Section 2.2) of this drilling cycle before the drilling pattern cycle is programmed.

### 2.3.1 Preconditions

#### **Drilling pattern cycles without drilling cycle call**

Drilling pattern cycles can also be used for other applications without the drilling cycle first being called modally because the drilling pattern cycles can be parameterized without reference to the drilling cycle used.

If there was no modal call of the subroutine prior to calling the drilling pattern cycle, error message 62100 "No drilling cycle active" appears.

You can acknowledge this error message with the error acknowledgment key and continue program processing by pressing the NC Start key. The drilling pattern cycle then approaches each of the positions calculated from the input data one after the other without calling a subroutine at these points.

#### **Behavior when quantity parameter is zero**

The number of holes in a drilling pattern must be parameterized. If the value of the quantity parameter is zero when the cycle is called (or if this parameter is omitted from the parameter list), alarm 61103 "Number of holes is zero" is output and the cycle is aborted.

#### **Checks in the case of limited ranges of input parameter values**

Generally there are no plausibility checks for defining parameters in the drilling pattern cycles if they are not expressly declared for a parameter with a description of the response.

### 2.3.2 Row of holes – HOLES1



#### Programming

HOLES1 (SPCA, SPCO, STA1, FDIS, DBH, NUM)



#### Parameters

SPCA	real	Abscissa of a reference point on the straight line (absolute)
SPCO	real	Ordinate of this reference point (absolute)
STA1	real	Angle to abscissa Value range $-180 < STA1 \leq 180$ degrees
FDIS	real	Distance between the first hole and the reference point (enter without sign)
DBH	real	Distance between the holes (enter without sign)
NUM	int	Number of holes




#### Function

With this cycle you can program a row of holes, i.e. a number of holes that lie along a straight line or a grid of holes. The type of hole is determined by the drilling cycle that has already been called modally.



#### Sequence of operations

To avoid unnecessary travel, the cycle calculates whether the row of holes is machined starting from the first hole or the last hole from the actual position of the plane axes and the geometry of the row of holes. The drilling positions are then approached one after the other in rapid traverse.





### Description of parameters

#### SPCA and SPCO (reference point abscissa and ordinate)

One point along the straight line of the row of holes is defined as the reference point for determining the distances between the holes. The distance to the first hole FDIS is defined from this point.

#### STA1 (angle)


The straight line can be in any position on the plane. It is specified both by the point defined by SPCA and SPCO and by the angle contained by the straight line and the abscissa of the workpiece coordinate system that is active when the cycle is called. The angle is entered under STA1 in degrees.

#### FDIS and DBH (distance)

Under FDIS you enter the distance between the first hole and the reference point defined under SPCA and SPCO. The parameter DBH contains the distance between any two holes.

#### NUM (number)

You determine the number of holes with the parameter NUM.






### Programming example

#### Row of holes

With this program you can machine a row of holes of five tapped holes positioned in parallel to the Z axis on the ZX plane, with a distance between each hole of 20mm. The row of holes starts at Z20 and X30, the first hole in the row being 10mm from this point. The geometry of the row of holes is described by the cycle HOLES1. First of all, drilling is performed with cycle CYCLE81 and then with CYCLE84 tapping (rigid). The holes are 80 mm deep. This is the difference between the reference plane and the final drilling depth.



```
DEF REAL RFP=102, DP=22, RTP=105
DEF REAL SDIS, FDIS
DEF REAL SPCA=30, SPCO=20, STA1=0, ->
-> DBH=20
DEF INT NUM=5
```

Definition of parameters with value assignments

```
N10 SDIS=3 FDIS=10
```

Value for safety distance and distance of the first hole to the reference point

```
N20 G90 F30 S500 M3 D1 T1
```

Specification of technology values for the machining section

```
N30 G18 G0 Z20 Y105 X30
```

Approach starting position

```
N40 MCALL CYCLE81 (RTP, RFP, SDIS, DP)
```

Modal call of drilling cycle

```
N50 HOLES1 (SPCA, SPCO, STA1, FDIS, ->
-> DBH, NUM)
```

Call of row of holes cycle, the cycle starts with the first hole. Only the drilling positions are approached in this cycle

```
N60 MCALL
```

Deselect modal call

```
...
```

Tool change

```
N70 G90 G0 Z30 Y75 X105
```

Traverse to position next to 5th hole

```
N80 MCALL CYCLE84 (RTP, RFP, SDIS, DP, ->
-> , 3, , 4.2, , , 400)
```

Modal call of tapping cycle

```
N90 HOLES1 (SPCA, SPCO, STA1, FDIS, ->
-> DBH, NUM)
```

Call of row of holes cycle started with the 5th hole in the row

```
N100 MCALL
```

Deselect modal call

```
N110 M30
```

End of program


-> Must be programmed in a single block



## Programming example

### Grid of holes

With this program you can machine a grid of holes consisting of five rows of five holes each that lie in the XY plane at a distance of 10mm from one another. The starting point of the grid is X30 Y20.



```
DEF REAL RFP=102, DP=75, RTP=105,
SDIS=3
```

Definition of parameters with value assignments

```
DEF REAL SPCA=30, SPCO=20, STA1=0, ->
-> DBH=10, FDIS=10
```

```
DEF INT NUM=5, LINENUM=5, COUNT=0
```

```
DEF REAL LINEDIST
```

```
N10 LINEDIST=DBH
```

Distance between rows = distance between holes

```
N20 G90 F300 S500 M3 D1 T1
```

Specification of technology values

```
N30 G17 G0 X=SPCA-10 Y=SPCO Z105
```

Approach starting position

```
N40 MCALL CYCLE81 (RTP, RFP, SDIS, DP)
```

Modal call of a drilling cycle

```
N50 MARK1: HOLES1 (SPCA, SPCO, STA1, ->
> FDIS, DBH, NUM)
```

Call of row of holes cycle

```
N60 SPCO=SPCO+LINEDIST
```

Ordinate of reference point for the next line

```
N70 COUNT=COUNT+1
```

Jump back to MARK1 if the condition is fulfilled

```
N80 IF COUNT<LINENUM GOTOB MARK1
```

```
N90 MCALL
```

Deselect modal call

```
N100 G90 G0 X=SPCA-10 Y=SPCO Z105
```

Approach starting position

```
N110 M30
```

End of program

-> Must be programmed in a single block



### 2.3.3 Hole circle – HOLES2



#### Programming

HOLES2 (CPA, CPO, RAD, STA1, INDA, NUM)



#### Parameters


CPA	real	Center point of circle of holes, abscissa (absolute)
CPO	real	Center point of circle of holes, ordinate (absolute)
RAD	real	Radius of circle of holes (enter without sign)
STA1	real	Initial angle Value range $-180 < STA1 \leq 180$ degrees
INDA	real	Indexing angle
NUM	int	Number of holes



#### Function

A circle of holes can be machined with this cycle. The machining plane must be defined before the cycle is called.


The type of hole is determined by the drilling cycle that has already been called modally.





### Sequence of operations

In the cycle, the drilling positions are approached one after the other on the plane with G0.



### Description of parameters

#### CPA, CPO and RAD (center point and radius abscissa, ordinate)

The position of the circle of holes in the machining plane is defined by the center point (parameters CPA and CPO) and the radius (parameter RAD). Only positive values are permissible for the radius.


#### STA1 and INDA (start angle and indexing angle)

The arrangement of the holes in the circle is defined by these parameters.

Parameter STA1 defines the angle of rotation between the positive direction of the abscissa in the coordinate system active before the cycle was called and the first hole. Parameter INDA contains the angle of rotation from one hole to the next. If parameter INDA is assigned the value zero, the indexing angle is calculated internally from the number of holes which are positioned equally in a circle.

#### NUM (number)

You determine the number of holes with the parameter NUM.






### Programming example

#### Hole circle

The program uses CYCLE82 4 to produce holes with a depth of 30mm. The final drilling depth is defined as a value relative to the reference plane. The circle is defined by the center point X70 Y60 and the radius 42mm in the XY plane. The initial angle is 45 degrees.

The safety distance in the drilling axis Z is 2mm.



DEF REAL CPA=70, CPO=60, RAD=42, STA1=45	Definition of parameters with value assignments
DEF INT NUM=4	
N10 G90 F140 S710 M3 D1 T40	Specification of technology values
N20 G17 G0 X50 Y45 Z2	Approach starting position
N30 MCALL CYCLE82 (2, 0, 2, , 30)	Modal call of drilling cycle, without dwell time, DP is not programmed
N40 HOLES2 (CPA, CPO, RAD, STA1, , NUM)	Call of circle of holes cycle, the indexing angle is calculated internally by the cycle as parameter INDA has been omitted
N50 MCALL	Deselect modal call
N60 M30	End of program

### 2.3.4 Dot matrix – CYCLE801 (SW 5.3 and higher)



#### Programming

```
CYCLE801 (_SPCA, _SPCO, _STA, _DIS1,  
_DIS2, _NUM1, _NUM2)
```



#### Parameters

_SPCA	real	Reference point for grid of holes in the 1st axis, abscissa (absolute)
_SPCO	real	Reference point for grid of holes in the 2nd axis, abscissa (absolute)
_STA	real	Angle to abscissa
_DIS1	real	Distance between columns (without sign)
_DIS2	real	Distance between rows (without sign)
_NUM1	int	Number of columns
_NUM2	int	Number of rows



#### Function

Cycle CYCLE801 can be used to machine a "grid of holes". The type of hole is determined by the drilling cycle that has already been called modally.



#### Sequence of operations

The cycle calculates the sequence of holes such that the empty paths between them are kept as short as possible. The starting position of the machining operation is defined according to the last position reached in the plane prior to the cycle call. Starting positions are one of the four possible corner positions in each case.



### Description of parameters

#### **\_SPCA and \_SPCO (reference point abscissa and ordinate)**

These two parameters determine the first point of the hole grid. The row and column distances are specified in relation to this point.

#### **\_STA (angle)**


The grid of holes can be positioned at any angle in the plane. This angle is programmed in degrees in **\_STA** and refers to the abscissa of the workpiece coordinate system active as the cycle is called.

#### **\_DIS1 and \_DIS2 (column and row distances)**

The distances must be entered without sign. To avoid unnecessary empty travel, the dot matrix is machined line by line or column by column based on a comparison of distance measurements.


#### **\_NUM1 and \_NUM2 (number)**

This parameter determines the number of columns or lines.



### Programming example

Cycle CYCLE801 is used to machine a dot matrix, consisting of 15 holes in three lines and five columns. The associated drilling program is called modally beforehand.



N10 G90 G17 F900 S4000 M3 T2 D1	Specification of technology values
N15 MCALL CYCLE82(10,0,1,-22,0,0)	Modal call of a drilling cycle
N20 CYCLE801(30,20,0,10,15,5,3)	Call dot matrix
N25 M30	End of program

## Notes

## Milling Cycles

3.1	General information.....	3-120
3.2	Preconditions.....	3-121
3.3	Thread cutting – CYCLE90 .....	3-123
3.4	Elongated holes on a circle – LONGHOLE .....	3-129
3.5	Slots on a circle – SLOT1 .....	3-135
3.6	Circumferential slot – SLOT2 .....	3-143
3.7	Milling rectangular pockets – POCKET1 .....	3-149
3.8	Milling circular pockets – POCKET2 .....	3-153
3.9	Milling rectangular pockets – POCKET3 .....	3-157
3.10	Milling circular pockets – POCKET4 .....	3-167
3.11	Face milling – CYCLE71 .....	3-173
3.12	Path milling – CYCLE72.....	3-179
3.13	Milling rectangular spigots – CYCLE76 (SW 5.3 and higher) .....	3-189
3.14	Milling circular spigots – CYCLE77 (SW 5.3 and higher).....	3-194
3.15	Pocket milling with islands – CYCLE73, CYCLE74, CYCLE75 (SW 5.2 and higher) ...	3-198
3.15.1	Transfer pocket edge contour – CYCLE74 .....	3-199
3.15.2	Transfer island contour – CYCLE75 .....	3-201
3.15.3	Contour programming .....	3-202
3.15.4	Pocket milling with islands – CYCLE73 .....	3-204
3.16	Swiveling – CYCLE800 (SW 6.2 and higher).....	3-227
3.16.1	Operation, parameter assignment, input screen form .....	3-229
3.16.2	Operating instructions .....	3-233
3.16.3	Parameters.....	3-234
3.16.4	Starting up CYCLE800 .....	3-238
3.16.5	User cycle TOOLCARR.spf.....	3-253
3.16.6	Error messages.....	3-258
3.17	High Speed Settings – CYCLE832 (SW 6.3 and higher) .....	3-259
3.17.1	Calling CYCLE832 in the HMI menu tree.....	3-262
3.17.2	Parameters.....	3-265
3.17.3	Customizing technology .....	3-266
3.17.4	Interfaces .....	3-268
3.17.5	Error messages.....	3-270

### 3.1 General information

The following sections describe how milling cycles are programmed.

This section is intended to guide you in selecting cycles and assigning them with parameters. In addition to a detailed description of the function of the individual cycles and the corresponding parameters, you will also find a sample program at the end of each section to familiarize you with the use of cycles.

The Sections are structured as follows:

- **Programming**
- **Parameters**
- **Function**
- **Sequence of operations**
- **Explanation of parameters**
- **Additional notes**
- **Sample program.**

"Programming" and "Parameters" explain the use of cycles sufficiently for the experienced user, whereas beginners can find all the information they need for programming cycles under "Function", "Sequence of operations", "Explanation of parameters", "Additional notes" and the "Sample program".



## 3.2 Preconditions

### Programs required in the control

The milling cycles call the programs

- MESSAGE.SPF and
- PITCH.SPF

internally as subroutines. Moreover, you need the data block GUD7.DEF and the macro definition file SMAC.DEF.

Load them in the parts program memory of the control unit before executing the milling cycles.

### Call and return conditions

Milling cycles are programmed independently of the actual axis names. You must activate a tool offset before you call the milling cycles.


The required values for the feedrate, spindle speed and spindle direction of rotation must be programmed in the parts program if no parameters are available for these in the milling cycle.

The center point coordinates of the milling pattern or the pocket to be machined are programmed in the right-handed coordinate system.

The G functions and current programmable frame active before the cycle was called remain active beyond the cycle.

### Plane definition

In milling cycles, it is generally assumed that the current workpiece coordinate system is defined by selecting plane G17, G18 or G19 and activating a programmable frame (if necessary). The infeed axis is always the 3rd axis of the coordinate system (see also Programming Guide).



## 3.2 Preconditions

### Spindle programming

The spindle commands in the cycles always refer to the active master spindle of the control.

If you want to use a cycle on a machine with several spindles, you must first define the spindle that is to be used as the master spindle with the command SETMS (see also Programming Guide).

### Machining status messages

Status messages are displayed on the control monitor during the processing of milling cycles.

The following messages might be displayed:

- "Elongated hole <No.>(first figure) is being machined"
- "Slot <No.>(other figure) is being machined"
- "Circumferential slot <No.>(last figure) is being machined".

In each case <No.> stands for the number of the figure that is currently being machined.

These messages do not interrupt program processing and continue to be displayed until the next message is displayed or the cycle is completed.

### Cycle setting data

A few parameters of milling cycles (SW 4 and higher) and their behavior can be modified by cycle settings.

The cycle setting data are defined in data block GUD7.DEF.

The following new cycle setting data are introduced:

<u>_ZSD[x]</u>	Value	Meaning	Cycles affected
<u>_ZSD[1]</u>	0	Depth computation in the new cycles is made between the reference plane + safety distance and depth ( <u>_RFP</u> + <u>_SDIS</u> - <u>_DP</u> )	POCKET1 to POCKET4, LONGHOLE,
	1	Depth computation is made without including safety distance	CYCLE71, SLOT1, CYCLE72, SLOT2
<u>_ZSD[2]</u>	0	Dimension of rectangular pocket or rectangular spigot from the center point	POCKET3
	1	Dimension of rectangular pocket or rectangular spigot from a corner	CYCLE76
<u>_ZSD[5]</u>	0	Execute at drilling depth M5 M0	CYCLE88
	1	Execute at drilling depth M5	

### 3.3 Thread cutting – CYCLE90



#### Programming

CYCLE90 (RTP, RFP, SDIS, DP, DPR, DIATH, KDIAM, PIT, FFR, CDIR, TYPTH, CPA, CPO)



#### Parameters


RTP	real	Retraction plane (absolute)
RFP	real	Reference plane (absolute)
SDIS	real	Safety distance (enter without sign)
DP	real	Final drilling depth (absolute)
DPR	real	Final drilling depth relative to reference plane (enter without sign)
DIATH	real	Nominal diameter, outside diameter of thread
KDIAM	real	Core diameter, inside diameter of thread
PIT	real	Thread pitch; Value range: 0.001 ... 2000.000mm
FFR	real	Feedrate for thread milling (enter without sign)
CDIR	int	Direction of rotation for thread milling Value: 2 (for thread milling with G2) 3 (for thread milling with G3)
TYPTH	int	Thread type: Values: 0= inside thread 1= outside thread
CPA	real	Center point of circle, abscissa (absolute)
CPO	real	Center point of circle, ordinate (absolute)



#### Function

You can produce inside and outside threads with cycle CYCLE90. The path in thread milling is based on helical interpolation. All three geometrical axes of the current plane which you define before calling the cycle are involved in this movement.

The programmed feedrate F depends on the axis grouping defined in the FGROUP instruction before the cycle call (see Programming Guide).





## Sequence of operations


### Outside threads

#### Position reached prior to cycle start:

This can be any position from which the starting position on the outside diameter of the thread at the retraction plane level can be reached without collision.

This start position for thread milling with G2 lies between the positive abscissa and the positive ordinate in the current level (i.e. in the 1st quadrant of the coordinate system). For thread milling with G3, the start position lies between the positive abscissa and the negative ordinate (i.e. in the 4th quadrant of the coordinate system).

The distance from the thread diameter depends on the thread size and the tool radius used.



#### The cycle implements the following motion sequence:

- Travel to the starting point with G0 at the retraction plane level in the applicate of the current plane
- Infeed to the reference plane brought forward by the safety distance with G0
- Movement to the thread diameter along a circular path in the direction G2/G3 opposite to that defined in CDIR
- Thread milling along a helical path with G2/G3 and feedrate FFR
- Travel-out movement along a circular path in the opposite direction G2/G3 and the reduced feedrate FFR
- Retraction to retraction plane in the applicate with G0

### Inside threads

#### Position reached prior to cycle start:

This can be any position from which the starting position on the center point of the thread at the retraction plane level can be approached without collision.

#### The cycle implements the following motion sequence:

- Travel to the center point of the thread with G0 at the retraction plane level in the applicate of the current plane
- Infeed to the reference plane brought forward by the safety distance with G0
- Approach with G1 and the reduced feedrate FFR along an approach circle calculated in the cycle
- Movement to the thread diameter along a circular path in the direction G2/G3 defined in CDIR
- Thread milling along a helical path with G2/G3 and feedrate FFR
- Travel-out movement along a circular path with the same direction of rotation and the reduced feedrate FFR
- Retraction to the center point of the thread with G0
- Retraction to retraction plane in the applicate with G0.

#### Thread from bottom to top

For technological reasons, it may be preferable to machine the thread from the bottom to the top. The retraction plane RTP is then below the thread depth DP.

This machining operation is possible, the depth data must be programmed as absolute values and before cycle start, the machine must be positioned on the retraction plane or one position behind the retraction plane.

### 3.3 Thread cutting – CYCLE90



#### Programming example

(thread from bottom to top)

A thread must be cut starting from –20 up to 0 with a 3mm pitch. The retraction plane is at 8.

```
N10 G17 X100 Y100 S300 M3 T1 D1 F1000
N20 Z8
N30 CYCLE90 (8, -20, 0, 0, 0, 46, 40, 3, 800, 3, 0, 50, 50)
N40 M2
```

The hole must have at least a depth of –21.5 (half pitch in excess).

#### Overshoot in the thread longitudinal direction

For thread milling, the travel-in and travel-out movements occur along all three axes concerned. This means that the travel-out movement includes a further step in the vertical axis, beyond the programmed thread depth. The overshoot is calculated:

$$\Delta z = \frac{p}{4} * \frac{2*WR + RDIFF}{DIATH}$$

$\Delta z$      Overshoot, internal

p        Thread pitch

WR      Tool radius

DIATH Outside diameter of the thread

RDIFF Radius difference for travel-out

For inside threads  $RDIFF = DIATH/2 - WR$ ,  
 For outside threads  $RDIFF = DIATH/2 + WR$ .



### Description of parameters



See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters RTP, RFP, SDIS, DP, DPR

#### DIATH, KDIAM and PIT (nominal diameter, core diameter and thread pitch)

With these parameters you define the thread data such as, nominal diameter, core diameter and pitch. Parameter DIATH is the outside diameter and KDIAM the inside diameter of the thread. The travel-in and travel-out movements are generated by the cycle based on these parameters.

#### FFR (feedrate)

The value of parameter FFR is defined as the current feedrate value for thread milling. In thread milling it is active for the movement along the helical path. This value is reduced in the cycle for the travel-in and travel-out movements. Retraction is performed outside the helical path with G0.

#### CDIR (direction of rotation)

You define the value for the machining direction of the thread in this parameter.

If the parameter is assigned an invalid value, the message

"Wrong milling direction, G3 will be generated" is output.


In this case the cycle is continued and G3 is automatically generated.

#### TYPTH (thread type)

With parameter TYPTH you determine whether an outside or inside thread is to be machined.

#### CPA and CPO (center point)

With these parameters you define the center point of the hole or spigot on which the thread is to be machined.



### 3.3 Thread cutting – CYCLE90

#### Further notes

The milling cutter radius is taken into account by the cycle. A tool offset must therefore be programmed before the cycle is called. Otherwise alarm 61000 "No tool offset active" is output and the cycle is aborted.


When the tool radius equals zero or a negative value, the cycle is also aborted with this alarm.

With inside threads, the tool radius is monitored and alarm 61105 "Cutter radius too large" is output and the cycle is aborted.

#### Programming example

##### Inside thread

With this program you can machine an inside thread at position X60 Y50 on the G17 plane.



```
DEF REAL RTP=48, RFP=40, SDIS=5, ->
-> DPR=40, DIATH=60, KDIAM=50
DEF REAL PIT=2, FFR=500, CPA=60, CPO=50
DEF INT CDIR=2, TYPH=0
```

Definition of variables with value assignment

```
N10 G90 G0 G17 X0 Y0 Z80 S200 M3
```

Approach starting position

```
N20 T5 D1
```

Specification of technology values

```
N30 CYCLE90 (RTP, RFP, SDIS, ->
-> DPR, DIATH, KDIAM, PIT, FFR, CDIR,
TYPH, CPA, CPO)
```

Cycle call

```
N40 G0 G90 Z100
```

Approach position after cycle

```
N50 M02
```

End of program

-> Must be programmed in a single block



### 3.4 Elongated holes on a circle – LONGHOLE



#### Programming

LONGHOLE (RTP, RFP, SDIS, DP, DPR, NUM, LENG, CPA, CPO, RAD, STA1, INDA, FFD, FFP1, MID)



#### Parameters

RTP	real	Retraction plane (absolute)
RFP	real	Reference plane (absolute)
SDIS	real	Safety distance (enter without sign)
DP	real	Elongated hole final drilling depth (absolute)
DPR	real	Elongated hole final drilling depth relative to reference plane (enter without sign)
NUM	int	Number of elongated holes
LENG	real	Length of elongated hole (enter without sign)
CPA	real	Center point of circle, abscissa (absolute)
CPO	real	Center point of circle, ordinate (absolute)
RAD	real	Radius of circle (enter without sign)
STA1	real	Initial angle
INDA	real	Indexing angle
FFD	real	Feedrate for depth infeed
FFP1	real	Feedrate for surface machining
MID	real	Maximum infeed depth for infeed (enter without sign)



*The cycle requires a milling cutter with an "end tooth cutting over center" (DIN 844).*

### 3.4 Elongated holes on a circle – LONGHOLE




#### Function

Elongated holes arranged on a circle can be machined with this cycle. The longitudinal axis of the elongated holes is arranged radially.

Unlike the slot, the width of the elongated hole is determined by the diameter of the tool.

To avoid unnecessary travel, the cycle calculates the most optimum path. If several depth infeed movements are required to machine an elongated hole, the infeed is performed at alternate end points.

The path to be traversed in the plane along the longitudinal axis of the elongated hole changes direction after every infeed. The cycle automatically looks for the shortest path when changing to the next elongated hole.






### Sequence of operations

#### Position reached prior to cycle start:

The starting position can be any position from which each of the elongated holes can be approached without collision.

#### The cycle implements the following motion sequence:

- The starting position of a cycle is approached with G0. The nearest end point of the first elongated hole to be machined is approached in both axes of the current plane at the retraction plane level in the applicator of this plane and then lowered in the applicator to the reference plane brought forward by the safety distance.
- Each elongated hole is milled in a reciprocating movement. Machining is performed in the plane with G1 and the feedrate programmed under FFP1. At each reversal point, the infeed to the next machining depth calculated by the cycle is performed with G1 and the feedrate FFD until the final depth is reached.
- Retraction to the retraction plane with G0 and approach to the next elongated hole along the shortest path.
- When the last elongated hole has been machined, the tool is traversed from the last position reached in the machining plane to the retraction plane with G0 and the cycle is terminated.





### Description of parameters



See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters RTP, RFP, SDIS. See Section 3.2 for cycle setting data `_ZSD[1]`.

#### DP and DPR (elongated hole depth)

The elongated hole depth can be defined as either absolute (DP) or relative (DPR) to the reference plane. If it is entered as a relative value, the cycle automatically calculates the correct depth on the basis of the positions of the reference and retraction planes.

#### NUM (number)

The number of elongated holes is determined with the parameter NUM.

#### LENG (elongated hole length)

The elongated hole length is programmed under LENG. If it is detected during the cycle run that this length is less than the cutter diameter, then the cycle is aborted with alarm 61105 "Cutter radius too large".

#### MID (infeed depth)

The maximum infeed depth is defined with this parameter.


The depth infeed is performed by the cycle in equally sized infeed steps.

Using MID and the total depth, the cycle automatically calculates this infeed which lies between 0.5x maximum infeed depth and the maximum infeed depth. The minimum possible number of infeed steps is used as the basis. `_MID=0` means that the cut to pocket depth is made with one infeed.

The depth infeed commences at the reference plane moved forward by the safety distance (as a function of `_ZSD[1]`).

#### FFD and FFP1 (feedrate depth and plane)

Feedrate FFP1 is active for all traversing movements performed in the plane at feedrate. FFD is active for infeeds that are perpendicular to this plane.



**CPA, CPO and RAD (center point and radius)**

The position of the circle in the machining plane is defined by the center point (parameters CPA and CPO) and the radius (parameter RAD). Only positive values are permissible for the radius.

**STA1 and INDA (start angle and indexing angle)**

The arrangement of the elongated holes around the circle is defined by these parameters.

If INDA=0 the indexing angle is calculated from the number of elongated holes so that they are equally distributed around the circle.

**Further notes**

A tool offset must be activated before the cycle is called. Otherwise the cycle is aborted and alarm 61000 "No tool offset active" is output.

If incorrect values are assigned to the parameters that determine the arrangement and size of the elongated holes and thus cause mutual contour violation of the elongated holes, the cycle is not started. The cycle is aborted after the error message 61104 "Contour violation of slots/elongated holes" is output.

During the cycle, the workpiece coordinate system is shifted and rotated. The values in the workpiece coordinate system are displayed on the actual value display as if the longitudinal axis of the elongated hole being machined were positioned on the first axis of the current machining plane.

When the cycle is completed, the workpiece coordinate system is again in the same position as it was before the cycle was called.


### 3.4 Elongated holes on a circle – LONGHOLE



#### Programming example

##### Machining elongated holes

With this program you can machine four elongated holes 30mm in length and with a relative depth of 23mm (difference between the reference plane and the base of the elongated hole) that lie in a circle with the center point Z45 Y40 and a radius of 20mm in the YZ plane. The initial angle is 45 degrees, the indexing angle is 90 degrees. The maximum infeed depth is 6mm, the safety distance is 1mm.



```
N10 G19 G90 S600 M3
```

Specification of technology values

```
T10 D1
```

```
M6
```

```
N20 G0 Y50 Z25 X5
```

Approach starting position

```
N30 LONGHOLE (5, 0, 1, , 23, 4, 30, ->  
-> 40, 45, 20, 45, 90, 100, 320, 6)
```

Cycle call

```
N40 M30
```

End of program

-> Must be programmed in a single block

### 3.5 Slots on a circle – SLOT1



#### Programming

SLOT1 (RTP, RFP, SDIS, DP, DPR, NUM, LENG, WID, CPA, CPO, RAD, STA1, INDA, FFD, FFP1, MID, CDIR, FAL, VARI, MIDF, FFP2, SSF, \_FALD, \_STA2)



#### Parameters

RTP	real	Retraction plane (absolute)
RFP	real	Reference plane (absolute)
SDIS	real	Safety distance (enter without sign)
DP	real	Slot depth (absolute)
DPR	real	Slot depth relative to the reference plane (enter without sign)
NUM	int	Number of slots
LENG	real	Slot length (enter without sign)
WID	real	Slot width (enter without sign)
CPA	real	Center point of circle, abscissa (absolute)
CPO	real	Center point of circle, ordinate (absolute)
RAD	real	Radius of circle (enter without sign)
STA1	real	Initial angle
INDA	real	Indexing angle
FFD	real	Feedrate for depth infeed
FFP1	real	Feedrate for surface machining
MID	real	Maximum infeed depth for infeed (enter without sign)
CDIR	int	Milling direction for machining the slot Value: 0...Down-cut milling (as spindle rotation) 1...Up-cut milling 2...with G2 (independent of spindle direction) 3...with G3
FAL	real	Final machining allowance on slot edge (enter without sign)
VARI	int	Machining type (enter without sign) UNITS DIGIT: Value: 0...Complete machining 1...Roughing 2...Finishing TENS DIGIT: Value: 0...Perpendicular with G0 1...Perpendicular with G1 3...Oscillation with G1
MIDF	real	Maximum infeed depth for finishing
FFP2	real	Feedrate for finishing

### 3.5 Slots on a circle – SLOT1

SSF	real	Speed for finishing
_FALD	real	Final machining allowance on the base of slot
_STA2	real	Maximum insertion angle for oscillation movement




The cycle requires a milling cutter with an "end tooth cutting over center" (DIN 844).



#### Function


Cycle SLOT1 is a combined roughing-finishing cycle.

With this cycle you can machine slots arranged on a circle. The longitudinal axis of the slots is arranged radially. Unlike the elongated hole, a value is defined for the slot width.



#### Sequence of operations


Position reached before the beginning of the cycle:  
The starting position can be any position from which each of the slots can be approached without collision.





**The cycle implements the following motion sequence:**

- Travel to the position marked in the figure on the right at the beginning of the cycle with G0
- Complete machining of a slot is performed in the following stages:
  - Approach to reference plane brought forward by the safety distance with G0.
  - Infeed to the next machining depth as programmed under VAR1 and at feed value FFD.
  - Solid machining of the slot to the final machining allowance on slot base and slot edge at feed value FFP1.
  - Subsequent finishing at feed value FFP2 and spindle speed SSF along the contour according to the machining direction programmed under CDIR.
  - The vertical depth infeed of G0/G1 always takes place at the same position in the machining plane until the final depth of the slot is reached.
  - With reciprocating machining, select the starting point so that the end point always reaches the same position in the machining plane.
- Retract tool to retraction plane and move to next slot with G0.
- At the end of machining the last slot the tool moves to the retraction plane with G0 and the cycle ends.





### Description of parameters



See Section 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters RTP, RFP, SDIS. See Section 3.2 for cycle setting data `_ZSD[1]`.

#### DP and DPR (slot depth)

The slot depth can be defined as either absolute (DP) or relative (DPR) to the reference plane.

If it is entered as a relative value, the cycle automatically calculates the correct depth on the basis of the positions of the reference and retraction planes.

#### NUM (number)

The number of slots is determined with the parameter NUM.

#### LENG and WID (slot length and slot width)

The shape of a slot in the plane is determined with parameters LENG and WID. The milling cutter diameter must be smaller than the slot width. Otherwise alarm 61105 "Cutter radius too large" will be activated and the cycle aborted.

The milling cutter diameter must not be smaller than half of the slot width. This is not checked.

#### CPA, CPO and RAD (center point and radius)

The position of the circle of holes in the machining plane is defined by the center point (parameters CPA and CPO) and the radius (parameter RAD). Only positive values may be entered for the radius.


#### STA1 and INDA (start angle and indexing angle)

The arrangement of the slot on the circle is defined by these parameters.

STA1 defines the angle between the positive direction of the abscissa of the workpiece coordinate system active before the cycle was called and the first slot.

Parameter INDA contains the angle from one slot to the next.

If  $INDA=0$ , the indexing angle is calculated from the number of slots so that they are arranged equally around the circle.



**FFD and FFP1 (feedrate depth and plane)**

Feedrate FFD is operative for vertical infeed to the machining plane with G1 and for insertion with oscillation motion.

Feedrate FFP1 is active for all movements in the plane traversed at feedrate when roughing.

**MID (infeed depth)**

The maximum infeed depth is defined with this parameter. The depth infeed is performed by the cycle in equally sized infeed steps.

Using MID and the total depth, the cycle automatically calculates this infeed which lies between 0.5x maximum infeed depth and the maximum infeed depth. The minimum possible number of infeed steps is used as the basis. MID=0 means that the cut to slot depth is made with one infeed.

The depth infeed commences at the reference plane moved forward by the safety distance (as a function of `_ZSD[1]`).

**CDIR (milling direction)**

You define the slot machining direction in this parameter.

Under parameter `_CDIR` the mill direction

- direct "2 for G2" and "3 for G3" or
- alternatively "up-cut milling" or "down-cut milling" can be programmed. Up-cut milling or down-cut milling is determined within the cycle via the spindle direction activated prior to the cycle call.

<b>Up-cut milling</b>	<b>Down-cut milling</b>
-----------------------	-------------------------

M3 → G3	M3 → G2
---------	---------

M4 → G2	M4 → G3
---------	---------

**FAL (final machining allowance at slot edge)**

With this parameter you can program a final machining allowance on the slot edge. FAL does not affect the depth infeed. If the value of FAL is greater than allowed for the specified width and the milling cutter used, FAL is automatically reduced to the maximum possible value. In the case of rough machining, milling is performed with a reciprocating movement and depth infeed at both end points of the slot.

### 3.5 Slots on a circle – SLOT1

#### **VARI, MIDF, FFP2 and SSF (machining type, infeed depth, feedrate and speed)**

You can define the type of machining with parameter VARI.

Possible values are:

UNITS DIGIT

- 0=Complete machining in two parts
  - Machining of the slot (SLOT1, SLOT2) or pocket (POCKET1, POCKET2) to the final machining allowance is performed at the spindle speed programmed before the cycle was called and with feedrate FFP1. Depth infeed is defined with MID.
  - Removing stock for the remaining final machining allowance takes place at the spindle speed preset by SSF and feed FFP2. The depth infeed takes place with vertical infeed via MIDF. If MIDF=0, the infeed is equal to the final depth.  
If FFP2 is not programmed, feed FFP1 acts.  
Similarly, if there is no message from SSF, i.e. the speed programmed before cycle start is active.
- 1=Roughing  
The slot (SLOT1, SLOT2) or pocket (POCKET1, POCKET2) is solid machined up to the final machining allowance at the speed programmed before the cycle call and feedrate FFP1. The depth infeed is programmed in MID.
- 2=Finishing  
The cycle requires that the slot (SLOT1, SLOT2) or pocket (POCKET1, POCKET2) is already machined to a remaining final machining allowance and that it is only necessary to machine the final machining allowance. If FFP2 and SSF are not programmed, the feedrate FFP1 or the speed programmed before the cycle call is active. Depth infeed takes place with via MIDF with paraxial infeed.  
In machining mode VARI=30 the edge finishing cut is performed at the last roughing depth.

TENS POINT (infeed)

- 0=Perpendicular with G0
- 1=Perpendicular with G1
- 3=Oscillation with G1

If another value is programmed for the parameter VARI, the cycle aborts after output of the alarm 61102 "Operating mode not defined correctly".

### **Cutter diameter=slot width (WID)**

- With complete machining, finishing machining only takes place on the base.
- In machining mode VARI=32 positioning is paraxial in Z with G1 followed by finish-cutting (infeed possible via MIDF).

### **\_FALD (final machining allowance on slot base)**

A separate final machining allowance on the base is taken into account in roughing operations.

### **\_STA2 (insertion angle)**

Parameter \_STA2 defines the maximum insertion angle for the oscillation motion.

- **Vertical insertion (VARI=0X, VARI=1X)**

Vertical depth insertion is always performed at the same position on the machining plane down to the final depth of the slot.

- **Insertion with oscillation on the center axis of the slot (VARI=3X)**

means that the mill center point oscillates along an oblique linear path until it has reached the next current depth. The maximum insertion angle is programmed under \_STA2, the length of the oscillation path is calculated from LENG-WID. The oscillating depth infeed ends at the same point as with vertical depth infeed motions, the starting point in the plane is calculated accordingly. The roughing operation begins in the plane once the current depth is reached. The feedrate is programmed under \_FFD.

### 3.5 Slots on a circle – SLOT1


#### Further notes

A tool offset must be activated before the cycle is called. Otherwise the cycle is aborted with Alarm 61000 "No tool offset active".

If incorrect values are assigned to the parameters that determine the arrangement and size of the slots and thus cause mutual contour violation of the slots, the cycle is not started. The cycle is aborted after the error message 61104 "Contour violation of slots/elongated holes".

During the cycle, the workpiece coordinate system is shifted and rotated. The values in the workpiece coordinate system displayed on the actual value display are such that the longitudinal axis of the slot that has just been machined corresponds to the first axis of the current machining plane.

When the cycle is completed, the workpiece coordinate system is again in the same position as it was before the cycle was called.




#### Programming example

##### Slots

This program produces the same arrangement of four slots on a circle as the program for elongated hole machining (see Section 3.4).

The slots have the following dimensions: Length 30mm, width 15mm and depth 23mm. The safety distance is 1mm, the final machining allowance is 0.5mm, the milling direction is G2, the maximum infeed in the depth is 10mm. The slots must be machined completely with an oscillating insertion motion.



```
N10 G19 G90 S600 M3
```

```
N15 T10 D1
```

```
N17 M6
```

```
N20 G0 Y20 Z50 X5
```

```
N30 SLOT1 (5, 0, 1, -23, , 4, 30, 15, ->
->40, 45, 20, 45, 90, 100, 320, 10, ->
->2, 0.5, 30, 10, 400, 1200, 0.6, 5)
```

```
N40 M30
```

Specification of technology values

Approach starting position

Cycle call, parameters VARI, MIDF, FFP2 and SSF omitted

End of program

-> Must be programmed in a single block

### 3.6 Circumferential slot – SLOT2



#### Programming

SLOT2 (RTP, RFP, SDIS, DP, DPR, NUM, AFSL, WID, CPA, CPO, RAD, STA1, INDA, FFD, FFP1, MID, CDIR, FAL, VARI, MIDF, FFP2, SSF, \_FFCP)



#### Parameters

RTP	real	Retraction plane (absolute)
RFP	real	Reference plane (absolute)
SDIS	real	Safety distance (enter without sign)
DP	real	Slot depth (absolute)
DPR	real	Slot depth relative to the reference plane (enter without sign)
NUM	int	Number of slots
AFSL	real	Angle for the slot length (enter without sign)
WID	real	Circumferential slot width (enter without sign)
CPA	real	Center point of circle, abscissa (absolute)
CPO	real	Center point of circle, ordinate (absolute)
RAD	real	Radius of circle (enter without sign)
STA1	real	Initial angle
INDA	real	Indexing angle
FFD	real	Feedrate for depth infeed
FFP1	real	Feedrate for surface machining
MID	real	Maximum infeed depth for infeed (enter without sign)
CDIR	int	Milling direction for machining the circumferential slot Value: 2 (for G2) 3 (for G3)
FAL	real	Final machining allowance on slot edge (enter without sign)
VARI	int	Type of machining UNITS DIGIT: Values: 0=Complete machining 1=Roughing 2=Finishing TENS DIGIT (SW 6.3 and higher) Value: 0=positioning from slot to slot in a straight line with G0 1=positioning from slot to slot on a circular path with feedrate
MIDF	real	Maximum infeed depth for finishing
FFP2	real	Feedrate for finishing
SSF	real	Speed for finishing
_FFCP (SW 6.3 and higher)	real	Feedrate for intermediate positioning on a circular path, in mm/min




*The cycle requires a milling cutter with an "end tooth cutting over center" (DIN 844).*



### Function

Cycle SLOT2 is a combined roughing-finishing cycle. With this cycle you can machine circumferential slots arranged on a circle.





### Sequence of operations

#### Position reached prior to cycle start:

The starting position can be any position from which each of the slots can be approached without collision.

#### The cycle implements the following motion sequence:

- Travel to the position marked in the figure on the right at the beginning of the cycle with G0.
- The circumferential slot is machined in the same steps as an elongated hole.
- After finishing a circumferential slot, the tool is withdrawn to the retraction plane and the transition to the next slot is made, either on a straight line with G0 or on a circular path at the feedrate programmed in \_FFCP.
- When the last slot has been machined, the tool is traversed to the end position reached in the machining plane specified in the display to the retraction plane with G0 and the cycle is terminated.







### Description of parameters



See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters RTP, RFP, SDIS.



See Section 3.5 (SLOT1) for a description of parameters DP, DPR, FFD, FFP1, MID, CDIR, FAL, VARI, MIDF, FFP2, SSF.

See Section 3.2 for cycle setting data `_ZSD[1]`.

#### NUM (number)

The number of slots is determined with the parameter NUM.

#### AFSL and WID (angle and circumferential slot width)

With parameters AFSL and WID you define the shape of a slot in the plane. The cycle checks whether the slot width is violated with the active tool. If this is the case, alarm 61105 "Cutter radius too large" is output and the cycle is aborted.

#### CPA, CPO and RAD (center point and radius)

The position of the circle in the machining plane is defined by the center point (parameters CPA and CPO) and the radius (parameter RAD). Only positive values are permissible for the radius.


#### STA1 and INDA (start angle and indexing angle)

The arrangement of circumferential slots on the circle is defined by these parameters.

STA1 defines the angle between the positive direction of the abscissa of the workpiece coordinate system active before the cycle was called and the first circumferential slot.

The INDA parameter contains the angle from one circumferential slot to the next.

If INDA=0, the indexing angle is calculated from the number of circumferential slots so that they are arranged equally around the circle.



**New machining types in SW 6.3 and higher:****Finishing the edge only (VARI=x3)**

- There is a new selection "Finishing the edge". This is the only machining type where the diameter of the cutter is allowed to be less than half the slot width. There is no checking of whether it is sufficiently large to execute the final machining allowance FAL.
- A number of depth infeeds are possible. These are programmed as usual by parameter MID. The slot is circumnavigated once at each depth.
- To approach and return from the contour, the cycle generates a smooth approach to the segment of the circular path.

**Intermediate positioning on the circular path****(VARI=1x)**

- Especially when used on turning machines, it can happen that there will be a spigot in the middle of the circle on which the slots lie, that does not allow one slot to be positioned directly to the next with G0.
- The circular path is taken to be the circle on which the slots lie (determined by parameters CPA, CPO and RAD). Positioning takes place at the same level as intermediate positioning on a straight line with G0. The positioning feedrate for the circular path is programmed under the parameter in mm/min.



### Further notes

A tool offset must be activated before the cycle is called. Otherwise the cycle is aborted and alarm 61000 "No tool offset active" is output.



If incorrect values are assigned to the parameters that determine the arrangement and size of the slots and thus cause mutual contour violation of the slots, the cycle is not started.

The cycle is aborted after the error message 61104 "Contour violation of slots/elongated holes" is output.

During the cycle, the workpiece coordinate system is shifted and rotated. The actual-value display in the workpiece coordinate system is always displayed such that the circumferential slot currently being machined on the 1st axis of the current processing level starts and the zero point of the workpiece coordinate system lies in the center of the circle. When the cycle is completed, the workpiece coordinate system is again in the same position as it was before the cycle was called.

### Special case: Slot width = cutter diameter

- The machining case of slot width = cutter diameter is allowed for roughing and finishing. This machining case occurs if  
slot width  $WID - 2 * \text{final machining allowance } FAL = \text{cutter diameter}$ .
- The traversing strategy is then as for the LONGHOLE cycle, i.e. depth infeed takes place alternately at the reversal points, see graphic.






### Programming example

#### Slots2

With this program you can machine three circumferential slots arranged on a circle whose center point is X60 Y60 and radius 42mm in the XY plane. The circumferential slots have the following dimensions: Width 15mm, angle for slot length 70 degrees, depth 23mm. The initial angle is 0 degrees, the indexing angle is 120 degrees. The slot contours are machined to a final machining allowance of 0.5mm, the safety distance in infeed axis Z is 2mm, the maximum depth infeed is 6mm. The slots are to be completely machined. The same speed and feedrate are used for finishing. Infeed during finishing is performed straight to the base of the slot.



```
DEF REAL FFD=100
```

Definition of variables with value assignment

```
N10 G17 G90 S600 M3
```

Specification of technology values

```
N15 T10 D1
```

```
N17 M6
```

```
N20 G0 X60 Y60 Z5
```

Approach starting position

```
N30 SLOT2 (2, 0, 2, -23, , 3, 70, ->
```

Cycle call

```
-> 15, 60, 60, 42, , 120, FFD, ->
```

Reference plane+SDIS=retraction plane means: Lower in infeed axis with G0 to reference plane+SDIS no longer applicable, parameters VAR, MIDF, FFP2 and SSF omitted

```
-> FFD+200, 6, 2, 0.5)
```

```
N40 M30
```

End of program

-> Must be programmed in a single block

### 3.7 Milling rectangular pockets – POCKET1



#### Programming

POCKET1 (RTP, RFP, SDIS, DP, DPR, LENG, WID, CRAD, CPA, CPD, STA1, FFD, FFP1, MID, CDIR, FAL, VARI, MIDF, FFP2, SSF)



#### Parameters

RTP	real	Retraction plane (absolute)
RFP	real	Reference plane (absolute)
SDIS	real	Safety distance (enter without sign)
DP	real	Pocket depth (absolute)
DPR	real	Pocket depth relative to the reference plane (enter without sign)
LENG	real	Pocket length (enter without sign)
WID	real	Pocket width (enter without sign)
CRAD	real	Corner radius (enter without sign)
CPA	real	Pocket center point, abscissa (absolute)
CPO	real	Pocket center point, ordinate (absolute)
STA1	real	Angle between longitudinal axis and abscissa Value range: $0 \leq \text{STA1} < 180$ degrees
FFD	real	Feedrate for depth infeed
FFP1	real	Feedrate for surface machining
MID	real	Maximum infeed depth for infeed (enter without sign)
CDIR	int	Milling direction for machining the pocket Value: 2 (for G2) 3 (for G3)
FAL	real	Final machining allowance on pocket edge (enter without sign)
VARI	int	Type of machining Value: 0=Complete machining 1=Roughing 2=Finishing
MIDF	real	Maximum infeed depth for finishing
FFP2	real	Feedrate for finishing
SSF	real	Speed for finishing



*The cycle requires a milling cutter with an "end tooth cutting over center" (DIN 844).*




The pocket milling cycle POCKET3 can be performed with any tool.

### 3.7 Milling rectangular pockets – POCKET1



#### Function

The cycle is a combined roughing-finishing cycle. With this cycle you can machine rectangular pockets in any position in the machining plane.




#### Sequence of operations

##### Position reached prior to cycle start:

This can be any position from which the starting position on the center point of the pocket at the retraction plane level can be approached without collision.

##### The cycle implements the following motion sequence:

- With G0, the pocket center point is approached at the retraction plane level and then, from this position, with G0 the reference plane brought forward by the safety distance is approached. Complete machining of the pocket is performed in the following stages:
  - Infeed to the next machining depth with G1 and feedrate FFD.
  - Pocket milling up to the final machining allowance with feedrate FFP1 and the spindle speed that was active before the cycle was called.
- After roughing is completed:
  - Infeed to the machining depth defined by MIDF
  - Final machining allowance along the contour at feedrate FFP2 and speed SSF.
  - The machining direction is defined by CDIR.



- When machining of the pocket is completed the tool is traversed to the pocket center point on the retraction plane and the cycle is terminated.



### Description of parameters



See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters RTP, RFP, SDIS.



See Section 3.5 (SLOT1) for a description of parameters FFD, FFP1, MID, CDIR, FAL, VARI, MIDF, FFP2, SSF.

See Section 3.2 for cycle setting data `_ZSD[1]`.

#### DP and DPR (pocket depth)

The pocket depth can be defined as either absolute (DP) or relative (DPR) to the reference plane.

If it is entered as a relative value, the cycle automatically calculates the correct depth on the basis of the positions of the reference and retraction planes.

#### LENG, WID and CRAD (length, width and radius)

The shape of a pocket in the plane is determined with parameters LENG, WID and CRAD.


If it is not possible to traverse to the programmed corner radius with the active tool because its radius is larger, the corner radius of the completed pocket corresponds to the tool radius. If the milling cutter radius is greater than half the length or width of the pocket, the cycle is aborted and alarm 61105 "Cutter radius too large" is output.

#### CPA, CPO (center point)

With parameters CPA and CPO you define the center point of the pocket in the abscissa and ordinate.

#### STA1 (angle)

STA1 defines the angle between the positive abscissa and the longitudinal axis of the pocket.



### 3.7 Milling rectangular pockets – POCKET1

#### Further notes

A tool offset must be activated before the cycle is called. Otherwise the cycle is aborted and alarm 61000 "No tool offset active" is output.

A new workpiece coordinate system that influences the actual value display is used in the cycle. The zero point of this coordinate system lies on the pocket center point.


The original coordinate system becomes active again after the end of the cycle.

#### Programming example

##### Pocket

With this program you can machine a pocket that is 60mm long, 40mm wide, 17.5mm deep (difference between the reference plane and the base of the pocket) and which has a corner radius of 8mm in the XY plane. The angle to the X axis is 0 degrees. The final machining allowance of the pocket edges is 0.75mm, the safety distance in the Z axis, which is added to the reference plane, is 0.5mm. The center point of the pocket lies at X60 and Y40, the maximum depth infeed is 4mm.

Only roughing is to be performed.



```
DEF REAL LENG, WID, DPR, CRAD
```

Definition of variables

```
DEF INT VARI
```

```
N10 LENG=60 WID=40 DPR=17.5 CRAD=8
```

Value assignments

```
N20 VARI=1
```

```
N30 G90 S600 M4
```

Specification of technology values

```
N35 T20 D2
```

```
N37 M6
```

```
N40 G17 G0 X60 Y40 Z5
```

Approach starting position

```
N50 POCKET1 (5, 0, 0.5, , DPR, ->
```

Cycle call

```
-> LENG, WID, CRAD, 60, 40, 0, ->
```

Parameters MIDF, FFP2 and SSF are omitted

```
-> 120, 300, 4, 2, 0.75, VARI)
```

```
N60 M30
```

End of program

-> Must be programmed in a single block



### 3.8 Milling circular pockets – POCKET2



#### Programming

POCKET2 (RTP, RFP, SDIS, DP, DPR, PRAD, CPA, CPO, FFD, FFP1, MID, CDIR, FAL, VARI, MIDF, FFP2, SSF)



#### Parameters

RTP	real	Retraction plane (absolute)
RFP	real	Reference plane (absolute)
SDIS	real	Safety distance (enter without sign)
DP	real	Pocket depth (absolute)
DPR	real	Pocket depth relative to the reference plane (enter without sign)
PRAD	real	Pocket radius (enter without sign)
CPA	real	Pocket center point, abscissa (absolute)
CPO	real	Pocket center point, ordinate (absolute)
FFD	real	Feedrate for depth infeed
FFP1	real	Feedrate for surface machining
MID	real	Maximum infeed depth for infeed (enter without sign)
CDIR	int	Milling direction for machining the pocket Value: 2 (for G2) 3 (for G3)
FAL	real	Final machining allowance on pocket edge (enter without sign)
VARI	int	Type of machining Value: 0=Complete machining 1=Roughing 2=Finishing
MIDF	real	Maximum infeed depth for finishing
FFP2	real	Feedrate for finishing
SSF	real	Speed for finishing




*The cycle requires a milling cutter with an "end tooth cutting over center" (DIN 844).*



The pocket milling cycle POCKET4 can be performed with any tool.

**Function**

The cycle is a combined roughing-finishing cycle. With this cycle you can machine circular pockets in the machining plane.

**Sequence of operations****Position reached prior to cycle start:**

This can be any position from which the starting position on the center point of the pocket at the retraction plane level can be approached without collision.

**The cycle implements the following motion sequence:**

- With G0, the pocket center point is approached at the retraction plane level and then, from this position, with G0 the reference plane brought forward by the safety distance is approached. Complete machining of the pocket is performed in the following stages:
  - Infeed perpendicular to the pocket center to the next machining depth with feedrate FFD.
  - Pocket milling up to the final machining allowance with feedrate FFP1 and the spindle speed that was active before the cycle was called.
- After roughing is completed:
  - Infeed to the next machining depth defined by MIDF.
  - Final machining along the contour with feedrate FFP2 and speed SSF.
  - The machining direction is defined by CDIR.
- When machining is completed the tool is traversed to the pocket center point in the retraction plane and the cycle is terminated.



### Description of parameters



See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters RTP, RFP, SDIS.

See Section 3.7 for a description of parameters DP, DPR.



See Section 3.5 (SLOT1) for a description of parameters FFD, FFP1, MID, CDIR, FAL, VARI, MIDF, FFP2, SSF.

See Section 3.2 for cycle setting data `_ZSD[1]`.


#### PRAD (pocket radius)

The shape of the circular pocket is determined by the radius only.

If the radius is less than the tool radius of the active tool, the cycle is aborted after alarm 61105 "Milling cutter radius too large" is output.

#### CPA, CPO (pocket center point)

With parameters CPA and CPO you define the center point of the circular pocket in the abscissa and ordinate.



### Further notes

A tool offset must be activated before the cycle is called. Otherwise the cycle is aborted and alarm 61000 "No tool offset active" is output.

The depth infeed is always made in the pocket center point. It can be useful to drill there beforehand.

A new workpiece coordinate system that influences the actual value display is used in the cycle. The zero point of this coordinate system lies on the pocket center point.


The original coordinate system becomes active again after the end of the cycle.



### Programming example

#### Circular pocket

With this program you can machine a circular pocket in the YZ plane. The center point is defined by Y50 Z50. The infeed axis for the depth infeed is the X axis, the pocket depth is entered as an absolute value. Neither a final machining allowance nor a safety distance is defined.



```
DEF REAL RTP=3, RFP=0, DP=-20, ->
```

```
-> PRAD=25, FFD=100, FFP1, MID=6
```

```
N10 FFP1=FFD*2
```

```
N20 G19 G90 G0 S650 M3
```

```
N25 T10 D1
```

```
N27 M6
```

```
N30 Y50 Z50
```

```
N40 POCKET2 (RTP, RFP, , DP, , PRAD, ->
```

```
-> 50, 50, FFD, FFP1, MID, 3, )
```

```
N50 M30
```

Definition of variables with value assignment

Specification of technology values

Approach starting position

Cycle call

Parameters FAL, VARI, MIDF, FFP2, SSF are omitted

End of program

-> Must be programmed in a single block

### 3.9 Milling rectangular pockets – POCKET3



The POCKET3 cycle is available in SW 4 and higher.



#### Programming

POCKET3 (\_RTP, \_RFP, \_SDIS, \_DP, \_LENG, \_WID, \_CRAD, \_PA, \_PO, \_STA, \_MID, \_FAL, \_FALD, \_FFP1, \_FFD, \_CDIR, \_VARI, \_MIDA, \_AP1, \_AP2, \_AD, \_RAD1, \_DP1)



#### Parameters

The following input parameters are always required:

_RTP	real	Retraction plane (absolute)
_RFP	real	Reference plane (absolute)
_SDIS	real	Safety distance (to be added to the reference plane, enter without sign)
_DP	real	Pocket depth (absolute)
_LENG	real	Pocket length for dimensioning from the corner with sign
_WID	real	Pocket width for dimensioning from the corner with sign
_CRAD	real	Pocket corner radius (enter without sign)
_PA	real	Pocket reference point, abscissa (absolute)
_PO	real	Pocket reference point, ordinate (absolute)
_STA	real	Angle between the pocket longitudinal axis and the first axis of the plane (abscissa, enter without sign); Value range: $0^\circ \leq \_STA < 180^\circ$
_MID	real	Maximum infeed depth (enter without sign)
_FAL	real	Final machining allowance on pocket edge (enter without sign)
_FALD	real	Final allowance at base (enter without sign)
_FFP1	real	Feedrate for surface machining
_FFD	real	Feedrate for depth infeed
_CDIR	int	Milling direction: (enter without sign) Value: 0...Down-cut milling (as spindle rotation) 1...Up-cut milling 2...with G2 (independent of spindle direction) 3...with G3
_VARI	int	Type of machining: (enter without sign) UNITS DIGIT: Value: 1...Roughing 2...Finishing

### 3.9 Milling rectangular pockets – POCKET3

#### TENS DIGIT:

Value: 0...Perpendicular to pocket center with G0

1...Perpendicular to pocket center with G1

2...Along a helix

3...Oscillating along the pocket longitudinal axis

The other parameters can be selected as options. They define the insertion strategy and overlapping for solid machining: (enter without sign)

<code>_MIDA</code>	real	Maximum infeed width during solid machining in the plane
<code>_AP1</code>	real	Basic size pocket length
<code>_AP2</code>	real	Basic size pocket width
<code>_AD</code>	real	Basic pocket depth from reference plane
<code>_RAD1</code>	real	Radius of the helical path on insertion (relative to the tool center point path) or maximum insertion angle for oscillating motion
<code>_DP1</code>	real	Insertion depth per 360° revolution on insertion along helical path




#### Function

The cycle can be applied to roughing and finishing. For finishing, a face cutter is needed.

The depth infeed will always start at the pocket center point and be performed vertically from there; thus predrill can be suitably performed in this position.

#### New functions compared to POCKET1:

- The milling direction can be defined with a G instruction (G2/G3) or up-cut milling or down-cut from the spindle direction
- For solid machining, the maximum infeed width in the plane is programmable
- Final machining allowance for the pocket base
- Three different insertion strategies:
  - Vertically at the pocket center point
  - Along a helical path around the pocket center
  - Oscillating around the pocket central axis
- Shorter approach paths in the plane for finishing
- Consideration of a blank contour in the plane and a basic size at the base (optimum processing of pre-formed pockets possible).





### Sequence of operations

#### Position reached prior to cycle start:

This can be any position from which the starting position on the center point of the pocket at the retraction plane level can be approached without collision.

#### Motion sequence when roughing (VARI=X1):

With G0, the pocket center point is approached at the retraction plane level and then, from this position, with G0 the reference plane brought forward by the safety distance is approached. Pocket machining is then performed according to the selected insertion strategy and considering the programmed base size.

#### Insertion strategies:

- **Vertical insertion to pocket center (VARI=0X, VARI=1X)** means that the current infeed depth internally calculated in the cycle ( $\leq$  programmed maximum infeed depth through `_MID`) is executed in one block with G0 or G1.


- **Insertion along helical path (VARI=2X)** means that the milling center point travels on the helical path determined by radius `_RAD1` and depth per revolution `_DP1`. The feedrate is always programmed through `_FFD`. The sense of rotation of this helical path corresponds to the direction to be used for machining the pocket.

The depth programmed under `_DP1` on insertion is calculated as the maximum depth and is always calculated as a whole number of revolutions of the helical path.

When the current depth for the infeed (these may be several revolutions on the helical path) has been calculated, a full circle is made to remove the slope on insertion.

Then pocket solid machining starts in this plane and continues until reaching the final machining allowance.

The starting point of the helical path described is on the pocket longitudinal axis in the "plus direction" and reached with G1.



### 3.9 Milling rectangular pockets – POCKET3

- **Oscillating insertion on center axis of pocket (VARI=3X)**

means that the mill center point oscillates along an oblique linear path until it has reached the next current depth. The maximum insertion angle is programmed under `_RAD1`, the position of the oscillation path is calculated within the cycle. When the current depth has been reached, the path is traversed again without depth infeed in order to remove the slope caused by insertion. The feedrate is programmed through `_FFD`.


#### Accounting for blank dimensions

During solid machining, it is possible to take blank dimensions (for example, in the machining of precast workpieces) into account.

The basic size for the length (`_AP1` and `_AP2`) are programmed without sign and their symmetrical positions around the pocket center computed in the cycle. They define the part of the pocket that does not have to be solid machined. The basic size for the depth (`_AD`) is also programmed without a sign and computed in the direction of the pocket depth from the reference plane.

Depth infeed to account for workpiece sizes is carried out according to the programmed type (helical path, oscillating, vertical). If the cycle recognizes that by means of the blank contour and the radius of the active tool there is enough room in the pocket center, infeed takes place as long as possible vertically downwards to the pocket center in order to avoid time-consuming approach paths in the open.

The pocket is solid machined beginning from the top and proceeding in the downward direction.





**Motion sequence when finishing (VARI=X2)**

Finishing is performed in sequence from the edge until reaching the final machining allowance on the base, then the base is finished. If one of the final machining allowances is equal to zero, this part of the finishing process is skipped.

- Finishing on the edge

While finishing on the edge, the pocket is only machined once.

For finishing on the edge the path includes one quadrant reaching the corner radius. The radius of this path is normally 2mm or, if "less room" is available, equals the difference between the corner radius and the mill radius.

If the final machining allowance on the edge is larger than 2 mm, the approach radius is increased accordingly.

The depth infeed is performed with G0 in the open towards the pocket center and the starting point of the approach path is also reached with G0.

- Finishing on the base

During finishing on the base, the machine performs G0 towards the pocket center until reaching a distance equal to pocket depth + final machining allowance + safety distance. From this point onwards, the tool is always fed in **vertically** at the depth infeed feedrate (since a tool with a front cutting edge is used for base finishing).

The base surface of the pocket is machined once.



### Description of parameters



See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters `_RTP`, `_RFP`, `_SDIS`

See Section 3.7 for a description of parameter `_DP`.

See Section 3.2 for cycle setting data `_ZSD[1]`, `_ZSD[2]`.

#### `_LENG`, `_WID` and `_CRAD` (pocket length, pocket width and corner radius)

The shape of a pocket in the plane is determined with parameters `_LENG`, `_WID` and `_CRAD`.

The pocket can be dimensioned from the center or from one corner point. When dimensioning from a corner point, use `_LENG` and `_WID` with sign.

If it is not possible to traverse to the programmed corner radius with the active tool because its radius is larger, the corner radius of the completed pocket corresponds to the tool radius.

If the milling cutter radius is greater than half the length or width of the pocket, the cycle is aborted and alarm

61105 "Cutter radius too large" is output.

#### `_PA`, `_PO` (reference point)

The center point of the pocket in the abscissa and ordinate is defined with parameters `_PA` and `_PO`.



This is either the pocket center point or a corner point. The value of this parameter depends on cycle setting data bit `_ZSD[2]`:

- 0 means pocket center point
- 1 means corner point

When dimensioning the pocket from a corner, the length and width parameters must be entered with sign (`_LENG`, `_WID`), thus completely defining the position of the pocket.

#### `_STA` (angle)

`_STA` indicates the angle between the 1st axis of the plane (abscissa) and the longitudinal axis of the pocket.



**\_MID (infeed depth)**

With this parameter you determine the maximum infeed depth when roughing.

The depth infeed is performed by the cycle in equally sized infeed steps.

The cycle automatically calculates this infeed using `_MID` and the total depth. The minimum possible number of infeed steps is used as the basis.

`_MID=0` means that the cut to pocket depth is made with one infeed.

**\_FAL (final machining allowance at the edge)**

The final machining allowance only affects machining of the pocket in the plane at the edge.

When the final machining allowance  $\geq$  tool diameter, the pocket will not necessarily be machined completely. The message

"Caution: Final machining allowance  $\geq$  tool diameter" is output but the cycle is continued.

**\_FALD (final machining allowance on the base)**

For roughing, a separate final machining allowance is considered on the base (POCKET1 does not normally consider any final machining allowance).

**\_FFD and \_FFP1 (infeed depth and plane)**

Feedrate `_FFD` is used for insertion into the material. Feedrate `FFP1` is used for all movements in the plane traversed at feedrate when machining.

**\_CDIR (milling direction)**

The value for the machining direction of the pocket is defined in this parameter.

Under parameter `_CDIR` the mill direction

- direct "2 for G2" and "3 for G3" or
- alternatively "up-cut milling" or "down-cut milling" can be programmed. Up-cut milling or down-cut milling is determined within the cycle via the spindle direction activated prior to the cycle call.

<b>Up-cut milling</b>	<b>Down-cut milling</b>
M3 → G3	M3 → G2
M4 → G2	M4 → G3

**\_VARI (machining mode)**

You can define the type of machining with parameter `_VARI`.

Possible values are:

**Units digit:**

- 1=Roughing
- 2=Finishing

**Tens digit (infeed):**

- 0=Perpendicular to the pocket center with G0
- 1=Perpendicular to the pocket center with G1
- 2=Along a helical path
- 3=Oscillating along the pocket longitudinal axis

If another value has been programmed for parameter `_VARI`, the cycle is aborted after alarm 61002 "Machining type incorrectly defined" is output.

**\_MIDA (max. infeed width)**

With this parameter you define the maximum infeed width for solid machining in the plane. In the same way as the known calculation of the infeed depth (equal distribution of the overall depth using the largest possible value), the width is evenly divided, using the value programmed in `_MIDA` as a maximum value.

If this parameter is not programmed, or if its value is 0, the cycle uses 80 percent of the mill diameter as maximum infeed width.

**Further notes**

Applies if the width infeed determined from edge machining is recalculated on reaching the full pocket depth; otherwise, the width infeed calculated at the start is retained for the full cycle.

**\_AP1, \_AP2, \_AD (blank dimension)**

With the parameters `_AP1`, `_AP2` and `_AD` you define the blank dimension (incremental) of the pocket in the horizontal and vertical planes.

**\_RAD1 (radius)**

With the parameter `_RAD1` you define the radius of the helical path (i.e. the tool center point path) or the maximum insertion angle for oscillation.

**\_DP1 (insertion depth)**

With the parameter `_DP1` you define the infeed depth for insertion on the helical path.

**Further notes**

A tool offset must be activated before the cycle is called. Otherwise the cycle is aborted and alarm 61000 "No tool offset active" is output.

A new workpiece coordinate system that influences the actual value display is used in the cycle. The zero point of this coordinate system lies on the pocket center point.

The original coordinate system becomes active again after the end of the cycle.




### Programming example

#### Pocket

With this program you can machine a pocket that is 60mm long, 40mm wide, 17.5mm deep in the XY plane, and which has a corner radius of 8mm. The angle in relation to the X axis is 0 degrees. The final machining allowance of the pocket edges is 0.75mm, 0.2mm at the base, the safety distance in the Z axis, which is added to the reference plane, is 0.5mm. The center point of the pocket lies at X60 and Y40, the maximum depth infeed is 4mm.

Up-cut milling uses the spindle rotation direction as direction of machining.

Only roughing is to be performed.



```
N10 G90 S600 M4
```

Specification of technology values

```
N15 T10 D1
```

```
N17 M6
```

```
N20 G17 G0 X60 Y40 Z5
```

Approach starting position

```
N25 _ZSD[2]=0
```

Dimensioning the pocket via the center point

```
N30 POCKET3 (5, 0, 0.5, -17.5, 60, ->
-> 40, 8, 60, 40, 0, 4, 0.75, 0.2, ->
-> 1000, 750, 0, 11, 5)
```

Cycle call

```
N40 M30
```

End of program

-> Must be programmed in a single block

### 3.10 Milling circular pockets – POCKET4



The cycle POCKET4 is available with SW 4.



#### Programming

POCKET4 (\_RTP, \_RFP, \_SDIS, \_DP, \_PRAD, \_PA, \_PO, \_MID, \_FAL, \_FALD, \_FFP1, \_FFD, \_CDIR, \_VARI, \_MIDA, \_AP1, \_AD, \_RAD1, \_DP1)



#### Parameters

The following input parameters are always required:

_RTP	real	Retraction plane (absolute)
_RFP	real	Reference plane (absolute)
_SDIS	real	Safety distance (to be added to the reference plane, enter without sign)
_DP	real	Pocket depth (absolute)
_PRAD	real	Pocket radius
_PA	real	Pocket center point, abscissa (absolute)
_PO	real	Pocket center point, ordinate (absolute)
_MID	real	Maximum infeed depth (enter without sign)
_FAL	real	Final machining allowance on pocket edge (enter without sign)
_FALD	real	Final allowance at base (enter without sign)
_FFP1	real	Feedrate for surface machining
_FFD	real	Feedrate for depth infeed
_CDIR	int	Milling direction: (enter without sign) Value: 0...Down-cut milling (as spindle rotation) 1...Up-cut milling 2...with G2 (independent of spindle direction) 3...with G3
_VARI	int	Type of machining: (enter without sign) UNITS DIGIT: Value: 1...Roughing 2...Finishing TENS DIGIT: Value: 0...Perpendicular to the pocket center with G0 1...Perpendicular to the pocket center with G1 2...Along a helix

### 3.10 Milling circular pockets – POCKET4

The other parameters can be selected as options. They define the insertion strategy and overlapping for solid machining: (enter without sign)

_MIDA	real	Maximum infeed width during solid machining in the plane
_AP1	real	Basic size pocket radius
_AD	real	Basic pocket depth from reference plane
_RAD1	real	Radius of the helical path during insertion related to the tool center point path)
_DP1	real	Insertion depth per 360° revolution on insertion along helical path



#### Function


With this cycle you can machine circular pockets in the machining plane.

For finishing, a face cutter is needed.

The depth infeed will always start at the pocket center point and be performed vertically from there; thus predrill can be suitably performed in this position.

#### New functions compared to POCKET2:

- The milling direction can be defined with a G instruction (G2/G3) or up-cut milling or down-cut from the spindle direction
- For solid machining, the maximum infeed width in the plane is programmable
- Final machining allowance for the pocket base
- Two different insertion strategies:
  - Vertically from the pocket center point
  - Along a helical path around the pocket center
- Shorter approach paths in the plane for finishing
- Consideration of a blank contour in the plane and a basic size at the base (optimum processing of pre-formed pockets possible)
- \_MIDA is recalculated when machining the edge.







### Sequence of operations

#### Position reached prior to cycle start:

This can be any position from which the starting position on the center point of the pocket at the retraction plane level can be approached without collision.

#### Motion sequence when roughing (VARI=X1):

With G0, the pocket center point is approached at the retraction plane level and then, from this position, with G0 the reference plane brought forward by the safety distance is approached. Pocket machining is then performed according to the selected insertion strategy and considering the programmed base size.



#### Insertion strategies:

see Section 3.9 (POCKET3)


#### Accounting for blank dimensions

During solid machining, it is possible to take blank dimensions (for example, in the machining of precast workpieces) into account.

For circular pockets, the basic size `_AP1` at the edge is also circular (with a smaller radius than the pocket radius).



For additional explanations see Section 3.9 (POCKET3)



### 3.10 Milling circular pockets – POCKET4

#### Motion sequence when finishing (VARI=X2):

Finishing is performed in sequence from the edge until reaching the final machining allowance on the base, then the base is finished. If one of the final machining allowances is equal to zero, this part of the finishing process is skipped.

- Finishing on the edge  
While finishing on the edge, the pocket is only machined once.  
For finishing on the edge the path includes one fourth of circle which reaches the pocket radius. The radius of this path is less or equal to 2mm or, if "less room" is available, equals the difference between the pocket radius and the mill radius.  
The depth infeed is performed with G0 in the open towards the pocket center and the starting point of the approach path is also reached with G0.
- Finishing on the base  
During finishing on the base, the machine performs G0 towards the pocket center until reaching a distance equal to pocket depth + final machining allowance + safety distance. From this point onwards, the tool is always fed in **vertically** at the depth infeed feedrate (since a tool with a front cutting edge is used for base finishing).  
The base surface of the pocket is machined once.



#### Description of parameters

See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters `_RTP`, `_RFP`, `_SDIS`


See Section 3.7 (POCKET1) for a description of parameter `_DP`.

See Section 3.9 (POCKET3) for a description of parameters `_MID`, `_FAL`, `_FALD`, `_FFP1`, `_FFD`, `_CDIR`, `_MIDA`, `_AP1`, `_AD`, `_RAD1`, `_DP1`.

See Section 3.2 for cycle setting data `_ZSD[1]`.

#### `_PRAD` (pocket radius)

The shape of the circular pocket is determined by the radius only.



If the radius is less than the tool radius of the active tool, the cycle is aborted after alarm 61105 "Milling cutter radius too large" is output.

#### **\_PA, \_PO (pocket center point)**

With parameters \_PA and \_PO you define the center point of the pocket. Circular pockets are always measured from the center.

#### **\_VARI (machining mode)**

You can define the type of machining with parameter \_VARI.

Possible values are:

##### **Units digit:**

- 1=Roughing
- 2=Finishing

##### **Tens digit (infeed):**

- 0=Perpendicular to the pocket center with G0
- 1=Perpendicular to the pocket center with G1
- 2=Along a helical path

If another value has been programmed for parameter \_VARI, the cycle is aborted after alarm 61002 "Machining type incorrectly defined" is output.

#### **Rough cutting only edge with POCKET4 (SW 5.3 and higher)**

POCKET4 (circular pocket) can now machine only the edge when rough-cutting.

Define the rough dimension in the depth (parameter \_AD) so that it is at least the same size as the pocket depth (DP) minus the final machining allowance depth (\_FALD).

Example:

Condition: depth calculation without including safety distance (\_ZSD[1]=1)

_RTP=0	reference plane
_SDIS=2	safety distance
_DP=-21	pocket depth
_FALD=1.25	depth allowance
→ _AD≥19.75	rough dimension for depth must be greater or equal to pocket depth incremental minus depth allowance, i.e. 21-1.25=19.75

### Further notes

A tool offset must be activated before the cycle is called. Otherwise the cycle is aborted and alarm 61000 "No tool offset active" is output.


A new workpiece coordinate system that influences the actual value display is used in the cycle. The zero point of this coordinate system lies on the pocket center point.

The original coordinate system becomes active again after the end of the cycle.

### Programming example

#### Circular pocket

With this program you can machine a circular pocket in the YZ plane. The center point is defined by Y50 Z50. The infeed axis for the depth infeed is the X axis. Neither a final machining allowance nor a safety distance is defined. The pocket will be machined using down-cut milling. Infeed occurs along a helical path.



```
N10 G19 G90 G0 S650 M3
```

Specification of technology values

```
N15 T20 D1
```

```
N17 M6
```

```
N20 Y50 Z50
```

Approach starting position

```
N30 Pocket4(3, 0, 0, -20, 25, 50, ->
50, 6, 0, 0, 200, 100, 1, 21, 0, -> 0,
0, 2, 3)
```

Cycle call

```
N40 M30
```

End of program

-> Must be programmed in a single block

### 3.11 Face milling – CYCLE71



The cycle CYCLE71 is available in SW 4 and higher.



#### Programming

CYCLE71 (\_RTP, \_RFP, \_SDIS, \_DP, \_PA, \_PO, \_LENG, \_WID, \_STA, \_MID, \_MIDA, \_FDP, \_FALD, \_FFP1, \_VARI, \_FDP1)



#### Parameters

The following input parameters are always required:


_RTP	real	Retraction plane (absolute)
_RFP	real	Reference plane (absolute)
_SDIS	real	Safety distance (to be added to the reference plane, enter without sign)
_DP	real	Depth (absolute)
_PA	real	Starting point, abscissa (absolute)
_PO	real	Starting point, ordinate (absolute)
_LENG	real	Rectangle length along the 1st axis, incremental. The corner from which dimensions are measured is given by the plus/minus sign.
_WID	real	Rectangle length along the 2nd axis, incremental. The corner from which dimensions are measured is given by the plus/minus sign.
_STA	real	Angle between the longitudinal axis of the rectangle and the first axis of the plane (abscissa, enter without sign); Value range: $0^\circ \leq \_STA < 180^\circ$
_MID	real	Maximum infeed depth (enter without sign)
_MIDA	real	Maximum infeed width value for solid machining in the plane (enter without sign)
_FDP	real	Retraction travel in cutting direction (incremental, enter without sign)
_FALD	real	Final machining allowance in depth (incremental, enter without sign) In the roughing mode, _FALD refers to the remaining material on the surface.
_FFP1	real	Feedrate for surface machining
_VARI	int	Type of machining: (enter without sign) UNITS DIGIT: Value: 1...Roughing 2...Finishing TENS DIGIT: Value: 1...Parallel to the abscissa, in one direction 2...Parallel to the ordinate, in one direction 3...Parallel to the abscissa, with changing direction 4...Parallel to the ordinate, with changing direction
_FDP1	real	Overrun travel in direction of plane infeed (incr., enter without sign)

### 3.11 Face milling – CYCLE71



#### Function

With cycle CYCLE71, you can face mill any rectangular surface. The cycle differentiates between roughing (machining the surface in several steps until reaching the final machining allowance) and finishing (end milling the surface in one step). Maximum infeed can be defined in width and depth. The cycle operates without cutter radius compensation. The depth infeed is programmed in the open.



#### Sequence of operations

##### Position reached prior to cycle start:

This can be any position from which the starting position on the infeed point at the retraction plane level can be reached without collision.

##### The cycle implements the following motion sequence:


- G0 is applied to approach the infeed point on the current position plane. The reference plane, shifted forward by the safety distance, is then also approached with G0 from this position. Then, also with G0, infeed to machining plane. G0 is possible, since infeed occurs in the open. There are several roughing strategies (paraxial in one direction or back and forth).
- Motion sequence when roughing (VARI=X1): Roughing is possible on several planes according to the programmed values `_DP`, `_MID` and `_FALD`. Machining will be performed in the downward direction, i.e. by removing stock on one plane at a time, and then executing the next depth infeed in open space (parameter `_FDP`). The traversing paths for stock removal on the plane are determined by the settings in parameters `_LENG`, `_WID`, `_MIDA`, `_FDP`, `_FDP1` and the cutter radius of the active tool.

The first path to be milled is always selected so that the infeed width is exactly  $\_MIDA$ , and thus no width exceeds the maximum possible value. The tool center point thus does not always travel exactly to the edge (only if  $\_MIDA$  = mill radius). The dimension by which the tool traverses outside the edge always equals

cutter diameter -  $\_MIDA$ ,

even when only 1 surface cut is performed, i.e. surface width + overrun less than  $\_MIDA$ . The other paths for width infeed are calculated internally so as to produce a uniform path width ( $\leq \_MIDA$ ).

- Motion sequence when finishing (VARI=X2):  
When finishing, the surface is once milled in the plane. The final machining allowance for roughing must also be selected so that the remaining depth can be machined in one pass with the finishing tool.  
After each surface milling pass in the plane, the tool retracts completely. The retraction travel is programmed by the parameter  $\_FDP$ .
- Machining in one direction stops at the final machining allowance + safety distance and the next starting point is reached at rapid traverse.  
Roughing in one direction stops when reaching the calculated infeed depth + safety distance. The infeed depth is performed towards the same point as for roughing.  
After finishing has been completed, the tool retracts from the last position reached to the retraction plane  $\_RTP$ .



### 3.11 Face milling – CYCLE71



#### Description of parameters

See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters `_RTP`, `_RFP`, `_SDIS`

See Section 3.9 (POCKET3) for a description of parameters `_STA`, `_MID`, `_FFP1`.

See Section 3.2 for cycle setting data `_ZSD[1]`.

#### `_DP` (depth)

The depth can be defined as an absolute value (`_DP`) in relation to the reference plane.

#### `_PA`, `_PO` (starting point)

With parameters `_PA` and `_PO` you define the starting point of the surface in the abscissa and ordinate.

#### `_LENG`, `_WID` (length)

With parameters `_LENG` and `_WID` you determine the length and width of the rectangle in the plane. The sign determines the position of the rectangle relative to `_PA` and `_PO`.


#### `_MIDA` (max. infeed width)

With this parameter, you define the maximum infeed width for solid machining in the plane. In the same way as the known calculation of the infeed depth (equal distribution of the overall depth using the largest possible value), the width is evenly divided, using the value programmed in `_MIDA` as a maximum value.

If this parameter is not programmed, or if its value is 0, the cycle uses 80 percent of the mill diameter as maximum infeed width.

#### `_FDP` (retraction travel)

This parameter defines the dimension for retraction travel in the plane. This parameter must be programmed with a value greater than zero.





**\_FDP1 (overrun travel)**

By means of this parameter an overrun travel in the direction of the plane infeed may be defined (`_MIDA`) allowing the deviation between the current cutter radius and the cutting edge (e.g. tool nose radius or inclined cutting tips) to be compensated. The last cutter center point path therefore always corresponds to `_LENG` (or `_WID`) + `_FDP1` tool radius (from correction table).

**\_FALD (final machining allowance)**

During roughing, the depth final machining allowance used is defined by this parameter. The residual material designated as the final machining allowance must always be specified for finish cutting so as to ensure that the tool can be lifted and inserted at the starting point of the next cut without risk of collision.

**\_VARI (machining mode)**

You can define the type of machining with parameter `_VARI`.

Possible values are:


**Units digit:**

- 1=Roughing to final machining allowance
- 2=Finishing.

**Tens digit:**

- 1=Parallel to the abscissa, in one direction
- 2=Parallel to the ordinate, in one direction
- 3=Parallel to the abscissa, with changing direction
- 4=Parallel to the ordinate, with changing direction.

If another value has been programmed for parameter `_VARI`, the cycle is aborted after alarm 61002 "Machining type incorrectly defined" is output.

**Further notes**

A tool offset must be activated before the cycle is called. Otherwise the cycle is aborted and alarm 61000 "No tool offset active" is output.

### 3.11 Face milling – CYCLE71



#### Programming example

##### Face milling

##### Parameters for cycle call:

- Retraction plane: 10mm
- Reference plane: 0mm
- Safety distance: 2mm
- Milling depth: -11mm
- Max. infeed depth 6mm
- No final machining allowance -
- Starting point of the rectangle X = 100mm  
Y = 100mm
- Rectangle dimensions X = +60mm  
Y = +40mm
- Angle of rotation in the plane 10 degrees
- Max. infeed width 10mm
- Retraction travel at the end of the milling path: 5mm
- Feedrate for surface machining 4000 mm/min
- Type of machining: roughing parallel to the X axis  
with changing direction
- Overrun on last cut as determined  
by the cutting edge geometry 2mm

```

%_N_TSTCYC71_MPF                                Program for face milling with CYCLE71
; $PATH=/_N_MPF_DIR
; *
$TC_DP1[1,1]=120                                Tool type
$TC_DP6[1,1]=10                                Tool radius
N100 T1
N102 M06
N110 G17 G0 G90 G54 G94 F2000 X0 Y0            Approach starting position
Z20
;
CYCLE71( 10, 0, 2,-11, 100, 100, ->          Cycle call
-> 60, 40, 10, 6, 10, 5, 0, 4000, 31, 2)
N125 G0 G90 X0 Y0
N130 M30                                        End of program
-> Must be programmed in a single block

```

### 3.12 Path milling – CYCLE72



The cycle CYCLE72 is available with SW 4 (not for FM-NC).



#### Programming

CYCLE72 (\_KNAME, \_RTP, \_RFP, \_SDIS, \_DP, \_MID, \_FAL, \_FALD, \_FFP1, \_FFD, \_VARI, \_RL, \_AS1, \_LP1, \_FF3, \_AS2, \_LP2)



#### Parameters

The following input parameters are always required:

_KNAME	string	Name of the contour subroutine
_RTP	real	Retraction plane (absolute)
_RFP	real	Reference plane (absolute)
_SDIS	real	Safety distance (to be added to the reference plane, enter without sign)
_DP	real	Depth (absolute)
_MID	real	Maximum infeed depth (incremental, enter without sign)
_FAL	real	Final machining allowance at the edge contour (enter without sign)
_FALD	real	Final machining allowance at the base (incremental, enter without sign)
_FFP1	real	Feedrate for surface machining
_FFD	real	Feedrate for depth infeed (enter without sign)
_VARI	int	Type of machining: (enter without sign) UNITS DIGIT: Value: 1...Roughing 2...Finishing TENS DIGIT: Value: 0...Intermediate paths with G0 1...Intermediate paths with G1 HUNDREDS DIGIT: Value: 0...Return at end of contour to _RTP 1...Return at end of contour to _RFP + _SDIS 2...Return at end of contour to _SDIS 3...No return to end of contour
_RL	int	Contouring is centric, on right or left (with G40, G41 or G42, enter without sign) Value: 40...G40 (approach and return, straight line only) 41...G41 42...G42

## 3.12 Path milling – CYCLE72

<code>_AS1</code>	int	Specification of approach direction/path: (enter without sign) UNITS DIGIT: Value: 1...Straight tangential line 2...Quadrant 3...Semicircle TENS DIGIT: Value: 0...Approach to the contour in the plane 1...Approach to the contour along a spatial path
<code>_LP1</code>	real	Length of the approach travel (along a straight line) or radius of the mill center path of the arc of approach (along a circle) (enter without sign)
The other parameter can be preset optionally (enter without sign).		
<code>_FF3</code>	real	Return feedrate and feedrate for intermediate positioning in the plane (when retracting)
<code>_AS2</code>	int	Specification of return direction/path: (enter without sign) UNITS DIGIT: Value: 1...Straight tangential line 2...Quadrant 3...Semicircle TENS DIGIT: Value: 0...Return to the contour in the plane 1...Return to the contour along a spatial path
<code>_LP2</code>	real	Length of the return travel (along a straight line) or radius of the return arc (along a circle) (enter without sign)



### Function

With the cycle CYCLE72 it is possible to mill along any contour defined in a subroutine. The cycle operates with or without cutter radius compensation. The contour does not need to be closed; internal or external machining is defined by the position of the cutter radius compensation (center, on left or right of contour).

**The contour must be programmed in the direction of milling and must be in the same plane.** In addition, it must consist of at least 2 contour blocks (start and end points) since the contour subroutine is invoked within the cycle.

#### Cycle functions:

- Selection of roughing (single-pass parallel to the contour considering a final machining allowance if necessary at several depths until reaching the final machining allowance) and finishing (single-pass of final contour, if necessary at several depths)
- Flexible approach and retraction to/from the contour either tangentially or radially (quadrant or semicircle)
- Programmable depth infeed
- Intermediate motions either with rapid traverse or at feedrate.




The requirement for executing a cycle is an NC SW 4.3. or higher that includes the function "Soft approach and return".



### Sequence of operations

#### Position reached prior to cycle start:

The starting position can be any position from which the start of the contour at the retraction plane level can be reached without collision.



### 3.12 Path milling – CYCLE72

#### The cycle creates the following motion sequence when roughing (VARI=XX1):

The depth infeeds are divided evenly using the highest possible value according to the preset parameter.

- Travel to starting point for initial cut with G0/G1 (and \_FF3). This point is calculated internally in the control and depends on
  - the contour starting point (first point in subroutine),
  - the direction of the contour at the starting point,
  - the approach mode and corresponding parameters and
  - the tool radius.

The cutter radius path compensation is activated in this block.

- Depth infeed to first or next machining depth plus programmed safety distance DISCL with G0/G1. The first processing depth is given by
  - the overall depth,
  - the final machining allowance and
  - the maximum possible depth infeed.
- Approach the contour perpendicular to the feed depth and approach in the plane then at the feedrate programmed for surface machining, or programmed under \_FAD for 3D machining corresponding to the programming for soft approach.
- Milling along the contour with G40/G41/G42.
- Soft retraction from the contour with G1 and still with the feedrate for surface machining by lift DISCL.
- Retraction with G0 /G1 (and feedrate for intermediate travel \_FF3) depending on program.
- Return to depth infeed point with G0/G1 (and \_FF3).
- This operating sequence is repeated on the next machining plane, until reaching the final machining allowance in depth.

When roughing is over, the tool lies on the contour starting point (calculated within the control unit) at the retraction plane level.

**The cycle creates the following motion sequence when finishing (VARI=XX2):**

During finishing, milling is performed at the relevant infeed along the base of the contour until the final dimension is reached.

Approaching and retraction to/from the contour is performed in a flexible way according to the corresponding preset parameters. The corresponding path is calculated within the control unit.

At the end of the cycle, the tool is positioned at the contour retraction point at the retraction plane level.

**Contour programming**

For programming the contour, please note the following:

- In the subroutine no programmable frame (TRANS, ROT, SCALE, MIRROR) may be selected before the first programmed position.
- The first block of the contour subroutine is a straight line block containing G90, G0 and defines the contour start.
- The cutter radius compensation is selected and deselected from the upper level cycle; then the contour subroutine has no G40, G41, G42 programmed.



### Description of parameters



See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters `_RTP`, `_RFP`, `_SDIS`



See Section 3.9 for a description of parameters `_MID`, `_FAL`, `_FALD`, `_FFP1`, `_FFD` and Section 3.11 for parameter `_DP`.

See Section 3.2 for cycle setting data `_ZSD[1]`.

#### `_KNAME` (name)

The contour to be milled is completely programmed in a subroutine. With parameter `_KNAME` you can define the name of the contour subroutine.

In SW 5.2 and higher, the milling contour can also be a section of the calling routine or from any other program. The section is identified by start or end labels or by block numbers. In this case, the program name and labels/block number are identified by an ":".

Examples:

`_KNAME="CONTOUR_1"`

The milling contour is the complete program "Contour\_1".

`_KNAME="START:END"`

The milling contour is defined as the section starting from the block labeled START to the block labeled END in the calling routine.


`_KNAME=`

`"/_N_SPF_DIR/_N_CONTOUR_1_SPF:N130:N210"`

The milling contour is defined in blocks N130 to N210 in program CONTOUR\_1. The program name must be entered complete with path and extension, see description of call in References: /PGA/ Programming Guide Advanced.



If the section is defined by block numbers, it must be noted that these block numbers for the section in `_KNAME` must be adjusted if the program is modified and subsequently renumbered.





**\_VARI (machining mode)**

You can define the type of machining with parameter `_VARI`. For possible values, see "Parameter CYCLE72".

**If another value has been programmed for parameter `_VARI`, the cycle is aborted after alarm 61002 "Machining type incorrectly defined" is output.**

**\_RL (travel around the contour)**

Parameter `_RL` is set to define how the tool must travel around the contour, i.e. along the center path or on the left or right-hand side with G40, G41 or G42. See "Parameter CYCLE72" for possible settings.

**\_AS1, \_AS2 (direction of approach/approach travel, direction of retraction/retraction travel)**

With the parameter `_AS1` you can specify the approach travel and with `_AS2` the retraction travel. For possible values, see "Parameter CYCLE72". If `_AS2` is not programmed, then the behavior programmed for the approach path will apply to the return path. The flexible approach of the contour along a 3-D path (helix or straight line) should be programmed only if the tool is suitable and not yet engaged.



With center path travel (G40), tool must approach and return along a straight line.


**\_LP1, \_LP2 (length, radius)**

Parameter `_LP1` is set to program the approach path or approach radius (distance between tool outer edge and contour starting point) and `_LP2` to program the return path or return radius (distance between tool outer edge and end point of contour).

Parameters `_LP1`, `_LP2` must be set to >0. A setting of zero generates error message 61116 "Approach or retract path=0."



When G40 is programmed, the approach or retract path corresponds to the distance between the tool center point and the starting or end point of the contour.



## 3.12 Path milling – CYCLE72

### **\_FF3 (retraction feedrate)**

Parameter `_FF3` is used to define a retraction feedrate for intermediate positioning in the plane (in the open) when intermediate motions are to be performed with feed (G01). If no feedrate is programmed, the intermediate motions are carried out with surface feed for G01.



### **Further notes**

A tool offset must be activated before the cycle is called. Otherwise the cycle is aborted and alarm 61000 "No tool offset active" is output.



### Programming example 1

#### Milling a closed contour externally


This program is used to mill a contour as shown in the figure.

#### Parameters for cycle call:

- Retraction plane 250mm
- Reference plane 200
- Safety distance 3mm
- Depth 175mm
- Maximum depth infeed 10
- Final machining allowance in depth 1.5mm
- Feedrate depth infeed 400 mm/min
- Final machining allowance in the plane 1mm
- Feedrate in the plane 800 mm/min
- Machining: Roughing up to the finishing allowance, intermediate travel with G1, during the intermediate motions, return along Z to `_RFP + _SDIS`

#### Parameters for the approach:

- G41 – to the left of the contour, i.e. external machining
- Approach and return on quadrant in plane 20mm radius
- Retraction feedrate 1000 mm/min



<code>%_N_RANDKONTUR1_MPF</code>	Program for re-milling a contour with CYCLE72
<code>;\$PATH=/_N_MPF_DIR</code>	
<code>N10 T20 D1</code>	T20: milling cutter with radius 7
<code>N15 M6</code>	Changing tool T20
<code>N20 S500 M3 F3000</code>	Program feedrate and spindle speed
<code>N25 G17 G0 G90 X100 Y200 Z250 G94</code>	Approach starting position
<code>N30 CYCLE72 ( "MYKONTUR", 250, 200, -&gt;</code> <code>-&gt; 3, 175, 10,1, 1.5, 800, 400, 111, -&gt;</code> <code>-&gt; 41, 2, 20, 1000, 2, 20)</code>	Cycle call
<code>N90 X100 Y200</code>	
<code>N95 M02</code>	End of program

-> Must be programmed in a single block

**3.12 Path milling – CYCLE72**

<code>%_N_MYKONTUR_SPF</code>	Subroutine for contour milling (for example)
<code>;\$PATH=/_N_SPF_DIR</code>	
<code>N100 G1 G90 X150 Y160</code>	Start point of contour
<code>N110 X230 CHF=10</code>	
<code>N120 Y80 CHF=10</code>	
<code>N130 X125</code>	
<code>N140 Y135</code>	
<code>N150 G2 X150 Y160 CR=25</code>	
<code>N160 M17</code>	

**Programming example 2 (SW 5.2 and higher)**

Milling round the outside of a closed contour as described in sample program 1, with the contour defined in the calling program

<code>\$TC_DP1[20,1]=120 \$TC_DP6[20,1]=7</code>	
<code>N10 T20 D1</code>	T20: milling cutter with radius 7
<code>N15 M6</code>	Changing tool T20
<code>N20 S500 M3 F3000</code>	Program feedrate and spindle speed
<code>N25 G17 G0 G90 G94 X100 Y200 Z250 -&gt;</code>	Approach starting position, cycle call
<code>CYCLE72 ( "START:END", 250, 200, -&gt;</code>	
<code>-&gt; 3, 175, 10,1, 1.5, 800, 400, 11, -&gt;</code>	
<code>-&gt; 41, 2, 20, 1000, 2, 20)</code>	
<code>N30 G0 X100 Y200</code>	
<code>N35 GOTOF END</code>	
<code>START:</code>	
<code>N100 G1 G90 X150 Y160</code>	
<code>N110 X230 CHF=10</code>	
<code>N120 Y80 CHF=10</code>	
<code>N130 X125</code>	
<code>N140 Y135</code>	
<code>N150 G2 X150 Y160 CR=25</code>	
<code>END:</code>	
<code>N160 M02</code>	

### 3.13 Milling rectangular spigots – CYCLE76 (SW 5.3 and higher)



#### Programming

CYCLE76 (\_RTP, \_RFP, \_SDIS, \_DP, \_DPR, \_LENG, \_WID, \_CRAD, \_PA, \_PO, \_STA, \_MID, \_FAL, \_FALD, \_FFP1, \_FFD, \_CDIR, \_VARI, \_AP1, \_AP2)



#### Parameters

The following input parameters are always required:


_RTP	real	Retraction plane (absolute)
_RFP	real	Reference plane (absolute)
_SDIS	real	Safety distance (to be added to the reference plane, enter without sign)
_DP	real	Depth (absolute)
_DPR	real	Depth relative to the reference plane (enter without sign)
_LENG	real	Spigot length, for dimensioning from corner with sign
_WID	real	Spigot width, for dimensioning from corner with sign
_CRAD	real	Spigot corner radius (enter without sign)
_PA	real	Spigot reference point, abscissa (absolute)
_PO	real	Spigot reference point, ordinate (absolute)
_STA	real	Angle between longitudinal axis and 1st axis of plane
_MID	real	Maximum depth infeed (incremental, enter without sign)
_FAL	real	Final machining allowance on edge contour (incremental)
_FALD	real	Final machining allowance at the base (incremental, enter without sign)
_FFP1	real	Feedrate on contour
_FFD	real	Feedrate for depth infeed
_CDIR	int	Milling direction: (enter without sign) Value: 0...Upcut milling 1...Downcut milling 2 with G2 (irrespective of spindle direction) 3...with G3
_VARI	int	Type of machining: Value: 1...Roughing to final machining allowance 2...Finishing (allowance X/Y/Z=0)
_AP1	real	Length of blank spigot
_AP2	real	Width of blank spigot

### 3.13 Milling rectangular spigots – CYCLE76 (SW 5.3 and higher)



#### Function

With this cycle you can machine rectangular spigots in the machining plane. For finishing, a face cutter is needed. Depth infeed is always performed in the position reached prior to semicircular positioning on the contour.



#### Sequence of operations

##### Position reached prior to cycle start:

The starting point is a position in the positive range of the abscissa with integrated approach semicircle and allowance for programmed, abscissa-related blank dimension.

##### Sequence of motions for roughing ( $\_VARI=1$ )

###### Approach to and exit from contour:


The retraction plane ( $\_RTP$ ) is approached in rapid traverse so that the tool can be positioned from there on the starting point in the machining plane. The starting point is defined as being 0 degrees in relation to the abscissa.

The tool is fed in at rapid traverse to the safety distance ( $\_SDIS$ ) and then traverses to machining depth at normal feedrate. The tool approaches the spigot contour along a semicircular path.

The milling direction can be defined as up-cut or down-cut milling in relation to the spindle direction.

If the spigot has been circumnavigated once, the tool lifts off the contour in the plane along a semicircular path and is then fed in to the next machining depth.

The contour is then approached again along a semicircle and the spigot circumnavigated once. This process is repeated until the programmed spigot depth is reached. The tool then approaches the retraction plane ( $\_RTP$ ) in rapid traverse.



**Depth infeed:**

- Infeed to safety distance
- Insertion to machining depth

The first machining depth is the product of:

- the total depth,
- the final machining allowance and
- the maximum possible depth infeed.

**Sequence of motions for finishing (VARI=X2)**

Depending on the setting of parameters `_FAL` and `_FALD`, a finishing operation is performed on the spigot surface or base or both. The approach strategy matches the motions in the plane executed for roughing operations.

**Description of parameters**

See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters `RTP`, `RFP`, `SDIS`, `DP`, `DPR`.

See Section 3.9 for a description of parameters `_MID`, `_FAL`, `_FALD`, `_FFP1`, `_FFD`.

See Section 3.2 for cycle setting data `_ZSD[2]`.

**`_LENG`, `_WID` and `_CRAD` (spigot length, spigot width and corner radius)**

The shape of a spigot in the plane is determined with parameters `_LENG`, `_WID` and `_CRAD`.

The spigot can be dimensioned from the center or from one corner point. When dimensioning from a corner point, use `_LENG` and `_WID` with sign.

The absolute length value (`_LENG`) always refers to the abscissa (with a plane angle of zero degrees).



**`_PA`, `_PO` (reference point)**

Parameters `_PA` and `_PO` are set to define the reference point of the spigot in abscissa and ordinate.

This is either the spigot center point or a corner point. The value of this parameter depends on cycle setting data bit `_ZSD[2]`:

- 0 means spigot center point
- 1 means corner point.

When the spigot is dimensioned from a corner, the length and width parameters must be entered with sign (`_LENG`, `_WID`) so that a unique position for the spigot is defined.



### 3.13 Milling rectangular spigots – CYCLE76 (SW 5.3 and higher)

#### **\_STA (angle)**

\_STA specifies the angle between the 1st axis of the plane (abscissa) and the longitudinal axis of the spigot.

#### **\_CDIR (milling direction)**

The machining direction of the spigot is defined in this parameter.

Under parameter \_CDIR the mill direction

- direct "2 for G2" and "3 for G3" or
- alternatively "up-cut milling" or "down-cut milling" can be programmed. Up-cut milling or down-cut milling is determined within the cycle via the spindle direction activated prior to the cycle call.

#### **Up-cut**

M3 → G3

M4 → G2

#### **Down-cut**

M3 → G2

M4 → G3

#### **\_VARI (machining mode)**

You can define the type of machining with parameter \_VARI.


Possible values are:

- 1=Roughing
- 2=Finishing.

#### **\_AP1, \_AP2 (blank dimensions)**

Blank dimensions (e.g. in the case of precast workpieces) can be taken into account in machining of the spigot.

The basic size for the length and width (\_AP1 and \_AP2) are programmed without sign and their symmetrical positions around the spigot center computed in the cycle. The internally calculated radius of the approach semicircle is dependent on this dimension.







### Further notes

A tool offset must be activated before the cycle is called. The cycle is otherwise aborted with alarm 61009 "Active tool number=0".

A new workpiece coordinate system that influences the actual value display is used in the cycle. The zero point of this coordinate system lies on the pocket center point.


The original coordinate system becomes active again after the end of the cycle.



### Programming example

#### Spigots

This program allows you to machine a spigot that is 60mm long, 40mm wide, 15mm deep in the XY plane and with a corner radius of 15mm. The spigot has an angle of 10 degrees in relation to the X axis and is programmed from a corner point P1. When a spigot is dimensioned with reference to corners, the length and width must be entered with a sign to define a unique position for the spigot. The spigot is premachined with an allowance of 80mm in its length and 50mm in its width.




---

N10 G90 G0 G17 X100 Y100 T20 D1 S3000 M3 Specification of technology values

---

N11 M6

---

N20 \_ZSD[2]=1

---

Dimensioning of spigot referred to corners

---

N30 CYCLE76 (10, 0, 2, -17.5, , -60, ->  
-> -40, 15, 80, 60, 10, 11, , , 900, ->  
-> 800, 0, 1, 80, 50)

---

Cycle call

---

N40 M30

---

End of program

---

-> Must be programmed in a single block

### 3.14 Milling circular spigots – CYCLE77 (SW 5.3 and higher)

#### 3.14 Milling circular spigots – CYCLE77 (SW 5.3 and higher)



##### Programming

CYCLE77 (\_RTP, \_RFP, \_SDIS, \_DP, \_DPR, \_PRAD, \_PA, \_PO, \_MID, \_FAL, \_FALD, \_FFP1, \_FFD, \_CDIR, \_VARI, \_AP1)



##### Parameters


The following input parameters are always required:

_RTP	real	Retraction plane (absolute)
_RFP	real	Reference plane (absolute)
_SDIS	real	Safety distance (to be added to the reference plane, enter without sign)
_DP	real	Depth (absolute)
_DPR	real	Depth relative to the reference plane (enter without sign)
_PRAD	real	Diameter of spigot (enter without sign)
_PA	real	Spigot center point, abscissa (absolute)
_PO	real	Spigot center point, ordinate (absolute)
_MID	real	Maximum depth infeed (incremental, enter without sign)
_FAL	real	Final machining allowance on edge contour (incremental)
_FALD	real	Final machining allowance at the base (incremental, enter without sign)
_FFP1	real	Feedrate on contour
_FFD	real	Feedrate for depth infeed (or spatial infeed)
_CDIR	int	Milling direction: (enter without sign) Value: 0...Upcut milling 1...Downcut milling 2 with G2 (irrespective of spindle direction) 3...with G3
_VARI	int	Type of machining Value: 1...Roughing to final machining allowance 2...Finishing (allowance X/Y/Z=0)
_AP1	real	Diameter of blank spigot



### Function

With this cycle you can machine circular spigots in the machining plane. For finishing, a face cutter is needed. Depth infeed is always performed in the position reached prior to semicircular positioning on the contour.



### Sequence of operations

#### Position reached prior to cycle start:

The starting point is a position in the positive range of the abscissa with integrated approach semicircle and allowance for programmed blank dimension.

#### Sequence of motions for roughing ( $\_VARI=1$ )

##### *Approach to and exit from contour:*

The retraction plane ( $\_RTP$ ) is approached in rapid traverse so that the tool can be positioned from there on the starting point in the machining plane. The starting point is defined as being 0 degrees in relation to the abscissa axis.


The tool is fed in at rapid traverse to the safety distance ( $\_SDIS$ ) and then traverses to machining depth at normal feedrate. The spigot contour is approached along a semicircular path, making allowance for the programmed blank spigot.

The milling direction can be defined as up-cut or down-cut milling in relation to the spindle direction.

If the spigot has been circumnavigated once, the tool lifts off the contour in the plane along a semicircular path and is then fed in to the next machining depth.

The contour is then approached again along a semicircle and the spigot circumnavigated once. This process is repeated until the programmed spigot depth is reached.

The tool then approaches the retraction plane ( $\_RTP$ ) in rapid traverse.



### 3.14 Milling circular spigots – CYCLE77 (SW 5.3 and higher)

#### *Depth infeed:*

- Infeed to safety distance
- Insertion to machining depth.

The first machining depth is the product of:

- the total depth,
- the final machining allowance and
- the maximum possible depth infeed.

#### **Sequence of motions for finishing (\_VARI=2)**

Depending on the setting of parameters `_FAL` and `_FALD`, a finishing operation is performed on the spigot surface or base or both. The approach strategy matches the motions in the plane executed for roughing operations.



#### **Description of parameters**

See Subsection 2.1.2. (Drilling, Centering – CYCLE81) for a description of parameters `RTP`, `RFP`, `SDIS`, `DP`, `DPR`.

See Section 3.9 for a description of parameters `_MID`, `_FAL`, `_FALD`, `_FFP1`, `_FFD`.

#### **\_PRAD (diameter of spigot)**

The diameter must be entered without a sign.

#### **\_PA, \_PO (spigot center point)**

With parameters `_PA` and `_PO` you define the reference point of the spigot.

Circular spigots are always measured from the center.

#### **\_CDIR (milling direction)**

The machining direction of the spigot is defined in this parameter.

Under parameter `_CDIR` the mill direction

- direct "2 for G2" and "3 for G3" or
- alternatively "up-cut milling" or "down-cut milling" can be programmed. Up-cut milling or down-cut milling is determined within the cycle via the spindle direction activated prior to the cycle call.

<b>Up-cut</b>	<b>Down-cut</b>
M3 → G3	M3 → G2
M4 → G2	M4 → G3

#### **\_VARI (machining mode)**

You can define the type of machining with parameter `_VARI`.

Possible values are:

- 1=Roughing
- 2=Finishing.

### 3.14 Milling circular spigots – CYCLE77 (SW 5.3 and higher)

#### \_AP1 (diameter of blank spigot)

This parameter defines the blank dimension of the spigot (without sign). The internally calculated radius of the approach semicircle is dependent on this dimension.

#### Further notes

A tool offset must be activated before the cycle is called. The cycle is otherwise aborted with alarm 61009 "Active tool number=0".


A new workpiece coordinate system that influences the actual value display is used in the cycle. The zero point of this coordinate system lies on the pocket center point.

The original coordinate system becomes active again after the end of the cycle.

#### Programming example

##### Circular spigot

Machine a spigot from a blank with a diameter of 55mm and a maximum infeed of 10mm per cut. Enter a final machining allowance for finishing the spigot surface. The entire spigot is machined in a down-cut milling operation.



```
N10 G90 G17 G0 S1800 M3 D1 T1
```

Specification of technology values

```
N11 M6
```

```
N20 CYCLE77 (10, 0, 3, -20, ,50, 60, ->
-> 70, 10, 0.5, 0, 900, 800, 1, 1, 55)
```

Roughing cycle call

```
N30 D1 T2 M6
```

Tool change

```
N40 S2400 M3
```

Specification of technology values

```
N50 CYCLE77 (10, 0, 3, -20, , 50, 60, ->
-> 70, 10, 0, 0, 800, 800, 1, 2, 55)
```

Finishing cycle call

```
N40 M30
```

End of program

-> Must be programmed in a single block

### 3.15 Pocket milling with islands – CYCLE73, CYCLE74, CYCLE75 (SW 5.2 and higher)



Pocket milling with islands is an option and requires SW 5.2 in both the NCK and MMC 103.

#### Precondition

To use the pocket milling cycle with islands, you need specific machine data settings.



**References:** for current infos see:

- the file "siemensd.txt" from the delivery software (standard cycles) or
- for HMI Advanced, F:\dh\cst.dir\HLP.dir\siemensd.txt.



#### Function

Cycles CYCLE73, CYCLE74 and CYCLE75 enable you to machine pockets with islands.

The contours of the pocket and islands are defined in DIN code in the same program as the pocket machining operation or as a subroutine.

Cycles CYCLE74 and CYCLE75 transfer the pocket edge contour or island contours to CYCLE73, the actual pocket milling cycle.

CYCLE73 uses a geometry processor to create a machining program which it then executes. To ensure correct program processing, it is important to program cycle calls in the proper sequence.

- CYCLE74( ) ;Transfer edge contour
- CYCLE75( ) ;Transfer island contour 1
- CYCLE75( ) ;Transfer island contour 2
- ...
- CYCLE73( ) ;Machine pocket

### 3.15.1 Transfer pocket edge contour – CYCLE74



Pocket milling with islands is an option and requires SW 5.2 in both the NCK and MMC 103.



#### Programming

CYCLE74 (\_KNAME, \_LSANF, \_LSEND)



#### Parameters

<code>_KNAME</code>	string	Name of contour subroutine of pocket edge contour
<code>_LSANF</code>	string	Block number/label identifying start of contour definition
<code>_LSEND</code>	string	Block number/label identifying end of contour definition



#### Function

Cycle CYCLE74 transfers the pocket edge contour to pocket milling cycle CYCLE73. This is done by creating a temporary internal file in the standard cycles directory and storing the transferred parameter values in it.

If a file of this type already exists, it is deleted and set up again.

For this reason, a program sequence for milling pockets with islands must always begin with a call for CYCLE74.



### Explanation of parameters

The edge contour can be programmed either in a separate program or in the main program that calls the routine. The contour is transferred to the cycle by parameter `_KNAME`, name of program or `_LSANF`, `_LSEND` and the program section from ... to identified by block numbers or labels.

So there are three options for contour programming:

- **Contour is defined in a separate program,**  
in which case only `_KNAME` needs to be programmed;  
e.g. CYCLE74 ("EDGE", "", "")
- **Contour is defined in the calling program,**  
in which case only `_LSANF` and `_LSEND` need to be programmed;  
e.g. CYCLE74 ("", "N10", "N160")
- **The edge contour is part of a program but not part of the program that calls the cycle,**  
in which case all three parameters need to be programmed.  
e.g. CYCLE74("EDGE", "MARKER\_START", "MARKER\_END")

The program name is describable by its path name and program type.

Example:

```
_KNAME="/N_WKS_DIR/_N_EXAMPLE3_WPD/_N_EDGE_MPF"
```



### 3.15.2 Transfer island contour – CYCLE75



Pocket milling with islands is an option and requires SW 5.2 in both the NCK and MMC 103.



#### Programming

CYCLE75 (\_KNAME, \_LSANF, \_LSEND)



#### Parameters

<code>_KNAME</code>	string	Name of contour subroutine of island contour
<code>_LSANF</code>	string	Block number/label identifying start of contour definition
<code>_LSEND</code>	string	Block number/label identifying end of contour definition



#### Function

Cycle CYCLE75 transfers island contours to the pocket milling cycle CYCLE73. The cycle is called once for each island contour. It need not be called if no island contours are programmed.

The transferred parameter values are written to the temporary file opened by CYCLE74.



#### Description of parameters

The number and meaning of parameters are the same as for CYCLE74.



(see CYCLE74)

### 3.15.3 Contour programming



Pocket edge and island contours must always be closed, i.e. the start and end points are identical.

The start point, i.e. first point on a contour must always be programmed with G0, and all other contour elements via G1 to G3.

When the contour is programmed, the last contour element (block with label or block number at end of contour) must not contain a radius or chamfer.

The tool may not stand at a starting position of the programmed contour element before CYCLE73 is invoked.

The necessary programs must always be stored in one directory (workpiece or parts program). It is permissible to use the subroutine memory for pocket edge or island contours.

Workpiece-related geometric dimensional data may be programmed in either metric or inches. Switching between these units of measurement within individual contour programs will cause errors in the machining program.

When G90/G91 are programmed alternately in contour programs, care must be taken to program the correct dimensional command at the start of the program in the sequence of contour programs to be executed.

When the pocket machining program is calculated, only the geometries in the plane are taken into account.

If other axes or functions (T., D., S., M., etc.) are programmed in contour sections, they are skipped when the contour is prepared internally in the cycle.

All machine-specific program commands (e.g. tool call, speed, M command) must be programmed before the cycle commences. Feedrates must be set as parameters in CYCLE73.

The tool radius must be greater than zero.

It is not possible to repeat island contours by offsets implemented by suitable control commands (e.g. zero offset, frames, etc.).

Every island to be repeated must always be programmed again with the offsets calculated into the coordinates.




### Programming example

Sample program 1.mpf (pocket with islands)

```

%_N_SAMPLE1_MPF
; $PATH=/_N_MPF_DIR
; Example_1: Pocket with islands
;
$TC_DP1[5,1]=120 $TC_DP6[5,1]=6 $TC_DP3[5,1]=111 ;Tool offset mill T5 D1
$TC_DP1[2,2]=120 $TC_DP6[2,2]=5 $TC_DP3[2,2]=130
N100 G17 G40 G90 ;Initial conditions G code
N110 T5 D1 ;Load milling tool
N120 M6
N130 S500 M3 F2000 M8
GOTOF _MACHINE
;
N510 _EDGE:G0 G64 X25 Y30 F2000 ;Define edge contour
N520 G1 X118 RND=5
N530 Y96 RND=5
N540 X40 RND=5
N545 X20 Y75 RND=5
N550 Y35
N560 _ENDEEDGE:G3 X25 Y30 CR=5
;
N570 _ISLAND1:G0 X34 Y58 ;Define bottom island
N580 G1 X64
N590 _ENDISLAND1:G2 X34 Y58 CR=15
;
N600 _ISLAND2:G0 X79 Y73 ;Define top island
N610 G1 X99
N620 _ENDISLAND2:G3 X79 Y73 CR=10
;
_MACHINE:
;Programming contours
SAMPLE_CONT:
CYCLE74 ("SAMPLE1", "_EDGE", "_ENDEEDGE") ;Transfer edge contour
CYCLE75 ("SAMPLE1", "_ISLAND1", "_ENDISLAND1") ;Transfer island contour 1
CYCLE75 ("SAMPLE1", "_ISLAND2", "_ENDISLAND2") ;Transfer island contour 2
ENDLABEL:
M30

```



### 3.15.4 Pocket milling with islands – CYCLE73



Pocket milling with islands is an option and requires SW 5.2 in both the NCK and MMC 103.



#### Programming

CYCLE73 (\_VARI, \_BNAME, \_PNAME, \_TN, \_RTP, \_RFP, \_SDIS, \_DP, \_DPR, \_MID, \_MIDA, \_FAL, \_FALD, \_FFP1, \_FFD, \_CDIR, \_PA, \_PO, \_RAD, \_DP1)



#### Parameters

_VARI	int	Type of machining: (enter without sign) UNITS POSITION (select machining): Value: 1...Rough cut (remove stock) from solid material 2...Rough cut residual material 3...Finish edge 4...Finish base 5...Rough drill TENS DIGIT (select insertion strategy): Value: 1...Perpendicular with G1 2...Along a helix 3...Oscillate HUNDREDS DIGIT (select liftoff mode): Values: 0...to retraction plane (_RTP) 1...by safety distance (_SDIS) via reference plane (_RFP) THOUSANDS DIGIT (select start point): Values: 1...Automatic 2...Manual
_BNAME	string	Name for program of drill positions
_PNAME	string	Name for pocket milling machining program
_TN	string	Name of stock removal tool
_RTP	real	Retraction plane (absolute)
_RFP	real	Reference plane (absolute)
_SDIS	real	Safety distance (to be added to the reference plane, enter without sign)
_DP	real	Pocket depth (absolute)
_DPR	real	Pocket depth (incremental)
_MID	real	Maximum infeed depth for infeed (enter without sign)
_MIDA	real	Maximum infeed depth in the plane (enter without sign)
_FAL	real	Final machining allowance in the plane (enter without sign)
_FALD	real	Final machining allowance on base (enter without sign)

<code>_FFP1</code>	real	Feedrate for surface machining
<code>_FFD</code>	real	Feedrate for depth infeed
<code>_CDIR</code>	int	Milling direction for machining the pocket: (enter without sign) Value: 0...Down-cut milling (as spindle rotation) 1...Downcut milling 2...with G2 (irrespective of spindle direction) 3...with G3
<code>_PA</code>	real	Start point in first axis (only with manual selection of start point)
<code>_PO</code>	real	Start point in second axis (only with manual selection of start point)
<code>_RAD</code>	real	Radius center-point path on insertion along helical path or max. insertion angle for oscillating insertion motion
<code>_DP1</code>	real	Insertion depth per 360° revolution on insertion along helical path



### Function

Cycle CYCLE73 enables you to machine pockets with or without islands. It supports complete machining of this type of pocket and offers the following machining operations:


- Rough drill
- Solid machine pocket
- Machine residual material
- Finish edge
- Finish base.

Pocket and island contours are freely programmed in DIN code supported, for example, by the geometry processor.

The cycle is executed once for each operation according to the programmed machining type (`_VARI`). In other words, in applications requiring roughing and finishing, or an additional rough-cut residual material operation, CYCLE73 must be called a second time.

#### Solid machine pocket

When a pocket is solid machined, it is machined with the active tool down to the programmed finishing dimensions. The insertion strategy for milling can be selected. The cutting operation is segmented in the pocket depth direction (tool axis) in accordance with the specified values.



**Machine residual material**

The cycle allows material to be removed with a smaller milling tool. The traversing motions defined by the residual material of the last milling operation and the current tool radius are output in the generated program. The residual material technology can be programmed repeatedly with a succession of decreasing tool radii. No check is made on completion of the cycle for any further residual material in the pocket.

**Edge/base finishing**

Another function of the cycle is to finish the pocket base or circumnavigate the pocket and individual islands in a finish operation.

**Rough drill**

Depending on the milling tool used, it may be necessary to drill before solid machining the workpiece. The cycle automatically calculates the rough drilling positions as a function of the solid machining operation to be performed afterwards. The drilling cycle called modally beforehand is executed at each of these positions. Rough drilling can be executed in a number of technological machining operations (e.g. 1. centering, 2. drilling).



### Rough drilling sequence

In the first machining section of the rough drilling operation, a REPEAT command must be used after a modal call for the drilling cycle to call a sequence of machining steps with the contents of CYCLE73 and the contour repetition. The drilling cycle must be deselected modally before the next tool change. Other drilling technologies can be programmed subsequently.

The next program section contains CYCLE73 which contains all necessary parameters as well as the programs for solid machining and drilling.

Parameter \_VARI is the only one to define all solid machining parameters and it must always be programmed for this reason.

The cycle now generates the solid machining and drilling position programs for the pocket. It then calls the drilling position program and executes it.

If the operation involves several different pockets, it will be necessary to call the associated contours again in this section. This block can be omitted if there is only one pocket.

This entire machining section must be marked by a skip command to the following "Solid machine pocket" section.

#### Example

Rough drill, with solid machining

ACCEPTANCE4_CONT:		;Marker with name for beginning of pocket
		;contour
CYCLE74("EDGEA01", , )		;Definition of contour for pocket edge
CYCLE75("ISL11A01", , )		;Definition of contour for 1st island
CYCLE75("ISL1A01", , )		
CYCLE75("ISL2A01", , )		
CYCLE75("ISL3A01", , )		
ENDLABEL:		;Marker for end of a pocket contour
T4 M6		
D1 M3 F1000 S4000		
MCALL CYCLE81(10,0,1,-3)		;Modal call of drilling cycle
REPEAT ACCEPTANCE4_MACH		;Execute drilling position program
ACCEPTANCE4_MACH_END		
MCALL		;Deselect drilling cycle modally

### 3.15 Pocket milling with islands – CYCLE73, CYCLE74, CYCLE75

GOTOF ACCEPTANCE4_MACH_END	;Branch to Solid machine pocket
ACCEPTANCE4_MACH:	;Start of section Generate programs
;REPEAT ACCEPTANCE4_CONT ENDLABEL	;Required only if there is more than one pocket ;contour
CYCLE73(1015,"ACCEPTANCE4_DRILL","ACCEPTANCE4_M ILL1","3",10,0,1,-12,0,,2,0.5,,9000,400,0,,,) )	
ACCEPTANCE4_MACH_END:	;End of section Generate programs
T3 M6	
D1 M3 S2000	
;REPEAT ACCEPTANCE4_CONT ENDLABEL	;Required only if there is more than one pocket ;contour
CYCLE73(1011,"ACCEPTANCE4_DRILL","ACCEPTANCE4_M; ILL1","3",10,0,1,-12,0,,2,0.5,,9000,400,0,,,) )	Solid machine pocket



#### Sequence for roughing, solid machining (\_VARI=XXX1)

All parameters must be written to the CYCLE73 command again.

The program performs the following machining steps:

- Approach a manually calculated or automatically generated start point located on the return plane. G0 is then used to traverse the axis to a reference plane brought forward by the safety distance.
- Infeed to the current machining depth according to the selected insertion strategy (\_VARI) with feed value \_FFD.
- Mill pocket with islands down to final machining allowance with feed \_FFP1. The machining direction corresponds to the setting in \_CDIR. The pocket can be split if the ratio between mill diameter and clearance between islands or between islands and edge contours is not ideal. For this purpose, the cycle calculates additional start points for mill insertion.
- Lift off in accordance with selected retraction mode and return to start point for next plane infeed.



- When the pocket has been machined, the tool is retracted either to the return plane or by the safety distance via the reference plane, depending on the selected liftoff mode. The tool position in the plane is above the pocket surface as determined by the generated program.



### Sequence of motions for finishing

#### (`_VARI=XXX3`)

- The pocket and island contours are circumnavigated once each during the edge finishing operation. Vertical insertion with G1 (`_VARI`) must be programmed as the insertion strategy. Approach and retraction at the start and edge points respectively of the finishing operation are each executed along a tangential circle segment.
- To finish the base, the tool is inserted to pocket depth + final machining allowance + safety distance with G0. From this position the tool is fed in vertically at the feedrate for depth infeed. The base surface of the pocket is machined once.
- Liftoff and retraction as the same as for solid machining.
- Parameters `_FAL`, `_FALD` and `_VARI=XXX4` must be assigned for simultaneous finishing in the plane and on the base.



### Description of parameters

#### **\_VARI (machining mode)**

You can define the type of machining with parameter \_VARI. Possible values are:

#### **Units digit:**

- 1=Rough cut (solid machine) from solid material
- 2=Rough cut residual material
- 3=Finish edge
- 4=Finish base
- 5=Rough drill.

When "Rough cut from solid material" is set, the machining program solid machines the pocket completely down to the final machining allowance.

If it is not possible to machine areas of the edge surfaces with the selected mill diameter, then setting "2" can be selected to machine them afterwards with a smaller milling tool. To do this, cycle CYCLE73 must be called again.

#### **Tens digit:**

- 1=Vertical with G1
- 2=Along a helical path
- 3=Oscillation.

#### **Selection of insertion strategies:**

- **Insert vertically (\_VARI=XX1X)**  
means that the current infeed depth calculated internally is executed in one block.
- **Insert along helical path (\_VARI=XX2X)**  
means that the mill center point traverses along the helical path determined by radius \_RAD and depth per revolution \_DP1. The feedrate is always programmed through \_FFD. The sense of rotation of this helical path corresponds to the direction to be used for machining the pocket. The depth programmed under \_DP1 on insertion is calculated as the maximum depth and is always calculated as a whole number of revolutions of the helical path.

When the current depth for the infeed (these may be several revolutions on the helical path) has been calculated, a full circle is made to remove the slope on insertion.

Then pocket solid machining starts in this plane and continues until reaching the final machining allowance.

- **Insertion with oscillation (\_VARI=XX3X)** means that the mill center point oscillates along an oblique linear path until it has reached the next current depth. The maximum insertion angle is programmed under \_RAD, the position of the oscillation path is calculated within the cycle. When the current depth has been reached, the path is traversed again without depth infeed in order to remove the slope caused by insertion. The feedrate is programmed through \_FFD.

#### Hundreds digit: (\_VARI=X1XX)

- 0=To retraction plane (\_RTP)
- 1=By safety distance (\_SDIS) via reference plane (\_RFP).

#### Thousands digit: (\_VARI=1XXX)

- 1=Start point automatic
- 2=Start point manual.


When the starting point is selected automatically, the cycle internally calculates the starting point for machining itself.

**Notice:** Manually specified start positions must not be too close to the island surface. Manually specified start positions are not monitored internally.

If the pocket has to be split as a result of the island position and the mill diameter used, then several start points are calculated automatically.

With manual start point selection, parameters \_PA and \_PO must also be programmed. However, these can only define one start point.

If the pocket has to be split, the required start points are calculated automatically.



**\_BNAME (name for drilling position program)****\_PNAME (name for pocket milling program)**

The pocket milling cycle generates programs with traversing blocks required to rough drill or mill the workpiece. These programs are stored in the same directory as the calling program in the parts program memory, i.e. in the "parts programs" directory (MPF.DIR) if the cycle is called from there or in the corresponding workpiece directory. The programs are always main programs (type MPF).

The names of these programs are defined by parameters `_BNAME` and `_PNAME`.

A drilling program name is needed only when `_VARI=XXX5`.

Example: No drilling program name:  
`CYCLE73(1011,"",ACCEPTANCE4_MILL,...)`

**\_TN (name of solid machining tool)**

This parameter must be set to the solid machining tool. Depending on whether the tool management function is active or not, the parameter must be set to a tool name or tool number.

Example:

- with tool management  
`CYCLE73(1015,"PART1_DRILL","PART1_MILL",  
"MILL3",...)`
- without tool management  
`CYCLE73(1015,"PART1_DRILL","PART1_MILL","3",...)`

Parameter `_TN` is defined as a compulsory parameter with a maximum length of 16 characters. It must therefore be assigned to the cutting tool in every subsequent `CYCLE73` call. When the residual material machining operation is used more than once, the tool from the last residual material removal process must be used.

**TOOL AND OFFSET:**

It must be ensured that the tool offset is processed exclusively by D1. Replacement tool strategies may not be used.

**\_RFP and \_RTP (reference plane and retraction plane)**

The reference plane (RFP) and retraction plane are generally set to different values. In the cycle it is assumed that the retraction plane lies in front of the reference plane. The distance between the retraction plane and the final drilling depth is therefore greater than the distance between the reference plane and the final drilling depth.

**\_SDIS (safety distance)**

The safety distance (SDIS) is effective with regard to the reference plane which is brought forward by the safety distance. The direction in which the safety distance is active is automatically determined by the cycle.

**\_DP (absolute pocket depth) and  
\_DPR (incremental pocket depth)**

The pocket depth can be specified as either an absolute value (\_DP) or relative value (\_DPR) in relation to the reference plane. If the incremental option is selected, the cycle automatically calculates the depth on the basis of the reference and retraction plane positions.

**\_MID (maximum infeed depth)**

The maximum infeed depth is defined with this parameter. The depth infeed is performed by the cycle in equally sized infeed steps.

The cycle calculates this infeed automatically on the basis of \_MID and the total depth.

The minimum possible number of infeed steps is used as the basis. \_MID=0 means that the cut to pocket depth is made with one infeed.

**\_MIDA (max. infeed depth in the plane)**

With this parameter you define the maximum infeed width for solid machining in the plane. This value is never exceeded.

If this parameter is not programmed, or if its value is 0, the cycle uses 80 percent of the mill radius as the maximum infeed width.

If an infeed width of more than 80 percent of the mill diameter is programmed, the cycle is aborted after output of alarm 61982 "Infeed width in plane too large".

### 3.15 Pocket milling with islands – CYCLE73, CYCLE74, CYCLE75

#### **\_FAL (final machining allowance in the plane)**

The final machining allowance only affects machining of the pocket in the plane at the edge. When the final machining allowance  $\geq$  tool diameter, the pocket will not necessarily be machined completely.

#### **\_FALD (final machining allowance on the base)**

A separate final machining allowance on the base is taken into account in roughing operations.

#### **\_FFD and \_FFP1 (feedrate for depth infeed and surface machining)**

Feedrate `_FFD` is used for insertion into the material. Feedrate `FFP1` is used for all movements in the plane traversed at feedrate when machining.

#### **\_CDIR (milling direction)**

The value for the machining direction of the pocket is defined in this parameter.


Under parameter `_CDIR` the mill direction

- direct "2 for G2" and "3 for G3" or
- alternatively "up-cut milling" or "down-cut milling" can be programmed. Up-cut milling or down-cut milling is determined within the cycle via the spindle direction activated prior to the cycle call.

<b>Up-cut milling</b>	<b>Down-cut milling</b>
M3 → G3	M3 → G2
M4 → G2	M4 → G3

#### **\_PA, \_PO (start point for first and second axes)**

When the start point is selected manually, the start point must be programmed in these parameters such that it can be approached without risk of collision. It must be noted that only one start point can be programmed (see description of parameter `_VARI`).



**\_RAD (center-point path or insertion angle)**

Parameter `_RAD` defines the radius of the helical path (referred to tool center point path) or the maximum insertion angle for oscillation.

**\_DP1 (insertion depth for helical path)**

With the parameter `_DP1` you define the infeed depth for insertion on the helical path.

**Further notes****Name for pocket machining (NAME)**

Pockets are generally machined in several technological machining steps. However, the contours defining the pocket geometries are defined only once. To ensure that contours can be automatically assigned to the appropriate machining step in the program, the contour definition is marked with labels and this program section then repeated later with the REPEAT instruction.

When programs are written using the cycles support function, a name for the pocket machining program is therefore entered in the respective screen forms. The name length is restricted to 8 characters.

In sample program 2, this is, for example "ACCEPTANCE4".

The T number contains the milling tool for all machining technologies. When residual material is machined more than once, the tool used beforehand must always be entered in the T number.

**Explanation of the cycle structure**

Cycle CYCLE73 is used to solve very complex problems associated with solid machining of pockets with islands which require a high level of computing capacity in the control. For optimum timing, the calculation is carried out in the MMC.

The calculation is started from the cycle. Its result contains programs with traversing blocks for drilling or milling operations which are stored in the file system of the control. These are then called by the cycle and executed.

This structure means that it is only necessary to perform the calculation the first time a program is executed with CYCLE73 call. From the second program run onwards, the generated traversing program is available for immediate call by the cycle.

Recalculation is performed when:

- A finished contour has been modified;
- A transfer parameter of the cycle has changed;
- A tool with different tool offset data has been activated prior to the cycle call;
- In the case of different technologies, such as solid machining and residual material, with machining programs generated in different ways.

#### **Program storage in the file system**

If the contours for CYCLE73 are programmed outside the program that makes the call, the following applies for the search in the file system of the control:

- If the calling program is stored in a workpiece directory, then the programs containing the edge or island contours must be stored in the same workpiece directory;
- If the invoked program is located in the "Parts Program" directory (MPF.DIR), a search is also made for the programs there.

The programs generated by the cycle are also stored in the same directory as the program containing the cycle call, i.e. in the same workpiece directory or in MPF.DIR or SPF.DIR.

#### **Note on simulation**

In the pocket milling simulation, the generated programs are saved to the NCU file system. Therefore, only the "NC Active Data" setting is practical since tool offset data flow into the program calculation.






### Programming example 1

The machining task involves machining a pocket with two islands from solid material and then finishing the pocket in plane X, Y

Sample program 1.mpf (pocket with islands)

```
%_N_SAMPLE1_MPF
;$PATH=/_N_WKS_DIR/_N_CC73BEI1_WPD
;Example_1: Pocket with islands
;Solid machine and finish
```



```
$TC_DP1[5,1]=120 $TC_DP3[5,1]=111 ;Tool offset mill T5 D1
```

```
$TC_DP6[5,1]=4
```

```
$TC_DP1[2,1]=120 $TC_DP3[2,1]=130
```

```
$TC_DP6[2,1]=5
```

```
N100 G17 G40 G90 ;Initial conditions G code
```

```
N110 T5 D1 ;Load milling tool
```

```
N120 M6
```

```
N130 M3 F2000 S500 M8
```

```
N140 GOTOF _MACHINE
```

```
;
```

```
N510 _EDGE:G0 G64 X25 Y30 ;Define edge contour
```

```
N520 G1 X118 RND=5
```

```
N530 Y96 RND=5
```

```
N540 X40 RND=5
```

```
N545 X20 Y75 RND=5
```

```
N550 Y35
```

```
N560 _ENEDGE:G3 X25 Y30 CR=5
```

```
;
```

```
N570 _ISLAND1:G0 X34 Y58 ;Define bottom island
```

```
N580 G1 X64
```

```
N590 _ENDISLAND1:G2 X34 Y58 CR=15
```

```
;
```

```
N600 _ISLAND2:G0 X79 Y73 ;Define top island
```

```
N610 G1 X99
```

```
N620 _ENDISLAND2:G3 X79 Y73 CR=10
```

```
;
```

**3.15 Pocket milling with islands – CYCLE73, CYCLE74, CYCLE75**

```
;Programming contours
```

```
_MACHINE:
```

```
SAMPLE1_CONT:
```

```
CYCLE74 ("","_EDGE","_ENEDGE")
```

```
CYCLE75 ("","_ISL1","_ENDISL1")
```

```
CYCLE75 ("","_ISL2","_ENDISL2")
```

```
ENDLABEL:
```

```
;Programming Mill Pocket
```

```
CYCLE73 (1021,"","SAMPLE1_MILL1","5",10,0,1,  
-17.5,0,,2,0.5,,9000,3000,0,,,4,3)
```

```
T2 D1 M6
```

```
S3000 M3
```

```
;Programming Finish Pocket
```

```
CYCLE73 (1113,"","SAMPLE1_MILL3","5",10,0,1,  
-17.5,0,,2,,,8000,1000,0,,,4,2)
```

```
M30
```




### Programming example 2

#### Machining task:

Before the pocket is milled, the workpiece must be rough drilled to ensure optimum insertion of the milling tool.

- Center for rough drilling
- Rough drill
- Solid machine pocket with islands, mill radius 12mm
- Solid machine residual material, mill radius 6mm
- Finish pocket, mill radius 5mm.

#### Sketch of machining operation



#### Machining program:

```

%_N_SAMPLE2_MPF
; $PATH=/_N_WKS_DIR/_N_CC73BEI2_WPD
; Example_2: Pocket with islands
; 2*rough drill, machine, machine resid. mat. , finish
;
; Tool offset data
$TC_DP1[2,1]=220 $TC_DP6[2,1]=10
$TC_DP1[3,1]=120 $TC_DP6[3,1]=12
$TC_DP1[4,1]=220 $TC_DP6[4,1]=3
$TC_DP1[5,1]=120 $TC_DP6[5,1]=5
$TC_DP1[6,1]=120 $TC_DP6[6,1]=6
TRANS X10 Y10

```

**3.15 Pocket milling with islands – CYCLE73, CYCLE74, CYCLE75**

```

;Defining machining contours
ACCEPTANCE4_CONT:
CYCLE74("EDGEA01",,)
CYCLE75("ISL1A01",,)
CYCLE75("ISL1A01",,)
CYCLE75("ISL2A01",,)
CYCLE75("ISL3A01",,)
ENDLABEL:

;Program centering
T4 M6
D1 M3 F1000 S4000
MCALL CYCLE81 (10,0,1,-3,)
REPEAT ACCEPTANCE4_MACH
ACCEPTANCE4_MACH_END
MCALL

;Program drilling
T2 M6
D1 M3 F2222 S3000
MCALL CYCLE81(10,0,1,-12,)
REPEAT ACCEPTANCE4_MACH
ACCEPTANCE4_MACH_END
MCALL

GOTOF ACCEPTANCE4_MACH_END
ACCEPTANCE4_MACH:
REPEAT ACCEPTANCE4_CONT ENDLABEL
CYCLE73(1015,"ACCEPTANCE4_DRILL","ACCEPTANCE4_MILL1",
"3",10,0,1,-12,0,,2,0.5,,2000,400,0,,,,)
ACCEPTANCE4_MACH_END:

;Program solid machining
T3 M6
D1 M3 S4000
REPEAT ACCEPTANCE4_CONT ENDLABEL
CYCLE73(1011,"","ACCEPTANCE4_MILL1","3",10,0,1,
-12,0,,2,0.5,,2000,400,0,,,,)

;Program solid machining of residual
material
T6 M6
D1 M3 S4000
REPEAT ACCEPTANCE4_CONT ENDLABEL
CYCLE73(1012,"","ACCEPTANCE4_2_MILL4","3",10,0,1,
-12,0,,2,0.5,,1500,800,0,,,,)

;Program finishing
T5 M6
D1 M3 S4500
REPEAT ACCEPTANCE4_CONT ENDLABEL
CYCLE73(1013,"","ACCEPTANCE4_MILL3","3",10,0,1,
-12,0,,2,,3000,700,0,,,,)
M30

```

**Edge contour programming example 2:**

```
%_N_EDGEA01_MPF
; $PATH=/_N_WKS_DIR/_N_CC73BEI2_WPD
; Ste 17.05.99
; Edge contour programming example 2
```

```
N5 G0 G90 X260 Y0
N7 G3 X260 Y120 CR=60
N8 G1 X170 RND=15
N9 G2 X70 Y120 CR=50
N10 G1 X0 RND=15
N11 Y0 RND=15
N35 X70 RND=15
N40 G2 X170 Y0 CR=50
N45 G1 X260 Y0
N50 M30
```

**Island contour sample program 2**

```
%_N_ISL1A01_MPF
; $PATH=/_N_WKS_DIR/_N_CC73BEI2_WPD
; Ste 18.06.99
; Island contour sample program 2
```

```
N5 G90 G0 X30 Y15
N10 G91 G3 X0 Y30 CR=15
N12 X0 Y-30 CR=15
N15 M30
```

```
%_N_ISL11A01_MPF
; $PATH=/_N_WKS_DIR/_N_CC73BEI2_WPD
; Ste 18.06.99
; Island contour sample program 2
```

```
N5 G90 G0 X30 Y70
N10 G91 G3 X0 Y30 CR=15
N12 X0 Y-30 CR=15
N15 M30
```

```
%_N_ISL2A01_MPF
; $PATH=/_N_WKS_DIR/_N_CC73BEI2_WPD
; Ste 18.06.99
; Island contour sample program 2
```

```
N5 G90 G0 X200 Y40
N10 G3 X220 Y40 CR=10
N15 G1 Y85
N20 G3 X200 Y85 CR=10
N25 G1 Y40
N30 M30
```

**3.15 Pocket milling with islands – CYCLE73, CYCLE74, CYCLE75**

```
%_N_ISL3A01_MPF  
; $PATH=/_N_WKS_DIR/_N_CC73BEI2_WPD  
; Ste 18.06.99  
; Island contour sample program 2
```

```
N5 G0 G90 X265 Y50
```

```
N10 G1 G91 X20
```

```
N15 Y25
```

```
N20 G3 X-20 I-10
```

```
N25 G1 Y-25
```

```
N30 M30
```



### Programming example 3

#### Machining task:

Shows the program sequence of a machining task, illustrated by two different pockets with islands. The machining process is tool-oriented, i.e. each time a new tool becomes available, all machining tasks requiring this particular tool are performed complete on both pockets before the next tool is used.

- Rough drill
- Solid machine pocket with islands
- Solid machine residual material.

```

%_N_SAMPLE3_MPF
; $PATH=/_N_WKS_DIR/_N_CC73BEI3_WPD
; Sample3
; 07.04.2000

; Tool offset data
$TC_DP1[2,1]=220 $TC_DP3[2,1]=330 $TC_DP6[2,1]=10
$TC_DP1[3,1]=120 $TC_DP3[3,1]=210 $TC_DP6[3,1]=12
$TC_DP1[6,1]=120 $TC_DP3[6,1]=199 $TC_DP6[6,1]=6

; Workpiece zero
; G54
$P_UIFR[1,X,TR]=620
$P_UIFR[1,Y,TR]=50
$P_UIFR[1,Z,TR]=-320
; G55
$P_UIFR[2,X,TR]=550
$P_UIFR[2,Y,TR]=200
$P_UIFR[2,Z,TR]=-320
;
N10 G0 G17 G54 G40 G90
N20 T2
M6
D1 M3 F2000 S500 M8
N30 G0 Z20

```

## 3.15 Pocket milling with islands – CYCLE73, CYCLE74, CYCLE75

```

;Machining contours pocket 1
GOTOF ENDLABEL
POCKET1_CONT:
CYCLE74("EDGE","","")
CYCLE75("ISLAND1","","")
CYCLE75("ISLAND2","","")
ENDLABEL:

;Machining contours pocket 2
GOTOF ENDLABEL
SAMPLE2_CONT:
CYCLE74("EDGEA01",,)
CYCLE75("ISL1A01",,)
CYCLE75("ISL1A01",,)
CYCLE75("ISL2A01",,)
CYCLE75("ISL3A01",,)
ENDLABEL:

;Drill
T2 M6
D1 M3 F6000 S4000
MCALL CYCLE81(10,0,1,-8,)
REPEAT POCKET1_MACH POCKET1_MACH_END
MCALL

G55
MCALL CYCLE81(10,0,1,-8,)
REPEAT SAMPLE2_MACH SAMPLE2_MACH_END
MCALL

;Removing pocket 1
T3 M6
G54 D1 M3 S3300
GOTOF POCKET1_MACH_END
POCKET1_MACH:
REPEAT POCKET1_CONT ENDLABEL
CYCLE73(1025,"POCKET1_DRILL","POCKET1_MILL1","3",10,0,1,-8,0,0,2,0,0,2000,400,0,0,0,3,4)
POCKET1_MACH_END:
REPEAT POCKET1_CONT ENDLABEL
CYCLE73(1021,"POCKET1_DRILL","POCKET1_MILL1","3",10,0,1,-8,0,0,2,0,0,2000,400,0,0,0,3,4)

;Removing pocket 2
G55
GOTOF SAMPLE2_MACH_END

SAMPLE2_MACH:
REPEAT SAMPLE2_CONT ENDLABEL
CYCLE73(1015,"SAMPLE2_DRILL","SAMPLE2_MILL1","3",10,0,1,-8,0,0,2,0,0,2000,400,0,0,0,3,4)
SAMPLE2_MACH_END:
REPEAT SAMPLE2_CONT ENDLABEL
CYCLE73(1011,"SAMPLE2_DRILL","SAMPLE2_MILL1","3",10,0,1,-8,0,0,2,0,0,2000,400,0,0,0,3,4)

```



```

;Removing residual material pocket 1 and pocket 2
T6 M6
D1 G54 M3 S222
REPEAT POCKET1_CONT ENDLABEL
CYCLE73(1012,"","POCKET1_3_MILL2","3",10,0,1,-8,0,,2,,2500,800,0,,,,)

G55
REPEAT SAMPLE2_CONT ENDLABEL
CYCLE73(1012,"","SAMPLE2_3_MILL2","3",10,0,1,-8,0,,2,,2500,800,0,,,,)
G0 Z100
M30

;Edge and island contours
;Pocket 2 corresponds to programming example 2
Pocket 1:
%_N_Edge_MPF
;$PATH=/_N_WKS_DIR/_N_CC73BEI3_WPD
;29.03.99

N1 G0 X0 Y0 G90
N3 G1 X200 Y0
N5 X200 Y100
N10 X0 Y100
N20 X0 Y0
M30

%_N_ISLAND1_MPF
;$PATH=/_N_WKS_DIR/_N_CC73BEI3_WPD
;29.03.99
N100 G0 X130 Y30 Z50 G90
N110 G1 X150 Y30
N120 X150 Y60
N130 X130 Y60
N200 X130 Y30
M30

%_N_ISLAND2_MPF
;$PATH=/_N_WKS_DIR/_N_CC73BEI3_WPD
;29.03.99
N12 G0 X60 Y20
N13 G1 X90 Y20
N14 X90 Y50
N30 X60 Y50
N40 X60 Y20
M30

```



## Explanation

### Alarms source CYCLE73...CYCLE75

Alarm number	Alarm text	Explanation, remedy
61703	"Internal cycle error while deleting file"	
61704	"Internal cycle error while writing file"	
61705	"Internal cycle error while reading file"	
61706	"Internal cycle error during checksum formation"	
61707	"Error in ACTIVATE on MMC"	
61708	"Error in READYPROG on MMC"	
61900	"No contour"	
61901	"Contour is not closed"	
61902	"No more free memory"	
61903	"Too many contour elements"	
61904	"Too many intersections"	
61905	"Cutter radius too small"	
61906	"Too many contours"	
61907	"Circle without center point measurement"	
61908	"No starting point specified"	
61909	"Helical radius too small"	
61910	"Helix violates contour"	
61911	"Several insertion points required"	
61912	"No path generated"	
61913	"No residual material generated"	
61914	"Programmed helix violates contour"	
61915	"Approach/liftoff motion violates contour"	
61916	"Ramp path too short"	
61917	"Residual corners might be left with less than 50 percent overlap"	
61918	"Cutter radius too large for residual material"	
61980	"Error in island contour"	
61981	"Error in edge contour"	
61982	"Infeed width in plane too large"	
61983	"Pocket edge contour missing"	
61984	"Tool parameter _TN not defined"	
61985	"Name of drilling position program missing"	
61986	"Machine pocket program missing"	
61987	"Drilling position program missing"	
61988	"Name of program for machining pocket missing"	
61989	"Not D1 programmed as active tool cutting edge"	

### 3.16 Swiveling – CYCLE800 (SW 6.2 and higher)



The Swiveling cycle is not an option, but is available for the HMI with SW 06.02 and NC SW 6.3 (CCU SW 4.3) and higher.

The functions

- 3/2 axes inclined machining and
- orientatable toolholder

are available in the basic version.



**References:** Description of Functions 840D/840Di/810D  
/W1/ "Tool Offset"  
/R2/ "Rotary Axes"  
/K2/ "System Frames" (SW 6.1 and higher)




#### Function

The cycle is used during milling to swivel on any type of surface so that it can be machined and/or measured. By calling the appropriate NC functions, the cycle converts the active workpiece zeroes and tool offsets to refer to the inclined surface, taking account of the kinematic chain on the machine, and positions the rotary axes (optional).

Swiveling can be implemented either axially, as a projection angle or as a solid angle.

Before the rotary axes are positioned, the linear axes can be retracted if desired.



#### Machine kinematics

1. Swivel-mounted toolholder (swivel head) → type T
2. Swivel-mounted workholder (swivel table) → type P
3. Mixed kinematics from 1 and 2 → type M



#### Important

The zero offset (ZO) with which the workpiece was scratched or measured must be programmed before the swivel cycle is first called in the main program. This zero offset is converted to the appropriate machining plane in the swivel cycle. The ZO value remains unchanged. Translational and rotational components are saved in system frames (swivel frame), tool reference (PARTFRAME), toolholder (TOOLFRAME) and workpiece reference (WPFRAME) (see HMI → parameters, active ZO).

### 3.16 Swiveling – CYCLE800 (SW 6.2 and higher)

The current machining plane (G17, G18, G19) is taken into account by the swivel cycle.

#### Swiveling onto a machining or auxiliary surface

always involves three steps:

- Offset of reference point prior to rotation (corresponds to TRANS or ATRANS)
- Rotation (corresponds to AROT or AROTS)
- Offset of zero point after rotation (corresponds to ATRANS)

**The offsets or rotations are not machine-specific, but refer to the coordinate system X, Y, Z of the workpiece.** No programmable frames are used in the swivel cycle. The frames programmed by the user are taken into account in additive swiveling. Swiveling to a **new** swivel plane clears the programmable frames (TRANS). After a program reset or if there is a power failure, the last swivel plane remains active, with the option to set via machine data. Any type of machining operation can be performed on the swivel plane, e.g. through calling standard or measuring cycles.

#### Note about calling the 5-axis transformation

If a program activating the 5-axis transformation (TRAORI) is to be executed on the swiveled machining plane, the system frames for the swivel head/swivel table must be deactivated before TRAORI is called (see example).

Example (machine with swivel table)

G54	
T="MILL_10mm"	
M6	
CYCLE800(1,"",0,57,0,40,0,-45,0,0,0,0,0,-1)	;Swivel cycle
CYCLE71(50,24,2,0,0,0,80,60,0,4,10,5,0,2000,31,5)	;Face mill
TCARR=0	;swivel data record deselection
PAROTOF	
TOROTOF	;(machine kinematic type "T" and "M" only)
TRAORI	
G54	;Calculation of new zero offset
EXTCALL "WALZ"	;5-axis machining program with direction vectors ;(A3, B3, C3)
M2	

### 3.16.1 Operation, parameter assignment, input screen form



#### Description of parameters

Interactive screen form CYCLE800 on standard interface

Swivel cycle/CYCLE800		Reference point for rotation around Y axis	
Name:			
Retract:		Z	
Schwenken:		Yes	
Swivel plane:		new	
Ref. point:	X0		0.000
	Y0		25.000
	Z0		0.000
Swivel mode:		axis by ax.	
Rot. around	X (A)		-15.000
Rot. around	Y (B)		0.000
Rot. around	Z (C)		0.000
Zero point:	X1		0.000
	Y1		0.000
	Z1		0.000
Direction:			Minus
Tracking TL			No

Reference point before rotation

Rotation

Zero after rotation

#### \_TC (name of swivel data record)

The existing swivel data records (see Start-Up of CYCLE800) can be selected (toggled).

Each swivel data record has a name. No name needs to be declared if there is only one swivel data record.  
"0" → swivel data record deselected.

#### \_FR (retraction)

- Do not retract
- Traverse axis Z
- Traverse axis Z, XY (only when CYCLE800 is active in the start-up menu).

The retraction positions can be entered in the start-up menu display.

The retraction positions are approached absolutely. If a different retraction sequence or incremental positioning is desired, the process can be modified accordingly in user cycle TOOLCARR during start-up.

**Note**

When programming with standard cycles and high settings for the retraction plane and large swivel angles (through 90 degrees with multiface machining) it is possible that the traversing area of the machine may be too small (software end position violation), as the order of approach is always the machining plane (for G17 X, Y) first, followed by the infeed axis (Z). The retraction plane can be reduced to optimize this behavior.

**\_DIR (swivel, direction)**

- **Swivel yes**

Rotary axes are positioned or the operator can turn the manual rotary axes.

- **Swivel no (calculation only)**

If rotary axes are not to be traversed after activating the swivel cycle, the "Swivel no" selection applies. Application: Auxiliary swivel levels according to workpiece drawing

- **Direction minus/plus**

Reference to rotary axis 1 or 2 when direction of travel is selected in the swivel cycle interactive screen form. Due to the angular range of the rotary axes of machine kinematics, the NCU calculates two possible solutions. One of these solutions is normally appropriate technologically. The rotary axis (1st or 2nd rotary axis) to which the two solutions are to refer, is selected in the CYCLE800 start-up menu. The choice between the two possible solutions to be traversed is made in the input screen form for the swivel cycle.

**\_ST (swivel plane)**

- **New**

Previous swivel frames and programmed frames are deleted and a new swivel frame formed according to the values specified in the input screen.



Every main program must begin with a swivel cycle with the **new** swivel plane to ensure that a swivel frame from another program is not active.

- **Additive**

The swivel frame is added to the swivel frame of the last swivel cycle.




If several swivel cycles are programmed in a program and programmable frames are also active between them (e.g. AROT ATRANS), these are taken into account in the swivel frame.

The following help displays relate to machining plane G17 (tool axis Z).

### X0, Y0, Z0 (reference points prior to rotation)

Reference points



### \_MODE (swivel mode)

This parameter defines the swivel mode for the axis.

- Axial
- Projection angle<sup>1)</sup>
- Solid angle<sup>1)</sup>


Swivel mode always refers to the coordinate system of the workpiece and is therefore not dependent on the machine.

You can set which swivel modes are available in the CYCLE800 start-up menu.


- With the axial swiveling variant, the tool is rotated about the individual axes in succession, with each rotation starting from the previous rotation. The axis sequence can be selected freely.
- When swiveling using the angle of projection, the angle value of the swiveled surface is projected onto the 1st two axes of the coordinate system. The 3rd rotation starts from the previous rotation. The axis sequence can be selected freely.
- With the solid angle variant, the tool is rotated first about the Z axis and then the X axis. The second rotation starts from the first.

The positive direction of each rotation for the different swivel variants is shown in the help displays.


### Axial



### Projection angle



### Solid angle






1) Only available if machine manufacturer is selected in the start-up screen form.



### 3.16 Swiveling – CYCLE800 (SW 6.2 and higher)

#### A, B, C (rotations)




- Rotations (axial, projection angle)



- Rotation (solid angle)



#### X1, Y1, Z1 (zero point after rotation)



#### Correction tool (\_TC\_N\_WZ)

- **yes / non**  
Display can be deactivated via the CYCLE800 start-up menu.
- **Yes:** When swiveling onto a machining plane, the rotary axes can be corrected to prevent risk of collision.  
Preconditions:
  1. TRAORI option is required.
  2. The machine manufacturer has adapted user cycle TOOLCARR.spf appropriately.



### 3.16.2 Operating instructions

- If the rotary axes of machine kinematics are defined as the manual axes (CYCLE800 start-up menu), the swivel angle to be set is displayed in cancel alarm 62180/62181.  
After rotation to the swivel angle, the NC program is continued with NC Start.
- It is possible to traverse the axes in the active swivel plane in JOG mode if key WCS is active on the machine control panel. This ensures that the geometry axes are traversed and not the machine axes.
- It is possible (without operator support) to deselect the swivel data record and cancel the swivel frame (WPFRAME, PARTFRAME, TOOLFRAME) by programming **CYCLE800()**.
- In CYCLE800, parameters can also be transferred as input values (e.g. result variable of measuring cycles `_OVR[19]`).

## 3.16.3 Parameters



## Programming

CYCLE800(\_FR, \_TC, \_ST, \_MODE, \_XO, \_YO, \_ZO, \_A, \_B, \_C, \_X1, \_Y1, \_Z1, \_DIR)



## Parameters

_FR	int	Retraction Value: 0...Do not retract 1...Retract axis Z (default) <sup>1)</sup> 2...Retract axis Z, X, Y <sup>1)</sup> 1) can be adjusted in user cycle TOOLCARR																																
_TC	String[20]	Name of swivel data record " " Swivel data record 1 (default) "HEAD1" Name of swivel data record "0" Deselection of data record																																
_ST	int	Swivel plane UNITS DIGIT: Value: 0... new 1... additive TENS DIGIT <sup>2)</sup> : Value: 0x...Do not correct tool tip 1x... Correct tool tip HUNDREDS DIGIT: Value: reserved 2) Precondition: Option TRAORI must be available																																
_MODE	int	Swivel mode Value: 0x...axial (default) 4x...Solid angle 8x...Projection angle Evaluation of angle: <div style="display: flex; align-items: center; margin-left: 20px;"> <table style="border-collapse: collapse; margin-right: 10px;"> <tr> <td style="border-bottom: 1px solid black; padding: 2px 5px;">7</td> <td style="border-bottom: 1px solid black; padding: 2px 5px;">6</td> <td style="border-bottom: 1px solid black; padding: 2px 5px;">5</td> <td style="border-bottom: 1px solid black; padding: 2px 5px;">4</td> <td style="border-bottom: 1px solid black; padding: 2px 5px;">3</td> <td style="border-bottom: 1px solid black; padding: 2px 5px;">2</td> <td style="border-bottom: 1px solid black; padding: 2px 5px;">1</td> <td style="border-bottom: 1px solid black; padding: 2px 5px;">0</td> </tr> </table> <div style="margin-left: 10px;"> <table style="border-collapse: collapse;"> <tr> <td style="border-left: 1px solid black; border-right: 1px solid black; padding: 2px 5px;">01: Rotation around 1<sup>st</sup> axis</td> <td rowspan="3" style="font-size: 2em; padding: 0 5px;">}</td> <td rowspan="3" style="padding: 0 5px;">Angle of rotation 1</td> </tr> <tr> <td style="border-left: 1px solid black; border-right: 1px solid black; padding: 2px 5px;">10: Rotation around 2<sup>nd</sup> axis</td> </tr> <tr> <td style="border-left: 1px solid black; border-right: 1px solid black; padding: 2px 5px;">11: Rotation around 3<sup>rd</sup> axis</td> </tr> <tr> <td style="border-left: 1px solid black; border-right: 1px solid black; padding: 2px 5px;">01: Rotation around 1<sup>st</sup> axis</td> <td rowspan="3" style="font-size: 2em; padding: 0 5px;">}</td> <td rowspan="3" style="padding: 0 5px;">Angle of rotation 2</td> </tr> <tr> <td style="border-left: 1px solid black; border-right: 1px solid black; padding: 2px 5px;">10: Rotation around 2<sup>nd</sup> axis</td> </tr> <tr> <td style="border-left: 1px solid black; border-right: 1px solid black; padding: 2px 5px;">11: Rotation around 3<sup>rd</sup> axis</td> </tr> <tr> <td style="border-left: 1px solid black; border-right: 1px solid black; padding: 2px 5px;">01: Rotation around 1<sup>st</sup> axis</td> <td rowspan="3" style="font-size: 2em; padding: 0 5px;">}</td> <td rowspan="3" style="padding: 0 5px;">Angle of rotation 3</td> </tr> <tr> <td style="border-left: 1px solid black; border-right: 1px solid black; padding: 2px 5px;">10: Rotation around 2<sup>nd</sup> axis</td> </tr> <tr> <td style="border-left: 1px solid black; border-right: 1px solid black; padding: 2px 5px;">11: Rotation around 3<sup>rd</sup> axis</td> </tr> <tr> <td style="border-left: 1px solid black; border-right: 1px solid black; padding: 2px 5px;">00: Swivel angle per axis (_A, _B, _C)</td> <td colspan="2"></td> </tr> <tr> <td style="border-left: 1px solid black; border-right: 1px solid black; padding: 2px 5px;">01: Solid angle (_A, _B)</td> <td colspan="2"></td> </tr> <tr> <td style="border-left: 1px solid black; border-right: 1px solid black; padding: 2px 5px;">10: Angle of projection (_A, _B, _C)</td> <td colspan="2"></td> </tr> </table></div> </div>	7	6	5	4	3	2	1	0	01: Rotation around 1 <sup>st</sup> axis	}	Angle of rotation 1	10: Rotation around 2 <sup>nd</sup> axis	11: Rotation around 3 <sup>rd</sup> axis	01: Rotation around 1 <sup>st</sup> axis	}	Angle of rotation 2	10: Rotation around 2 <sup>nd</sup> axis	11: Rotation around 3 <sup>rd</sup> axis	01: Rotation around 1 <sup>st</sup> axis	}	Angle of rotation 3	10: Rotation around 2 <sup>nd</sup> axis	11: Rotation around 3 <sup>rd</sup> axis	00: Swivel angle per axis (_A, _B, _C)			01: Solid angle (_A, _B)			10: Angle of projection (_A, _B, _C)		
7	6	5	4	3	2	1	0																											
01: Rotation around 1 <sup>st</sup> axis	}	Angle of rotation 1																																
10: Rotation around 2 <sup>nd</sup> axis																																		
11: Rotation around 3 <sup>rd</sup> axis																																		
01: Rotation around 1 <sup>st</sup> axis	}	Angle of rotation 2																																
10: Rotation around 2 <sup>nd</sup> axis																																		
11: Rotation around 3 <sup>rd</sup> axis																																		
01: Rotation around 1 <sup>st</sup> axis	}	Angle of rotation 3																																
10: Rotation around 2 <sup>nd</sup> axis																																		
11: Rotation around 3 <sup>rd</sup> axis																																		
00: Swivel angle per axis (_A, _B, _C)																																		
01: Solid angle (_A, _B)																																		
10: Angle of projection (_A, _B, _C)																																		

Note Bits 0 to 5 have no meaning for solid angle

<code>_X0, _Y0, _Z0</code>	real	Reference point prior to rotation
<code>_A</code>	real	1. Axis angle (axial swivel mode) 2. Angle of rotation in XY plane about the Z axis (swivel mode 'solid angle') 3. Axis angle (swivel mode 'projection angle') sequence of axes
<code>_B</code>	real	1. Axis angle (axial swivel mode) 2. Angle of rotation in space about the Y axis (swivel mode 'solid angle')
<code>_C</code>	real	Axis angle (swivel modes 'axial', 'projection angle')
<code>_X1, _Y1, _Z1</code>	real	Zero point after rotation
<code>_DIR</code>	int	direction If the NC calculates two solutions when the swivel cycle is called, the operator can select a preferred direction. The machine manufacturer specifies the axis to which the preferred direction refers. Value: -1 (minus)...lower rotary axis value (default) +1 (plus)...higher rotary axis value 0...no movement of rotary axes (calculation only)



### Programming example 1

#### Set swivel plane ZERO

```

%_N_SWIVEL_0_SPF
; $PATH=/_N_WCS_DIR/_N_HAA_SWIVEL_WPD
G54
CYCLE800(1,"",0,57,0,0,0,0,0,0,0,0,-1)
M2

```

Swivel cycle/CYCLE800 Reference point for rotation around X axis


Name:	<input type="text"/>	
Retract:	<input type="text"/>	Z
Schwenken:	<input type="text"/>	Yes
Swivel plane:	<input type="text"/>	new
Ref. point:	X0	<input type="text" value="0.000"/>
	Y0	<input type="text" value="0.000"/>
	Z0	<input type="text" value="0.000"/>
Swivel mode:	axis by ax.	
Rot. around	X (A)	<input type="text" value="0.000"/>
Rot. around	Y (B)	<input type="text" value="0.000"/>
Rot. around	Z (C)	<input type="text" value="0.000"/>
Zero point:	X1	<input type="text" value="0.000"/>
	Y1	<input type="text" value="0.000"/>
	Z1	<input type="text" value="0.000"/>
Direction:	<input type="text" value="Minus"/>	

## 3.16 Swiveling – CYCLE800 (SW 6.2 and higher)



## Programming example 2

Face milling and milling a circular pocket on a machining plane swiveled through 15 degrees



```

%_N_SWIVEL_CIRCULARPOCKET_SPF
; $PATH=/_N_WCS_DIR/_N_HAA_SWIVEL_WPD
N12 T="MILL_26mm"
N14 M6
N16 G57
N18 CYCLE800(1,"",0,57,0,0,0,0,0,0,0,0,0,1)
N20 M3 S5000
N22 CYCLE71(50,2,2,0,0,0,80,60,0,4,15,5,0,2000,31,5) ;Face milling
N24 CYCLE800(1,"",0,57,0,25,0,-15,0,0,0,0,0,-1)

```

Swivel cycle/CYCLE800		Angle of 1st rotation
Name: <input type="text"/>		
Retract:		Z
Schwenken:		Yes
Swivel plane:		new
Ref. point:	X0	0.000
	Y0	25.000
	Z0	0.000
Swivel mode:		axis by ax.
Rot. around	X (A)	15.000
Rot. around	Y (B)	0.000
Rot. around	Z (C)	0.000
Zero point:	X1	0.000
	Y1	0.000
	Z1	0.000
Direction:		Minus

```

N26 CYCLE71(50,12,2,0,0,0,80,60,0,4,10,5,0,2000,31,5) ;Face milling
N28 CYCLE800(1,"",1,57,0,0,0,0,0,0,40,30,0,1)

```

Swivel cycle/CYCLE800		Zero point of X axis swivel plane
Name: <input type="text"/>		
Retract:		Z
Schwenken:		Yes
Swivel plane:		new
Ref. point:	X0	0.000
	Y0	0.000
	Z0	0.000
Swivel mode:		axis by ax.
Rot. around	X (A)	0.000
Rot. around	Y (B)	0.000
Rot. around	Z (C)	0.000
Zero point:	X1	40.000
	Y1	30.000
	Z1	0.000
Direction:		Minus
Tracking TL		No

---

N30 T="MILL\_10mm"

---

N32 M6

---

N34 M3 S5000

---

N36 POCKET4(50,0,1,-15,20,0,0,4,0.5,0.5,1000,1000,0,11,,,,,);Circular pocket

---

N38 POCKET4(50,0,1,-15,20,0,0,4,0,0,1000,1000,0,12,,,,,)

---

N40 M2

---

### 3.16.4 Starting up CYCLE800



When CYCLE800 is started up, the data (swivel data record) is set in the tool data \$TC\_CARR1...40. This is grouped to form Swivel start-up menus.

→ Operating area "Start-up"; Soft key "Swivel cycle"



**References:** for current infos see:

- the file "siemensd.txt" from the delivery software (standard cycles) or
- for HMI Advanced, F:\dh\cst.dir\HLP.dir\siemensd.txt.

The following cycles must be loaded:

- CYCLE800.SPF, CYCPE\_SC.SPF (standard cycles)
- TOOLCARR-SPF (user cycle)
- PROG\_EVENT.SPF (manufacturer cycle).

The GUD variables \_TC\_FR to \_TC\_NUM (GUD7.def) must be activated.

#### Machine data

To use the swiveling cycle, the machine data below must be set as follows (minimum requirement):

- Machine data with an exact value assignment (G)
  - is machine data that must not be changed
- Machine data with a variable value assignment (V)
  - is machine data where the default value can be set to a higher or lower value.

MD No.	MD identifiers	Value	Comments	Can be changed
10602	\$MN_FRAME_GEOAX_CHANGE_MODE	1	<sup>1)</sup>	V
11450	\$MN_SEARCH_RUN_MODE	Bit 1=1	<sup>1)</sup>	G
18088	\$MN_MM_NUM_TOOL_CARRIER	n>0	n → Number of swivel data records <sup>1)</sup>	G
20108	\$MC_PROG_EVENT_MASK	0	-	V
20110	\$MC_RESET_MODE_MASK	'H4041'	Bit 14=1	G
20112	\$MC_START_MODE_MASK	'H400'	-	G
21100	\$MC_ORIENTATION_IS_EULER	0	Angles of rotations are interpreted as RPY	G
20126	\$MC_TOOL_CARRIER_RESET_VALUE	0...n	is described in CYCLE800	V
20150	\$MC_GCODE_RESET_VALUES[41]	1	TCOABS <sup>1)</sup>	G
20150	\$MC_GCODE_RESET_VALUES[51]	2	PAROT <sup>1)</sup>	G
20150	\$MC_GCODE_RESET_VALUES[52]	1	TOROT <sup>1)</sup> (for kinematics type T and M only)	V



1) For note on machine data, see next page

MD No.	MD identifiers	Value	Comments	Can be changed
20152	\$MC_GCODE_RESET_MODE[41]	0	(default) <sup>1)</sup>	G
20152	\$MC_GCODE_RESET_MODE[51]	0	(default) <sup>1)</sup>	V
20152	\$MC_GCODE_RESET_MODE[52]	0	(default) <sup>1)</sup>	V
20180	\$MC_TOCARR_ROT_ANGLE_INCR[0]	0	(default) <sup>1)</sup>	G
20180	\$MC_TOCARR_ROT_ANGLE_INCR[1]	0	(default) <sup>1)</sup>	G
20182	\$MC_TOCARR_ROT_ANGLE_OFFSET[0]	0	(default) <sup>1)</sup>	G
20182	\$MC_TOCARR_ROT_ANGLE_OFFSET[1]	0	(default) <sup>1)</sup>	G
20184	\$MC_TOCARR_BASE_FRAME_NUMBER	-1	(default) <sup>1)</sup>	G
22530	\$MC_TOCARR_CHANGE_M_CODE	0	<sup>1)</sup>	V
24006	\$MC_CHSFRAME_RESET_MASK	Bit 4=1	if system frame WPFAME is to remain active after a reset	V
24008	\$MC_CHSFRAME_POWERON_MASK	Bit 4, 3, 2=1	if system frames PAROT, TOROT, WPFAME are to be cleared on power ON	V
28082	\$MC_MM_SYSTEM_FRAME_MASK	Bit 4, 3, 2=1	Setting up system frames	G
30455	MISC_FUNCTION_MASK	Bit 2, 0=1	for rotary axes defined as modulo axes <sup>1)</sup>	V

#### Setting data

SD no.	SD identifier	Value	Comments	Can be changed
42980	\$SC_TOFRAME_MODE	3	kinematics type "T" and "M" only	V



Changes to the relevant machine data result in reorganization of the buffered memory (data loss!).

Series start-up must be performed after setting the MD and before NCK reset.



**References:** /IAM/ HMI/MMC Installation and Start-Up Guide



1) For note on machine data, see this page and the next

#### Note on MD 10602:

If after TRAORI, the ZO is not to be reprogrammed. e.g. for tool correction.

#### Note on MD 11450/MD 20108:

Activate PROGEVENT after block search

**Note about MD 18088:**

If several channels are defined in the NCU, the number of swivel data records is divided, taking MD 28085: MM\_LINK\_TOA\_UNIT into account.

Example:

MD 18088 MM\_NUM\_TOOL\_CARRIER =4

Number of channels=2.

Two swivel data records are provided for each channel.

**Note on MD 20150/MD 20152:**

Equals 0, if there is no plane changeover + SWIVEL (G17-G19).

**Note on MD 20180/MD 20182:**

The swivel data record with the Hirth tooth system is described in the CYCLE800 rotary axes start-up screen.

**Note about MD 22530:**

If more than one swivel data record is declared per channel, and if machine functions need to be activated on changeover between swivel heads or tables, an M command can be issued in the PLC program on switchover to another swivel data record.

Example: Number of swivel data records in channel 1 =2

MD 22530: TOCARR\_CHANGE\_M\_CODE = **-800**


Programming of swivel data record 1 (TCARR=1) → M801

Programming of swivel data record 2 (TCARR=2) → M802

By outputting special functions, the PLC can, for example, limit or invert the spindle speed.

**Note on MD 30455**

This allows the axis to traverse for G90 with DC (shortest path); see user cycle TOOLCARR.spf

Soft key 

Current swivel data record is saved as the parts program. The parts program corresponds to the name of the swivel data record.

Soft key 

Current swivel data record is deleted.



The CYCLE800 start-up process is supported by the following menu displays:

### Start-up of kinematic chain

Kinematic channel1			
Kinematics	Inclinable head	Name:	HEAD_1 No.: 1
Retract:	X	Y	Z
Retract position			200.000
Offset vector I1	0.000	0.030	-63.000
Rotary axis vector V1	0.000	0.000	1.000
Offset vector I2	0.000	0.000	40.000
Rotary axis vector V2	1.000	0.000	0.000
Offset vector I3	0.000	-0.030	23.000
Display opt.	axial +projection angle		
Swivel mode:			
Direction:	Rot. axis 1		
Tracking TL	No		

A swivel data record must be created for each swivel head, swivel table or each swivel head/table combination.

Swivel data records can be declared in several channels.

The number of swivel data records is limited by the following machine data:

- MD 18088: MM\_NUM\_TOOL\_CARRIER or
- MD: NUM\_CHANNELS (Number of channels option)
- MD 28085: MM\_LINK\_TOA\_UNIT

The swivel data record is assigned to the tool data by parameters \$TC\_CARR1[n] to \$TC\_CARR40[n].

The meaning of the parameters in the "Kinematics" screen form is as follows:

**Name: Swivel data record** \$TC\_CARR34[n]

n → No. of swivel data record

If more than one swivel data record is declared in each NC channel, then a name is assigned to each record. No name need be specified if the swivel-mounted toolholder is not exchangeable (i.e. one swivel data record per channel). The program is advanced to the next swivel data record and the next channel via soft keys (channel +/- swivel data record +/-).



Only characters valid for NC programming must appear in the name!

### 3.16 Swiveling – CYCLE800 (SW 6.2 and higher)

#### Kinematic type \$TC\_CARR23[n]

- Swivel head (type T)
- Swivel table (type P)
- Swivel head + swivel table (type M).

#### Retraction/Retraction position

\$TC\_CARR38[n] X; \$TC\_CARR39[n] Y; \$TC\_CARR40[n] Z

n → No. of swivel data record

The start-up engineer determines whether the options 'Retract axis Z' and 'Retract axes Z,X,Y' are possible in the input menu for the swivel cycle.

The mode of retraction can be modified in user cycle TOOLCARR.spf (marker \_M41, \_M40) if necessary. If user cycle TOOLCARR.spf is not modified, the retraction position is approached as an absolute machine position.



Please note the following when moving the tool axes:

Retract the tool axis in such a way that the tool and workpiece cannot collide when swiveled.

#### Offset rotary axis vectors (machine kinematics)

\$TC\_CARR1[n] ... \$TC\_CARR20[n]

The positions in the kinematic chain are measured by the machine manufacturer; they are always relevant with respect to a swivel head table (swivel data record). Offset vectors I1 to I4 refer to the **non-swiveled state of the rotary axes**.

The machine kinematics used need not be fully implemented from the control viewpoint. But then be aware that the traversing range in the swivel planes may be restricted. If machine kinematics are to be implemented with just one rotary axis, this must always be declared as the 1st rotary axis.

Manually adjustable rotary axes with or without measuring systems are possible and can be used with "plain machines".

Swivel head (type T)	Swivel table (type P)	Swivel head + swivel table (type M)
Offset vector I1	Offset vector I2	Offset vector I1
Rotary axis vector V1	Rotary axis vector V1	Rotary axis vector V1
Offset vector I2	Offset vector I3	Offset vector I2
Rotary axis vector V2	Rotary axis vector V2	Offset vector I3
Offset vector I3	Offset vector I4	Rotary axis vector V2
		Offset vector I4

The vector meanings are as follows:

**References:** Description of Functions  
840D/840Di/810D  
/W1/ "Tool Offset  
(3/2 axis inclined machining)

- Offset vector I1  
→ Distance between reference point of toolholder and rotary axis 1
- Offset vector I2  
→ Distance between rotary axis 1 and rotary axis 2
- Offset vector I3  
→ Distance between rotary axis 2 and tool reference point
- Offset vector I4  
→ Distance between rotary axis 2 and table reference point
- Rotary axis vector V1  
→ Direction of rotary axis 1
- Rotary axis vector V2  
→ Direction of rotary axis 2.

The offset vectors must not necessarily point to the pivot point of the rotary axes, but it is important that they are directed towards a point in the direction of rotation.

The plus/minus sign of the rotary axis vectors is determined by the direction of rotation of the particular rotary axis around the corresponding machine axis.

→ see start-up examples.



The following display options affect the input screen form for the swivel cycle:

- **Swivel mode**

- **axial**

- **axial and projection angle**

- **axial and projection angle and solid angle**

Example:

Selection of swivel mode during start-up:

Axial, angle of projection

In this case, only 'axial' or 'projection angle'

is included in the input menu. Programming of a

solid angle is not desired or possible in this

example.

- **Direction**

- **Rotary axis 1**

- **Rotary axis 2**

- **no**

When direction of travel is selected in the swivel cycle interactive screen form, reference to **rotary axis 1** or **2**.

Because of the angular range of **rotary axes** of machine kinematics, the NCU calculates 2 possible solutions. One of these solutions is normally appropriate technologically. The selection as to which **rotary axis** the two solutions must refer to is made in the start-up menu. The selection of the solution to be applied is made in the interactive screen form for the swivel cycle.

With "no", the direction parameter is not displayed in the operating screen.

- **Correct tool**

- **no**

- **yes**

"Correct tool" display in the swivel cycle interactive screen form. The function correct tool the option 5-axis transformation (TRAORI).

In the user cycle, query TOOLCARR.spf Variable GUD7 \_TC\_N\_WZ.

## Starting up rotary axis parameters

Rotary axis channel1					
Kinematics	Inclinable head	Name:	HEAD_2	No.:	2
<b>Rot. axis 1</b>	Identifier	B	Mode	Manual	
	Angle area	0.000	-	360.000	deg
	Hirth teeth	Yes	Angle offset	0.000	deg
	Aut.override	No	Angle grid	2.500	deg
<b>Rot. axis 2</b>	Identifier	C	Mode	Manual	
	Angle area	-90.000	-	90.000	deg
	Hirth teeth	Yes	Angle offset	0.000	deg
	Aut.override	No	Angle grid	2.500	deg
	Swivel data record change	No			
	Tool changing	Automatically			



### Input of data relevant to the swivel cycle for rotary axes 1 and 2.

Name/kinematics → see CYCLE800 "Kinematics" start-up menu

#### Identifiers

\$TC\_CARR35[n] rotary axis 1

\$TC\_CARR36[n] rotary axis 2

Axis identifiers of rotary axes. The following identifiers should be chosen where possible:

Axis rotates about machine axis X --> A

Axis rotates about machine axis Y --> B

Axis rotates about machine axis Z --> C

If the axes of the NCU are known, the same axis identifiers of the relevant NC rotary axes must be selected (see automatic mode).

If the axes of the NCU are not known, no known identifiers can be used.

#### Mode

\$TC\_CARR37[n] see display options

- **Automatic**

NC rotary axes are automatically moved to the appropriate swivel angle

- **Manual**

**Rotary axes** are moved manually by the operator to the appropriate position. On the "plainest machines" with manually adjustable **rotary axes** (measuring system: Steel gauge), the axis identifier need not be registered with the NCU.



Even mixed machine kinematics (e.g. 1st rotary axis automatic, 2nd rotary axis manual), and "incomplete" machine kinematics (e.g. 1st rotary axis rotates around axis X) are allowed. If machine kinematics are to be implemented with just one rotary axis, this must always be declared as the 1st rotary axis.



For the swivel angle display, see display messages  
CYCLE800 → 62180/62181

#### Angular range

\$TC\_CARR30[n] .. \$TC\_CARR33[n]

A valid angular range must be assigned to each **rotary axis**. This must not be the software end position range of the particular rotary axis.

With modulo axes, enter a traversing range of between **0 and 360 degrees**.

#### Hirth tooth system

\$TC\_CARR26[n]... \$TC\_CARR29[n]

- **no**  
The fields below are concealed.
- **yes**
  - **Angular offset** of Hirth tooth system at beginning of gearing.
  - **Angular grid** of Hirth tooth system
  - **Automatic correction yes/no**  
The tool might exit the angular grid set for the Hirth tooth system if the swivel head jams. If this happens, the swiveled frame will need to be recalculated (TCOABS) with the current angular values (of the Hirth tooth system). This functionality is calculated by the **Automatic correction (yes)** setting in the swivel cycle.

#### Swivel data record change (only relevant for ShopMill/ShopTurn)

- **no**
- **automatic**
- **manual**

#### Tool change (only relevant for ShopMill/ShopTurn)

- **automatic**
- **manual**

"Tool change" display for kinematic type T and M only


3.16 Swiveling – CYCLE800 (SW 6.2 and higher)



Start-up examples for machine kinematics

Example 1: Swivel head 1 "HEAD\_1"

Rotary axis 1(C) (manual) about Z; rotary axis 2(A) (manual) about X  
(drawing not true-to-scale)



Kinematic channel1			
Kinematics	<b>Inclinable head</b>	Name:	HEAD_1 No.: 1
Retract:	X	Y	Z
Retract position			200.000
Offset vector I1	0.000	0.030	-63.000
Rotary axis vector V1	0.000	0.000	1.000
Offset vector I2	0.000	0.000	40.000
Rotary axis vector V2	1.000	0.000	0.000
Offset vector I3	0.000	-0.030	23.000
Display opt.			
Swivel mode:	axial +projection angle		
Direction:	Rot. axis 1		
Tracking TL	No		






### Example 2: Swivel head 2 "HEAD\_2"

Offset vector I1: Distance between point on **rotary axis 1** and the reference point of the tool

Offset vector I2: Distance between point on **rotary axis 2** and point on **rotary axis 1**

Offset vector I3: Distance between the reference point of the tool and the point on **rotary axis 2**



Kinematic channel1			
Kinematics	Inclinable head		Name: HEAD_2 No.: 2
Retract:	X	Y	Z
Retract position			200.000
Offset vector I1	0.000	-172.000	-265.800
Rotary axis vector V1	0.000	1.000	0.000
Offset vector I2	0.000	172.000	172.000
Rotary axis vector V2	0.000	-1.000	1.000
Offset vector I3	0.000	0.000	93.800
Display opt.			
Swivel mode:	axial + projection angle		
Direction:	Rot. axis 1		
Tracking TL	No		

### 3.16 Swiveling – CYCLE800 (SW 6.2 and higher)



#### Example 3: Table 2


In this example, the offset vectors are not defined as described for example 3, but as a closed system as defined below:

Offset vector I2: Distance between machine reference point and point on **rotary axis 1**

Offset vector I3: Distance between point on **rotary axis 1** and point on **rotary axis 2**

Offset vector I4: Distance between point on **rotary axis 2** and machine reference point

The advantage of this method is that the position values do not change in the unswiveled state, regardless of whether or not the swivel table is selected.



Kinematic channel1			
Kinematics	Swivel table	Name:	TABLE_2 No.: 3
Retract:	X	Y	Z
Retract position			100.000
Offset vector I2	0.000	-95.000	190.000
Rotary axis vector V1	0.000	-1.000	1.000
Offset vector I3	0.000	-380.000	160.000
Rotary axis vector V2	0.000	0.000	1.000
Offset vector I4	0.000	475.000	-350.000
Display opt.			
Swivel mode:	axial+projection angle+solid angle		
Direction:	Rot. axis 1		
Tracking TL	No		




#### Example 4: MIXED 2

In this example, the reference points of the toolholder and the tool are identical, as well as the reference points of the table and the machine.

Thus:  $I1 = -I2$  and  $I3 = -I4$

resulting in each case in a closed system.

The advantage of this method is that the position values do not change in the unswiveled state, regardless of whether the swivel head or table is selected.



## 3.16 Swiveling – CYCLE800 (SW 6.2 and higher)

Kinematic channel1			
Kinematics	Inclin.head+swivel table		Name: MIXED_2 No.: 4
Retract:	X	Y	Z
Retract position			100.000
Offset vector I1	0.000	0.000	-100.000
Rotary axis vector V1	0.000	1.000	1.000
Offset vector I2	0.000	0.000	100.000
Offset vector I3	300.000	-200.000	0.000
Rotary axis vector V2	0.000	0.000	-1.000
Offset vector I4	-300.000	200.000	0.000
Display opt.			
Swivel mode:	axial+projection angle+solid angle		
Direction:	Rot. axis 1		
Tracking TL	Yes		

### 3.16.5 User cycle TOOLCARR.spf




#### Customization by the machine manufacturer


All axis positions during swiveling are traversed by means of user cycle TOOLCARR.spf. This is called from the swivel cycle CYCLE800 or E\_TCARR (ShopMill) or F\_TCARR (ShopTurn). The cycle can be modified by the user (machine manufacturer during start-up) in order to cater to the properties of specific machines.

If the user cycle is not modified, during retraction before swiveling, axis Z (marker \_M41) or axis Z is moved first, followed by axes X, Y (marker \_M42).

The positions correspond to the start-up menu CYCLE800 "Kinematics" → retraction positions.



3.16 Swiveling – CYCLE800 (SW 6.2 and higher)




**Note on markers \_M20 to \_M37**

Markers \_M20 to \_M37 are distinguished by kinematics with two or one rotary axis. A distinction is also made between automatic rotary axes (known to the NCU) and manual rotary axes.

There is only ever one valid marker for the active swivel data record. Control via parameter/GUD7 variable \_TC\_ST.

3.16 Swiveling – CYCLE800 (SW 6.2 and higher)





**Note on ShopMill/ShopTurn**

In the user cycle Toolcarr.spf, cycle E\_SWIV\_H or F\_SWIV\_H is called under ShopMill/ShopTurn (see markers \_M2 to \_M9).

E\_SWIV\_H parameters (Par 1, Par 2, Par 3)

- Par 1: Number of the swivel data record (\_TC1)
- Par 2: Angle of the 1st rotary axis
- Par 3: Angle of the 2nd rotary axis

Modification examples:

If the rotary axes (swivel head/table) are **not to be positioned** for swivel data change/tool change, the call of cycle E\_SWIV\_H can be commented out at the relevant markers.


If the rotary axes are to move to a certain position, an angle value can be transferred in parameters Par 2, Par 3.

## 3.16.6 Error messages



## Explanation

## Alarm source CYCLE800

Alarm number	Alarm text	Explanation, remedy
61180	"No name assigned to swivel data record even though machine data \$MN_MM_NUM_TOOL_CARRIER > 1" exist	No name assigned to swivel data record even though several swivel data records (\$MN_MM_NUM_TOOL_CARRIER>0) or no swivel data record defined (\$MN_MM_NUM_TOOL_CARRIER=0)
61181	"NCK software version too old (no TOOLCARRIER functionality)"	TOOLCARRIER functionality as from NCU 6.3xx
61182	"Name of swivel data record unknown"	See Swivel cycle start-up CYCLE800 → Kinematics Name (swivel data record)
61183	"Retraction mode GUD7 _TC_FR outside value range 0..2"	See Swivel cycle start-up CYCLE800 → Retraction; 1st transfer parameter CYCLE800(x,...) is faulty >2
61184	"No solution can be found with current angle inputs"	
61185	"Rotary axis angle ranges incorrect (min>max) or not defined"	Check start-up of swivel cycle CYCLE800
61186	"Invalid rotary axis vectors"	Swivel cycle start-up CYCLE800: Rotary axis vector V1 or V2 not entered or incorrect
61187	"Block search computation end of block not valid for SWIVEL"	Select block search with calculation contour
61188	"No axis name 1st rotary axis declared"	Swivel cycle start-up CYCLE800: no entry under rotary axis 1 identifier
62180	"Set rotary axes x.x [deg]"	Angles to be set for manual rotary axes
62181	"Set rotary axes x.x [deg]"	Angle to be set for manual rotary axis
 Typical display of the swivel angle to be set for a manual rotary axis in CYCLE800		
62180	"Set rotary axes B: 32.5 [deg]"	


### 3.17 High Speed Settings – CYCLE832 (SW 6.3 and higher)



The standard cycle High Speed Settings CYCLE832 is available for the HMI in SW 6.3 and higher and NCU SW 6.3 (CCU SW 4.3).

Application of CYCLE832:

- for technological support when machining free-form contours (surfaces) in the 3- or 5-axis high-speed machining range (High Speed Cutting - HSC)
- used predominantly in the HSC milling range (possibility of use for turning or grinding)
- groups the important G codes and machine and setting data that are needed for HSC machining
- technology / geometry separation by relevant NC program architecture



When executing CAM programs in the HSC range, the control has to process high feedrates with the shortest NC blocks. The user expects a good **surface finish** with great **accuracy** in the 1  $\mu\text{m}$  range with extremely high **machining feedrates** >10 m/min. By applying different machining strategies, the user can fine-tune the program with the aid of CYCLE832.

When **roughing**, smoothing the contour puts the weighting on **speed**.

When **finishing**, enabling the NC block compressor puts the weighting on **accuracy**.

In both cases, specifying a tolerance retains the machining contour in order to achieve the desired surface finish.

When defining the tolerance values for smoothing the contour, the operator must have precise knowledge of the subsequent CAM program. The CYCLE832 cycle supports machine types where a maximum of three linear and two rotary axes are involved in the machining.

The following functions can be defined or enabled/disabled by CYCLE832:

- Tolerance band of the contour to be machined
- Smoothing (G64, G641, G642)
- NC block compressor (COMPCAD, COMPCURV, COMPOF)<sup>1)</sup>
- Feedforward control (FFWON, FFWOF)
- Jerk limitation (SOFT, BRISK)
- 5-axis transformation (TRAORI, TRAF OF)<sup>1)</sup>
- B spline

1) only if the relevant option is set.



### Function

The CYCLE832 cycle groups the important G codes and the machine or setting data required for HSC machining. In CYCLE832, a distinction is made between three technological executions:

- "Finishing",
- "Rough-finishing" and
- "Roughing".

In CAD programs, the three machining types are in the HSC range in direct relation to the accuracy and speed of the path contour (see help display). The operator / programmer uses the **tolerance value** to give relevant weighting.

Different tolerances and settings (customizing technology) can be assigned to the three machining types.

In the input screen form, the relevant G codes are preset (customizing technology) to ensure a smoothing path contour or that the CAM program is executed at optimum speed.

The cycle is located in the main menu before the CAM program (see typical CYCLE832 call).

Different interpretations of the tolerance values are taken into account. For example, for G641, the tolerance value is transferred as ADIS= and for G642, the axis-specific MD 33100 COMPRESS\_POS\_TOL[AX] is updated.

When activating the "Customize technology" input field, you can enable or disable:

- compression (COMPCAD, COMPCURV, COMPOF, B-SPLINE),
- continuous-path mode (G64, G641, G642) or
- velocity control (FFWON, FFWOF, SOFT, BRISK).

If 5-axis transformation (TRAORI) is set up, this can be enabled/disabled in the transformation input field.



Take note of the machine manufacturer's comments!

Calling the "Machining deselection" cycle resets the changed machine/setting data to the value generated by the machine manufacturer (machine data settings).

If the machine manufacturer wants an additional CYCLE832 response that goes beyond the customization of the technology, the cycle can be copied to the directory CMA.dir (HMI manufacturer) and loaded to the NCU. In this case, CYCLE832.spf in CST.dir (HMI standard cycle directory) must be unloaded. The machine manufacturer must document the changes.

#### Typical CYCLE832 call

---

T1 D1

---

G54

---

M3 S12000

---

**CYCLE832(0.2,1003)**

---

EXTCALL "CAM\_Form\_Schrupp"

---

**CYCLE832(0.01,102001)**

---

EXTCALL "CAM\_Form\_Schlicht"

---

M02

---



CYCLE832 does not absolve the machine manufacturer from the requisite optimization tasks when commissioning the machine. This involves the optimization of the axes involved in machining and the settings of the NCU (block search, feedforward control, jerk limitation, etc.).

#### Reduced program call

The following call options of CYCLE832 with a reduced parameter transfer are possible:

- CYCLE832() corresponds to the selection of interactive screen form "Machining" "Deselection"
- CYCLE832(0.01) Entering the tolerance value.  
The active G commands are not changed in the cycle.

### 3.17.1 Calling CYCLE832 in the HMI menu tree



#### Description of parameters

Entry area Programs / **Milling**

Soft key  →

is displayed.

Interactive screen form CYCLE832 on standard interface

#### Machining (\_TOLM)

- Finishing (default)
- Rough-finishing
- Roughing
- Deselection.

For variable \_TOLM coding see Subsection 3.17.2, Parameters.

At "Machining deselection", the G commands or the setting/machine data return to the value generated by the machine manufacturer.

#### Tolerance (\_TOL)

The tolerance of the axes (corresponds to MD 33100: COMPRESS\_POS\_TOL[AX]) involved in machining. The tolerance value is effective for G642 and for COMPCURV or COMPCAD. If the machining axis is a rotary axis, the tolerance value is written with a factor (default factor = 8) to MD 33100: COMPRESS\_POS\_TOL[AX] of the rotary axis.

With G641, the tolerance value corresponds to the ADIS value.

On initial entry, the following values are set for the tolerance:

- **Finishing:** 0.01 (linear axes) 0.08 deg (rotary axes)
- **Rough-finishing:** 0.05 (linear axes) 0.4 deg (rotary axes)
- **Roughing:** 0.1 (linear axes) 0.8 deg (rotary axes)
- **Deselection:** 0.1 (linear axes) 0.1 deg (rotary axes)

The mm/inch system of units is taken into account.



If the tolerance value is also to be effective for rotary axes, 5-axis transformation must be set up by the machine manufacturer.

#### Transformation (**\_TOLM**)

The transformation input field is only displayed when the NC option is set (machining package 5 axes set).

- **No**  
CAM programs with resolved rotary axis positions are supported.
- **TRAORI**
- **TRAORI(2)**

Selection of the transformation number or of the manufacturer cycle to call 5-axis transformation. The parameter is in relation to the following GUD7 variables **\_TOLT2**.

The name of a manufacturer cycle can be stored, resulting in calling the manufacturer cycle of transformation. If **\_TOLT2** is empty ("" default), selection transformation 1,2... calls the 5-axis transformation with **TRAORI(1)**, **TRAORI(2)**.

#### Customization, customizing the technology

(see subsection 3.17.3)

- **Yes**
- **No**

The subsequent input parameters can only be changed if customization is set to "Yes".

**Compression, NC block compressor (\_TOLM)**

- **None** (COMPOF)
- **COMPCAD** (default)
- **COMPCURV**
- **B SPLINE**



The input field is only displayed if the compressor function option is set.

The selection B spline is only made if the option spline interpolation is set.

Option → A, B and C splines/compressor function

**Path control (\_TOLM)**

- **G642** (default)
- **G641**
- **G64**

With NC block compressor with COMPCAD, COMPCURV, G642 is always the permanent selection.

**Feedforward control, velocity control (\_TOLM)**

- **FFWON SOFT** (default)
- **FFWOF SOFT**
- **FFWOF BRISK**

The selection of feedforward control (FFWON) and jerk limitation (SOFT) presupposes that the machine manufacturer has optimized the control or the machining axes.



### 3.17.2 Parameters




#### Programming

CYCLE832(\_TOL, \_TOLM)



#### Parameters

_TOL	real	Tolerance of machining axes → Unit. mm/inch; deg
_TOLM	int	Tolerance mode



1) Setting may be changed by machine manufacturer, see Section "Customizing technology"

### 3.17.3 Customizing technology



With input field "Customizing technology" "Yes", both the machine manufacturer and the operator/programmer can customize the technology for HSC machining.

Always take note of the technology of the subsequent CAM program.

#### Customization by the machine manufacturer

Preconditions:



- **The manufacturer password is set,**
- Input field "Customizing technology" → "Yes"

When the interactive cycle screen form CYCLE832 is opened, the parameters are preassigned with the values of GUD7 variables `_TOLV[n]`, `_TOLT[n]`. (n = machining: finishing, rough-finishing, roughing, deselection)

When the parameters are changed, the values are written directly to the GUD7 variables `_TOLV[n]` or `_TOLT[n]`.

This gives the machine manufacturer the opportunity to customize the basic settings to his machining tasks.

Example:

Calling cycle CYCL832 roughing with three axes machining axes tolerance 0.1mm with G642 (Siemens default values).

The machine manufacturer can modify the roughing technology with setting: machining axes tolerance 0.3mm, TRAORI, G641.

Each time the tolerance cycle is called, this setting is then displayed and takes effect during the execution.



#### Notes for the machine manufacturer

1. In order to optimize the path control response when traversing with G64, in CYCLE832, the velocity jumps overload factor is recalculated in accordance with the following table:

#### Computation of the velocity jumps overload factor of all the machining axes

IPO [msec]	Overload factor
≥ 12	1.2
9	1.3
6	1.4
4	1.6
3	1.8

IPO: MD 10071: \$MN\_IPO\_CYCLE\_TIME

Overload factor MD 32310:

\$MA\_MAX\_ACCEL\_OVL\_FACTOR[AX]

Computation of the overload factor by CYCLE832 can be disabled by setting the local variable (CYCLE832) **\_OVL\_on=0**.

2. The tolerance for the active NC block compressor or for smoothing is written in CYCLE832 to MD 33100:  
\$MA\_COMPRESS\_POS\_TOL[AX] (linear machining axes). If rotary axes are involved in the machining (TRAORI) this tolerance is written with **factor 8** to MD 33100:  
\$MA\_COMPRESS\_POS\_TOL[AX] of the rotary axes. If a different factor is to be used, the local variable (CYCLE832) **\_FAKTOR** can be preassigned with the relevant value.

#### Customization by the operator/programmer

Preconditions:



- **The manufacturer password is deleted,**
- Input variable "Customizing technology" → "Yes".

To customize the technology, the operator/programmer must have precise knowledge of the subsequent CAM machining program.

The modified data is used to generate CYCLE832. The next time the tolerance cycle is called, the settings of the machine manufacturer will take effect again (GUD7 variables **\_TOLV[n]**, **\_TOLT[n]** are not changed).

### 3.17.4 Interfaces



#### G codes

List of the G commands programmed in CYCLE832:

- G64, G641, G642
- G601
- FFWON, FFWOF
- SOFT, BRISK
- COMPCAD, COMPCURV, COMPOF, B-SPLINE
- TRAORI, TRAORI(2), TRAOFF
- UPATH

Note: The G commands should not be generated in the subsequent CAM program. Technology – Geometry separation.



#### Machine data

The following machine data is evaluated in cycle CYCLE832:

MD No.	MD identifiers	Comments
10071	\$MN_IPO_CYCLE_TIME	– interpolation cycle
20480	\$MC_SMOOTHING_MODE	
20482	\$MC_COMPRESSOR_MODE	
20490	MC_IGNORE_OVL_FACTOR_FOR_ADIS	

The following machine data is rewritten in cycle CYCLE832:

MD No.	MD identifiers	Comments
33100	COMPRESS_POS_TOL[AX]	Geometry axes 1...3
33100	COMPRESS_POS_TOL[AX]	Rotary axes 1 and 2 <sup>1)</sup>
32310	MAX_ACCEL_OVL_FACTOR[AX]	Geometry axes 1...3
32310	MAX_ACCEL_OVL_FACTOR[AX]	Rotary axes 1 and 2 <sup>1)</sup>

1) as per 5-axis transformation machine data



#### Setting data

List of setting data rewritten in CYCLE832:

SD no.	SD identifier	Comments
42465	\$SC_SMOOTH_CONTUR_TOL	Corresp. to the tolerance of the linear axes
42466	\$SC_SMOOTH_ORI_TOL	Corresp. to the tolerance of the rotary axes
42475	\$SC_COMPRESS_CONTUR_TOL	for COMPCURV only
42476	\$SC_COMPRESS_ORI_TOL	for COMPCURV only
42477	\$SC_COMPRESS_ORI_ROT_TOL	for COMPCURV only

1) The efficiency of setting data \$SC\_SMOOTH\_CONTUR\_TOL and \$SC\_SMOOTH\_ORI\_TOL depends on MD20480: \$MC\_SMOOTHING\_MODE.  
The efficiency of setting data \$SC\_COMPRESS\_CONTUR\_TOL and \$SC\_COMPRESS\_ORI\_TOL depends on MD20482: \$MC\_COMPRESSOR\_MODE



### GUD7 global variables

The following global variables must be activated for CYCLE832 functionality (machine manufacturer).

The definitions are a component of the GUD7 definitions of the SIEMENS standard cycle package.

Parameters	Format	Assignment	Comments
<code>_TOLT2[ 2 ]</code>	STRING[32]	"" (default)	Program name of the subroutine for calling 5-axis transformation
<code>_TOLT[ 4 ]</code>	int	<b>Field (4):</b> 0: Deselection 1: Finishing 2: Rough-finishing 3: Roughing	Field for saving the technological data settings of the machine manufacturer Coding corresponds to variable <code>_TOLM</code> (see parameters)
<code>_TOLV[ 4 ]</code>	real	<b>Field (4):</b> 0: Deselection 1: Finishing 2: Rough-finishing 3: Roughing	Field for saving the the tolerance values of the machining axes through the machine manufacturer settings (see customizing the technology). Default values: 0.1 Deselection (GUD7.def) 0.01 Finishing 0.05 Rough-finishing 0.1 Roughing

## 3.17.5 Error messages



## Explanation

## Alarm source CYCLE832

Alarm number	Alarm text	Explanation, remedy
61191	"5-axis transformation not set up"	1. Machining package five axes option or multi-axis interpolation not set.
61192	"Second 5-axis transformation not set up"	2. Check MD 24100: \$MC_TRAFO_TYPE_1 to \$MC_TRAFO_TYPE_8 for a valid 5-axis transformation type
61193	"Compressor option not set up"	Set spline interpolation option (A, B and C
61194	"Spline interpolation option not set up"	splines/compressor function



## Turning Cycles

4.1	General information.....	4-272
4.2	Preconditions.....	4-273
4.3	Grooving cycle – CYCLE93.....	4-277
4.4	Undercut cycle – CYCLE94.....	4-287
4.5	Stock removal cycle – CYCLE95 .....	4-291
4.6	Thread undercut – CYCLE96 .....	4-304
4.7	Thread cutting – CYCLE97 .....	4-308
4.8	Thread chaining – CYCLE98.....	4-316
4.9	Thread recutting (SW 5.3 and higher).....	4-323
4.10	Extended stock removal cycle – CYCLE950 (SW 5.3 and higher) .....	4-325

## 4.1 General information

The following sections describe how turning cycles are programmed. This section is intended to guide you in selecting cycles and assigning them with parameters. In addition to a detailed description of the function of the individual cycles and the corresponding parameters, you will also find a programming example at the end of each section to familiarize you with the use of cycles.

The sections are structured as follows:

- **Programming**
- **Parameters**
- **Function**
- **Sequence of operations**
- **Explanation of parameters**
- **Additional notes**
- **Programming example.**

"Programming" and "Parameters" explain the use of cycles sufficiently for the experienced user, whereas beginners can find all the information they need for programming cycles under "Function", "Sequence of operations", "Explanation of parameters", "Additional notes" and the "Programming example".



## 4.2 Preconditions

### Data block for turning cycles

The turning cycles require module GUD7.DEF. It is supplied on diskette together with the cycles.

### Call and return conditions

The G functions active before the cycle is called and the programmable frame remain active beyond the cycle.

### Plane definition


The machining plane must be defined before the cycle is called. In the case of turning, this is usually the G18 (ZX) plane. The two axes of the turning plane are referred to below as the longitudinal axis (first axis of this plane) and the plane axis (second axis of this plane).

If diameter programming is active, the second axis of the plane is always taken as facing axis (see Programming Guide).

### Spindle handling

The turning cycles are written in such a way that the spindle commands always refer to the active master spindle of the control.

If you want to use a cycle on a machine with several spindles, the active spindle must first be defined as the master spindle (see Programming Guide).



**Machining status messages**

Status messages are displayed on the control monitor during processing of the turning cycles. The following messages can be displayed:

- "Thread start <No.> – longitudinal thread machining"
- "Thread start <No.> – face thread machining"

In each case <No.> stands for the number of the figure that is currently being machined.

These messages do not interrupt program processing and continue to be displayed until the next message is displayed or the cycle is completed.

**Cycle setting data**

For the stock removal cycle CYCLE95, Software Release 4 and higher has provision for setting data that is stored in module GUD7.DEF.

Cycle setting data `_ZSD[0]` can be used to vary the calculation of the depth infeed MID in CYCLE95. If it is set to zero, the parameter is calculated as before.

- `_ZSD[0]=1` MID is a radius value
- `_ZSD[0]=2` MID is a diameter value

For the groove cycle CYCLE93, software release 4 and higher has provision for setting data in module GUD7.DEF. This cycle setting data `_ZSD[4]` can affect the retraction after the 1st groove.

- `_ZSD[4]=1` Retraction with G0
- `_ZSD[4]=0` Retraction with G1 (as before)

With SW 6.2 and higher, there is an option for setting mirroring behavior in `_ZSD[6]` for grooving cycle CYCLE93.

- `_ZSD[6]=0` The tool offsets are exchanged in the cycle when mirroring is active (for use without orientatable toolholder)
- `_ZSD[6]=1` The tool offsets are not exchanged in the cycle with active mirroring (for use with orientatable toolholder)

### Contour monitoring with respect to tool clearance angle

Some turning cycles in which travel movements with relief cutting are generated monitor the tool clearance angle of the active tool for possible contour violation.

This angle is entered as a value in the tool offset (under parameter P24 in the D offset).

An angle between 0 and 90 degrees is entered without a sign.

When entering the tool clearance angle, remember that this depends on whether machining is longitudinal or facing. If a tool is to be used for longitudinal and face machining, two tool offsets must be applied if the tool clearance angles are different.

A check is made in the cycle to determine whether the programmed contour can be machined with the selected tool.



If machining is not possible with this tool, then

- the cycle is terminated with an error message (while cutting) or
- contour machining continues and a message is output (in undercut cycles). The tool nose geometry then determines the contour.

Note that active scale factors or rotations in the current plane modify the relationships at the angles, and that this cannot be allowed for in the contour monitoring that takes place within the cycle.

If the tool clearance angle is specified as zero in the tool offset, this monitoring function is deactivated.

The precise reactions are described in the various cycles.



## 4.2 Preconditions

### Turning cycles with active adapter transformation

With NCK SW 6.2 and higher, turning cycles can also be executed with an active adapter transformation. The transformed tool offset data for the tool point direction and clearance angle are always read.

### 4.3 Grooving cycle – CYCLE93



#### Programming

CYCLE93 (SPD, SPL, WIDG, DIAG, STA1, ANG1, ANG2, RCO1, RCO2, RCI1, RCI2, FAL1, FAL2, IDEP, DTB, VARI, \_VRT)





#### Parameters

SPD	real	Starting point in the facing axis (enter without sign)
SPL	real	Starting point in the longitudinal axis
WIDG	real	Width of groove (enter without sign)
DIAG	real	Depth of groove (enter without sign)
STA1	real	Angle between contour and longitudinal axis Value range: $0 \leq \text{STA1} \leq 180$ degrees
ANG1	real	Flank angle 1: on the side of the groove defined by the starting point (enter without sign) Value range: $0 \leq \text{ANG1} < 89.999$ degrees
ANG2	real	Flank angle 2: on the other side (enter without sign) Value range: $0 \leq \text{ANG2} < 89.999$
RCO1	real	Radius/chamfer 1, outside: on the side defined by the starting point
RCO2	real	Radius/chamfer 2, outside
RCI1	real	Radius/chamfer 1, inside: on the starting point side
RCI2	real	Radius/chamfer 2, inside
FAL1	real	Final machining allowance on the base of the groove
FAL2	real	Final machining allowance on the flanks
IDEP	real	Infeed depth (enter without sign)
DTB	real	Dwell time at base of groove
VARI	int	Type of machining Value range 1...8 and 11...18
_VRT	real	Variable retraction distance from contour, incremental (enter without sign)
from SW 6.2 and higher		



### Function

With the grooving cycle you can make symmetrical and asymmetrical grooves for longitudinal and traverse machining on straight contour elements. You can machine both external and internal grooves.




### Sequence of operations


The depth infeed (towards the base of the groove) and infeed across the width (from groove to groove) are distributed evenly and with the greatest possible value. If the groove is being machined on an inclined surface, travel from one groove to the next follows the shortest path, i.e. parallel to the cone on which the groove is being machined. The safety distance to the contour is calculated in the cycle.

**1st step**


Paraxial roughing to the base of the groove in single infeed steps. After each infeed, the tool is retracted for chip breaking.

**2nd step**

The groove is machined perpendicular to the infeed direction in one or more cuts. Each cut is again divided up according to the infeed depth. From the second cut along the groove width the tool is withdrawn by 1 mm before it is fully retracted.

**3rd step**


Cutting of the flanks in one step, if angles are programmed under ANG1 or ANG2. The infeed along the groove width is performed in several steps if the flank width is larger.



### 4.3 Grooving cycle – CYCLE93

#### 4th step

Cutting of final machining allowance parallel to the contour from the edge to the center of the groove. The tool radius compensation is automatically selected and deselected by the cycle.







### Description of parameters



#### SPD and SPL (starting point)

You define the starting point of the groove from where the cycle calculates the shape with these coordinates. The cycle itself determines the starting point to be approached at the beginning. In the case of an external groove, the longitudinal axis direction is first traversed and in the case of an internal groove, the facing axis direction is first traversed. Grooves on curved surfaces can be created in a variety of ways. Depending on the shape and radius of the curve, either a paraxial straight line can be placed on the maximum of the curve or a tangential oblique line can be placed on one of the edge points of the groove.

Radii and chamfers on the groove edge of a curved surface should only be programmed if the edge point in question is positioned on the straight line defined for the cycle.

#### WIDG and DIAG (groove width and groove depth)

The shape of the groove is defined with the parameters groove width (WIDG) and groove depth (DIAG). The cycle always starts its calculation from the point programmed with SPD and SPL. If the groove is wider than the active tool, the groove is machined in several steps. The total width is divided into equal sections in the cycle. The maximum infeed is 95 percent of the tool width after subtracting the tool nose radii. This ensures a cut overlap.



### 4.3 Grooving cycle – CYCLE93

If the programmed groove width is less than the actual tool width, the error message 61602 "Tool width incorrectly defined" is output, the cycle is not started and machining is aborted. The alarm is also output if the value zero has been entered for the tool nose width.

#### STA1 (angle)

The angle of the oblique surface on which the groove is to be machined is programmed with parameter STA1. The angle can have any value between 0 and 180 degrees and always refers to the longitudinal axis.



#### ANG1 and ANG2 (flank angle)

Asymmetrical grooves can be described by separate flank angles. The angles can be assigned any value between 0 and 89.999 degrees.

#### RCO1, RCO2 and RC11, RC12 (radius/chamfer)

The shape of the groove can be modified by entering radii/chamfers for the edge or base of the groove. The values for the radii must always be positive, the values for the chamfers must always be negative. You can use the tens setting for the VARI parameter to determine the type of calculation for programmed milling.

- With  $VARI < 10$  (tens=0) the absolute value of this parameter is regarded as chamfer length (chamfering with CHF programming).
- With  $VARI > 10$ , it is regarded as path length (chamfering with CHR programming).



**FAL1 and FAL2 (machining allowance)**

You can program separate final machining allowances for the groove base and the flanks. Roughing is performed to this final machining allowance. Then, the same tool is used to machine a contour-parallel cut along the final contour.

**I DEP (infeed depth)**

By programming an infeed depth you can divide the paraxial grooving action into several depth infeeds. After every infeed, the tool is retracted for chipbreaking by 1 mm or, from SW 6.2 or higher onwards, by the distance programmed under `_VRT`. Parameter `I DEP`, anyway, is to be programmed.

**DTB (dwell time)**

A dwell time at the base of the groove should be chosen that allows at least one spindle revolution. The dwell time is programmed in seconds.

**VARI (type of processing)**

The units digit of the `VARI` parameter determines the type of processing for the groove. This parameter can be assigned any of the values shown in the figure.


The tens value of the `VARI` determines the type of calculation for the chamfer.

`VARI 1...8`: Chamfers are calculated as CHF

`VARI 11...18`: Chamfers are calculated as CHF

Input of the ones position in cycle support is distributed among three selection fields:

1. Field: longitudinal/plane
2. Field: external/internal
3. Field: starting point left/right (for longitudinal) or top/bottom (for plane)



VARI		Selection of cycle support
1/11		longitudinal, external, left
5/15		longitudinal, external, right
3/13		longitudinal, internal, left
7/17		longitudinal, internal, right
6/16		plane, external, top
8/18		plane, external, bottom
2/12		plane, internal, top
4/14		plane, internal, bottom

If the parameter is assigned another value, the cycle is aborted and alarm

61002 "Machining type incorrectly programmed".

is output.

The contour monitoring performed by the cycle ensures that a realistic groove contour results. This is not the case if the radii/chamfers touch each other at the base of the groove or overlap or if an attempt at face grooving is made on a section of the contour that runs parallel to the longitudinal axis. In these cases, the cycle is aborted with alarm 61603 "Groove form incorrectly defined".

#### **\_VRT (variable retraction path)**

With SW 6 and higher, the retraction path can be programmed on the basis of the outside or inside diameter of the groove in parameter `_VRT`. If `_VRT=0` (parameter not programmed), liftoff is 1mm.

The retraction path is always measured in the programmed system of units inch or metric.

The same retraction path is also used for chip-breaking after each depth infeed into the groove.



### Further notes

You must activate a double-edged tool before calling the grooving cycle. You must enter the offset values for the two tool edges in two successive D numbers of the tool, the first of which must be activated before the cycle is called. The cycle determines itself which of the two tool offsets it requires for which machining step and activates them automatically. After the cycle is completed, the offset number programmed before the cycle call becomes active again. If no D number has been programmed for a tool offset when the cycle is called, the cycle is aborted with alarm 61000 "No tool offset active" and the cycle is aborted.

For SW 5.1 and higher, cycle setting data `_ZSD[4]` can be used to influence the retraction after the 1st groove.

`_ZSD[4]=0` means retraction with G1 as before,  
`_ZSD[4]=1` means retraction with G0.

With SW 6.2 and higher, cycle data `_ZSD[6]` can be set to define how the tool offset is handled in the cycle.

`_ZSD[6]=0` TO is exchanged internally in the cycle  
(without orientatable toolholder)

`_ZSD[6]=1` TO is not exchanged internally in the cycle  
(with orientatable toolholder)

## 4.3 Grooving cycle – CYCLE93



## Programming example


## Grooving

This program machines a groove on an oblique surface (longitudinal, outside).

The starting point is at X35 Z60.

The cycle uses tool offsets D1 and D2 of tool T1.

The grooving tool must be defined correspondingly.



<pre>DEF REAL SPD=35, SPL=60, WIDG=30, -&gt; -&gt; DIAG=25, STA1=5, ANG1=10, ANG2=20, -&gt; -&gt; RCO1=0, RCI1=-2, RCI2=-2, RCO2=0, -&gt; -&gt; FAL1=1, FAL2=1, IDEP=10, DTB=1 DEF INT VARI=5</pre>	Definition of parameters with value assignments
<pre>N10 G0 G18 G90 Z65 X50 T1 D1 S400 M3</pre>	Starting point before the beginning of the cycle
<pre>N20 G95 F0.2</pre>	Specification of technology values
<pre>N30 CYCLE93 (SPD, SPL, WIDG, DIAG, -&gt; -&gt; STA1, ANG1, ANG2, RCO1, RCO2, -&gt; -&gt; RCI1, RCI2, FAL1, FAL2, IDEP, -&gt; -&gt; DTB, VARI)</pre>	Cycle call
<pre>N40 G0 G90 X50 Z65</pre>	Next position
<pre>N50 M02</pre>	End of program

-> Must be programmed in a single block

## 4.4 Undercut cycle – CYCLE94



### Programming

CYCLE94 (SPD, SPL, FORM, \_VARI)



### Parameters

SPD	real	Starting point in the facing axis (enter without sign)
SPL	real	Starting point of the contour in the longitudinal axis (enter without sign)
FORM	char	Definition of the form Values: E (for form E) F (for form F)
_VARI	int	Specification of undercut position
(SW 6.2 and higher)		Values: 0 According to tool point direction 1...4 Define position




### Function

With this cycle you can machine undercuts of form E and F in accordance with DIN509 with the usual load on a finished part diameter of >3mm.



Another cycle CYCLE96 exists for producing thread undercuts (see Section 4.6).





### Sequence of operations

#### Position reached prior to cycle start:

The starting position can be any position from which the undercut can be approached without collision.

#### The cycle implements the following motion sequence:

- Approach to the starting point calculated in the cycle with G0
- Selection of tool nose radius compensation according to active tool point direction and traversal of undercut contour at feedrate programmed prior to cycle call
- Retraction to the starting point with G0 and deselection of the tool nose radius compensation with G40




### Description of parameters

#### SPD and SPL (starting point)

The finished part diameter for the undercut is entered in parameter SPD. With parameter SPL you define the finished part dimensions in the longitudinal axis.

If the value programmed for SPD results in a final diameter that is <3mm, the cycle is aborted with the alarm 61601 "Finished part diameter too small". is output.






**FORM (definition)**

Form E and Form F are defined in DIN509 and determined by this parameter.

If the parameter is assigned a value other than E or F, the cycle is aborted and alarm 61609 "Form incorrectly defined" is output.


**\_VARI (undercut position)**

The position of the undercut can be either specified directly or derived from the tool point direction with parameter `_VARI`.

`VARI=0`: According to tool point direction

The cycle automatically determines the tool point direction from the active tool offset. The cycle can then only work with tool point directions 1 to 4.


If the cycle recognizes a tool point direction 5 ... 9, alarm 61608 "Wrong tool point direction programmed" is output and the cycle is aborted.



`_VARI=1...4`: Definition of undercut position

The cycle determines the starting point automatically. This lies 2mm from the final diameter and 10mm from the final dimension in the longitudinal axis. The position of this starting point in relation to the programmed coordinate values is determined by the tool point direction of the active tool.

The cycle monitors the clearance angle of the active tool if a value has been assigned to the relevant parameter of the tool offset. If the cycle ascertains that the undercut form cannot be machined with the selected tool because the clearance angle is too small, the message "Altered undercut form" appears on the control, but machining is continued.



## 4.4 Undercut cycle – CYCLE94

When `_VARI<>0` the following applies:

- The actual tool point direction is not checked, i.e. all directions can be used if this is meaningful technologically,
- No special consideration is given to functions such as adapter transformation, orientatable toolholder in the cycle. It is assumed that the user is familiar with the conditions on the machine and has specified the position correctly;
- Similarly, mirroring is not specially treated either, the user must be responsible for making the correct settings.


### Further notes

You must activate a tool offset before you call the cycles. Otherwise alarm 61000 "No tool offset active" is output and the cycle is aborted.

### Programming example

#### Undercut\_form\_E

You can machine an undercut of form E with this program.



```
N10 T25 D3 S300 M3 G18 G95 F0.3
```

Specification of technology values

```
N20 G0 G90 Z100 X50
```

Selection of starting position

```
N30 CYCLE94 (20, 60, "E")
```

Cycle call

```
N40 G90 G0 Z100 X50
```

Approach next position

```
N50 M02
```

End of program

## 4.5 Stock removal cycle – CYCLE95



### Programming

CYCLE95 (NPP, MID, FALZ, FALX, FAL, FF1, FF2, FF3, VARI, DT, DAM, \_VRT)




### Parameters

NPP	string	Name of the contour subroutine
MID	real	Infeed depth (enter without sign)
FALZ	real	Final machining allowance in the longitudinal axis (enter without sign)
FALX	real	Final machining allowance in the facing axis (enter without sign)
FAL	real	Final machining allowance along contour (enter without sign)
FF1	real	Feedrate for roughing without relief cut
FF2	real	Feedrate for insertion into relief cut elements
FF3	real	Feedrate for finishing
VARI	int	Type of machining Value range: 1 ... 12 HUNDREDS DIGIT (SW 6.2 and higher): Values: 0...with rounding at the contour No residual corners will remain, the contour is rounded overlapping meaning that the contours are rounded over several points of intersection. 2...without rounding at the contour The machine always rounds to the previous roughing intersection and then retracts. Depending on the ratio of tool radius to infeed depth (MID), residual corners might be left.
DT	real	Dwell time for chip breaking during roughing
DAM	real	Path length after which each roughing cut is interrupted for chip breaking
_VRT	real	Retraction distance from contour for roughing, incremental (enter without sign)
With SW 4.4 and higher		



### Function

With this stock removal cycle you can machine a contour programmed in a subroutine from a blank with paraxial stock removal. Relief cut elements can be included in the contour. With this cycle, contours can be machined in the longitudinal and facing directions, inside and outside. The technology is freely selectable (roughing, finishing, complete machining). During roughing, paraxial cuts are generated from the maximum programmed infeed depth and when a point of intersection with the contour is reached, the residual corners are immediately removed cutting parallel to the contour. Roughing is performed to the programmed final machining allowance. Finishing is performed in the same direction as roughing. The tool radius compensation is automatically selected and deselected by the cycle.





### Sequence of operations

#### Position reached prior to cycle start:

The starting position can be any position from which the starting point of the contour can be approached without collision.

#### The cycle implements the following motion sequence:



- The cycle starting point is calculated in the cycle and then approached in both axes simultaneously with G0.

#### Roughing without relief cut elements:

- Paraxial infeed to the actual depth is calculated internally and then approached with G0.
- Approach roughing point paraxially with G1 and feedrate FF1.
- Machine parallel to the contour at contour + final machining allowance to the last roughing intersection point with G1/G2/G3 and FF1.
- Lift off contour by the amount programmed in `_VRT` in every axis and retraction with G0.
- This procedure is repeated until the total depth of the section to the machining step has been reached.
- When roughing without relief cut elements, retraction to the cycle starting point is effected axis by axis.

#### Roughing the relief cut elements:

- Approach the starting point for the next relief cut axis by axis with G0. An additional safety distance is calculated internally.
- Infeed parallel to the contour + final machining allowance with G1/G2/G3 and FF2.
- Approach roughing point paraxially with G1 and feedrate FF1.
- Machine to the last roughing point. Lift and retract as in the first machining section.
- If further relief cut elements are to be machined, repeat the above procedure for each relief cut element.



## 4.5 Stock removal cycle – CYCLE95

### Finishing:

- The calculated cycle starting point is approached in both axes simultaneously with G0 and tool nose radius compensation is selected.
- Both axes then continue to move; with G0 up to an amount final machining allowance + tool nose radius + 1 mm safety distance ahead of the contour starting point, and from there with G1 to the contour starting point.
- Finish cutting along the contour with G1/G2/G3 and FF3.
- Retraction to starting point with both axes and G0.



### Description of parameters

#### NPP (name)

Enter the name of the contour subroutine under this parameter. This contour subroutine must not be a subroutine with a parameter list.

Please use the name conventions described in the Programming Guide when naming the contour subroutine.

In SW 5.2 and higher, the machining contour can also be a section of the calling routine or from any other program. The section is identified by start or end labels or by block numbers. In this case, the program name and labels/block number are identified by an ":".

Examples:

NPP="CONTOUR\_1"


The machining contour is the complete program "Contour\_1".

NPP="START:END"

The machining contour is defined as the section starting from the block labeled START to the block labeled END in the calling routine.

NPP="/\_N\_SPF\_DIR/\_N\_CONTOUR\_1\_SPF:N130:N210"

The machining contour is defined in blocks N130 to N210 in program CONTOUR\_1. Write the full program name together with path and extension, refer to CALL description in the References: /PGA/ Programming Guide Advanced.



If the section is defined by block numbers, it must be noted that these block numbers for the section in NPP must be correspondingly adjusted if the program is modified and subsequently renumbered.

**MID (infeed depth)**

Under parameter MID you define the maximum possible infeed depth for the roughing operation.

The interpretation of this parameter depends on the cycle setting data for software release 4 and higher `_ZSD[0]` (see Section 4.2).

The cycle automatically calculates the actual infeed depth for roughing.


Where contours with relief cut elements are to be machined, the cycle divides up the roughing operation into single roughing steps. The cycle recalculates the actual infeed depth for every roughing step. This actual infeed depth always lies between the programmed infeed depth and half its value. The number of required roughing cuts is derived from the total depth of a roughing section and the programmed maximum infeed depth. The total depth to be machined is then divided equally amongst these roughing cuts. This method ensures optimum cutting conditions. The machining steps shown in the figure above are used for roughing this contour.

Example for the calculation of the actual infeed depths:

Machining section 1 has a total depth of 39mm. If the maximum infeed depth is 5mm, eight roughing cuts are required. These are performed with an infeed of 4.875mm.

In machining section 2, eight roughing cuts, each with an infeed of 4.5mm are also executed (total difference 36mm).

Machining section 3 is roughed twice with an actual infeed of 3.5 (total difference 7mm).



## 4.5 Stock removal cycle – CYCLE95

### FAL, FALZ and FALX (final machining allowance)

The final machining allowance for the roughing operation is either defined in parameters FALZ and FALX if you wish to enter different final machining allowances for each axis or in parameter FAL if you wish to enter a final machining allowance that follows a contour. In this case, this value is used for the final machining allowance in both axes.


The programmed values are not subjected to a plausibility check. If all three parameters are assigned values, all the final machining allowances are calculated by the cycle. It is, however, advisable to decide on one or the other form of final machining allowance definition.

**Roughing** is always performed to these final machining allowances. After each paraxial roughing operation the resulting residual corners are immediately cut parallel to the contour so that these do not have to be removed after the roughing operation is completed. If no final machining allowances have been programmed, roughing is performed to the final contour.

The **finish cut** machining mode does not consider programmed values. Turning always takes place down to finishing dimension.

### FF1, FF2 and FF3 (feedrate)

You can define different feedrates for the different machining steps as is shown in the figure on the right.





**VARI (machining types)**

You can call the machining types as follows:

Machining   
 (Roughing/Finishing/Complete)  
 Selection   
 (Longitudinal/Transverse)  
 Selection   
 (Outside/Inside)

The machining types are shown in the table below.

Value	Machining	Selection	Selection
1	Roughing	long.	outside
2	Roughing	transv.	outside
3	Roughing	long.	inside
4	Roughing	transv.	inside
5	Finishing	long.	outside
6	Finishing	transv.	outside
7	Finishing	long.	inside
8	Finishing	transv.	inside
9	Complete machining	long.	outside
10	Complete machining	transv.	outside
11	Complete machining	long.	inside
12	Complete machining	transv.	inside




*Infeed is always performed in the facing axis with longitudinal machining and in the longitudinal axis with face machining.*

*Outside machining means that infeed is performed in the direction of the negative axis. In inside machining, infeed is performed in the direction of the positive axis.*


*When roughing in CYCLE95, you can choose between "with rounding" or "without rounding" at the contour in SW 6.2 and higher. For doing so, the HUNDREDS DIGIT is implemented in parameter VARI.*

A plausibility check is performed on parameter VARI. If you select an invalid value, the cycle is aborted and alarm 61002 "Wrong machining type defined" is put out.



**DT and DAM (dwell time and path length)**

With these two parameters you can program an interruption in the individual roughing cuts after a defined path for the purposes of chip breaking. These parameters only apply to roughing. In parameter DAM you define the maximum path after which chip breaking is to be performed. In DT you can also program a dwell time to be included at each of the interruption points. If no path has been specified for cut interruption (DAM = 0), then uninterrupted roughing cuts without dwell times are generated.

**\_VRT (lift)**

With SW 4.4. and higher, the amount by which the tool is lifted off the contour in both axes during roughing operations can be programmed in parameter \_VRT.

If \_VRT=0 (parameter not programmed), liftoff is 1mm. The retraction distance is always measured in inches or metric depending on the programmed system, i.e. \_VRT=1 for inch → programming produces a tool retract of 1 inch.

**Further notes****Contour definition**

The contour is programmed in a subroutine whose name is defined as a parameter.

The contour subroutine must contain at least three blocks with movements in both axes of the machining plane.

The machining plane (G17, G18, G19) is set in the main program before the cycle is called or applied according to the basic setting of this G group on the machine. It cannot be altered in the contour subroutine.

If the contour subroutine is shorter, alarms 10933 "The contour subroutine contains too few contour blocks" and 61606 "Error in preprocessing contour" and the cycle is aborted.

Relief cut elements can be programmed consecutively.

Blocks without movement in the plane are not subject to any limitations.

All the traversing blocks for the first two axes in the current plane are preprocessed in the cycle as only these axes are involved in the machining operation. Movements for other axes can be included in the contour subroutine but their travel paths are suppressed during the cycle run.

The only geometry permitted in the contour are straight line and circular programming with G0, G1, G2 and G3. Commands for fillets and chamfers can also be programmed. If any other motion commands are programmed in the contour, it is aborted with alarm 10930 "Illegal interpolation type in the machining contour".

The first block containing a traversing movement in the current machining plane must contain a travel command G0, G1, G2 or G3, otherwise the cycle is aborted with the alarm 15800 "Wrong starting conditions for CONTPRON". This alarm is also activated when G41/G42 is active. The starting point of the contour is the first position on the machining plane programmed in the contour subroutine.

The maximum possible number of blocks for the contour containing travel commands for the current plane depends on the type of contour. In principle, there is no limit to the possible number of relief cuts.

If a contour contains more contour elements than the cycle memory can hold, the cycle is aborted with the alarm 10934 "Overflow contour table".

## 4.5 Stock removal cycle – CYCLE95

Machining must then be divided into several machining sections each of which is represented by its own contour subroutine and each cycle called separately.

If the maximum diameter in one contour subroutine is not within the programmed end point or starting point of the contour, the cycle automatically extends a paraxial straight line to the maximum point of the contour at the end of the machining operation and this part of the contour is then removed as a relief cut.

If any of the following are programmed in the contour subroutine:

- Radius compensation plane with G17/G18/G19
- Frames
- An axis of the plane in which machining is performed is traversed as a positioning axis
- Selection of tool radius compensation with G41/G42


alarm 10931 "Incorrect machining contour" is activated and aborts the cycle.

### Contour direction

With SW 4.4 and higher, the direction in which the stock removal contour can be programmed is freely selectable. The machining direction is automatically defined in the cycle. With complete machining operations, the contour is finished in the same direction in which rough cutting took place.

If only finishing is selected, the contour is always traversed in the programmed direction.

The first and last programmed contour points are the criteria for selecting the machining direction. For this reason, both coordinates must always be programmed in the first block of the contour subroutine.



### Contour monitoring

The cycle performs contour monitoring of the following:

- Clearance angles of the active tool
- Programming of arcs with an aperture angle of > 180 degrees

In the case of relief cut elements, the cycle checks whether machining is possible with the active tool. If the cycle detects that this machining is leading to a contour violation, it outputs alarm 61604 "Active tool violates the programmed contour" and machining is aborted.

Contour monitoring is not performed if the clearance angle has been defined as zero in the tool offset.

If the arcs in the offset are too large, alarm 10931 "Incorrect machining contour" is output.

Overhanging contours cannot be machined by CYCLE95. Contours of this type are not monitored by the cycle and consequently there is no alarm.

### Starting point



The cycle determines the starting point of the machining operation automatically. The starting point is positioned on the axis in which infeed is performed at a distance from the contour corresponding to final machining allowance + liftoff distance (parameter `_VRT`). In the other axis, it is positioned at a distance corresponding to final machining allowance + `_VRT` in front of the contour starting point.

The tool nose radius compensation is selected internally in the cycle when the starting point is approached.

The last point before the cycle is called must therefore be selected such that it can be approached without risk of collision and adequate space is available for the compensating movement.

### Approach strategy of the cycle

The starting point calculated by the cycle is always approached in the two axes simultaneously for roughing and one axis at a time for finishing. In finishing, the infeed axis is the first to travel.






### Programming example 1

#### Stock removal cycle

The contour illustrated in the figure explaining the assignment parameters must be machined completely (longitudinal, outside). Axis-specific final machining allowances have been defined. No interruption between cuts has been programmed. The maximum infeed is 5mm. The contour is stored in a separate program.



DEF STRING[8] UPNAME	Definition of a variable for the contour name
N10 T1 D1 G0 G18 G95 S500 M3 Z125 X81	Approach position before cycle call
UPNAME="CONTOUR_1"	Assignment of subroutine name
N20 CYCLE95 (UPNAME, 5, 1.2, 0.6, , -> -> 0 .2, 0.1, 0.2, 9, , , 0.5)	Cycle call
N30 G0 G90 X81	Reapproach to starting position
N40 Z125	Traverse in each axis separately
N50 M30	End of program
PROC CONTOUR_1	Beginning of contour subroutine
N100 G1 Z120 X37	Traverse in each axis separately
N110 Z117 X40	
N120 Z112	Rounding with radius 5
N130 G1 Z95 X65 RND=5	Traverse in each axis separately
N140 Z87	
N150 Z77 X29	
N160 Z62	
N170 Z58 X44	
N180 Z52	
N190 Z41 X37	
N200 Z35	
N210 G1 X76	
N220 M17	End of subroutine


-> Must be programmed in a single block



### Programming example 2

#### Stock removal cycle

The stock removal contour is defined in the calling program. After the stock removal cycle, the program is ended.



```

N110 G18 DIAMOF G90 G96 F0.8
N120 S500 M3
N130 T11 D1
N140 G0 X70
N150 Z60
N160 CYCLE95 ("START:END",2.5,0.8, ->      Cycle call
0.8,0,0.8,0.75,0.6,1)
N170 M02
START:
N180 G1 X10 Z100 F0.6
N190 Z90
N200 Z=AC(70) ANG=150
N210 Z=AC(50) ANG=135
N220 Z=AC(50) X=AC(50)
END:
N230 M02

```

## 4.6 Thread undercut – CYCLE96



### Programming

CYCLE96 (DIATH, SPL, FORM, \_VARI)




### Parameters

DIATH	real	Nominal diameter of the thread
SPL	real	Starting point on the contour of the longitudinal axis
FORM	char	Definition of the form Values: A (for Form A) B (for Form B) C (for Form C) D (for Form D)
_VARI	int	Specification of undercut position
(SW 6.2 and higher)		Values: 0 According to tool point direction 1...4 Define position



### Function

This cycle is for machining thread undercuts in accordance with DIN 76 on parts with a metric ISO thread.







### Sequence of operations

#### Position reached prior to cycle start:

The starting position can be any position from which any thread undercut can be approached without collision.

#### The cycle implements the following motion sequence:

- Approach to the starting point calculated in the cycle with G0
- Selection of the tool radius compensation for the active tool point direction. Retraction along the undercut contour at the feedrate programmed before cycle call.
- Retraction to the starting point with G0 and deselection of tool radius compensation with G40.



### Description of parameters


#### DIATH (nominal diameter)

With this cycle you can machine thread undercuts for metrical ISO threads from M3 to M68.

If the value programmed in DIATH results in a final diameter of <3mm, the cycle is aborted and alarm 61601 "Finished part diameter too small" is output. If the parameter is assigned a value other than that defined by DIN76 Part 1, again the cycle is aborted and the alarm 61001 "Thread pitch incorrectly defined" is output.

#### SPL (starting point)

With parameter SPL you define the final dimension in the longitudinal axis.



## 4.6 Thread undercut – CYCLE96

### FORM (definition)

Thread undercuts of forms A and B are defined for external threads, form A for normal thread run-outs, form B for short thread run-outs.

Thread undercuts of forms C and D are used for internal threads, form C for normal thread run-outs, form D for short thread run-outs.

If the parameter is assigned a value other than A ... D, the cycle is aborted and alarm 61609 "Form incorrectly defined" is output.

The tool radius compensation is automatically selected by the cycle.

### \_VARI (undercut position)



The position of the undercut can be either specified directly or derived from the tool point direction with parameter \_VARI.

See \_VARI with CYCLE94

The cycle automatically determines the starting point that is defined by the tool point direction of the active tool and the thread diameter. The position of this starting point in relation to the programmed coordinate values is determined by the tool point position of the active tool.

The cycle monitors the clearance angle of the active tool if forms A and B are being machined. If the cycle detects that the undercut form cannot be machined with the selected tool, the message "Changed undercut form"

is output by the control but machining is continued.





### Further notes


You must activate a tool offset before the cycle is called. Otherwise error message 61000 "No tool offset active" is output and the cycle is aborted.



### Programming example

#### Thread undercut\_Form\_A

You can machine a thread undercut of form A with this program.



N10 D3 T1 S300 M3 G95 F0.3	Specification of technology values
N20 G0 G18 G90 Z100 X50	Selection of starting position
N30 CYCLE96 (10, 60, "A")	Cycle call
N40 G90 G0 X30 Z100	Approach next position
N50 M30	End of program

## 4.7 Thread cutting – CYCLE97



### Programming

CYCLE97 (PIT, MPIT, SPL, FPL, DM1, DM2, APP, ROP, TDEP, FAL, IANG, NSP, NRC, NID, VARI, NUMT, \_VRT)



### Parameters

PIT	real	Thread pitch as value (enter without sign)
MPIT	real	Thread pitch as thread size Value range 3 (for M3) ... 60 (for M60)
SPL	real	Starting point of the thread in the longitudinal axis
FPL	real	End point of the thread in the longitudinal axis
DM1	real	Diameter of the thread at the starting point
DM2	real	Diameter of the thread at the end point
APP	real	Arc-in section (enter without sign)
ROP	real	Arc-out section (enter without sign)
TDEP	real	Thread depth (enter without sign)
FAL	real	Final machining allowance (enter without sign)
IANG	real	Infeed angle Value range: "+" (for flank infeed on flank) "-" (for alternating flank infeed)
NSP	real	Starting point offset for the first thread (enter without sign)
NRC	int	Number of rough cuts (enter without sign)
NID	int	Number of noncuts (enter without sign)
VARI	int	Definition of the machining type for the thread Value range: 1 ... 4
NUMT	int	Number of threads (enter without sign)
_VRT	real	Variable retraction distance based on initial diameter, incremental
from SW		(enter without sign)
6.2 or		
higher		



### Function

With this cycle you can machine cylindrical and tapered outside and inside threads with constant lead in longitudinal or face machining. Both single threads and multiple threads can be cut. In multiple thread cutting, the threads are cut one after the other.


Infeed is automatic. You can select either constant infeed per cut or constant cross-section of cut.

A right-hand or left-hand thread is determined by the direction of rotation of the spindle programmed before the cycle call.

Feedrate and spindle override both have no effect in thread travel blocks.



*A speed-controlled spindle with a position measuring system is required to operate this cycle.*



### Sequence of operations

#### Position reached prior to cycle start:

The starting position is any position from which the programmed thread starting point + arc-in section can be approached without collision.

### The cycle implements the following motion sequence:

- Approach to the starting point determined by the cycle at the beginning of the arc-in section for the first thread with G0.
- Infeed for roughing according to the infeed type defined under VARI.
- Thread cutting is repeated according to the number of roughing cuts programmed.
- In the next cut with G33 the final machining allowance is removed.
- This cut is repeated according to the number of programmed noncuts.
- The total motion sequence is repeated for each additional thread.




### Description of parameters

#### PIT and MPIT (value and thread size)

The thread pitch is a paraxial value and entered without a sign. If metric cylindrical threads are being machined it is also possible to define the thread pitch in parameter MPIT as a thread size (M3 to M60). These two parameters should be used as alternatives. If they contain conflicting values, the cycle generates alarm 61001 "Thread pitch wrong" and is aborted.

#### DM1 and DM2 (diameter)

This parameter is set to program the thread diameter of the start and end points of the thread. With an inside thread, this corresponds to the tap hole diameter.



**Connection between SPL, FPL, APP and ROP  
(starting point, end point, arc-in section and arc-out section)**

The programmed starting point (SPL) and end point (FPL) are the basis of the thread. However, the starting point used in the cycle is the starting point brought forward by the arc-in section APP and, in the same way, the end point is the programmed end point brought back by the arc-out section ROP. The starting point defined by the cycle always lies 1 mm outside the programmed thread diameter in the facing axis. This retraction plane is automatically generated by the control.

**Connection between TDEP, FAL, NRC and NID  
(thread depth, final machining allowance, number of cuts)**

The programmed final machining allowance has an effect parallel to the axis and is subtracted from the preset thread depth TDEP and the remainder is divided into roughing cuts.

The cycle automatically calculates the individual actual infeed depths depending on the parameter VARI.

The thread depth to be machined is divided into infeeds with the same cross-section of cut so that the cutting pressure remains constant for all rough cuts. Infeed is then performed with differing values for the infeed depth.



In a second method, the total thread depth is divided into constant infeed depths. The cross-section of cut gets larger from cut to cut. However, if the values for the thread depth are small, this method can create better cutting conditions.

The final machining allowance FAL is removed in one cut after roughing. After this, the noncuts programmed under parameter NID are executed.

**IANG (infeed angle)**

With parameter IANG you define the infeed angle. If infeed is to be performed at right angles to the cutting direction in the thread this parameter must be assigned the value zero. I.e., this parameter can also be omitted from the parameter list as it is then automatically assigned the default value zero. If infeed is to be performed along the flank, the absolute value of this parameter must be no more than half the flank angle of the tool.

The sign entered for this parameter defines how this infeed is performed. If a positive value is entered, infeed is always performed on the same flank, if a negative value is entered, infeed is performed alternately on both flanks. The infeed type on both flanks alternately can only be used for cylindrical threads. However, if a negative value is assigned to parameter IANG for a tapered thread, the cycle automatically performs a flank infeed along one flank.


**NSP (starting point offset)**

Under this parameter you can program the angular value that defines the point of the first cut for the first thread turn on the circumference on the turned part. This value is a starting point offset. The parameter can be assigned any value between 0.0001 and +359.9999 degrees. If no starting point offset has been entered or the parameter has been omitted from the parameter list, the first thread automatically starts at the zero degrees mark.



**VARI (machining type)**

With parameter VARI, you define if machining is to be internal or external and with which technology the infeed will be machined during roughing. The parameter VARI can be one of the values between 1 and 4 with the following meaning:



Value	Outside/inside	Const. infeed/const. cross-section of cut
1	Outside	Constant infeed
2	Inside	Constant infeed
3	Outside	Constant cross-section of cut
4	Inside	Constant cross-section of cut


If another value has been programmed for parameter VARI, the cycle is aborted after alarm 61002 "Machining type incorrectly defined" is output.

**NUMT (number of thread starts)**

With parameter NUMT you specify the number of thread starts for a multiple thread. If you require a single thread, either assign the value zero to the parameter or omit it from the parameter list.

The thread starts are distributed uniformly around the circumference of the turned part, the first thread is defined in parameter NSP.

If a multiple-start thread with a non-uniform distribution of threads around the circumference is to be machined, the cycle must be called for every thread start and the corresponding starting point offset must be programmed.




**\_VRT (variable retraction path)**

With SW 6 and higher, the retraction path can be programmed on the basis of the initial thread diameter in parameter `_VRT`.

When `_VRT = 0` (parameter not programmed), the retraction path is 1mm. The retraction path is always measured in the programmed system of units inch or metric.

**Further notes****Difference between a longitudinal thread and a face thread**

The cycle automatically calculates whether a longitudinal or face thread is to be machined. This depends on the angle of the taper on which the thread is to be machined. If the angle at the taper  $\leq 45$  degrees, the longitudinal axis thread is machined, otherwise it will be the face thread.






### Programming example

#### Thread cutting

With this program you can cut a metric outside thread M42x2 with flank infeed. The infeed is performed with a constant cross-section of cut. Five roughing cuts are made to a thread depth of 1.23mm without final machining allowance. After machining has been completed, 2 noncuts are performed.



```
DEF REAL MPIT=42, SPL=0, FPL=-35,
DM1=42, DM2=42, APP=10, ROP=3,
TDEP=1.23, FAL=0, IANG=30, NSP=0
DEF INT NRC=5, NID=2, VARI=3, NUMT=1
```

Definition of parameters with value assignments

```
N10 G0 G18 G90 Z100 X60
```

Selection of starting position

```
N20 G95 D1 T1 S1000 M4
```

Specification of technology values

```
N30 CYCLE97 ( , MPIT, SPL, FPL, DM1, ->
-> DM2, APP, ROP, TDEP, FAL, IANG, ->
-> NSP, NRC, NID, VARI, NUMT)
```

Cycle call

```
N40 G90 G0 X100 Z100
```

Approach next position

```
N50 M30
```

End of program

→ Must be programmed in a single block

## 4.8 Thread chaining – CYCLE98



### Programming

CYCLE98 (PO1, DM1, PO2, DM2, PO3, DM3, PO4, DM4, APP, ROP, TDEP, FAL, IANG, NSP, NRC, NID, PP1, PP2, PP3, VARI, NUMT, \_VRT)




### Parameters

PO1	real	Starting point of the thread in the longitudinal axis
DM1	real	Diameter of the thread at the starting point
PO2	real	First intermediate point in the longitudinal axis
DM2	real	Diameter at the first intermediate point
PO3	real	Second intermediate point
DM3	real	Diameter at the second intermediate point
PO4	real	End point of the thread in the longitudinal axis
DM4	real	Diameter at the end point
APP	real	Arc-in section (enter without sign)
ROP	real	Arc-out section (enter without sign)
TDEP	real	Thread depth (enter without sign)
FAL	real	Final machining allowance (enter without sign)
IANG	real	Infeed angle Value range: "+" (for flank infeed on flank) "–" (for alternating flank infeed)
NSP	real	Starting point offset for the first thread (enter without sign)
NRC	int	Number of rough cuts (enter without sign)
NID	int	Number of noncuts (enter without sign)
PP1	real	Thread pitch 1 as value (enter without sign)
PP2	real	Thread pitch 2 as value (enter without sign)
PP3	real	Thread pitch 3 as value (enter without sign)
VARI	int	Definition of the machining type for the thread Value range 1 ... 4
NUMT	int	Number of threads (enter without sign)
_VRT	real	Variable retraction distance based on initial diameter, incremental
SW 6.2		(enter without sign)
and		
higher		



### Function

With this cycle you can produce several concatenated cylindrical or tapered threads with a constant lead in longitudinal or face machining, all of which can have different thread leads.



### Sequence of operations

#### Position reached prior to cycle start:

The starting position is any position from which the programmed thread starting point + arc-in section can be approached without collision.

#### The cycle implements the following motion sequence:

- Approach to the starting point determined by the cycle at the beginning of the arc-in section for the first thread with G0.
- Infeed to commence roughing according to the infeed type defined under VARI.
- Thread cutting is repeated according to the number of roughing cuts programmed.
- In the next cut with G33 the final machining allowance is cut.
- This cut is repeated according to the number of programmed noncuts.
- The total motion sequence is repeated for each additional thread.



### Description of parameters

#### PO1 and DM1 (starting point and diameter)

With these parameters you define the original starting point of the thread chain. The starting point calculated by the cycle that is approached at the beginning with G0 is the length of the arc-in section in front of the programmed starting point (starting point A).

#### PO2, DM2 and PO3, DM3 (intermediate point and diameter)

With these parameters you define two intermediate points in the thread.

#### PO4 and DM4 (endpoint and diameter)

The original end point of the thread is programmed under parameters PO4 and DM4.



With an inside thread, DM1...DM4 corresponds to the tap hole diameter.


#### Connection between APP and ROP (arc-in, arc-out sections)

The starting point used in the cycle is the starting point brought forward by the arc-in section APP and, in the same way, the end point is the programmed end point brought back by the arc-out section ROP.

The starting point defined by the cycle always lies 1mm outside the programmed thread diameter in the facing axis. This retraction plane is automatically generated by the control.

#### Connection between TDEP, FAL, NRC and NID (thread depth, final machining allowance, number of rough cuts and noncuts)

The programmed final machining allowance is subtracted from the defined thread depth TDEP and the remainder divided into rough cuts. The cycle automatically calculates the individual actual infeed depths depending on the parameter VARI. The thread depth to be machined is divided into infeeds with the same cross-section of cut so that the cutting pressure remains constant for all rough cuts. Infeed is then performed with differing values for the infeed depth.





In a second method, the total thread depth is divided into constant infeed depths. The cross-section of cut gets larger from cut to cut. However, if the values for the thread depth are small, this method can create better cutting conditions.

The final machining allowance FAL is removed in one cut after roughing. After this, the noncuts programmed under parameter NID are executed.

### IANG (infeed angle)

With parameter IANG you define the infeed angle. If infeed is to be performed at right angles to the cutting direction in the thread this parameter must be assigned the value zero. I.e., this parameter can also be omitted from the parameter list as it is then automatically assigned the default value zero. If infeed is to be performed along the flank, the absolute value of this parameter must be no more than half the flank angle of the tool.

The sign entered for this parameter defines how this infeed is performed. If a positive value is entered, infeed is always performed on the same flank, if a negative value is entered, infeed is performed alternately on both flanks. The infeed type on both flanks alternately can only be used for cylindrical threads. However, if a negative value is assigned to parameter IANG for a tapered thread, the cycle automatically performs a flank infeed along one flank.



**NSP (starting point offset)**


Under this parameter you can program the angular value that defines the point of the first cut for the first thread turn on the circumference on the turned part. This value is a starting point offset. The parameter can be assigned any value between 0.0001 and +359.9999 degrees. If no starting point offset has been entered or the parameter has been omitted from the parameter list, the first thread automatically starts at the zero degrees mark.

**PP1, PP2 and PP3 (thread pitch)**

With these parameters you determine the thread pitch from the three sections of the thread chain. The pitch value must be entered as a paraxial value without a sign.

**VARI (machining type)**

With parameter VARI, you define if machining is to be internal or external and with which technology the infeed will be machined during roughing. The parameter VARI can be one of the values between 1 and 4 with the following meaning:



Value	Outside/inside	Const. infeed/const. cross-section of cut
1	Outside	Constant infeed
2	Inside	Constant infeed
3	Outside	Constant cross-section of cut
4	Inside	Constant cross-section of cut



If another value is assigned to parameter VARI, the cycle is aborted and alarm 61002 "Machining type incorrectly programmed" is output.

#### **NUMT (number of thread starts)**

With parameter NUMT you specify the number of thread starts for a multiple thread. If you require a single thread, either assign the value zero to the parameter or omit it from the parameter list.


The thread starts are distributed uniformly around the circumference of the turned part, the first thread is defined in parameter NSP.

If a multiple-start thread with a non-uniform distribution of threads around the circumference is to be machined, the cycle must be called for every thread start and the corresponding starting point offset must be programmed.

#### **\_VRT (variable retraction path)**

With SW 6.2 and higher, the retraction path can be programmed on the basis of the initial thread diameter in parameter \_VRT.

When \_VRT = 0 (parameter not programmed), the retraction path is 1mm. The retraction path is always measured in the programmed system of units inch or metric.






### Programming example

#### Thread chain

With this program you can produce a chain of threads starting with a cylindrical thread. Infeed is perpendicular to the thread. Neither a final machining allowance nor a starting point offset have been programmed. Five roughing cuts and one noncut are performed.

The machining type defined is longitudinal, outside, with constant cross-section of cut.



N10 G18 G95 T5 D1 S1000 M4	Specification of technology values
N20 G0 X40 Z10	Approach starting position
N30 CYCLE98 (0, 30, -30, 30, -60, -> -> 36, -80, 50, 10, 10, 0.92, , , , -> -> 5, 1, 1.5, 2, 2, 3, 1)	Cycle call
N40 G0 X55	Traverse in each axis separately
N50 Z10	
N60 X40	
N70 M30	End of program

-> Must be programmed in a single block

## 4.9 Thread recutting (SW 5.3 and higher)



SW 5.3 contains thread cutting cycles CYCLE97 and CYCLE98 which allow threads to be recut.



### Function

The angular offset of a thread start resulting from tool breakage or remeasurement is taken into account and compensated for by the "Thread recut" function.

This function can be executed in JOG mode in the Machine operating area.

The cycles calculate an additional offset angle for each thread, which is applied in addition to the programmed starting point offset, from the data stored in the thread start during synchronization.

### Preconditions


The channel in which the thread recutting program must be executed is already selected; the relevant axes must already be referenced. The channel is in the Reset state, the spindle is stationary.



### Sequence of operations

- Select JOG in "Machine" operating area.
- Press soft key "Finish thread"
  - ➔ Open screen form for this function.

**Finish thread**
**Select plane G17, G18, G19**



Select plane		G18
Spindle position	C	0.000 grd
Position	Z	0.000 mm
Position	X	0.000 mm

- Thread into thread start using the threading tool.
- Select soft key "Sync Point" when the cutting tool is positioned exactly in the thread start.

## 4.9 Thread recutting (SW 5.3 and higher)

- Press soft key "Cancel" to return to the next-higher soft key menu without activating the function (no data are then stored in the NC).
- Select soft key "OK" to transfer all values to the GUD in the NC.
- Then retract the tool and move it to its starting position.
- Select "Automatic" and position the program pointer using block search in front of the thread cycle call.
- Start the program with NC start.



### Special functions

You can delete values stored earlier by selecting another soft key labeled "Delete".

If several spindles are operating in the channel, another box is displayed in the screenform in which you can select a spindle to machine the thread.

#### 4.10 Extended stock removal cycle – CYCLE950 (SW 5.3 and higher)



The extended stock removal cycle is an option.  
It requires SW 5.3 in the NCK and MMC.



#### Programming

CYCLE950 (\_NP1, \_NP2, \_NP3, \_NP4, \_VARI, \_MID, \_FALZ, \_FALX, \_FF1, \_FF2, \_FF3, \_FF4, \_VRT, \_ANGB, \_SDIS, \_NP5, \_NP6, \_NP7, \_NP8, \_APZ, \_APZA, \_APX, \_APXA, \_TOL1)



#### Parameters

_NP1	string	Name of the contour subroutine for the finished part contour
_NP2	string	Label / block number start of finished part contour, optional (this can be used to define contour sections)
_NP3	string	Label / block number end of finished part contour, optional (this can be used to define contour sections)
_NP4	string	Name of the stock removal program to be generated
_VARI	int	Type of machining: (enter without sign) ONES DIGIT: Values: 1...Longitudinal 2...Face 3...Parallel to contour TENS DIGIT: Values: 1...Programmed infeed direction X- 2...Programmed infeed direction X+ 3...Programmed infeed direction Z- 4...Programmed infeed direction Z+ HUNDREDS DIGIT: Values: 1...Roughing 2...Finishing 3...Complete THOUSANDS DIGIT: Values: 1...With rounding 2...Without rounding (liftoff) TEN THOUSANDS DIGIT: Values: 1...Machine relief cuts 2...Do not machine relief cuts HUNDRED THOUSANDS DIGIT: Values: 1...Programmed machining direction X- 2...Programmed machining direction X+ 3...Programmed machining direction Z- 4...Programmed machining direction Z+
_MID	real	Infeed depth (enter without sign)
_FALZ	real	Final machining allowance in the longitudinal axis (enter without sign)
_FALX	real	Final machining allowance in the facing axis (enter without sign)
_FF1	real	Feedrate for longitudinal roughing

**4.10 Extended stock removal cycle – CYCLE950 (SW 5.3 and higher)**

_FF2	real	Feedrate for face roughing
_FF3	real	Feedrate for finishing
_FF4	real	Feedrate at contour transition elements (radius, chamfer)
_VRT	real	Liftoff distance for roughing, incremental (enter without sign)
_ANGB	real	Liftoff angle for roughing
_SDIS	real	Safety distance for avoiding obstacles, incremental
_NP5	string	Name of contour program for blank contour
_NP6	string	Label / block number start of blank contour, optional (this can be used to define contour sections)
_NP7	string	Label / block number end of blank contour, optional (this can be used to define contour sections)
_NP8	string	Name of contour program for updated blank contour
_APZ	real	Axial value for defining blank for longitudinal axis
_APZA	int	Absolute or incremental evaluation of parameter _APZ 90=absolute, 91=incremental
_APX	real	Axial value for defining blank for facing axis
_APXA	int	Absolute or incremental evaluation of parameter _APX 90=absolute, 91=incremental
_TOL1	real	Blank tolerance



### Function

With the extended stock removal cycle CYCLE950 you can machine a contour programmed with paraxial or parallel-contour stock removal. Any blank can be defined and is considered during stock removal. The finished part contour must be continuous and may contain any number of relief cut elements. You can specify a blank as a contour or by means of axial values.

Contours can be machined in the longitudinal and facing directions with this cycle. You can freely select a technology (roughing, finishing, complete machining, machining and infeed directions). It is possible to update a blank.


For roughing, the programmed infeed depth is observed precisely; the last two roughing steps are divided equally. Roughing is performed to the programmed final machining allowance.

Finishing is performed in the same direction as roughing.

The tool radius compensation is automatically selected and deselected by the cycle.

**New functions compared to CYCLE95:**

- You can define a blank either by programming a contour, specifying an allowance on the finished-part contour or entering a blank cylinder (or hollow cylinder in the case of internal machining) from which stock must be removed.
- It is possible to detect residual material that cannot be machined with the current tool. The cycle can generate an updated blank, which is stored as a program in the parts program memory.
- You can specify the contours for stock removal:
  - in a separate program,
  - in the calling main program or
  - as section of any given program.
- During roughing, it is possible to choose between paraxial and contour-parallel machining.
- During roughing, you have the option of machining along the contour so that no corners are left over, or removing stock immediately at the roughing intersection.
- The angle for stock removal at the contour during roughing is programmable.
- Optionally, relief cuts can be machined or skipped during roughing.

**Sequence of operations****Position reached prior to cycle start:**

The initial position can be any position from which the blank contour can be approached collision-free. The cycle calculates collision-free approach movements to the starting point for machining but does not consider the tool holder data.

**Movement for paraxial roughing:**

- The starting point for roughing is calculated internally in the cycle and approached with G0.



- The infeed to the next depth, calculated in accordance with the specifications in parameter `_MID`, is carried out with G1, and paraxial roughing then performed with G1. The feedrate during roughing is calculated internally in the cycle according to the path as the feedrate that results from the values specified for longitudinal and face feed (`_FF1` and `_FF2`).
- For "Rounding along contour", the previous intersection is approached parallel to the contour.
- When the previous intersection is reached or for machining "Without rounding along contour", the tool is lifted off at the angle programmed in `_ANGB` and then retracted to the starting point for the next infeed with G0. If the angle is 45 degrees, the programmed liftoff path `_VRT` is also followed precisely; it is not exceeded for other angles.
- This procedure is repeated until the full depth of the machining section has been reached.

**Sequence of motions for roughing in parallel with contour:**

- The starting point for roughing and the individual infeed depths are calculated as for paraxial roughing and approached with G0 or G1.
- Roughing is carried out in contour-parallel paths.
- Liftoff and retraction is carried out in the same way as for paraxial roughing.



### Description of parameters

#### **\_NP1, \_NP2, \_NP3 (contour programming finished part)**

The finished part contour can be programmed optionally in a separate program or in the current main program that calls the routine. The data are transferred to the cycle via parameters `_NP1` – Name of the program or `_NP2, _NP3` – ID of program section from ... to using block numbers or labels.

So there are three options for contour programming:

- The contour is defined in a separate program – in which case only `_NP1` need be programmed;  
(see programming example 1)
- The contour is defined in the calling program in which case only `_NP2` and `_NP3` have to be programmed;  
(see programming example 2)
- The stock removal contour is part of a program but not part of the program that calls the cycle in which case all three parameters must be programmed.

When the contour is programmed as a program section, the last contour element (block with label or block number end of blank contour) must not contain a radius or chamfer.

Write the program name in `_NP1` with path name and program type.

Example:

```
_NP1="/_N_SPF_DIR/_N_PART1_SPF"
```

#### **\_NP4 (name of the stock removal program)**

The stock removal cycle generates a program for the travel blocks that are required for stock removal between the blank and the finished part. This program is stored in the same directory as the calling program in the parts program memory if no other path is specified when it is generated. If a path is entered, it is stored accordingly in the file system.

The program is a main program (type MPF) if no other type is specified.

Parameter `_NP4` defines the name of this program.

## 4.10 Extended stock removal cycle – CYCLE950 (SW 5.3 and higher)

### **\_VARI (machining type)**

Parameter `_VARI` defines the type of machining.

Possible values are:

#### **Units digit:**

- 1=Longitudinal
- 2=Face
- 3=Parallel to the contour

#### **Tens digit:**

- 1=Programmed infeed direction X-
- 2=Programmed infeed direction X+
- 3=Programmed infeed direction Z-
- 4=Programmed infeed direction Z+

#### **Hundreds digit:**

- 1=Roughing
- 2=Finishing
- 3=Complete

#### **Thousands digit:**

- 1=With rounding
- 2=Without rounding (liftoff)

The selection with or without rounding along the contour determines whether or stock removal starts at the roughing intersection immediately or whether machining is performed along the contour up to the previous intersection so that there are no residual corners.

#### **Ten thousands digit:**

- 1=Machine relief cuts
- 2=Do not machine relief cuts




#### **Hundred thousands digit:**

- 1=Programmed machining direction X-
- 2=Programmed machining direction X+
- 3=Programmed machining direction Z-
- 4=Programmed machining direction Z+

#### **Example:**

`_VARI=312311` means machining:

- longitudinal,
- infeed direction X- (i.e. external),
- complete;
- the workpiece is not rounded along the contour, relief cuts are machined,
- machining direction Z-.



**\_MID (infeed depth for roughing)**

The infeed depth for roughing is programmed with the parameter `_MID`. Roughing steps are generated with this infeed until the remaining depth is less than twice the infeed depth. Then two steps are performed each at half of the remaining depth. `_MID` is interpreted as a radius or diameter depending on the value of cycle setting data `_ZSD[0]` if the facing axis is involved in the infeed for roughing.

`_ZSD[0]=0`: `_MID` is interpreted according to the G group for radius/diameter programming, as a radius with `DIAMOF`, otherwise as a diameter.

`_ZSD[0]=1`: `_MID` is a radius value

`_ZSD[0]=2`: `_MID` is a diameter value

When rough cutting parallel to contour, the infeed depth does not act in relation to the specified infeed axis but vertically to the contour. This always results in more cuts than in paraxial rough-cutting with the same value for infeed depth.

**\_FALZ, \_FALX (machining allowance)**

The default for a final machining allowance for roughing is provided by the parameters `FALZ` (for Z axis) and `FALX` (for X axis). Roughing always takes place down to these final machining allowances. If no machining allowances are programmed, stock removal is performed up to the end contour during roughing.


If final machining allowances are programmed, these are applied correspondingly.

**\_FF1, \_FF2, \_FF3 and FF4 (feedrate)**

Separate feedrates can be specified for roughing and finishing, as shown in the figure opposite. Separate feedrates apply for longitudinal (`_FF1`) and face (`_FF2`) during roughing. If inclined or circular path sections are traversed when machining the contour, the appropriate feedrate is calculated automatically inside the cycle.

The feedrates programmed at the contour are active during finishing. If none are programmed there, the finishing feedrate in `_FF3` and the feedrates at radii and chamfers in `_FF4` apply to these contour transition elements.

(see sample program 1 for programming of the parts in the figure below)



**\_VRT (liftoff) and \_ANGB (lift angle)**

The parameter `_VRT` can be used to program the amount of liftoff during roughing in both axes.

If `_VRT=0` (parameter not programmed), liftoff is 1 mm.

It is also possible to program the angle at which the axis is retracted from the contour in parameter `_ANGB`. If nothing is programmed, the angle is 45°.

**\_SDIS (safety distance)**

Parameter `_SDIS` determines the amount of clearance for obstructions. This clearance is active for retraction from a relief cut and approach to the next relief cut, for example.

If no value is programmed, the clearance is 1 mm.

**\_NP5, \_NP6, \_NP7 (contour programming blank)**

If a blank is programmed as a contour, it can be programmed as a program name using parameter `_NP5` or as a program section with parameters `_NP6` and `_NP7`.

Otherwise, programming is carried out as for finished parts (see `_NP1`, `_NP2`, `_NP3`).

**\_NP8 (name of contour program for updated blank contour)**

Cycle CYCLE950 can detect residual material that cannot be removed with the active tool.

To continue this machining with a different tool, it is possible to generate an updated blank contour automatically. This is stored as a program in the parts program memory. You can specify the program name in parameter `_NP8` with or without path details (see sample program 3).

An updated blank contour is always generated when a travel program is generated.




## 4.10 Extended stock removal cycle – CYCLE950 (SW 5.3 and higher)

### **\_APZ, \_APZA, \_APX, \_APXA (blank definition)**

You can also define a blank by entering the dimensions of a blank cylinder (or hollow cylinder) or as an allowance on the finished-part contour in parameters **\_APZ** and **\_APX**.

You can enter the cylinder dimensions as either absolute or incremental values, although an allowance on the finished-part contour is always interpreted incrementally.

Absolute or incremental values are selected via parameters **\_APZA** and **\_APXA** (**\_APZA**, **\_APXA**: 90 – absolute 91 – incremental).



**\_TOL1 (blank tolerance)**

Since a blank does not always correspond exactly to the blank definition when it is cast or forged for example, it makes sense not to travel to the blank contour with G0 for roughing and for the infeed but to activate G1 shortly beforehand to compensate for any tolerances.

Parameter `_TOL1` defines the distance from the blank at which G1 becomes active.

Traversing is started with G1 at this incremental amount before the blank. If the parameter is not programmed, it has the value 1mm.

**Further notes****Contour definition**


Unlike CYCLE95, one block that contains a link to the current plane is sufficient for contour programming.

For further details of contour definition, see CYCLE95.

**Blank contour definition**

A blank contour must either be a closed contour (starting point=end point) which encompasses the finished-part contour either partially or fully, or a contour section between the starting and end points of the finished-part contour. The programmed direction is irrelevant.

Blank contours always must be described in a way that they are not partly identical with the finished-part contours, i.e. the machined materials are not combined



**Explanation of the cycle structure**

CYCLE950 is used to solve very complex problems during stock removal, which require high processing power in the control. For best timing, the calculation is carried out in the MMC.

The calculation is started in the cycle and a program with traversing blocks for stock removal generated in its result and stored in the file system of the control, where it is called and executed immediately.

This structure means that it is only necessary to perform the calculation the first time a program is executed with CYCLE950 call. When called a second time, the traversing program is available and can be called by the cycle.

Recalculation is performed when:

- A finished contour has been modified;
- A transfer parameter of the cycle has changed;
- A tool with different tool offset data has been activated before the cycle call.

**Program storage in the file system**

If the contours for CYCLE950 are programmed outside the program that makes the call, the following applies for the search in the file system of the control:

- If the calling program is stored in a workpiece directory, then the programs which define the finished-part or blank contour must also be stored in the same workpiece directory, or at least programmed with path information.
- If the invoked program is located in the "Parts program" directory (MPF.DIR), a search is also made there for the programs if no path is specified.

The cycle creates a program that contains the traversing blocks for stock removal and, optionally, an updated blank contour.

These are either stored in the same directory as the cycle-calling program or in accordance with the specified path.



**Note on simulation**

In the simulation of the extended stock removal cycle CYCLE950, the generated programs are saved to the NCU file system. Therefore, only the "NC Active Data" setting is practical since tool offset data are included in program calculation.

**Blank updating**

The extended stock removal cycle CYCLE950 detects residual material during roughing and is able to generate an updated blank contour outside the machining process, which can be used in a further machining step.

To do this, the cycle internally considers the angle at the tool point.

The relief cut angle of the tool must be entered in the tool offset data (parameter 24).



The cycle defines the main cutting edge angle automatically according to the tool point position.

For tool point positions 1 to 4, the blank update is calculated with a main cutting edge angle of  $90^\circ$ . For tool point positions 5 to 9, the main cutting angle is assumed to be identical to the relief cut angle.

If CYCLE950 is called more than once, each time with blank update, in the same program, different names for the generated blank contours must be assigned; it is not permissible to use the program name (parameter `_NP8`) more than once.



Extended stock removal cannot be performed in m:n configurations.





### Programming example 1


From a preshaped blank, the contour saved in program PART1.MPF is to be machined.

The type of machining for the stock removal process is

- only roughing,
- longitudinal,
- outside,
- with rounding (so that no corners are left over),
- relief cuts are to be machined.

The blank contour is specified in program BLANK1.MPF.

A turning steel with tool point position 3 and a radius of 0.8mm is used.



#### Machining program:

```
%_N_EXAMPLE_1_MPF
; $PATH=/_N_WKS_DIR/_N_STOCK_REMOVAL_NEW_WPD
; Example 1: Stock removal with blank
; Sca, 01.04.99
;
; Tool offset data
N10 $TC_DP1[3,1]=500 $TC_DP2[3,1]=3
$TC_DP6[3,1]=0.8 $TC_DP24[3,1]=60
N15 G18 G0 G90 DIAMON
N20 T3 D1
N25 X300
N30 Z150
N35 G96 S500 M3 F2
N45 CYCLE950("Part1",,, "Machine_Part1",
311111,1.25,1,1,0.8,0.7,0.6,0.3,0.5,45,2,
"Blank1",,,,,,1)
N45 G0 X300
N50 Z150
N60 M2
```

#### Finished part contour:

```
%_N_PART1_MPF
; $PATH=/_N_WKS_DIR/_N_STOCK_REMOVAL_NEW_WPD
; Finished part contour Example 1
;
```

## 4.10 Extended stock removal cycle – CYCLE950 (SW 5.3 and higher)

```

N100 G18 DIAMON F1000
N110 G1 X0 Z90
N120 X20 RND=4
N130 X30 Z80
N140 Z72
N150 X34
N160 Z58
N170 X28 Z55 F300
N180 Z50 F1000
N190 X40
N200 X60 Z46
N210 Z30
N220 X76 CHF=3
N230 Z0
N240 M17

```

### Blank contour:

```

%_N_BLANK1_MPF
; $PATH=/_N_WKS_DIR/_N_STOCK_REMOVAL_NEW_W
PD
; Blank contour Example 1
;
N100 G18 DIAMON F1000
N110 G0 X0 Z93
N120 G1 X37
N130 Z55
N140 X66
N150 Z35
N160 X80
N170 Z0
N180 X0
N190 Z93
N200 M17

```

End point=Starting point  
Blank contour must be closed

After machining, a new program called MACHINING\_PART1.MPF is present in the workpiece STOCK\_REMOVAL\_NEW.WPD. MACHINING\_PART1.MPF. This program is created during the first program call and contains the traversing motions for machining the contour in accordance with the blank.



### Programming example 2


A simple inside contour is to be machined on the same part as in sample program 1.

A center bore is made first using a diameter-10 drill.

Then, the inside contour is roughed parallel to the contour, since the hole roughly corresponds to the end contour.

This is done by defining a blank contour again for inside machining.

The stock removal contour is located in the same program as the cycle call in the blocks N400 to N420, the blank contour in blocks N430 to N490.



### Machining program:

```

%_N_EXAMPLE_2_MPF
; $PATH=/_N_WKS_DIR/_N_STOCK_REMOVAL_NEW_WPD
; Example 1: inside stock removal,
parallel to contour
; Sca, 01.04.99
;
; Tool offset data for turning tool,
inside
N100 $TC_DP1[2,1]=500 $TC_DP2[2,1]=6
$TC_DP6[2,1]=0.5 $TC_DP24[2,1]=60
N105 $TC_DP1[1,1]=200 $TC_DP3[1,1]=100
$TC_DP6[1,1]=5
N110 G18 G0 G90 DIAMON
N120 X300
N130 Z150
N140 T1 D1 M6 Change drill with diameter 10
N150 X0 Center drilling in three steps
N160 Z100
N170 F500 S400 M3
N175 G1 Z75
N180 Z76
N190 Z60
N200 Z61
N210 Z45
N220 G0 Z100
N230 X300 Approach tool change point
N240 Z150
N250 T2 D1 M6 Insert turning tool for inside machining

```

**4.10 Extended stock removal cycle – CYCLE950 (SW 5.3 and higher)**

```

N260 G96 F0.5 S500 M3
N275 CYCLE950("","N400","N420",
"Machine_Part1_Inside",311123,1.25,0,0,
0.8,0.5,0.4,0.3,0.5,45,1,"","N430","N490"
,,,,,,,,,1)
N280 G0 X300
N290 Z150
N300 GOTOF _END                               Skip contour definition
N400 G0 X14 Z90                                N400 to N420 finished part contour
N410 G1 Z52
N420 X0 Z45
N430 G0 X10 Z90                                N430 to N490 blank contour
N440 X16
N450 Z40
N460 X0
N470 Z47
N480 X10 Z59
N490 Z90
N500 _END:M2

```



### Programming example 3

The same part as in sample program 1 should now be machined in two steps.

In the first machining step (N45), roughing is carried out using a tool with tool point position 9 and a large radius with deep infeed depth and no blank specified. The result to be generated is an updated blank with the name blank3.MPF.

The type of machining for this step is:

- only roughing,
- longitudinal,
- outside,
- with rounding,
- relief cuts are not be machined.

In the second machining step (N70), the residual material on this blank is machined with a different tool and then finished.

The type of machining for this step is:

- complete machining (roughing and finishing)
- longitudinal,
- outside,
- with rounding (so that there are no residual corners),
- relief cuts are to be machined.

#### Machining program:

```

%_N_EXAMPLE_3_MPF
; $PATH=/_N_WKS_DIR/_N_STOCK_REMOVAL_NEW_W
PD
; Example 3: stock removal in two steps
with blank update
; Sca, 09.04.99
;
; Tool offset data
; T3: Roughing steel for rough machining,
tool point position 9, radius 5
N05 $TC_DP1[3,1]=500 $TC_DP2[3,1]=9
$TC_DP6[3,1]=5 $TC_DP24[3,1]=80
; T4: Turning steel for residual material
and finishing
; Tool point position 3, radius 0.4

```

## 4.10 Extended stock removal cycle – CYCLE950 (SW 5.3 and higher)

```
N10 $TC_DP1[4,1]=500 $TC_DP2[4,1]=3
```

```
$TC_DP6[4,1]=0.4 $TC_DP24[4,1]=80
```

```
N15 G18 G0 G90 DIAMON
```

```
N20 T3 D1
```

Tool for roughing

```
N25 X300
```

```
N30 Z150
```

```
N35 G96 S500 M3 F2
```

```
N45 CYCLE950("Part1",,,, "Machine_Part3",
321111,8,1,1,0.8,0.7,0.6,0.5,1,45,6,
"DEFAULT",,,, "Blank3",0,91,0,91,1)
```

```
N50 G0 X300
```

```
N55 Z150
```

```
N60 T4 D1
```

Tool for roughing residual material and finishing


```
N65 G96 S500 M3 F2
```

```
N75
```

```
CYCLE950("Part1",,,, "Finish_Part3",311311,
0.5,0.25,0.25,0.8,0.7,0.6,0.5,1,45,6, "Blank3",,,,,,1)
```

```
N160 M2
```

**Finished part contour:**  
as for sample program 1



**4.10 Extended stock removal cycle – CYCLE950 (SW 5.3 and higher)****Explanation****Alarm source CYCLE950**

Alarm number	Alarm text	Explanation, remedy
61701	"Error in contour description of finished part"	Either none of parameters _NP1, _NP2 or _NP3 is assigned or error in programming of finished-part contour
61702	"Error in contour description of blank"	Either none of parameters _NP5, _NP6 or _NP7 is assigned or error in programming of blank contour
61703	"Internal cycle error while deleting file"	
61704	"Internal cycle error while writing file"	
61705	"Internal cycle error while reading file"	
61706	"Internal cycle error during checksum formation"	
61707	"Internal cycle error during ACTIVATE at MMC"	
61708	"Internal cycle error during READYPROG at MMC"	
61709	"Timeout for contour calculation"	
61720	"Illegal input"	
61721	"Error: unable to determine contour direction"	
61722	"System error"	
61723	"Unable to perform machining"	Use a tool with a larger clearance angle
61724	"No material available"	
61725	"Out of memory, error in contour generation"	
61726	"Internal error: Out of memory _FILECTRL_INTERNAL_ERROR"	
61727	"Internal error: Out of memory _FILECTRL_EXTERNAL_ERROR"	
61728	"Internal error: Out of memory _ALLOC_P_INTERNAL_ERROR"	



## 4.10 Extended stock removal cycle – CYCLE950 (SW 5.3 and higher)

Alarm number	Alarm text	Source	Explanation, remedy
61729	"Internal error: Out of memory _ALLOC_P_EXTERNAL_ERROR"		
61730	"Internal error: Invalid Memory"		
61731	"Internal error: Floating-point exception"		
61732	"Internal error: Invalid instruction"		
61733	"Internal error: Floating_Point_Error"		
61734	"Tool point position not compatible with cutting direction"		
61735	"Finished part lies outside blank contour"		Check definition of blank contour
61736	"Tool insert length < machining depth"		
61737	"Machining_Depth_Of_Cut > Max._Tool_Cutting_Depth"		
61738	"Machining_Cutting_Depth < Min._Tool_Cutting_Depth"		
61739	"Incorrect position of tool for this type of machining"		
61740	"Blank must be a closed contour"		Blank contour must be closed, starting point = end point
61741	"Out of memory"		
61742	"Collision during approach, offset not possible"		

■

## Notes

## Error Messages and Error Handling

5.1	General information.....	5-348
5.2	Troubleshooting in the cycles.....	5-348
5.3	Overview of cycle alarms .....	5-349
5.4	Messages in the cycles .....	5-355

**5.1 General information**

If error conditions are detected in the cycles, an alarm is output and execution of the cycle is aborted. The cycles also output messages in the dialog line of the control. These messages do not interrupt processing.



For more information on errors and required responses as well as messages output in the control's dialog line, please refer to the section for the relevant cycle.

**5.2 Troubleshooting in the cycles**

If error conditions are detected in the cycles, an alarm is output and processing is aborted. Alarms with numbers between 61000 and 62999 are output in the cycles. This range is again subdivided according to alarm responses and acknowledgment criteria.

The text displayed with the number provides an explanation of the cause of the error.

Alarm number	Cancel criterion	Alarm reaction
61000 ... 61999	NC_RESET	Block preprocessing in the NC is aborted
62000 ... 62999	Cancel key	Block preprocessing is interrupted, the cycle can be continued with NC Start once the alarm has been canceled

### 5.3 Overview of cycle alarms

The alarm numbers are classified as follows:

6	-	X	-	-
---	---	---	---	---

- X=0 General cycle alarms
- X=1 Drilling, drilling pattern and milling cycle alarms
- X=6 Turning cycle alarms

The table below lists the errors that occur in the cycles, when they occur and how to eliminate them.

Alarm number	Alarm text	Source	Explanation, remedy
61000	"No tool offset active"	LONGHOLE SLOT1 SLOT2 POCKET1 to POCKET4 CYCLE71 CYCLE72 CYCLE90 CYCLE93 to CYCLE96	D offset must be programmed before the cycle is called
61001	"Thread lead incorrect"	CYCLE84 CYCLE840 CYCLE96 CYCLE97	Check parameters for thread size and check pitch information (contradict each other)
61002	"Machining type incorrectly defined"	SLOT1 SLOT2 POCKET1 to POCKET4 CYCLE71 CYCLE72 CYCLE76 CYCLE77 CYCLE93 CYCLE95 CYCLE97 CYCLE98	The value assigned to parameter VARI for the machining type is incorrect and must be altered

## 5.3 Overview of cycle alarms

Alarm number	Alarm text	Source	Explanation, remedy
61003	"No feedrate programmed in the cycle"	CYCLE71 CYCLE72	The parameter for feedrate has been incorrectly set and must be altered.
61005	"3rd geometry axis not available"	CYCLE86	When used on turning machines without Y axis in G18 plane.
61009	"Active tool number = 0"	CYCLE71 CYCLE72	No tool (T) is programmed prior to the cycle call.
61010	"Final machining allowance too great"	CYCLE72	The final machining allowance on the base is greater than the total depth and must be reduced.
61011	"Scaling not allowed"	CYCLE71 CYCLE72	A scale factor is currently active that is not permissible for this cycle.
61012	"Scaling in the plane different"	CYCLE76 CYCLE77	
61101	"Reference plane incorrectly defined"	CYCLE71 CYCLE72 CYCLE81 CYCLE90 CYCLE840 SLOT1 SLOT2 POCKET1 to POCKET4 LONGHOLE	Either different values must be entered for the reference plane and the retraction plane if they are relative values or an absolute value must be entered for the depth
61102	"No spindle direction programmed"	CYCLE86 CYCLE87 CYCLE88 CYCLE840 POCKET3 POCKET4	Parameter SDIR (or SDR in CYCLE840) must be programmed
61103	"Number of holes equals zero"	HOLES1 HOLES2	No value has been programmed for the number of holes
61104	"Contour violation of the slots/elongated holes"	SLOT1 SLOT2 LONGHOLE	Incorrect parameterization of the milling pattern in the parameters that define the position of the slots/elongated holes in the cycle and their shape

Alarm number	Alarm text	Source	Explanation, remedy
61105	"Cutter radius too large"	SLOT1 SLOT2 POCKET1 to POCKET4 LONGHOLE CYCLE90	The diameter of the milling cutter being used is too large for the figure that is to be machined; either a tool with a smaller radius must be used or the contour must be changed
61106	"Number of or distance between circular elements"	HOLES2 LONGHOLE SLOT1 SLOT2	Incorrect parameterization of NUM or INDA, the circular elements cannot be arranged in a full circle
61107	"First drilling depth incorrectly defined"	CYCLE83	First drilling depth is incompatible with final drilling depth
61108	"No admissible values for parameters _RAD1 and _DP1"	POCKET3 POCKET4	Parameters _RAD1 and _DP which define the path for depth infeed have been incorrectly set.
61109	"Parameter _CDIR incorrectly defined"	POCKET3 POCKET4	The value of the parameter for milling direction _CDIR has been incorrectly set and must be altered.
61110	"Final machining allowance on the base > depth infeed"	POCKET3 POCKET4	The final machining allowance on the base has been set to a higher value than the maximum depth infeed; either reduce final machining allowance or increase depth infeed.
61111	"Infeed width > tool diameter"	CYCLE71 POCKET3 POCKET4	The programmed infeed width is greater than the diameter of the active tool and must be reduced.
61112	"Negative tool radius"	CYCLE72 CYCLE76 CYCLE77 CYCLE90	The radius of the active tool is negative, the setting must be changed to a positive value.
61113	"Parameter _CRAD for corner radius too high"	POCKET3	The parameter for corner radius _CRAD has been set too high and must be reduced.
61114	"Machining direction G41/G42 incorrectly defined"	CYCLE72	The machining direction of the cutter radius compensation G41/G42 has been incorrectly set.

## 5.3 Overview of cycle alarms

Alarm number	Alarm text	Source	Explanation, remedy
61115	"Contour approach or return mode (straight line/circle/plane/space) incorrectly defined"	CYCLE72	The contour approach or return mode has been incorrectly programmed; check parameter _AS1 or AS2.
61116	"Approach or return travel=0"	CYCLE72	The approach or return travel is set to zero and must be increased; check parameter _LP1 or _LP2.
61117	"Active tool radius <= 0"	CYCLE71 POCKET3 POCKET4	The radius of the active tool is negative or zero and must be altered.
61118	"Length or width = 0"	CYCLE71	The length or width of the milling surface is not permissible; check parameters _LENG and _WID.
61124	"Infeed width has not been programmed"	CYCLE71	A value for the infeed width _MIDA must always be programmed for active simulation without a tool.
61125	"Technology selection in parameter _TECHNO incorrectly defined"	CYCLE84 CYCLE84 0	Check parameter _TECHNO.
61126	"Thread length too short"	CYCLE84 0	Program lower spindle speed/raise reference plane
61127	"Gear ratio of tapping axis incorrectly defined (machine data)"	CYCLE84 CYCLE84 0	Check machine data 31050 and 31060 in the appropriate gear stage of the tapping axis
61128	"Plunge angle=0 for insertion with oscillation or helix"	SLOT1	Check parameter _STA2
61180	"No name assigned to swivel data record even though machine data \$MN_MM_NUM_TOOL_CARRIER > 1"	CYCLE800	No name assigned to swivel data record even though several swivel data records exist (\$MN_MM_NUM_TOOL_CARRIER>0) or no swivel data record defined (\$MN_MM_NUM_TOOL_CARRIER=0)
61181	"NCK software version too old (no TOOLCARRIER functionality)"	CYCLE800	TOOLCARRIER functionality as from NCU 6.3xx
61182	"Name of swivel data record unknown"	CYCLE800	See Swivel cycle start-up CYCLE800 → Kinematics Name (swivel data record)



Alarm number	Alarm text	Source	Explanation, remedy
61183	"Retraction mode GUD7 _TC_FR outside value range 0..2"	CYCLE800	See Swivel cycle start-up CYCLE800 → Retraction; 1st transfer parameter CYCLE800(x,...) is faulty >2
61184	"No solution can be found with current angle inputs"	CYCLE800	
61185	"Rotary axis angle ranges incorrect (min>max) or not defined"	CYCLE800	Check start-up of swivel cycle CYCLE800
61186	"Invalid rotary axis vectors"	CYCLE800	Swivel cycle start-up CYCLE800: Rotary axis vector V1 or V2 not entered or incorrect
61187	"Block search computation end of block not valid for SWIVEL"	CYCLE800	Select block search with calculation contour
61188	"No axis name 1st rotary axis declared"		Swivel cycle start-up CYCLE800: no entry under rotary axis 1 identifier
61191	"5-axis transformation not set up"	CYCLE832	
61192	"Second 5-axis transformation not set up"	CYCLE832	
61193	"Compressor option not set up"	CYCLE832	
61194	"Spline interpolation option not set up"	CYCLE832	
61200	"Too many elements in machining block"	CYCLE76 CYCLE77	Revise machining block, if necessary deleting elements
61213	"Circle radius too small"	CYCLE77	Enter higher value for circle radius
61215	"Blank dimension incorrectly programmed"	CYCLE76 CYCLE77	Check unmachined part spigot dimensions. The unmachined part spigot must be larger than the machined part spigot.
61601	"Finished part diameter too small"	CYCLE94 CYCLE96	A finished part diameter has been programmed
61602	"Tool width incorrectly defined"	CYCLE93	Parting tool is larger than programmed groove width
61603	"Groove shape incorrectly defined"	CYCLE93	<ul style="list-style-type: none"> <li>• Radii/chamfers on the groove base are not suitable for the groove width</li> <li>• Face groove of a contour element parallel to the longitudinal axis is not possible</li> </ul>

## 5.3 Overview of cycle alarms

Alarm number	Alarm text	Source	Explanation, remedy
61604	"Active tool violates programmed contour"	CYCLE95	Contour violation in relief cut elements as a result of the clearance angle of the tool being used, i.e. use a different tool or check the contour subroutine
61605	"Contour incorrectly programmed"	CYCLE76 CYCLE77 CYCLE95	Illegal relief cut element detected
61606	"Error on contour preparation"	CYCLE95	An error was detected during contour preparation, this alarm is always output with NCK alarm 10930 ... 10934, 15800 or 15810
61607	"Starting point incorrectly programmed"	CYCLE95	The starting point reached before the cycle was called does not lie outside the rectangle described by the contour subroutine
61608	"Wrong tool point direction programmed"	CYCLE94 CYCLE96	A tool point direction between 1 ... 4 that matches the undercut form must be programmed
61609	"Form incorrectly programmed"	CYCLE94 CYCLE96	Check parameters for the undercut form
61610	"No infeed depth programmed"	CYCLE76 CYCLE77 CYCLE96	
61611	"No intersection found"	CYCLE95	The system cannot calculate an intersection with the contour. Check contour programming or change infeed depth
61612	"Thread cannot be recut"	CYCLE97 CYCLE98	
61613	"Undercut position incorrectly defined"	CYCLE94 CYCLE96	Check value in parameter _VARI
61803	"Programmed axis does not exist"	CYCLE83 CYCLE84 CYCLE840	Check parameter _AXN
61807	"Incorrect spindle direction programmed (active)"	CYCLE840	Check parameters SDR and SDAC
62100	"No drilling cycle active"	HOLES1 HOLES2	No drilling cycle was called modally before the drilling pattern cycle was called
62105	"Number of columns or rows is zero"	CYCLE800	
62180	"Set rotary axes x.x [deg]"	CYCLE800	Angles to be set for manual rotary axes
62181	"Set rotary axes x.x [deg]"	CYCLE800	Angle to be set for manual rotary axis

## 5.4 Messages in the cycles

The cycles output messages in the dialog line of the control. These messages do not interrupt processing.

They provide information about specific cycle behavior and how machining is progressing and are usually displayed for the duration of the machining operation or until the end of the cycle. The following messages can be displayed:

Message text	Source
"Depth: According to value for relative depth"	CYCLE81 ... CYCLE89, CYCLE840
"Machining elongated hole"	LONGHOLE
"Machining slot"	SLOT1
"Machining circumferential slot"	SLOT2
"Wrong mill direction: G3 will be generated"	SLOT1, SLOT2, POCKET1, POCKET2, CYCLE90
"Changed form of the undercut"	CYCLE94, CYCLE96
"1st drilling depth: According to value for relative depth"	CYCLE83
"Caution: Final machining allowance $\geq$ tool diameter!"	POCKET1, POCKET2
"Thread: – longitudinal thread machining"	CYCLE97, CYCLE98
"Thread: – transversal thread machining"	CYCLE97, CYCLE98
"Simulation active, no tool programmed, final contour being traversed"	POCKET1...POCKET4, SLOT1, SLOT2, CYCLE93, CYCLE72
"Simulation active, no tool programmed"	CYCLE71, CYCLE90, CYCLE94, CYCLE96
"Waiting for spindle reversal"	CYCLE840



## Notes

**Appendix**

A	Abbreviations.....	A-358
B	Terms .....	A-367
C	References .....	A-375
D	Index.....	A-389
E	Identifiers .....	A-393

**A Abbreviations**

<b>AS</b>	Automation System
<b>ASCII</b>	American Standard Code for Information Interchange
<b>ASIC</b>	Application Specific Integrated Circuit: User switching circuit
<b>ASUB</b>	Asynchronous Subroutine
<b>AuxF</b>	Auxiliary Function
<b>AV</b>	Production planning
<b>BA</b>	Operating mode
<b>BAG</b>	Mode group
<b>BB</b>	Ready
<b>BCD</b>	Binary Coded Decimals: Decimals number coded in binary format
<b>BCS</b>	Basic Coordinate System
<b>BIN</b>	Binary Files
<b>BIOS</b>	Basic Input Output System
<b>BOT</b>	Boot Files: Boot files for SIMODRIVE 611D
<b>BP</b>	Basic Program
<b>C Bus</b>	Communications Bus
<b>C1 .. C4</b>	Channel 1 to channel 4
<b>CAD</b>	Computer-Aided Design
<b>CAM</b>	Computer-Aided Manufacturing

<b>CNC</b>	Computerized Numerical Control
<b>COM</b>	Communication
<b>COR</b>	COordinate Rotation
<b>CP</b>	Communications processor
<b>CPU</b>	Central Processing Unit
<b>CR</b>	Carriage Return
<b>CRC</b>	Cutter Radius Compensation
<b>CRT</b>	Cathode Ray Tube: Teletube
<b>CSB</b>	Central Service Board: PLC module
<b>CSF</b>	Control System Flowchart (programming method for PLC)
<b>CTS</b>	Clear To Send: Clear to send for serial interfaces
<b>CUTOM</b>	CUTter radius cOMPensation: Tool radius compensation
<b>DAC</b>	Digital Analog Converter
<b>DB</b>	Data Block on the PLC
<b>DBB</b>	Data Block Byte on the PLC
<b>DBW</b>	Data Block Word on the PLC
<b>DBX</b>	Data Block bit on the PLC
<b>DC</b>	Direct Control: Movement of the rotary axis across the shortest path to the absolute position within one revolution
<b>DCD</b>	Data Carrier Detect
<b>DCE</b>	Data Communications Equipment
<b>DDE</b>	Dynamic Data Exchange
<b>DIN</b>	German Industrial Standard

<b>DIO</b>	Data Input/Output: Data transfer display
<b>DIR</b>	Directory
<b>DLL</b>	Dynamic Link Library
<b>DOS</b>	Disk Operating System
<b>DPM</b>	Dual Port Memory
<b>DPR</b>	Dual port RAM
<b>DRAM</b>	Dynamic Random Access Memory
<b>DRF</b>	Differential Resolver Function (handwheel)
<b>DRY</b>	DRY Run: Dry run feedrate
<b>DSB</b>	Decoding Single Block
<b>DTE</b>	Data terminal equipment
<b>DW</b>	Data word
<b>EIA Code</b>	Special punch tape code: Number of punched holes per character is always odd
<b>ENC</b>	ENCoder
<b>EPROM</b>	Erasable Programmable Read Only Memory
<b>ERROR</b>	ERROR from printer
<b>FB</b>	Function Block
<b>FBS</b>	Slimline screen
<b>FC</b>	Function Call: Function block on the PLC
<b>FDB</b>	Product database
<b>FDD</b>	Floppy Disk Drive



<b>FDD</b>	Feed drive
<b>FEPROM</b>	Flash EPROM: Readable and writable memory
<b>FIFO</b>	First in first out: Memory that operates without addresses where the data are always read out in the same order in which they were stored.
<b>FIPO</b>	Fine InterPolator
<b>FM</b>	Function Module
<b>FM-NC</b>	Function Module Numerical Control
<b>FPU</b>	Floating Point Unit
<b>FRA</b>	FRAME block
<b>FRAME</b>	Data block (frame)
<b>FST</b>	Feed STop
<b>GUD</b>	Global User Data
<b>GWRC</b>	Grinding Wheel Radius Compensation
<b>HD</b>	Hard Disk
<b>HEX</b>	Hexadecimal number
<b>HHU</b>	Hand-held unit
<b>HMI</b>	Operator control and monitoring
<b>HMS</b>	High resolution measuring system
<b>HW</b>	Hardware
<b>I</b>	Input
<b>I/O</b>	Input/output

<b>I/RF</b>	Power feed/return converter unit on the SIMODRIVE 611(D)
<b>IBN</b>	Installation and start-up
<b>IC (GD)</b>	Implicit Communication (Global Data)
<b>ICA</b>	Interpolatory Compensation with Absolute values
<b>IF</b>	Pulse enable for drive module
<b>IM</b>	Interface Module
<b>IMR</b>	Interface Module Receive: Interface module for receiving data
<b>IMS</b>	Interface Module Send: Interface module for transmitting data
<b>INC</b>	Increment: Incremental dimension
<b>INI</b>	INItializing data
<b>IPO</b>	InterPOLator
<b>IS</b>	Interface
<b>IS</b>	Interface Signal
<b>ISA</b>	International Standard Architecture
<b>ISO</b>	International Standard Organization
<b>ISO Code</b>	Special punch tape code: number of punched holes per character is always even
<b>JOG</b>	JOGging: Jog mode
<b>K<sub>ü</sub></b>	Transmission ratio
<b>K<sub>v</sub></b>	Servo gain factor
<b>LAD</b>	LADder logic (programming method for PLC)
<b>LCD</b>	Liquid Crystal Display

<b>LEC</b>	Leadscrew Error Compensation
<b>LED</b>	Light Emitting Diode
<b>LF</b>	Line Feed
<b>LR</b>	Position controller
<b>LUD</b>	Local User Data
<b>MB</b>	Megabyte(s)
<b>MC</b>	Measuring circuit
<b>MCP</b>	Machine Control Panel
<b>MCS</b>	Machine Coordinate System
<b>MD</b>	Machine Data
<b>MDA</b>	Manual Data Automatic: Manual input (MDI)
<b>MLFB</b>	Machine-readable product designation
<b>MMC</b>	Man Machine Communication: User interface on numerical control systems for operator control, programming and simulation
<b>MPF</b>	Main Program File: NC parts program (main program)
<b>MPI</b>	MultiPort Interface
<b>MS</b>	Microsoft (software manufacturer)
<b>MSD</b>	Main Spindle Drive
<b>NC</b>	Numerical Control
<b>NCK</b>	Numerical Control Kernel: Numerical kernel with block preparation, positioning range etc.
<b>NCU</b>	Numerical Control Unit: NCK hardware unit
<b>NRK</b>	Numeric Robotic Kernel: Name of NCK operating system

<b>NURBS</b>	Non-Uniform Rational Basis (B) Spline
<b>O</b>	Output
<b>OB</b>	Organization Block on PLC
<b>OEM</b>	Original Equipment Manufacturer
<b>OI</b>	Operator Interface
<b>OP</b>	Operator Panel
<b>OPI</b>	Operator Panel Interface: operator panel interface module
<b>OPT</b>	Options
<b>OSI</b>	Open Systems Interconnection: Standardization for computer communication
<b>P Bus</b>	Peripheral Bus
<b>PC</b>	Personal Computer
<b>PCIN</b>	Name of SW for data exchange with the control
<b>PCMCIA</b>	Personal Computer Memory Card International Association: Memory plug-in board normalization
<b>PG</b>	Programming device
<b>PLC</b>	Programmable Logic Control
<b>PMS</b>	Position Measuring System
<b>POS</b>	POSitioning
<b>RAM</b>	Random Access Memory: in which data can be read and written
<b>REF</b>	REFerence point approach function
<b>REPOS</b>	REPOSitioning function

<b>RISC</b>	Reduced Instruction Set Computer: type of processor with small instruction set and ability to process instructions at high speed
<b>ROV</b>	Rapid OVerride: Input adjustment
<b>RPA</b>	R Parameter Active: memory area on the NCK for R parameter numbers (RVA)
<b>RPY</b>	Roll Pitch Yaw: Type of rotation of a coordinate system
<b>RS-232-C</b>	Serial interface (definition of interchange circuit between DTE and DCE) (V.24)
<b>RTS</b>	Request To Send: control signal on serial data interfaces
<b>RVA</b>	R Variable Active (RPA)
<b>SBL</b>	Single BLock
<b>SD</b>	Setting Data
<b>SDB</b>	System Data Block
<b>SEA</b>	SEtting data Active: Identifier (file type) for setting data
<b>SFB</b>	System Function Block
<b>SFC</b>	System Function Call
<b>SK</b>	Soft Key
<b>SKP</b>	SKiP: Skip block
<b>SM</b>	Stepper Motor
<b>SPF</b>	Subroutine file: subroutine
<b>SR</b>	Subroutine
<b>SRAM</b>	Static RAM
<b>SSI</b>	Serial Synchronous Interface

<b>STL</b>	Statement list
<b>SW</b>	Software
<b>SYF</b>	System Files
<b>T</b>	Tool
<b>TC</b>	Tool Change
<b>TEA</b>	TEsting data Active: Refers to machine data
<b>TLC</b>	Tool Length Compensation
<b>TO</b>	Tool Offset
<b>TOA</b>	Tool Offset Active: Identifier (file type) for tool offsets
<b>TRANSMIT</b>	TRANSform Milling Into Turning: Coordinate conversion on turning machine for milling operations
<b>TRC</b>	Tool Radius Compensation
<b>UFR</b>	User Frame: Zero offset/work offset
<b>UI</b>	User Interface
<b>WCS</b>	Workpiece Coordinate System (Work)
<b>WO</b>	Work Offset (ZO)
<b>WOP</b>	Workshop-Oriented Programming
<b>WPD</b>	WorkPiece Directory
<b>ZO</b>	Zero Offset (WO)
<b>ZOA</b>	Zero Offset Active: Identifier (file type) for zero offset data
<b>μC</b>	Microcontroller

**B Terms****A****Alarms**

Important terms are listed in alphabetical order. The symbol "->" precedes terms which are explained under a separate entry in this list

All -> messages and alarms are displayed on the operator panel in plain text with date and time as well as the appropriate symbol for the reset criterion. Alarms and messages are displayed separately.  
Alarms and messages in the parts program  
Alarms and messages can be displayed directly from the parts program in plain text.  
Alarms and messages from PLC  
Alarms and messages relating to the machine can be displayed directly from the PLC program in plain text. No additional function block packages are required for this purpose.  
Cycle alarms lie in the number range 60000 to 69999.

**B****Blank**

The part used to start machining a workpiece.

**Block**

A section of a -> parts program terminated with a line feed. A distinction is made between -> main blocks and -> subblocks.

**Block search**

The block search function allows selection of any point in the parts program at which machining must start or be continued. The function is provided for the purpose of testing parts programs or continuing machining after an interruption.

**Booting**

Loading the system program after power ON.

**C****CNC**

-> NC

**CNC high-level language**

The high-level language offers: -> User variables, -> Predefined user variables, -> System variables, -> Indirect programming, -> arithmetic and trigonometric functions, -> Comparison operations and logic operations, -> Program branches and jumps, -> Program coordination (SINUMERIK 840D), -> Macros.

<b>COM</b>	Component of the NC control for the implementation and coordination of communication.
<b>Contour</b>	Outline of a -> workpiece.
<b>Coordinate system</b>	See -> machine coordinate system, -> workpiece coordinate system
<b>CPU</b>	Central Processor Unit, -> PLC
<b>Cycle</b>	Protected subroutine for executing a machining process that is repeated on the -> workpiece
<b>Cycle setting data</b>	Using these special setting data the cycle parameter calculation can be varied.
<b>Cycle support</b>	The available cycles are listed in menu "Cycle support" in the "Program" operating area. Once the desired machining cycle has been selected, the parameters required for assigning values are displayed in plain text.
<b>D</b>	
<b>Data module</b>	A data unit on the -> PLC which can be accessed by -> HIGHSTEP programs. A data unit on the -> NC: Data modules contain data definitions for global user data. These data can be initialized directly when they are defined.
<b>Data transfer program PCIN</b>	PCIN is an auxiliary program for transmitting and receiving CNC user data, e.g. parts programs, tool offsets, etc. via the serial interface. The PCIN program can run under MS-DOS on standard industrial PCs.
<b>Diagnosis</b>	Operating area of the control. The control has both a self-diagnosis program as well as test functions for servicing purposes: status, alarm and service displays.
<b>Dimensions specification, metric and inches</b>	Position and lead values can be programmed in inches in the machining program. The control is set to a basic system regardless of the programmable dimensional specification (G70/G71). The cycle are programmed independent of the measuring system.
<b>E</b>	
<b>Editor</b>	The editor makes it possible to create, modify, extend, join and import programs/texts/program blocks.



**F****Finished-part contour**

Contour of the finished workpiece. See also -> Blank.

**Frame**

A frame is a calculation rule that translates one Cartesian coordinate system into another Cartesian coordinate system. A frame contains the components -> zero offset, -> rotation, -> scaling, -> mirroring. Inside the cycle, additive frames programmed, which have an effect on the actual-value display during the cycle. After the cycle, the same workpiece coordinate system is active as before the call.

**G****Geometry axis**

Geometry axes are used to describe a 2 or 3-dimensional area in the workpiece coordinate system.

**Global main program/subroutine**

Each global main program/subroutine may appear only once under its name in the directory. It is not possible to use the same program name in different directories with different contents as a global program.

**I****Identifier**

Words in compliance with DIN 66025 are supplemented by identifiers (names) for variables (arithmetic variables, system variables, user variables), for subroutines, for keywords and for words with several address letters. These supplements have the same meaning as the words with respect to block format. Identifiers must be unambiguous. It is not permissible to use the same identifier for different objects.

**Imperial measurement system**

Measurement system which defines distances in "inches" and fractions of inches.

**J****JOG**

Control operating mode (setup operation): The machine can be set up in the Jog mode. Individual axes and spindle can be traversed in jog mode by means of the direction keys. Other functions which are executed in jog mode are -> reference point approach, -> REPOS and -> preset (set actual value).

**L****Languages**

The operator-prompt display texts, system messages and system alarms are available (on diskette) in five system languages:

**English, French, German, Italian and Spanish.**

The user can select **two** of the listed languages at a time in the control.

**M****Machine**

Operating area of the control.

**Machine coordinate system**

A coordinate system which is related to the axes of the machine tool.

**Machine origin**

A fixed point on the machine tool which can be referenced by all (derived) measurements systems.

**Macros**

A collections of instructions under a common identifier. The identifier in the program refers to the collected sequence of instructions.

**Main program**

-> Parts program identified by a number or name in which further main programs, subroutines or -> cycles may be called.

**MDA**

A mode in the control: Manual Data Automatic: In the MDA mode, individual program blocks or block sequences with no reference to a main program or subroutine can be input and executed immediately afterwards through actuation of the NC start key.

**Messages**

All messages programmed in the parts program and -> alarms detected by the system are displayed on the operator panel in plain text with date and time as well as the appropriate symbol for the reset criterion. Alarms and messages are displayed separately.

**Metric measurement system**

Standardized system of units: for lengths in millimeters (mm), meters (m), etc.

**Mirroring**

Mirroring exchanges the leading signs of the coordinate values of a contour in relation to an axis. Mirroring can be performed simultaneously in relation to several axes.

**Module**

"Module" is the term given to any files required for creating and processing programs.

**N****NC**

Numerical control It incorporates all the components of the of the machine tool control system: -> NCK, -> PLC, -> MMC, -> COM. Note CNC (computerized numerical control) would be a more appropriate description for the SINUMERIK 810D or 840D.

**NCK**

Numeric Control Kernel: Components of the NC control which executes -> parts programs and essentially coordinates the movements on the machine tool.

**O****Oriented spindle stop**

Stops the workpiece spindle with a specified orientation angle, e.g. to perform an additional machining operation at a specific position. This function is used in several drilling cycles.

**P****Parameter****840D:**

- Operating area of the control unit
- Computation parameter, can be set or scanned in the program at the discretion of the programmer for any purposes he may deem meaningful.

**Parts program**

A sequence of instructions to the NC control which combine to produce a specific -> workpiece by performing certain machining operation on a given -> blank.

**Parts program management**

The parts program management function can be organized according to -> workpieces. The number of programs and data to be managed determine the size of the user memory. Each file (programs and data) can be given a name consisting of a maximum of 24 alphanumeric characters.

**PG**

Programming device

**PLC**

Programmable logic control: -> Programmable logic control. Component of the -> NC control: A control which can be programmed to control the logic on a machine tool.

**Polar coordinates**

A coordinate system which defines the position of a point on a plane in terms of its distance from the origin and the angle formed by the radius vector with a defined axis.

<b>Power ON</b>	Control is switched off and then switched on again. After loading the cycles it is always necessary to carry out a Power ON.
<b>Program</b>	Operating area of the control. Sequence of instructions to the control.
<b>R</b>	
<b>Rapid traverse</b>	The highest traversing speed of an axis. It is used to move the tool from rest to the -> workpiece contour or retract the tool from the contour.
<b>Rigid tapping</b>	Rigid tapping can be drilled with the help of this function. When the rigid tapping function is used, interpolation of the spindle acting as a rotary axis and the drilling axis ensures that threads are cut exactly to the end of the drilling depth, e.g. tapped blind hole (precondition: spindle is operating in axis mode). -> CYCLE84
<b>Rotation</b>	Component of a -> frame which defines a rotation of the coordinate system through a specific angle.
<b>R-Parameter</b>	Calculation parameter. The programmer of the -> parts program can assign or request the values of the R parameter as required.
<b>S</b>	
<b>Scaling</b>	Component of a -> frame which causes axis-specific alterations in the scale.
<b>Serial RS-232 interface</b>	For the purpose of data input and output, one serial RS-232 interface (similar to European Standard V.24) (RS232) is provided on the MMC module MMC 100 and two RS-232 interfaces on the MMC modules MMC 101 and MMC 102. It is possible to load and save machining programs, cycles as well as manufacturer and user data via these interfaces.
<b>Services</b>	Operating area of the control.
<b>Setting data</b>	Data which provide the NC control with information on properties of the machine tool in a way defined by the system software.

<b>Standard cycles</b>	<p>Standard cycles are provided for machining operations which are frequently repeated:</p> <p>Cycles for drilling/milling applications</p> <p>Cycles for turning applications (SINUMERIK FM-NC)</p> <p>The available cycles are listed in menu "Cycle support" in the "Program" operating area. Once the desired machining cycle has been selected, the parameters required for assigning values are displayed in plain text.</p>
<b>Subroutine</b>	<p>A sequence of instructions of a -&gt; parts program which can be called repetitively with various defining parameters. The subroutine is called from a main program. Every subroutine can be protected against unauthorized read-out and display. -&gt; Cycles are a type of subroutine.</p>
<b>T</b>	
<b>Tapping with compensating chuck</b>	<p>Tapping is carried out without spindle encoder (G33 or G63) -&gt; CYCLE840</p>
<b>Text editor</b>	<p>-&gt; Editor</p>
<b>Tool</b>	<p>A part used on the machine tool for machining. Examples of tools include cutting tools, mills, drills, laser beams, etc.</p>
<b>Tool edge radius compensation</b>	<p>When a contour is programmed, it is assumed that a pointed tool is used. Since this is not always possible, the control makes allowance for the curvature radius of the tool being used. The curvature centre point displaced by the curvature radius is guided equidistantly to the contour.</p> <p>Turning and milling cycles select and deselect the cutting radius offset internally.</p>
<b>Tool offset</b>	<p>A tool is selected through the programming of a <b>T function</b> (5 decades, integer) in the block. Up to nine cutting edges (D addresses) can be assigned to each T number. The number of tools to be managed in the control is set at the configuration stage.</p>
<b>Tool radius compensation</b>	<p>In order to program a desired -&gt; workpiece contour directly, the control must traverse a path equidistant to the programmed contour with allowance for the radius (G41/G42).</p>

**U****User-defined variables**

Users can define variables in the -> parts program or data block (global user data) for their own use. A definition contains a data type specification and the variable name. See also -> System variable. Cycles work internally with user-defined variables.

**V****Variable definition**

A variable definition includes the specification of a data type and a variable name. The variable name can be used to address the value of the variable.

**W****Workpiece**

Part to be created/machined by the machine tool.

**Workpiece contour**

Setpoint contour of the -> workpiece to be created/machined.

**Workpiece coordinate system**

The starting position of the workpiece coordinate system is the -> workpiece origin. When programming in the workpiece coordinate system, the dimensions and directions refer to this system.

**Workpiece origin**

The workpiece origin is the starting point for the -> workpiece coordinate system. It is defined by the distance to the machine origin.

**Z****Zero offset**

Specification of a new reference point for a coordinate system through reference to an existing origin and a -> frame settable.

SINUMERIK FM-NC: Four independent zero offsets can be selected for each CNC axis. SINUMERIK 840D: A configurable number of settable zero offsets are available for each CNC axis. The offsets – which are selected by means of G functions – take effect alternately.  
External

In addition to all the offsets which define the position of the workpiece zero, it is possible to superimpose an external zero offset

- by means of a handwheel (DRF offset) or
- from the PLC.

Programmable

It is possible to program zero offsets for all path and positioning axes by means of the TRANS statement.

**C References****General Documentation**

**/BU/** SINUMERIK 840D/840Di/810D/802S, C, D  
Ordering Information  
Catalog NC 60  
Order number: E86060-K4460-A101-A9-7600

**/ST7/** **SIMATIC**  
SIMATIC S7 Programmable Logic Controllers  
Catalog ST 70  
Order number: E86060-K4670-A111-A3-7600

**/Z/** SINUMERIK, SIROTEC, SIMODRIVE  
Connections & System Components  
Catalog NC Z  
Order number: E86060-K4490-A001-A8-7600

**Electronic Documentation**

**/CD1/** The SINUMERIK System (11.02 Edition)  
DOC ON CD  
(includes all SINUMERIK 840D/840Di/810D/802 and SIMODRIVE  
publications)  
Order number: 6FC5 298-6CA00-0BG3

**User Documentation**

<b>/AUK/</b>	SINUMERIK 840D/810D <b>AutoTurn Short Operating Guide</b> Order number: 6FC5 298-4AA30-0BP3	(09.01 Edition)
<b>/AUP/</b>	SINUMERIK 840D/810D <b>AutoTurn Graphic Programming System</b> Operator's Guide Programming/Setup Order number: 6FC5 298-4AA40-0BP3	(02.02 Edition)
<b>/BA/</b>	SINUMERIK 840D/810D <b>Operator's Guide MMC</b> Order number: 6FC5 298-6AA00-0BP0	(10.00 Edition)
<b>/BAD/</b>	SINUMERIK 840D/840Di/810D <b>Operator's Guide: HMI Advanced</b> Order number: 6FC5 298-6AF00-0BP2	(11.02 Edition)
<b>/BEM/</b>	SINUMERIK 840D/810D <b>Operator's Guide: HMI Embedded</b> Order number: 6FC5 298-6AC00-0BP2	(11.02 Edition)
<b>/BAH/</b>	SINUMERIK 840D/840Di/810D <b>Operator's Guide HT 6 (HPU New)</b> Order number: 6FC5 298-0AD60-0BP2	(06.02 Edition)
<b>/BAK/</b>	SINUMERIK 840D/840Di/810D <b>Short Operating Guide</b> Order number: 6FC5 298-6AA10-0BP0	(02.01 Edition)
<b>/BAM/</b>	SINUMERIK 810D/840D <b>Operator's Guide ManualTurn</b> Order number: 6FC5 298-6AD00-0BP0	(08.02 Edition)



<b>/BAS/</b>	SINUMERIK 840D/810D <b>Operator's Guide ShopMill</b> Order number: 6FC5 298-6AD10-0BP1	(09.02 Edition)
<b>/BAT/</b>	SINUMERIK 810D/840D <b>Operator's Guide ShopTurn</b> Order number: 6FC5 298-6AD50-0BP2	(10.02 Edition)
<b>/BAP/</b>	SINUMERIK 840D/840Di/810D <b>Handheld Programming Unit</b> Order number: 6FC5 298-5AD20-0BP1	(04.00 Edition)
<b>/BNM/</b>	SINUMERIK 840D/840Di/810D <b>User's Guide Measuring Cycles</b> Order number: 6FC5 298-6AA70-0BP2	(11.02 Edition)
<b>/DA/</b>	SINUMERIK 840D/840Di/810D <b>Diagnostics Guide</b> Order number: 6FC5 298-6AA20-0BP3	(11.02 Edition)
<b>/KAM/</b>	SINUMERIK 840D/810D <b>Short Guide ManualTurn</b> Order number: 6FC5 298-5AD40-0BP0	(04.01 Edition)
<b>/KAS/</b>	SINUMERIK 840D/810D <b>Short Guide ShopMill</b> Order number: 6FC5 298-5AD30-0BP0	(04.01 Edition)
<b>/PG/</b>	SINUMERIK 840D/840Di/810D <b>Programming Guide Fundamentals</b> Order number: 6FC5 298-6AB00-0BP2	(11.02 Edition)
<b>/PGA/</b>	SINUMERIK 840D/840Di/810D <b>Programming Guide Advanced</b> Order number: 6FC5 298-6AB10-0BP2	(11.02 Edition)
<b>/PGK/</b>	SINUMERIK 840D/840Di/810D <b>Short Guide Programming</b> Order number: 6FC5 298-6AB30-0BP1	(02.01 Edition)
<b>/PGM/</b>	SINUMERIK 840D/840Di/810D <b>Programming Guide ISO Milling</b> Order number: 6FC5 298-6AC20-0BP2	(11.02 Edition)

**/PGT/** SINUMERIK 840D/840Di/810D  
**Programming Guide ISO Turning** (11.02 Edition)  
Order number: 6FC5 298-6AC10-0BP2

**/PGZ/** SINUMERIK 840D/840Di/810D  
**Programming Guide Cycles** (11.02 Edition)  
Order number: 6FC5 298-6AB40-0BP2

**/PI/** **PCIN 4.4**  
Software for Data Transfer to/from MMC Module  
Order number: 6FX2 060-4AA00-4XB0 (English, French, German)  
Order from: WK Fürth

**/SYI/** SINUMERIK 840Di  
**System Overview** (02.01 Edition)  
Order number: 6FC5 298-6AE40-0BP0

### Manufacturer/Service Documentation

#### a) Lists

**/LIS/** SINUMERIK 840D/840Di/810D/  
SIMODRIVE 611D  
**Lists** (11.02 Edition)  
Order number: 6FC5 297-6AB70-0BP3

**b) Hardware**

<b>/BH/</b>	SINUMERIK 840D/840Di/810D <b>Operator Components Manual (HW)</b> Order number: 6FC5 297-6AA50-0BP2	(11.02 Edition)
<b>/BHA/</b>	SIMODRIVE <b>Sensor</b> <b>Absolute Encoder with PROFIBUS DP</b> User's Guide (HW) Order number: 6SN1 197-0AB10-0YP1	(02.99 Edition)
<b>/EMV/</b>	SINUMERIK, SIROTEC, SIMODRIVE <b>EMC Installation Guideline</b> Planning Guide (HW) Order number: 6FC5 297-0AD30-0BP1	(06.99 Edition)
<b>/PHC/</b>	SINUMERIK 810D <b>Configuring Manual (HW)</b> Order number: 6FC5 297-6AD10-0BP0	(03.02 Edition)
<b>/PHD/</b>	SINUMERIK 840D <b>Configuring Manual NCU 561.2-573.2 (HW)</b> Order number: 6FC5 297-6AC10-0BP2	(10.02 Edition)
<b>/PHF/</b>	SINUMERIK FM-NC <b>Configuring Manual NCU 570 (HW)</b> Order number: 6FC5 297-3AC00-0BP0	(04.96 Edition)
<b>/PMH/</b>	SIMODRIVE <b>Sensor</b> <b>Hollow-Shaft Measuring System</b> Configuring/Installation Guide, SIMAG H (HW) Order number: 6SN1197-0AB30-0BP0	(05.99 Edition)

**c) Software****/FB1/**

SINUMERIK 840D/840Di/810D

**Description of Functions, Basic Machine (Part 1)** (11.02 Edition)

(the various manuals are listed below)

Order number: 6FC5 297-6AC20-0BP2

- A2 Various Interface Signals
- A3 Axis Monitoring, Protection Zones
- B1 Continuous Path Mode, Exact Stop and Look Ahead
- B2 Acceleration
- D1 Diagnostic Tools
- D2 Interactive Programming
- F1 Travel to Fixed Stop
- G2 Velocities, Setpoint/Actual Value Systems, Closed-Loop Control
- H2 Output of Auxiliary Functions to PLC
- K1 Mode Group, Channels, Program Operation Mode
- K2 Coordinate Systems, Axis Types, Axis Configurations,  
Actual-Value System for Workpiece, External Zero Offset
- K4 Communication
- N2 EMERGENCY STOP
- P1 Transverse Axes
- P3 Basic PLC Program
- R1 Reference Point Approach
- S1 Spindles
- V1 Feeds
- W1 Tool Compensation

**/FB2/**

SINUMERIK 840D/840Di/810D(CCU2)

**Description of Functions, Extended Functions** (Part 2) (11.02 Edition)

including FM-NC: Turning, Stepping Motor

(the various manuals are listed below)

Order number: 6FC5 297-6AC30-0BP2

- A4 Digital and Analog NCK I/Os
- B3 Several Operator Panels and NCUs
- B4 Operation via PG/PC
- F3 Remote Diagnostics
- H1 Jog with/without Handwheel
- K3 Compensations
- K5 Mode Groups, Channels, Axis Replacement
- L1 FM-NC Local Bus
- M1 Kinematic Transformation
- M5 Measurements
- N3 Software Cams, Position Switching Signals
- N4 Punching and Nibbling
- P2 Positioning Axes
- P5 Oscillation
- R2 Rotary Axes
- S3 Synchronous Spindles
- S5 Synchronized Actions (SW 3 and lower, higher /FBSY/)
- S6 Stepper Motor Control
- S7 Memory Configuration
- T1 Indexing Axes
- W3 Tool Change
- W4 Grinding

**/FB3/**

SINUMERIK 840D/840Di/810D

**Description of Functions Special Functions (Part 3)** (11.02 Edition)

(the various manuals are listed below)

Order number: 6FC5 297-6AC80-0BP2

- F2 3-Axis to 5-Axis Transformation
- G1 Gantry Axes
- G3 Cycle Times
- K6 Contour Tunnel Monitoring
- M3 Coupled Axes and ESR
- S8 Constant Workpiece Speed for Centerless Grinding
- T3 Tangential Control
- TE0 Installation and Activation of Compile Cycles
- TE1 Clearance Control
- TE2 Analog Axis
- TE3 Speed/Torque Coupling Master-Slave
- TE4 Transformation Package Handling
- TE5 Setpoint Exchange
- TE6 MCS Coupling
- TE7 Retrace Support
- TE8 Unlocked Path-Synchronous Switching Signal Output
- V2 Preprocessing
- W3 3D Tool Radius Compensation

**/FBA/**

SIMODRIVE 611D/SINUMERIK 840D/810D

**Description of Functions, Drive Functions** (11.02 Edition)

(the various sections are listed below)

Order number: 6SN1 197-0AA80-0BP9

- DB1 Operational Messages/Alarm Reactions
- DD1 Diagnostic Functions
- DD2 Speed Control Loop
- DE1 Extended Drive Functions
- DF1 Enable Commands
- DG1 Encoder Parameterization
- DL1 Linear Motor MD
- DM1 Calculation of Motor/Power Section Parameters and Controller Data
- DS1 Current Control Loop
- DÜ1 Monitors/Limitations

**/FBAN/**

SINUMERIK 840D/SIMODRIVE 611 DIGITAL

**Description of Functions ANA-MODULE** (02.00 Edition)

Order number: 6SN1 197-0AB80-0BP0

<b>/FBD/</b>	SINUMERIK 840D Description of Functions <b>Digitizing</b> (07.99 Edition) Order number: 6FC5 297-4AC50-0BP0 DI1 Start-Up DI2 Scanning with Tactile Sensors (scancad scan) DI3 Scanning with Lasers (scancad laser) DI4 Milling Program Generation (scancad mill)
<b>/FBDN/</b>	CAM Integration DNC NT-2000 Description of Functions <b>System for NC Data Management and Data Distribution</b> (01.02 Edition) Order number: 6FC5 297-5AE50-0BP2
<b>/FBDT/</b>	SINUMERIK 840D/840Di/810D IT Solutions <b>Data Transfer via Network (SinDNC)</b> (09.01 Edition) Description of Functions Order number: 6FC5 297-1AE70-0BP1
<b>/FBFA/</b>	SINUMERIK 840D/840Di/810D Description of Functions <b>ISO Dialects for SINUMERIK</b> (11.02 Edition) Order number: 6FC5 297-6AE10-0BP2
<b>/FBFE/</b>	SINUMERIK 840D/810D Description of Functions <b>Remote Diagnosis</b> (11.02 Edition) Order number: 6FC5 297-0AF00-0BP2
<b>/FBH/</b>	SINUMERIK 840D/810D <b>HMI Programming Package</b> (11.02 Edition) Order number: (is part of the SW delivery) Part 1 User's Guide Part 2 Description of Functions
<b>/FBHLA/</b>	SINUMERIK 840D/SIMODRIVE 611 digital Description of Functions <b>HLA Module</b> (04.00 Edition) Order number: 6SN1 197-0AB60-0BP2
<b>/FBMA/</b>	SINUMERIK 840D/810D Description of Functions <b>ManualTurn</b> (08.02 Edition) Order number: 6FC5 297-6AD50-0BP0

<b>/FBO/</b>	<p>SINUMERIK 840D/810D Description of Functions <b>Configuring of OP 030 Operator Interface</b> (09.01 Edition) (the various sections are listed below) Order number: 6FC5 297-6AC40-0BP0</p> <p>BA Operator's Guide EU Development Environment (Configuring Package) PSE Introduction to Configuring of Operator Interface IK Screen Kit: Software Update and Configuration PS Online only: Configuring Syntax (Configuring Package)</p>
<b>/FBP/</b>	<p>SINUMERIK 840D Description of Functions <b>C-PLC Programming</b> (03.96 Edition) Order number: 6FC5 297-3AB60-0BP0</p>
<b>/FBR/</b>	<p>SINUMERIK 840D/810D IT Solutions Description of Functions <b>Computer Link (SINCOM)</b> (09.01 Edition) Order number: 6FC5 297-6AD60-0BP0</p> <p>NFL Host Computer Interface NPL PLC/NCK Interface</p>
<b>/FBSI/</b>	<p>SINUMERIK 840D/SIMODRIVE Description of Functions <b>SINUMERIK Safety Integrated</b> (09.02 Edition) Order number: 6FC5 297-6AB80-0BP1</p>
<b>/FBSP/</b>	<p>SINUMERIK 840D/810D Description of Functions <b>ShopMill</b> (09.02 Edition) Order number: 6FC5 297-6AD80-0BP1</p>
<b>/FBST/</b>	<p><b>SIMATIC</b> <b>FM STEPDRIVE/SIMOSTEP</b> (01.01 Edition) Description of Functions Order number: 6SN1 197-0AA70-0YP4</p>
<b>/FBSY/</b>	<p>SINUMERIK 840D/810D Description of Functions <b>Synchronized Actions</b> (10.02 Edition) for Wood, Glass, Ceramics and Presses Order number: 6FC5 297-6AD40-0BP2</p>



<b>/FBT/</b>	SINUMERIK 840D/810D Description of Functions <b>ShopTurn</b> Order number: 6FC5 297-6AD70-0BP2	(10.02 Edition)
<b>/FBTC/</b>	SINUMERIK 840D/810D IT Solutions <b>SINUMERIK Tool Data Communication SinTDC</b> Description of Function Order number: 6FC5 297-5AF30-0BP0	(01.02 Edition)
<b>/FBTD/</b>	SINUMERIK 840D/810D Description of Functions <b>Tool Information System</b> (SinTDI) with Online Help Order number: 6FC5 297-6AE00-0BP0	(02.01 Edition)
<b>/FBU/</b>	<b>SIMODRIVE 611 universal</b> Description of Functions Closed-Loop Control Component for Speed Control and Positioning Description of Functions Order number: 6SN1 197-0AB20-0BP6	(08.02 Edition)
<b>/FBW/</b>	SINUMERIK 840D/810D Description of Functions <b>Tool Management</b> Order number: 6FC5 297-6AC60-0BP1	(10.02 Edition)
<b>/FBWI/</b>	SINUMERIK 840D/840Di/810D Description of Functions <b>WinTPM</b> Order number: This document is part of the software	(02.02 Edition)
<b>/HBA/</b>	SINUMERIK 840D/840Di/810D <b>Manual @Event</b> Order number: 6AU1900-0CL20-0BA0	(01.02 Edition)
<b>/HBI/</b>	SINUMERIK 840Di <b>Manual</b> Order number: 6FC5 297-6AE60-0BP0	(09.02 Edition)
<b>/INC/</b>	SINUMERIK 840D/840Di/810D Commissioning Tool <b>SINUMERIK SinuCOM NC</b> Order number: (an integral part of the online Help for the start-up tool)	(02.02 Edition)
<b>/PFK/</b>	<b>SIMODRIVE</b> Planning Guide <b>1FT5/1FT6/1FK6 Motors</b> AC Servo Motors for Feedrate and Main Spindle Drives Order number: 6SN1 197-0AC20-0BP0	(12.01 Edition)

<b>/PJE/</b>	<p>SINUMERIK 840D/810D  <b>HMI Embedded Configuring Package</b> (08.01 Edition)          Description of Functions: Software Update, Configuration,          Installation          Order number: 6FC5 297-6EA10-0BP0          (the document PS Configuring Syntax is supplied with the software          and available as a pdf file)</p>
<b>/PJFE/</b>	<p><b>SIMODRIVE</b>          Planning Guide (09.01 Edition)  <b>Built-In Synchronous Motors 1FE1</b>          Three-Phase AC Motors for Main Spindle Drives          Order number: 6SN1 197-0AC00-0BP1</p>
<b>/PJLM/</b>	<p><b>SIMODRIVE</b>          Planning Guide <b>Linear Motors 1FN1, 1FN3</b> (11.01 Edition)          ALL General Information about Linear Motors          1FN1 1FN1 Three-Phase Linear Motor          1FN3 1FN3 Three-Phase Linear Motor          CON Connections          Order number: 6SN1 197-0AB70-0BP2</p>
<b>/PJM/</b>	<p><b>SIMODRIVE</b>          Planning Guide <b>Motors</b> (11.00 Edition)          Three-Phase AC Motors for Feed and Main Spindle Drives          Order number: 6SN1 197-0AA20-0BP5</p>
<b>/PJU/</b>	<p><b>SIMODRIVE 611</b>          Planning Guide <b>Inverters</b> (08.02 Edition)          Order number: 6SN1 197-0AA00-0BP6</p>
<b>/PMS/</b>	<p><b>SIMODRIVE</b> (04.02 Edition)          Planning Guide <b>ECO Motor Spindle</b> for Main Spindle Drives          Order number: 6SN1 197-0AD04-0BP0</p>
<b>/POS1/</b>	<p><b>SIMODRIVE POSMO A</b>          User's Guide (08.02 Edition)          Distributed Positioning Motor on PROFIBUS DP          Order number: 6SN2 197-0AA00-0BP3</p>
<b>/POS2/</b>	<p><b>SIMODRIVE POSMO A</b>          Installation Guide (enclosed with every POSMO A) (12.98 Edition)          Order number: 462 008 0815 00</p>

<b>/POS3/</b>	<b>SIMODRIVE POSMO SI/CD/CA</b> Distributed Servo Drive Systems, Operator's Guide Order number: 6SN2 197-0AA20-0BP3	(08.02 Edition)
<b>/PPH/</b>	<b>SIMODRIVE</b> Planning Guide <b>1PH2/1PH4/1PH7 Motors</b> AC Induction Motors for Main Spindle Drives Order number: 6SN1 197-0AC60-0BP0	(12.01 Edition)
<b>/PPM/</b>	<b>SIMODRIVE</b> Planning Guide <b>Hollow-Shaft Motors</b> Hollow-Shaft Motors for Main Spindle Drives 1PM4 and 1PM6 Order number: 6SN1 197-0AD03-0BP0	(10.01 Edition)
<b>/S7H/</b>	<b>SIMATIC S7-300</b> Reference Manual: CPU Data (HW Description) Reference Manual: Module Data Order number: 6ES7 398-8AA03-8AA0	(10.98 Edition)
<b>/S7HT/</b>	<b>SIMATIC S7-300</b> Manual STEP 7, Fundamentals, V. 3.1 Order number: 6ES7 810-4CA02-8AA0	(03.97 Edition)
<b>/S7HR/</b>	<b>SIMATIC S7-300</b> Manual STEP7, Reference Manuals, V3.1 Order number: 6ES7 810-4CA02-8AR0	(03.97 Edition)
<b>/S7S/</b>	<b>SIMATIC S7-300</b> <b>FM 353</b> Stepper Drive Positioning Module Order in conjunction with configuring package	(04.97 Edition)
<b>/S7L/</b>	<b>SIMATIC S7-300</b> <b>FM 354</b> Positioning Module for Servo Drive Order together with configuring package	(04.97 Edition)
<b>/S7M/</b>	<b>SIMATIC S7-300</b> <b>FM 357</b> Multimodule for Servo and Stepper Drives Order together with configuring package	(10.99 Edition)

**/SP/****SIMODRIVE 611-A/611-D,****SimoPro 3.1**

Program for Configuring Machine-Tool Drives

Order number: 6SC6 111-6PC00-0AA□,

Order from: WK Fürth

**d) Installation and Start-Up****/IAA/****SIMODRIVE 611A****Installation and Start-Up Guide**

(10.00 Edition)

(including description of SIMODRIVE 611D start-up software)

Order number: 6SN 1197-0AA60-0BP6

**/IAC/**

SINUMERIK 810D

**Installation and Start-Up Guide**

(11.02 Edition)

(including description of SIMODRIVE 611D start-up software)

Order number: 6FC5 297-6AD20-0BP0

**/IAD/**

SINUMERIK 840D/SIMODRIVE 611D

**Installation and Start-Up Guide**

(11.02 Edition)

(including description of SIMODRIVE 611D start-up software)

Order number: 6FC5 297-6AB10-0BP2

**/IAM/**

SINUMERIK 840D/840Di/810D

**HMI/MMC Installation and Start-Up Guide**

(11.02 Edition)

Order number: 6FC5 297-6AE20-0BP2

AE1	Updates/Options
BE1	Expand the operator interface
HE1	Online Help
IM2	Start-Up HMI Embedded
IM4	Start-Up HMI Advanced
TX1	Setting Foreign Language Texts

**D Index****A**

Absolute drilling depth 2-65, 3-132, 3-138, 3-151,  
3-176, 3-213  
Axis assignment 1-21

**B**

Behavior when quantity parameter is zero 2-108  
Blank 4-328  
Blank updating 4-337  
Blueprint programming 1-43  
Boring 2-61  
Boring 1 2-91  
Boring 2 2-94  
Boring 3 2-98  
Boring 4 2-101  
Boring 5 2-103  
Boring cycle 2-61

**C**

Call 1-21, 2-62  
Call conditions 1-21  
Centering 2-64  
Circumferential slot – SLOT2 3-143  
Configuring cycle selection 1-29  
Configuring help displays 1-34  
Configuring input screen forms 1-31  
Configuring tools 1-35  
Contour 1-line 1-43  
Contour 2-line 1-43  
Contour 3-line 1-43  
Contour definition 4-298, 4-335  
Contour monitoring 4-275, 4-301  
Contour programming 4-330  
CONTPRON 4-299  
Cycle alarms 5-349  
Cycle auxiliary subroutines 1-20  
Cycle call 1-23

Cycle parameterization 1-31  
Cycle setting data, milling 3-122  
Cycle setting data, turning 4-274  
Cycle startup (SW 6.2 and higher) 1-53  
Cycle support for user cycles (SW 6.2 and higher)  
1-48  
Cycle support in program editor 1-27  
Cycle support in program editor (SW 5.1 and  
higher) 1-40  
CYCLE71 3-173  
CYCLE72 3-179  
CYCLE73 3-198, 3-204  
CYCLE74 3-198, 3-199  
CYCLE75 3-198, 3-201  
CYCLE76 3-189  
CYCLE77 3-194  
CYCLE800 3-227  
CYCLE801 2-116  
CYCLE81 2-64  
CYCLE82 2-67  
CYCLE83 2-69  
CYCLE832 3-259  
CYCLE84 2-77  
CYCLE840 2-83  
CYCLE85 2-91  
CYCLE86 2-94  
CYCLE87 2-98  
CYCLE88 2-101  
CYCLE89 2-103  
CYCLE90 3-123  
CYCLE93 4-277  
CYCLE94 4-287  
CYCLE95 4-291  
CYCLE950 4-325  
CYCLE96 4-304  
CYCLE97 4-308  
CYCLE98 4-316

- D**  
Deep hole drilling with chip breaking 2-72  
Deep hole drilling with swarf removal 2-71  
Deep hole drilling 2-69  
Definition files for cycles 1-54  
Dot matrix 2-116  
Drill pattern cycles 1-19, 2-108  
Drilling 2-64  
Drilling cycles 1-19, 2-60  
Drilling pattern cycles without drilling cycle call  
2-108  
Drilling, counterboring 2-67
- E**  
Elongated holes on a circle – LONGHOLE 3-129  
Error Messages and Error Handling 5-347  
Extended stock removal cycle – CYCLE950  
4-325
- F**  
Face milling 3-173  
Face thread 4-314  
FGROUP 3-123  
Form of delivery for cycles in HMI Advanced 1-55  
Free contour programming 1-43
- G**  
Geometrical parameters 2-62  
Grooving cycle – CYCLE93 4-277
- H**  
High Speed Settings – CYCLE832 3-259  
Hole circle 2-113  
HOLES1 2-109  
HOLES2 2-113
- I**  
Independence of language 1-37  
Inside threads 3-125
- Integrating user cycles into the MMC 103  
simulation function 1-38
- L**  
Level definition 1-21  
Loading to the control 1-36  
LONGHOLE 3-129  
Longitudinal thread 4-314
- M**  
Machine data 1-53, 1-56  
Machining parameters 2-62  
Machining plane 1-21  
MCALL 2-105  
Messages 1-22, 5-355  
Milling circular pockets – POCKET2 3-153  
Milling circular pockets – POCKET4 3-167  
Milling circular spigots – CYCLE77 3-194  
Milling cycles 1-19  
Milling Cycles 3-119  
Milling rectangular pockets – POCKET1 3-149  
Milling rectangular pockets – POCKET3 3-157  
Milling rectangular spigots – CYCLE76 3-189  
Modal call 2-105
- O**  
Operating the cycles support function 1-38  
Outside threads 3-124  
Overview cycle files 1-28  
Overview of cycle alarms 5-349  
Overview of cycles 1-18
- P**  
Parallel-contour 4-327  
Parameter list 1-23  
Path milling 3-179  
Plausibility checks 2-108  
Pocket milling with islands 3-198  
Pocket milling with islands – CYCLE73 3-204  
POCKET1 3-149

POCKET2 3-153

POCKET3 3-157

POCKET4 3-167

## R

Reference plane 2-65, 3-213

Relative drilling depth 2-65, 3-132, 3-138, 3-151,  
3-176, 3-213

Residual material 4-328

Retraction plane 2-65, 3-213

Return conditions 1-21

Rigid tapping 2-77

Row of holes 2-109

## S

Safety distance 2-65, 3-213

SETMS 3-122

Simulation of cycles 1-26

Simulation without tool 1-26

SLOT1 3-135

SLOT2 3-143

Slots on a circle – SLOT1 3-135

Spindle handling 4-273

SPOS 2-79, 2-80

Starting point 4-301

Stock removal cycle – CYCLE95 4-291

Swiveling– CYCLE800 3-227

## T

Tapping with compensating chuck 2-83

Tapping with compensating chuck with encoder  
2-85

Tapping with compensating chuck without  
encoder 2-85

Thread chaining – CYCLE98 4-316

Thread cutting 3-123

Thread cutting – CYCLE97 4-308

Thread recutting (SW 5.3 and higher) 4-323

Thread undercut – CYCLE96 4-304

Tool clearance angle 4-275

Transfer island contour – CYCLE75 3-201

Transfer pocket edge contour – CYCLE74 3-199

Turning cycles 1-20, 4-271

Typical user cycle configuration 1-39

## U

Undercut cycle – CYCLE94 4-287

## Notes



840 D  
NCU 571840 D  
NCU 572  
NCU 573

810 D



840Di

## E Identifiers

List of input/output variables for measuring cycles

<i>Name</i>	<i>Meaning in English</i>	<i>Meaning in German</i>
<b>AD</b>	Allowance depth	Rohmaß Taschentiefe von Referenzebene
<b>AFSL</b>	Angle for slot length	Winkel für die Nutlänge
<b>ANG1, ANG2</b>	Flank angle	Flankenwinkel
<b>ANGB</b>	Liftoff angle for roughing	Abhebwinkel beim Schruppen
<b>AP1</b>	Unfinished dimension in plane	Rohmaß Taschenlänge/Taschenradius
<b>AP2</b>	Unfinished dimension in plane	Rohmaß Taschenbreite
<b>APP</b>	Approach path	Einlaufweg
<b>APX</b>	Axial value for defining blank for facing axis	achsweiser Wert zur Rohteildefinition für Planachse
<b>APXA</b>	Absolute or incremental evaluation of parameter APX	Bewertung des Parameters _APX absolut oder inkrementell
<b>APZ</b>	Axial value for defining blank for longitudinal axis	achsweiser Wert zur Rohteildefinition für Längsachse
<b>APZA</b>	Absolute or incremental evaluation of parameter APZ	Bewertung des Parameters _APZ absolut oder inkrementell
<b>AS1, AS2</b>	Direction of approach/approach travel	Spezifikation der Anfahrrichtung/-bahn
<b>AXN</b>	Tool axis	Werkzeugachse
<b>BNAME</b>	Name for program of drill positions	Name für Programm der Bohrpositionen
<b>CDIR</b>	Circle direction	Drehrichtung, Fräsrichtung
<b>CPA</b>	Center point, abscissa	Mittelpunkt des Lochkreises, Abszisse (absolut)
<b>CPO</b>	Center point,ordinate	Mittelpunkt des Lochkreises, Ordinate (absolut)
<b>CRAD</b>	Corner radius	Eckenradius
<b>DAM</b>	Degression value, Path for roughing interrupt	Degressionsfaktor / Weglänge
<b>DBH</b>	Distance between holes	Abstand zwischen den Bohrungen
<b>DIAG</b>	Groove depth	Einstichtiefe
<b>DIATH</b>	Diameter of thread	Nenndurchmesser, Außendurchmesser des Gewindes
<b>DIS1</b>	Distance	programmierbarer Vorhalteabstand
<b>DIS1</b>	Distance between columns	Abstand der Spalten
<b>DIS2</b>	Number of lines, Distance between rows	Abstand der Zeilen

840 D  
NCU 571840 D  
NCU 572  
NCU 573

810 D



840Di

<b>DM1 ... DM4</b>	Diameter	Durchmesser des Gewindes am Anfangspunkt
<b>DP</b>	Depth	Tiefe (absolut)
<b>DP1</b>	First depth	Eintauchtiefe
<b>DPR</b>	Depth, relative	Tiefe relativ zur Referenzebene
<b>DT</b>	Dwell time	Verweilzeit zum Spänebrechen beim Schruppen
<b>DTB</b>	Dwell time at bottom	Verweilzeit auf Endbohrtiefe/am Einstichgrund
<b>DTD</b>	Dwell time at depth	Verweilzeit auf Endbohrtiefe
<b>DTS</b>	Dwell time at starting point	Verweilzeit am Anfangspunkt
<b>ENC</b>	Tapping with/without encoder	Gewindebohren mit/ohne Geber
<b>FAL</b>	Finish allowance	konturgerechtes Schlichtaufmaß am Nutrand/Taschenrand
<b>FAL1</b>	Finish allowance on groove base	Schlichtaufmaß am Einstichgrund
<b>FAL2</b>	Finish allowance on flanks	Schlichtaufmaß an den Flanken
<b>FALD</b>	Finish allowance depth	Schlichtaufmaß am Grund
<b>FALZ</b>	Finish allowance, z axis	Schlichtaufmaß in der Längsachse
<b>FALX</b>	Finish allowance, x axis	Schlichtaufmaß in der Planachse
<b>FDEP</b>	First depth	erste Bohrtiefe (absolut)
<b>FDIS</b>	First distance	Abstand der ersten Bohrung vom Bezugspunkt
<b>FDP1</b>	Overrun path in direction to plane	Überlaufweg in Richtung der Ebenenzustellung
<b>FDPR</b>	First depth, relative	erste Bohrtiefe relativ zur Referenzebene
<b>FF1</b>	Feedrate for roughing	Vorschub für Schruppen
<b>FF2</b>	Feedrate for insertion	Vorschub zum Eintauchen
<b>FF3</b>	Feedrate for finishing	Vorschub für Schlichten
<b>FF4</b>	Feedrate for contour transition elements	Vorschub an Konturübergangselementen
<b>FFCP (ab SW 6.3)</b>	Feedrate for circular positioning	Vorschub für Zwischenpositionierung auf Kreisbahn
<b>FFD</b>	Feedrate for depth	Vorschub für Tiefenzustellung
<b>FFP1</b>	Feedrate surface	Vorschub für Flächenbearbeitung
<b>FFP2</b>	Feedrate for finishing	Vorschub für Schlichtbearbeitung
<b>FFR</b>	Feedrate	Vorschub
<b>FORM</b>	Definition of form	Definition der Form
<b>FPL</b>	Final point along longitudinal axis	Endpunkt in der Längsachse
<b>FRF</b>	Feedrate factor	Vorschubfaktor
<b>IANG</b>	Infeed angle	Zustellwinkel
<b>INDA</b>	Incremental angle	Fortschaltwinkel

840 D  
NCU 571840 D  
NCU 572  
NCU 573

810 D



840Di

<b>IDEP</b>	Infeed depth	Zustelltiefe
<b>KNAME</b>	Name of the contour subroutine	Name des Konturunterprogramms
<b>LSANF</b>	Block number/label identifying start of contour definition	Satznummer/Label des Beginns der Konturbeschreibung
<b>LSEND</b>	Block number/label identifying end of contour definition	Satznummer/Label des Endes der Konturbeschreibung
<b>LP1</b>	Length of approach travel, radius	Länge des Anfahrwegs, Radius
<b>LP2</b>	Length of return travel, radius	Länge des Abfahrwegs, Radius
<b>KDIAM</b>	Internal diameter of thread	Kerndurchmesser, Innendurchmesser des Gewindes
<b>LENG</b>	Elongated hole length, pocket length	Langlochlänge, Taschenlänge
<b>MDEP</b>	Minimum depth	Mindestbohrtiefe
<b>MID</b>	Maximum infeed depth	maximale Zustelltiefe für eine Zustellung
<b>MIDA</b>	Maximum infeed width	maximale Zustellbreite
<b>MIDF</b>	Maximum infeed depth for finishing	maximale Zustelltiefe für Schlichtbearbeitung
<b>MPIT</b>	Thread lead as thread size	Gewindesteigung als Gewindegröße
<b>NID</b>	Number of noncuts	Anzahl der Leerschnitte
<b>NP1 ... NP8</b>	Name/Label ...	Name des Konturunterprogramms der Fertigteilkontur/Label
<b>NPP</b>	Name of parts program	Name des Konturunterprogramms
<b>NRC</b>	Number of roughing cuts	Anzahl der Schruppschnitte
<b>NSP</b>	Start point offset first thread	Startpunktversatz für den ersten Gewindegang
<b>NUM</b>	Number of holes	Anzahl der Bohrungen
<b>NUM1</b>	Number of columns	Anzahl der Spalten
<b>NUM2</b>	Number of lines	Anzahl der Zeilen
<b>NUMT</b>	Number of threads	Anzahl der Gewindegänge
<b>PA</b>	Reference point, abscissa	Bezugspunkt Tasche
<b>PO</b>	Reference point, ordinate	Bezugspunkt Tasche
<b>PO1 ... PO4</b>	Point in longitudinal axis	Anfangspunkt/Zwischenpunkt/Endpunkt des Gewindes in der Längsachse
<b>PIT</b>	Thread lead	Gewindesteigung als Wert
<b>PNAME</b>	Name for pocket milling machining program	Name für Taschenfräsen Bearbeitungsprogramm
<b>POSS</b>	Position for oriented spindle stop	Spindelposition
<b>PP1 ... PP3</b>	Thread pitch 1...3 as value	Gewindesteigung 1...3 als Wert
<b>PRAD</b>	Pocket radius	Taschenradius
<b>RAD</b>	Radius	Radius des Kreises
<b>RAD1</b>	Radius	Radius der Helixbahn beim Eintauchen
<b>RCO1, RCO2</b>	Radius/chamfer outside	Radius/Fase, außen

840 D  
NCU 571840 D  
NCU 572  
NCU 573

810 D



840Di

<b>RCI1, RCI2</b>	Radius/chamfer inside	Radius/Fase, innen
<b>RFF</b>	Retract feed	Rückzugsvorschub
<b>RFP</b>	Reference plane	Referenzebene (absolut)
<b>ROP</b>	Run out path	Auslaufweg
<b>RPA</b>	Retract path, abscissa	Rückzugsweg in der Abszisse
<b>RPAP</b>	Retract path, applicate	Rückzugsweg in der Applikate
<b>RPO</b>	Retract path, ordinate	Rückzugsweg in der Ordinate
<b>RL</b>	Bypass contour	Umfahren der Kontur mittig
<b>RTP</b>	Retract plane	Rückzugsebene (absolut)
<b>SDAC</b>	Spindle direction after cyle	Drehrichtung nach Zyklusende
<b>SDIR</b>	Spindle direction	Spindelrichtung
<b>SDIS</b>	Safety distance	Sicherheitsabstand
<b>SDR</b>	Spindle direction for retraction	Drehrichtung für Rückzug
<b>SPCA</b>	Reference point, abscissa	Abszisse eines Bezugspunktes auf der Geraden (absolut)
<b>SPCO</b>	Reference point, ordinate	Ordinate dieses Bezugspunktes (absolut)
<b>SPD</b>	Starting point in the facing axis	Anfangspunkt in der Planachse
<b>SPL</b>	Starting point along longitudinal axis	Anfangspunkt in der Längsachse
<b>SSF</b>	Speed for finishing	Drehzahl bei Schlichtbearbeitung
<b>SST</b>	Speed for tapping	Drehzahl für Gewindebohren
<b>SST1</b>	Speed for retraction	Drehzahl für Rückzug
<b>STA, STA1</b>	Angle	Winkel
<b>STA2</b>	Insertion angle	Maximaler Eintauchwinkel für Pendelbewegung
<b>TDEP</b>	Thread depth	Gewindetiefe
<b>TN</b>	Name of stock removal tool	Name des Ausräumwerkzeuges
<b>TOL1</b>	Blank tolerance	Rohteiltoleranz
<b>TYPTH</b>	Typ of thread	Gewindetyp
<b>VARI</b>	Working	Bearbeitungsart
<b>VRT</b>	Variable return path	variabler Rückzugsbetrag / Rückzugsweg
<b>WID</b>	(Pocket) width	Taschenbreite
<b>WIDG</b>	Groove width	Einstichbreite


To  
 SIEMENS AG  
 A&D MC BMS  
 P.O. Box 3180  
 91050 Erlangen, Germany  
 Phone: ++49(0)180-5050-222 [Hotline]  
 Fax: ++49(0)9131-98-2176 [Documentation]  
 E-mail: [motioncontrol.docu@erlf.siemens.de](mailto:motioncontrol.docu@erlf.siemens.de)

<b>From</b>	Suggestions
Name	Corrections
Company/Department	for Publication/Manual:
Address:	SINUMERIK 840D/840Di/810D
Zip Code:	Cycles
Phone: /	User Documentation
Fax: /	Programming Guide
	Order no.: 6FC5 298-6AB40-0BP2
	Edition: 11.02
	If you come across any printing errors in this document, please let us know using form provided. We would also appreciate and new ideas and/or suggestion for improvements.

**Suggestions and/or corrections**



# Overview of SINUMERIK 840D/840Di/810D Documentation (11.2002)



\*) These documents are a minimum requirement

**Siemens AG**

Automation & Drives

Motion Control Systems

P.O. Box 3180, D-91050 Erlangen

Germany

[www.ad.siemens.de](http://www.ad.siemens.de)

© Siemens AG, 2002  
Subject to change without prior notice  
Order No: 6FC5 298-6AB40-0BP2

Printed in Germany