

SECTION 2

Spindle

WRG_0023E_wye_delta_contactors




Wrg_0024A_spindle_motor_connection




FOR VMC 2216, 3016, 3020, 4020, 6030, 8030.


Wrg_0026B_1980_0_15k_air_oil



WRG_0043A_encoder_cable_E5D



WRG_0046C_Tool_IO_switch_on_spindle



Installation procedure is given in FSP-W1042.